

March 22, 2012

John Rimmer, General Manager City of West Memphis WWTP P.O. Box 1868 West Memphis, AR 72303

RE: Pretreatment Compliance Inspection

RE: AFIN: 18-00879 NPDES Permit No.: AR0022039

Dear Mr. Rimmer:

On December 7, 2011 and December 9, 2011 fellow inspector Brent Walker and I performed a routine pretreatment compliance inspection of the waste water treatment facility in accordance with the provisions of the Federal Clean Water Act, the Arkansas Water and Air Pollution Control Act, and the regulations promulgated thereunder. This inspection revealed the following violations:

- 1. The IU site visit to Quala Wash (Previously PSC Container) revealed:
 - a. Lack of familiarity with pretreatment requirements by facility representative.
 - b. Inadequate sample point. The sampling hose was placed horizontally inside a PVC "T".
 - c. Tanker contents were drained onto the ground and bypassed pretreatment equipment.
 - d. The drain valve was open on the secondary containment to the outdoor holding tank.
- 2. The IU site visit to ATM Oil / Jim's Tank Service revealed the following violations:
 - a. Lack of familiarity with pretreatment requirements by facility representatives.
 - b. This facility routinely discharged leachate into the West Memphis Collection system in violation of the pretreatment permit. Additionally, West Memphis POTW personnel were not aware of the leachate received from this industrial user.
 - c. Inadequate sampling. Wastewater was hauled from Marion to West Memphis by truck and discharged into a manhole. Samples were usually taken from the bottom of the tanker, and not from the top where oil was present.
- 3. The Baseline Monitoring Reports (BMR) were not reviewed for compliance with 40 CFR 403.12 (b). The BMR for Quala Wash did not include process flow diagrams, and a certification of compliance.
- 4. All permitted facilities were not inspected by the POTW. Only Categorical Industrial Users were inspected.

John Rimmer, City of West Memphis WWTP March 22, 2012 Page 2

The above items require your immediate attention. Please submit a written response to these findings to Water Division Enforcement Branch of this Department. This response should be mailed to the address below and should contain documentation describing the course of action taken to correct each item noted. This corrective action should be completed as soon as possible, and the written response is due by **April 4, 2012.**

For additional information you may contact the Enforcement Branch by telephone at 501-682-0639 or by fax at 501-682-0910.

If I can be of assistance, please contact me at greenway@adeq.state.ar.us or 870-935-7221 ext.-15.

Sincerely,

Michael B. Greenway

District 3 Field Inspector

Water Division

cc: Water Division Enforcement Branch

Water Division Permits Branch

ADEQ Water NPDES Inspection	AFIN: 18-00879	Permit #: AR0022039

\$ EPA					Form Approved OMB No. 2040-0003			
		UNITED STATES ENVIRONM		AGENCY				
	NPDES Compliance Inspection Report							
		\$	Section A: Nationa	al Data S	ystem Coding		•	
1	Transaction Code N 2 5 3 A R	0 0 2 2 0		12 1 emarks	Yr/Mo/Day 1 1 2 0 9 17	Insp 18	pec. Type Inspector Fac. Type 19 S 20 2	
	0 0 2 C							
	Inspection Work Days 67 69	Facility Evaluation R 70 N	Ĭ	N 72	QA 74 75]	Reserved	
			Section B	: Facility	Data			
Name and Location of Facility Inspected (For industrial users discharging to POTW, also include POTW name and NPDES permit number) Entry Time/Date 13:00 / December 09, 2011					Permit Effective Date August 1, 2008			
ATM Oil / Jim's Tank Service 435 Dacus Rd. West Memphis, AR Crittenden Co.			39	Exit Time/Date 14:40 / December 09, 2011		Permit Expiration Date July 31, 2013		
	Name(s) of On-Site Representative(s)/Title(s)/Phone and Fax Number(s) Dena West /Controller-Reg. Agent / 870-357-7237 Other Facility Data					·		
Name, Address of Responsible Official/Title/Phone and Fax Number Lance Berryhill / Chief Manager / 901-357-7237 ATM Oil / Jim's Tank Service 435 Dacus Rd. Marion, AR 72364			Contacted		55.190591 0.126310 DS # 064406			
Section C: Areas Evaluated During Inspection (S = Satisfactory, M = Marginal, U = Unsatisfactory, N = Not Evaluated)								
	Permit	Flow Measurement	nt	Op	perations & Maintenance		Sampling	
	Records/Reports	Self-Monitoring I	Program		udge Handling/Disposal		Pollution Prevention	
	Facility Site Review	Compliance Sche	dules	es Y Pretreatment			Multimedia	
	Effluent/Receiving Waters	Laboratory	Storm Water of Findings/Comments (Attach additional sheets if necessary)		7)	Other:		
See the attached IU Site Visit form and the PCI Inspection Report from this date for additional information								
Name(s) and Signature(s) of Inspector(s) Michael Greenway Brent L. Walker Agency/Office/Telephone/ AR Dept. of Environment		ental Quality-Jonesboro		Date				
Middle Graph Brest 2 Walker (870) 935-7221 ext. 15/(870) 935-4715 (Fax) January 25, 2011			January 25, 2011					
Sig	nature of Reviewer		Agency/Office/I	Phone and	1 Fax Numbers		Date	

Industrial User Site Visit

Nan	ne of Industry: ATM Oil / Jim's Tank S	ervice					
Ind	ustry Contacts: Dena West, Controller(ATM Oil)	/ Reg. Ag	gent (Jim's	s Tank So	ervice)	
Тур	e of Industry: Environmental Services (Spill clea	nup, tank	cleaning,	leachate	disposal)	
Dat	e of Visit: December 09, 2011						
1.	Significant industrial user?		_ Yes	X	_ No		N/A
2.	Pretreatment equipment or procedures?	X	_ Yes		_ No		N/A
3.	Pretreatment equipment maintained and operational?	X	_ Yes		_ No		_ N/A
4.	Hazardous waste generated or stored?	X	_ Yes		_ No		_ N/A
5.	Proper solid waste disposal?	X	_ Yes		_ No		_ N/A
6.	Solvent management/TTO control?		_ Yes		_ No	X	_ N/A
7.	Suitable sampling location?		_ Yes	X	_ No		_ N/A
8.	Appropriate self-monitoring procedures/equipment?		_ Yes		_ No	<u> </u>	_ N/A
9.	Adequate spill prevention?		Yes	X	_ No		_ N/A
10.	Industry familiar with limits and requirements?		_ Yes	X	_ No		_ N/A
Faci	litional Comments: ility representatives did not appear familia		_				
The	s facility discharged wastewater mixed wit wastewater is hauled from Marion to Wes ally taken from the bottom of the tanker, a	st Mempl	nis by truc	ck and dis	charged i	into a man	•
Visi	t Conducted by: Brent L. Walker Brent	t 2 Walk	₩& Mich	ael B. Gre	eenway_	Date: 12	2-09-2011



WEST MEMPHIS UTILITY COMMISSION

604 East Cooper P O Box 1868 West Memphis, AR 72301

Phone: 870-735-3355 Fax: 870-732-7623

April 3, 2012

Arkansas Department of Environmental Quality Water Enforcement Division 5301 Northshore Drive North Little Rock, Arkansas 72118-5317

Re:

NPDES Compliance Evaluation Inspection Wastewater Treatment Plant NPDES Sanitary Sewer Overflow Inspection Pretreatment Compliance Inspection

AFIN: 18-00879

NPDES Permit No.:

AR0022039 and ARR00C405

We recently received a letter addressing a routine compliance inspection performed back in December 2011. The inspection revealed several violations in all areas addressed. This letter is to address those violations:

Wastewater Treatment Plant:

- 1. Improper operation and maintenance. This violates Part III, Section B. Item 1.a. of the permit, which requires that the permittee shall at all times properly operate and maintain all facilities and systems of treatment and control (and related appurtenances) which are installed or used by the permittee to achieve compliance with the conditions of this permit. The following items were noted:
 - a) There was a small leak from a valve in the effluent wet well. Water from the leak had bypassed the UV treatment system.
 - b) There was sludge on the ground next to a manhole located between the headworks and the sludge drying beds.
 - c) There was a moderate amount of foam observed in the clarifiers and effluent wet well.

Response:

- a) The valve nuts were tightened and the valve was greased to prevent leaks. (See picture-WWTP-1).
- b) Two pumps have been installed to pump the waste filtrate. These pumps replace the filtrate station that was pumping the filtrate. There should be no more overflows at this manhole. (See picture-WWTP-2 & 3).
- c) There is a 0041 filament in the sludge that I am using c12 in the return sludge to control.

2. Samples taken during the month of May 2011 were not representative of volume and nature of the discharge during that month. It appeared that samples were normally collected on Monday, Tuesday and Wednesday of each week. However on May 2-3, 2011, effluent flow exceeded 20 MGD and the UV treatment system was bypassed. During this week, samples were collected on Thursday, Friday and Saturday (May 5-7, 2011) after effluent flow dropped to less than 8 MGD. This violates Part III, Section C. Item 1. of the permit.

Response:

From this day forward, all samples will be pulled on Monday, Tuesday and Wednesday.

3. Dissolved Oxygen (D.O.) concentration was not accurately reported on the DMR's. D.O. concentration was reported in ug/L instead of mg/L as required by part I, Section A. of the permit.

Response:

All DMRs are corrected. Net DMR is also corrected.

- 4. The Industrial stormwater (ARROOC405) inspection revealed the following violations:
 - a) Sampling was not performed as required.
 - b) The SWPPP was incomplete. Specifically the generator, equalization basin, and the amount of acreage were not identified in SWPPP.

Response:

- a) We have the permit now and sampling is being performed as required.
- b) All of this has been corrected.

Sanitary Sewer Overflow:

- 1. Station #8 (610 East Jefferson)
 - a) There was an uncovered hole in the floor where a pump had been removed.

Response:

- a) This has been repaired. The holes have been filled (See picture-Pump Station #8 (610 East Jefferson-Inside-1).
- 2. Station #9 (1620 South Avalon)
 - a) There was excessive grease and solids in the wet well.
 - b) There were uncovered holes in the floor.

Response:

- a) The wet well will be cleaned and will be on a cleaning schedule.
- b) This hasn't been completed. Two of the areas have been repaired, and one has not. This will be done within the week. (See picture-Pump Station #9 (1620 South Avalon)-Inside 2, 3, & 4).
- 3. Station #6 (401 South Avalon)
 - a) One of the three pumps was not operational.
 - b) There was excessive grease and solids in the wet well.
 - c) One of the pumps did not have a driveshaft guard in place.
 - d) The lights for the lower level were inoperative.

Response:

- a) Two pumps are operational and are all that is needed. The third is not need and is not operational but was just left in place.
- b) The wet well has been cleaned and will be on a cleaning schedule. (See picture-Pump Station #6 (410 South Avalon)-Wet Well 1 & 2).
- c) The one pump that does not have a driveshaft guard is the one that is not needed and is not operational.
- d) The light in the lower level are now operational. (See picture-Pump Station #6 (410 South Avalon)-Inside 3 & 4).
- 4. Station #26A (Shady Grove)
 - a) There was excessive grease and solids in the wet well.
 - b) The pumps were not alternating: both ran at the same time.

Response:

- a) The wet well has been cleaned and will be on a cleaning schedule. (See picture-Pump Station 26A-Wet Well-1).
- b) This issue was actually a problem with the floats. It has been corrected.
- 5. Station #13A (Park Plaza)
 - a) A manhole behind station was damaged and partially uncovered.

Response:

- a) This has been repaired. (See picture-Pump Station #13A (Park Plaza)-Outside-1 & 2).
- 6. Station #29 (Lalman Mobile Home Park)

a) It appeared this was a significant source of inflow, due to the unprotected sewer connections that were not in use.

Response:

- a) These are private sewer lines. If this issue needs to be addressed further we would appreciate ADEQ submitting a letter addressing the issue.
- 7. Station #35 (Southland Drive)
 - a) There was excessive grease and solids in the wet well.
 - b) Lights in the lower level were inoperative.
 - c) It appeared that pumps were not properly maintained. One of the drive shafts did not appear to be properly greased and the pump was noisy during operation.
 - d) Guards did not adequately cover drive shafts.

Response:

- a) Wet well has been cleaned and will be on a cleaning schedule. (See picture-Pump Station #35 (Southland Drive)-Wet Well-1).
- b) Lights are now operational. (See picture-Pump Station #35 (Southland Drive)-Inside-1).
- c) This has been corrected.
- d) This will be corrected.
- 8. Station #33 (Bill's Grill)
 - a) There was excessive grease and solids in the wet well.
 - b) The door to the pumps station was unlocked. Additionally, the door could not be unlocked with a key from the outside.
 - c) Guards did not adequately cover drive shafts.

Response:

- a) Wet well has been cleaned and will be on a cleaning schedule. (See picture-Pump Station #33 (Bills Grill)-Wet Well-1).
- b) This has been corrected. (See picture-Pump Station #33 (Bills Grill)-Outside-1).
- c) This will be corrected.

Also included with this letter will be a copy of a Corrective Action Plan. This plan has somewhat been reworked from the last copy received by the inspectors.

Pretreatment Compliance Inspection:

- 1. The IU site visit to Quala Wash (Previously PSC Container) revealed:
 - a) Lack of familiarity with pretreatment requirements by facility representative.

- b) Inadequate sample point. The sampling hose was placed horizontally inside a PVC "T".
- c) Tanker contents were drained onto the ground and bypassed pretreatment equipment.
- d) The drain value was open on the secondary containment to the outdoor holding tank.

Response:

All of the above will be addressed with Quala Wash in a letter. When the letter is sent I will copy Michael Greenway/Brent Walker.

- 2. The IU site visit to ATM Oil/Jim's Tank Service revealed the following violations:
 - a) Lack of familiarity with pretreatment requirements by facility representatives.
 - b) This facility routinely discharged leachate into the West Memphis collection system in violation of the pretreatment permit. Additionally, West Memphis POTW personnel were not aware of the leachate received from this industrial user.
 - c) Inadequate sampling. Wastewater was hauled from Marion to West Memphis by truck and discharged into a manhole. Samples were usually taken from the bottom of the tanker and not from the top where oil was present.

Response:

- a) At the time of the inspection, everyone familiar with the requirements was working off site.
- b) This is has already been addressed somewhat with the City Attorney and will be addressed further now that we have received the letter addressing the issue.
- c) This has been changed and all samples are now taken from the top of the tanker.
- 3. The baseline Monitoring Reports (BMR) were not reviewed for compliance with 40 CFR 403.12 (b). The BMR for Quala Wash did not include process flow diagrams, and a certification of compliance.

Response:

This will be addressed in a letter along with the other issues addressed. A copy of the letter will be sent to Michael Greenway/Brent Walker.

4. All permitted facilities were not inspected by the POTW. Only Categorical Industrial Users were inspected.

Response:

All Industrial User will be inspected this year.

If you needed additional information you may contact Denise Bosnick, Director Environmental Quality at 870-702-5141.

If I can be of assistance, please contact me at 870-702-5103.

Sincerely,

John Rimmer

General Manager

Corrective Action Plan

The West Memphis Utility Commission proposes to enact a 5 year Corrective Action Plan to address the problems associated with excessive I/I onto the sanitary sewer system. This plan will address current problems and develop a program to abate future problems through an improved maintenance program. The following is a 4-step plan and the associated timeline.

- Begin immediately a Phase I rehabilitation program to correct defects located during the SSES. All of the Priority 1 defects and most of the Priority 2 defects will be rehabilitated in 2013. This will consist of various methods of rehab including but not limited to:
 - A. Mainline point repairs
 - B. Relining or replacement of mainlines
 - C. Repair or replacement of manholes
 - D. Installation of rain caps for manholes
 - E. Root removal and mainline cleaning
 - F. Rehab of deficient pump stations
- 2. Upon completion of Phase I rehabilitation program, the SSES will be resumed in the areas that were not investigated during the initial SSES. The initial SSES included mapping, database development, pump station analysis and hydraulic assessment for the entire system. There fore, the second phase SSES will consist primarily of field tasks to locate defects and prepare rehab recommendations within the area of the collection system that were not investigated in Phase I.

Another aspect to be undertaken in the Phase II SSES will be monitoring the results of the Phase I rehabilitation program and the effects on I/I reduction. These results will be used for future rehab programs to determine the most effective methods for achieving I/I reduction.

- 3. Based upon the results of the Phase II SSES, the Phase II rehabilitation program will be developed. All priority 1 defects found will be correct and based upon the effectiveness of priority 2 rehab in Phase I, a determination made Priority 2 repairs. Phase II rehab will be spread over a 2 year period as the area covered in the study is twice the size of the initial program.
- 4. The final step in the Corrective Action Plan is the development and implementation of a Comprehensive Maintenance Management Program (CMMP). The CMMP will be designed as a program to manage the maintenance and capital improvements of the system for the purpose of the efficient overall operation of the system to maintain regulatory compliance and eliminate customer service problems. The basis of the program is to provide a well organized approach in a proactive manner in identifying and correcting maintenance problems before they become customer service complaints or regulatory violations.

Specific aspects to be addressed in the development of a CMMP are as follows:

- A. Identify specific goals and objective of CMMP
- B. System and software to manage program
 - i. GIS Software
 - ii. Database development
- C. Evaluation of Equipment Needs for Operation of Program
 - i. Cleaning and Inspection of Equipment
 - ii. Investigate tools (smoke test)


The development of the CMMP will begin immediately with the program being implemented completely within 5 years.

Conclusion


West Memphis Utility Commission will be hiring an Engineering Consultant and RJN inc. to inspect a basin every year for the next 5 years. With there recommendations, make repairs where they are needed. West Memphis Utility Commission agrees to adopt this 5-year plan to achieve not only regulatory compliance, but also the efficient and cost effective collection and treatment of wastewater for its customers in West Memphis. This commitment is evident through the development of this Plan and the SSES. Further evidence of this commitment can be found in the following examples:


- I. Rehabbed 5 pump stations in the last 3 years and currently have ordered material for a future rehab.
- II. Replaced 50' of 24" pipe that was having major I/I problems.
- III. Acquiring budgetary numbers to install SCADA in all pumping stations.
- IV. Hiring an outside specialist to inspect pumps to see if they are pumping to capacity.
- V. Creating specifications for new installations to prevent future I/I problems
- VI. Self inspections of all 42 stations, repairs have been completed.

These projects and this Plan are strong evidence of the commitment by the City of West Memphis to address the sewer infrastructure in an aggressive and proactive manner. The elements of this plan will allow the City to achieve the stated goals and objectives of regulatory compliance and I/I reduction.




















































	The state of the s	man and a man a man a later to the state of
	FRI - 06 APR A4 0215 8753 9674 4930 PRIORITY OVERNIGHT	Align top of FedEx Express Shipping Label here.
	X2 LITA 72118 AR-US MEM	
	Empf 33454 85APR12 NQAA 512C1/C440/A278	
		117 1 04.30 04.30
	Fedex US Air bill Freshing B753.9574.49.30 1 From This portion can be removed for Recipient's records. Date 4-5-12 Fedex Tracking Number B753967449.30	4a Express Package Service To most locations. FedEx Priority Overnight A New Express Priority And the Company of the Company
	Sonders Denise Bosnick 422 Phone B70 735-3355 Company WEST MEMPHIS UTILITY COMM.	FedEx 2Day Secret Nations day Thorston Secret Nations day Secret Nations Secre
FedEx 1800,463,3339	Address 604 E COOPER AVE Chy WEST MEMPHIS State AR ZIP 72301-3249 2 Your Internal Billing Reference	FodEx 2Doy Freight. Spread before free: "The product of interest with the definement of the product of the pro
dex.com 1800.664 edits	3 To Recipients Name Arkansas Dept. of Environmental Quality Company Water Enforcement Division 5301 Northshore Drive ARKANSAS Dept. of Environmental Quality Company Water Enforcement Division HOLD Weekday Recipients and The Recipients an	6 Special Handling and Delivery Signature Options SATURDAY Delivory NOT evaluate the Feels Standard Overhight, Feels Express Saves, or Feels 2Day Freight. No Signature Required Package may be in the wirecut contraining assignate in College, and College freight Someone active Direct Signature Someone active Direct Signature Indirect Signature Honores a registration advance, represent an elegistration advance, represent an elegistration advance any plan for defence, free applies. Does this shipment contain dangerous goods?
12	Address Problems of P.O. 2/P codes. We cannot deliver to P.O. boxes or P.O. 2/P codes. HOLD Solutions Address Use this line for the HOLD boxes and delivers or for continuation of year ehipping address. City North Little Rock State AR ZIP 72118	One has must be checked. No Assuranced Support Decisions on Confedence on Federal Day Confedenc
	0434864722 1 (o ^C)	Total Packages Total Weight Credit Card Cash/Check Total Packages Total Weight Credit Card Auth. Total Packages Total Weight Credit Card Auth. Toward Card Auth. Toward Card Auth.
	**************************************	The transmit the product tennes with the all and Stick Airtill or Pough