

March 6, 2017

Derek Ratchford, Area Manager Anthony Forest Products Company, LLC P.O. Box 724 Strong, AR 71765

#### RE: Anthony Forest Products Compan Inspections (Union Co) AFIN: 70-00473 NPDES Permit No.: AR0047384 ARG550398 ARG550540 ARR000977

Dear Mr. Ratchford:

On February 6, 2017, I performed a Compliance Evaluation Inspections and an Industrial Stormwater Inspection of the above-referenced facility in accordance with the provisions of the Federal Clean Water Act, the Arkansas Water and Air Pollution Control Act, and the regulations promulgated thereunder. Copies of the inspection reports are enclosed for your records.

Please refer to the "Summary of Findings" section of each of the attached inspection reports and provide a written response for each violation that was noted. This response should be mailed to the attention of the Office of Water Quality Inspection Branch at the address at the bottom of this letter or e-mailed to <u>Water-Inspection-Report@adeq.state.ar.us</u>. This response should contain documentation describing the course of action taken to correct each item noted. This corrective action should be completed as soon as possible, and the written response with all necessary documentation (i.e., photos) is due by <u>March 20, 2017</u>.

If I can be of any assistance, please contact me at <u>youngm@adeq.state.ar.us</u> or (501) 837-2073.

Sincerely,

Ming

Michael Young District 8 Field Inspector Office of Water Quality

cc: Amanda Gallagher, GBMc and Associates, agallagher@gbmcassoc.com

Inspection Report: Anthony Forest Products Compan, AFIN: 70-00473, Permit #: AR0047384

	WATER DIVISION INSPECTION REPORT							
		AFIN: 70-00473 PERMIT #: AR004738		7384		DATE:	2/6/2017	
		CC	UNTY: 70 Unio	on	PDS #: 095665			MEDIA: WN
Department of Environmental Quality GPS LA			S LAT: 33.159	614 LONG: -92.443	8849 L	OCATION:	Entrance	9
	FACILITY INFORMAT	ION		IN	SPEC	TION INFOR	MATIO	N
NAME: Anthony Forest Products Company – Urbana Sawmill LOCATION:			FACILITY TYPE: 2 - Industrial	101	TOR ID#: 531 S - State			
	86 Urbana Road			FACILITY EVALUATION RATIN 4 - Satisfactory		Com	TION TYPE: Ipliance	Evaluation
EI	Dorado, AR 71730			. ,	NTRY TIME:	EXIT TIME: 14:00		FECTIVE DATE:
	RESPONSIBLE OFFIC	CIAL			0.00	14.00	6/1/20 PERMIT EX	<b>J12</b> KPIRATION DATE:
	:/TITLE						5/31/2	2017
COMF				FAYETTEVILLE	SHAL	E RELATED	): N	
An	thony Forest Products Company, NG ADDRESS:	, LL(	C	FAYETTEVILLE				
	NG ADDRESS: <b>). Box 724</b>							S
- /	STATE, ZIP:			NAME/TITLE/PHONE/FAX/EMA	IL/ETC.:			-
	ong AR 71765 E & EXT: / FAX:			Randy Evans/E 3206/Randy.Eva			902-	
	)-962-3206 / 870-962-3320			Amanda Gallag			nmental	
EMAIL	-			Engineer/501-8				
	rek.Ratchford@canfor.com NTACTED DURING INSPECTION:	Va	<u></u>	- Tobin Fulmer/A		D8 Water Ins	spector	
00	NTACTED DORING INSPECTION.	. re:		ALUATIONS				
	(S=S	atisfac		Satisfactory, N=Not Applicable	/Evaluated	I)		
S	PERMIT	Μ	FLOW MEASU	JREMENT	Ν	STORMW	ATER	
S	RECORDS/REPORTS	S	LABORATOR		S	FACILITY	SITE RE	VIEW
S	<b>OPERATION &amp; MAINTENANCE</b>	Ν	EFFLUENT/R	ECEIVING WATER	S	SELF-MON	NITORIN	IG PROGRAM
S	SAMPLING	Ν	SLUDGE HAN	IDLING/DISPOSAL	N	PRETREA	TMENT	
**	OTHER:							
				OF FINDINGS				-
	The flow device at Outfall 001 is			•				-
(se	(see Photo 1). This is a violation of permit condition Part III. (C.) (2.). SEE FLOW DEVICE COMMENTS							

Inspection Report: Anthony Forest Products Compan, AFIN: 70-00473, Permit #: AR0047384

#### **GENERAL COMMENTS**

On February 6, 2017 I performed an inspection at Anthony Forest Products Company – Urbana Sawmill. The inspection was completed with Randy Evans, EHS Manager, and Amanda Gallagher, Environmental Engineer with GBMc. GBMc is a consulting agency that is contracted to conduct pH and DO sampling and receiving the samples from Outfall 001 that are collected by Mr. Evans. GBMc transports the samples to American Interplex Laboratory in Little Rock, AR for analysis. Sampling is taking place at the frequency and on the effluent characteristics required in Part IA. The facility has had effluent violations at Outfall 001 for Fecal Coliform Bacteria (FCB) and GBMc has conducted site investigations to attempt to discover the source of the violations. The facility believes that the FCB violations are produced from faulty or inadequate treatment from septic units on the property. An ARG550000 permit has been approved for the facility and a Norweco Singular 960 Aerobic Treatment Unit with chlorination will be installed to provide adequate treatment to domestic waste (see separate inspection report for permit ARG550540). Therefore, treated domestic waste will no longer be discharge to Outfall 001 and will be removed during permit renewal in an effort to cease the FCB violations at Outfall 001. Also, boiler blowdown is also no longer discharged to Outfall 001 and will be removed in the permit renewal.

#### FLOW DEVICE COMMENTS:

During the inspection, I observed materials in the weir box and roots growing up and through the V-notch weir used to measure flow at Outfall 001 (see Photo 1). The flow device needs to be maintained to be free of turbulence and materials that would affect the flow measurement. An image of the weir properly maintained will be required as a response to this violation.

Miller	
INSPECTOR'S SIGNATURE: Michael Young	DATE: 2/7/2017
Kerri MS Cole	
SUPERVISOR'S SIGNATURE:Kerri McCabe	DATE: 3/3/2017

Inspection Report: Anthony Forest Products Compan, AFIN: 70-00473, Permit #: AR0047384

	ermit #: AR0047384
SECTION A: PERMIT VERIFICATION	
PERMIT SATISFACTORILY ADDRESSES OBSERVATIONS	
DETAILS:	
1. CORRECT NAME AND MAILING ADDRESS OF PERMITTEE:	🗹 y 🗆 n 🗆 na 🗆 ne
2. NOTIFICATION GIVEN TO EPA/STATE OF NEW DIFFERENT OR INCREASED DISCHARGES:	
3. NUMBER AND LOCATION OF DISCHARGE POINTS AS DESCRIBED IN PERMIT:	
4. ALL DISCHARGES ARE PERMITTED:	
SECTION B: RECORDKEEPING AND REPORTING EVALUATION	
RECORDS AND REPORTS MAINTAINED AS REQUIRED BY PERMIT	ØS OM OU ONA ONE
DETAILS:	
1. ANALYTICAL RESULTS CONSISTENT WITH DATA REPORTED ON DMRS:	
2. SAMPLING AND ANALYSES DATA ADEQUATE AND INCLUDE:	Øs 🗆m 🗇u 🗇na 🗇ne
a. DATES AND TIME(S) OF SAMPLING:	
b. EXACT LOCATION(S) OF SAMPLING:	
c. NAME OF INDIVIDUAL PERFORMING SAMPLING:	
d. ANALYTICAL METHODS AND TECHNIQUES:	
e. RESULTS OF CALIBRATIONS:	
f. RESULTS OF ANALYSES:	
g. DATES AND TIMES OF ANALYSES:	
h. NAME OF PERSON(S) PERFORMING ANALYSES:	
3. LABORATORY EQUIPMENT CALIBRATION AND MAINTENANCE RECORDS ADEQUATE:	
4. PLANT RECORDS INCLUDE SCHEDULES, DATES OF EQUIPMENT MAINTENANCE AND REPAIR:	
5. EFFLUENT LOADINGS CALCULATED USING DAILY EFFLUENT FLOW AND DAILY ANALYTICAL DATA: Concentration o	
SECTION C: OPERATIONS AND MAINTENANCE	
TREATMENT FACILITY PROPERLY OPERATED AND MAINTAINED	
DETAILS:	
1. TREATMENT UNITS PROPERLY OPERATED:	
2. TREATMENT UNITS PROPERLY MAINTAINED:	
STANDBY POWER OR OTHER EQUIVALENT PROVIDED: <u>Treatment unit is entirely gravity fed.</u>	
J. STANDDIT OWEN ON OTHEN EQUIVALENT TROVIDED. Treatment unit is entitely dravity red.	
4. ADEQUATE ALARM SYSTEM FOR POWER OR EQUIPMENT FAILURES AVAILABLE:	Os Om Ou Øna One
<ol> <li>ADEQUATE ALARM SYSTEM FOR POWER OR EQUIPMENT FAILURES AVAILABLE:</li> <li>ALL NEEDED TREATMENT UNITS IN SERVICE:</li> </ol>	Os Om Ou Øna One Øs Om Ou Ona One
<ol> <li>ADEQUATE ALARM SYSTEM FOR POWER OR EQUIPMENT FAILURES AVAILABLE:</li> <li>ALL NEEDED TREATMENT UNITS IN SERVICE:</li> <li>ADEQUATE NUMBER OF QUALIFIED OPERATORS PROVIDED: <u>Contract operators hired for maintenance.</u></li> </ol>	OS OM OU ØNA ONE Øs Om Ou Ona One Øs Om Ou Ona One
<ol> <li>ADEQUATE ALARM SYSTEM FOR POWER OR EQUIPMENT FAILURES AVAILABLE:</li> <li>ALL NEEDED TREATMENT UNITS IN SERVICE:</li> <li>ADEQUATE NUMBER OF QUALIFIED OPERATORS PROVIDED: <u>Contract operators hired for maintenance.</u></li> <li>SPARE PARTS AND SUPPLIES INVENTORY MAINTAINED:</li> </ol>	OS OM OU ØNA ONE ØS OM OU ONA ONE ØS OM OU ONA ONE ØS OM OU ONA ONE
<ol> <li>ADEQUATE ALARM SYSTEM FOR POWER OR EQUIPMENT FAILURES AVAILABLE:</li> <li>ALL NEEDED TREATMENT UNITS IN SERVICE:</li> <li>ADEQUATE NUMBER OF QUALIFIED OPERATORS PROVIDED: <u>Contract operators hired for maintenance.</u></li> <li>SPARE PARTS AND SUPPLIES INVENTORY MAINTAINED:</li> <li>OPERATION AND MAINTENANCE MANUAL AVAILABLE:</li> </ol>	Image: Second state       Image: Second state<
<ol> <li>ADEQUATE ALARM SYSTEM FOR POWER OR EQUIPMENT FAILURES AVAILABLE:</li> <li>ALL NEEDED TREATMENT UNITS IN SERVICE:</li> <li>ADEQUATE NUMBER OF QUALIFIED OPERATORS PROVIDED: <u>Contract operators hired for maintenance.</u></li> <li>SPARE PARTS AND SUPPLIES INVENTORY MAINTAINED:</li> <li>OPERATION AND MAINTENANCE MANUAL AVAILABLE:</li> <li>STANDARD OPERATING PROCEDURES AND SCHEDULES ESTABLISHED:</li> </ol>	Image: Second
<ol> <li>ADEQUATE ALARM SYSTEM FOR POWER OR EQUIPMENT FAILURES AVAILABLE:</li> <li>ALL NEEDED TREATMENT UNITS IN SERVICE:</li> <li>ADEQUATE NUMBER OF QUALIFIED OPERATORS PROVIDED: <u>Contract operators hired for maintenance.</u></li> <li>SPARE PARTS AND SUPPLIES INVENTORY MAINTAINED:</li> <li>OPERATION AND MAINTENANCE MANUAL AVAILABLE:</li> <li>STANDARD OPERATING PROCEDURES AND SCHEDULES ESTABLISHED:</li> <li>PROCEDURES FOR EMERGENCY TREATMENT CONTROL ESTABLISHED:</li> </ol>	Image: Second state       Image: Second state<
<ol> <li>ADEQUATE ALARM SYSTEM FOR POWER OR EQUIPMENT FAILURES AVAILABLE:</li> <li>ALL NEEDED TREATMENT UNITS IN SERVICE:</li> <li>ADEQUATE NUMBER OF QUALIFIED OPERATORS PROVIDED: <u>Contract operators hired for maintenance.</u></li> <li>SPARE PARTS AND SUPPLIES INVENTORY MAINTAINED:</li> <li>OPERATION AND MAINTENANCE MANUAL AVAILABLE:</li> <li>STANDARD OPERATING PROCEDURES AND SCHEDULES ESTABLISHED:</li> <li>PROCEDURES FOR EMERGENCY TREATMENT CONTROL ESTABLISHED:</li> <li>HAVE BYPASSES/OVERFLOWS OCCURRED AT THE PLANT OR IN THE COLLECTION SYSTEM IN THE LAST YEAR:</li> </ol>	Image: Second
<ol> <li>ADEQUATE ALARM SYSTEM FOR POWER OR EQUIPMENT FAILURES AVAILABLE:</li> <li>ALL NEEDED TREATMENT UNITS IN SERVICE:</li> <li>ADEQUATE NUMBER OF QUALIFIED OPERATORS PROVIDED: <u>Contract operators hired for maintenance.</u></li> <li>SPARE PARTS AND SUPPLIES INVENTORY MAINTAINED:</li> <li>OPERATION AND MAINTENANCE MANUAL AVAILABLE:</li> <li>STANDARD OPERATING PROCEDURES AND SCHEDULES ESTABLISHED:</li> <li>PROCEDURES FOR EMERGENCY TREATMENT CONTROL ESTABLISHED:</li> <li>HAVE BYPASSES/OVERFLOWS OCCURRED AT THE PLANT OR IN THE COLLECTION SYSTEM IN THE LAST YEAR:</li> <li>IF SO, HAS THE REGULATORY AGENCY BEEN NOTIFIED:</li> </ol>	Image:
<ol> <li>ADEQUATE ALARM SYSTEM FOR POWER OR EQUIPMENT FAILURES AVAILABLE:</li> <li>ALL NEEDED TREATMENT UNITS IN SERVICE:</li> <li>ADEQUATE NUMBER OF QUALIFIED OPERATORS PROVIDED: <u>Contract operators hired for maintenance.</u></li> <li>SPARE PARTS AND SUPPLIES INVENTORY MAINTAINED:</li> <li>OPERATION AND MAINTENANCE MANUAL AVAILABLE:</li> <li>STANDARD OPERATING PROCEDURES AND SCHEDULES ESTABLISHED:</li> <li>PROCEDURES FOR EMERGENCY TREATMENT CONTROL ESTABLISHED:</li> <li>HAVE BYPASSES/OVERFLOWS OCCURRED AT THE PLANT OR IN THE COLLECTION SYSTEM IN THE LAST YEAR:</li> <li>IF SO, HAS THE REGULATORY AGENCY BEEN NOTIFIED:</li> <li>HAS CORRECTIVE ACTION BEEN TAKEN TO PREVENT ADDITIONAL BYPASSES/OVERFLOWS:</li> </ol>	Image:
<ol> <li>ADEQUATE ALARM SYSTEM FOR POWER OR EQUIPMENT FAILURES AVAILABLE:</li> <li>ALL NEEDED TREATMENT UNITS IN SERVICE:</li> <li>ADEQUATE NUMBER OF QUALIFIED OPERATORS PROVIDED; <u>Contract operators hired for maintenance.</u></li> <li>SPARE PARTS AND SUPPLIES INVENTORY MAINTAINED:</li> <li>OPERATION AND MAINTENANCE MANUAL AVAILABLE:</li> <li>STANDARD OPERATING PROCEDURES AND SCHEDULES ESTABLISHED:</li> <li>PROCEDURES FOR EMERGENCY TREATMENT CONTROL ESTABLISHED:</li> <li>HAVE BYPASSES/OVERFLOWS OCCURRED AT THE PLANT OR IN THE COLLECTION SYSTEM IN THE LAST YEAR:</li> <li>IF SO, HAS THE REGULATORY AGENCY BEEN NOTIFIED:</li> </ol>	OS OM OU ØNA ONE Øs Om Ou Ona One Øs Om Ou Ona One

SECTION D: SAMPLING	
PERMITTEE SAMPLING MEETS PERMIT REQUIREMENTS	ØS OM OU ONA ONE
DETAILS:	
1. SAMPLES TAKEN AT SITE(S) SPECIFIED IN PERMIT:	
2. LOCATIONS ADEQUATE FOR REPRESENTATIVE SAMPLES:	
3. FLOW PROPORTIONED SAMPLES OBTAINED WHEN REQUIRED BY PERMIT:	
4. SAMPLING AND ANALYSES COMPLETED ON PARAMETERS SPECIFIED IN PERMIT:	
5. SAMPLING AND ANALYSES PERFORMED AT FREQUENCY SPECIFIED IN PERMIT:	
6. SAMPLE COLLECTION PROCEDURES ADEQUATE:	
a. SAMPLES REFRIGERATED DURING COMPOSITING:	
b. PROPER PRESERVATION TECHNIQUES USED:	
c. CONTAINERS AND SAMPLE HOLDING TIMES CONFORM TO 40 CFR 136:	
7. IF MONITORING IS PERFORMED MORE OFTEN THAN REQUIRED ARE RESULTS REPORTED ON THE DMR:	
SECTION E: FLOW MEASUREMENT	
PERMITTEE FLOW MEASUREMENT MEETS PERMIT REQUIREMENTS	□S ØM □U □NA □NE
DETAILS:	
1. PRIMARY FLOW MEASUREMENT DEVICE PROPERLY INSTALLED AND MAINTAINED: TYPE OF DEVICE: V-notch weir	Øy 🗆n 🗆na 🗇ne
2. FLOW MEASURED AT EACH OUTFALL AS REQUIRED:	
3. SECONDARY INSTRUMENTS (TOTALIZERS, RECORDERS, ETC.) PROPERLY OPERATED AND MAINTAINED:	
4. CALIBRATION FREQUENCY ADEQUATE:	
5. RECORDS MAINTAINED OF CALIBRATION PROCEDURES:	
6. CALIBRATION CHECKS DONE TO ASSURE CONTINUED COMPLIANCE:	
<ol> <li>FLOW ENTERING DEVICE WELL DISTRIBUTED ACROSS THE CHANNEL AND FREE OF TURBULENCE: <u>Roots and other main weir.</u></li> </ol>	
8. FLOW MEASUREMENT EQUIPMENT ADEQUATE TO HANDLE EXPECTED RANGE OF FLOW RATES:	Øy 🛛 n 🗆 na 🗆 ne
9. HEAD MEASURED AT PROPER LOCATION:	Øy 🗆n 🗆na 🗇ne
SECTION F: LABORATORY	
PERMITTEE LABORATORY PROCEDURES MEET PERMIT REQUIREMENTS	ØS OM OU ONA ONE
DETAILS:	
1. EPA APPROVED ANALYTICAL PROCEDURES USED (40 CFR 136.3 FOR LIQUIDS, 503.8(B) FOR SLUDGES) :	Øy 🛛 n 🗆 na 🗆 ne
2. IF ALTERNATIVE ANALYTICAL PROCEDURES ARE USED, PROPER APPROVAL HAS BEEN OBTAINED:	
3. SATISFACTORY CALIBRATION AND MAINTENANCE OF INSTRUMENTS AND EQUIPMENT:	ØY ON ONA ONE
4. QUALITY CONTROL PROCEDURES ADEQUATE:	
5. DUPLICATE SAMPLES ARE ANALYZED ≥10% OF THE TIME:	
6. SPIKED SAMPLES ARE ANALYZED <u>&gt;</u> 10% OF THE TIME:	
7. COMMERCIAL LABORATORY USED:	ØY 🗆 N 🗆 NA 🗆 NE
a. LAB NAME: <u>American Interplex</u>	
b. LAB ADDRESS: <u>8600 Kanis Road Little Rock, AR</u>	
c. PARAMETERS PERFORMED: <u>All except pH and DO</u>	
8. BIOMONITORING PROCEDURES ADEQUATE:	
a. PROPER ORGANISMS USED:	
b. PROPER DILUTION SERIES FOLLOWED:	
c. PROPER TEST METHODS AND DURATION:	
d. RETESTS AND/OR TRE PERFORMED AS REQUIRED:	

SECTION G	SECTION G: EFFLUENT/RECEIVING WATERS OBSERVATIONS							
BASED ON	BASED ON VISUAL OBSERVATIONS ONLY							
DETAILS:								
OUTFALL #:	OIL SHEEN	GREASE	TURBIDITY	VISIBLE FOAM	FLOATING SOLIDS	COLOR	OTHER	
001	No Discharge	No Discharge	No Discharge	No Discharge	No Discharge	No Discharge		
SECTION H	: SLUDGE DIS	POSAL						
SLUDGE D	DISPOSAL ME	ETS PERMIT F	REQUIREMEN	ſS			U ⊡NA ØNE	
DETAILS:	Sludge is main	tained in the tw	o-cell system.					
1. SLUDGE M	ANAGEMENT ADEQU	ATE TO MAINTAIN EF	FLUENT QUALITY:			□s □m		
2. SLUDGE R	ECORDS MAINTAINED	O AS REQUIRED BY 40	) CFR 503:			⊡s ⊡m		
3. FOR LAND	APPLIED SLUDGE, TY	PE OF LAND APPLIE	D TO: (E.G., FOREST,	AGRICULTURAL, PUE	BLIC CONTACT SITE):			
SECTION I:	SAMPLING IN	SPECTION PRO	CEDURES					
SAMPLE R	ESULTS WITH	HIN PERMIT R	EQUIREMENT	S			U ⊠NA ⊡NE	
DETAILS:								
1. SAMPLES	OBTAINED THIS INSPI	ECTION:				ΠY	🗆 n 🗹 na 🗆 ne	
2. TYPE OF S	AMPLE: GRAB:		IETHOD: FREQUE	NCY:				
3. SAMPLES PRESERVED:								
4. FLOW PROPORTIONED SAMPLES OBTAINED:								
5. SAMPLE OBTAINED FROM FACILITY'S SAMPLING DEVICE:							On Øna One	
6. SAMPLE R	6. SAMPLE REPRESENTATIVE OF VOLUME AND NATURE OF DISCHARGE:							
7. SAMPLE SI	PLIT WITH PERMITTEI	E:				ΠY	□n Øna □ne	
8. CHAIN-OF-	CUSTODY PROCEDU	RES EMPLOYED:					□n Øna □ne	
9. SAMPLES	COLLECTED IN ACCO	RDANCE WITH PERM	IT:			ΠY	□n Øna □ne	
			PREVENTION					
	ATER MANAG	EMENT MEET	S PERMIT RE	QUIREMENTS			U ⊠NA ⊡NE	
DETAILS:								
1. SWPPP UP	DATED AS NEEDED:	_ DATE OF LAST UP	DATE:					
2. SITE MAP I	NCLUDING ALL DISCH	HARGES AND SURFAC	CE WATERS:					
3. POLLUTION	N PREVENTION TEAM	IDENTIFIED:						
4. POLLUTION	N PREVENTION TEAM	PROPERLY TRAINED	):					
5. LIST OF PC	DTENTIAL POLLUTAN	SOURCES:						
	DTENTIAL SOURCES A							
	TORM WATER DISCH	ARGES ARE AUTHOR	IZED:					
	RUCTURAL BMPS:							
	DN-STRUCTURAL BMF							
	PERLY OPERATED A							
11. INSPECTIC	INS CONDUCTED AS	REQUIRED:				۵Y		

#### **DMR Calculation Check**

Reporting Period:	From	2015 Year	01 Month	01 Day	_ To	2015 Year	01 Month	<u>31</u> Day
Parameter Checked:		TSS	-					
		Loading Mass				Concer Mon		
	Mo.	Avg Ibs/o	day	Mo. A	vg I	ng/l	7-day Avg	mg/l
Reported Value:		N/A			16.5		17.0	)
Calculated Value:		N/A			16.5		17.0	)
Permit Value:		N/A			35		53	

If calculated value does not equal reported value, explain:

<u>Equal</u>



Figure 1. Overview of Anthony Forest Company – Urbana Sawmill. Indicated are the processing areas of the facility, the wet deck area, and the treatment cells. Also indicated is the location of Outfall 001. There is a pond on the south-side of the facility that is indicated that previously operated as a wet deck pond, but there is currently no process water being discharged from this pond. The pond is now Outfall 009 and monitored under permit ARR000977.



Melissa,

Would you please attach this e-mail to WID's 21749, 21750 and 21752?

Thank you,

Michael Young District 8 Inspector El Dorado Field Office ADEQ Water Division Cell Phone: 501-837-2073 youngm@adeq.state.ar.us

From: Young, Michael
Sent: Thursday, March 16, 2017 10:34 AM
To: 'Amanda Gallagher'
Cc: 'Randy.Evans@canfor.com'
Subject: RE: Anthony Forest Products Company Inspections (Union Co)

Amanda,

A two-week extension from the due date of March 20, 2017 is granted. The response will be due April 3, 2017.

As a reminder, if the corrective measure for the response to the "summary of Findings" will take longer than the required due-date, please provide a timeframe of completion.

Thank you,

Michael Young District 8 Inspector El Dorado Field Office ADEQ Water Division Cell Phone: 501-837-2073 youngm@adeq.state.ar.us Michael,

On behalf of Anthony Forest, I would like to request at least a two week extension on the required response to the inspection. Due to the intricacy of the findings and the potential required long term actions, additional time is necessary to adequately address the inspection findings. Thank you for your time.

Amanda Gallagher, P.E. GBMc & Associates 219 Brown Lane Bryant, AR 72022 Phone: (501) 847-7077

From: McCabe, Kerri [mailto:MCCABE@adeq.state.ar.us]
Sent: Monday, March 06, 2017 10:46 AM
To: Derek.Ratchford@canfor.com; Randy.Evans@canfor.com; Amanda Gallagher
<agallagher@gbmcassoc.com>
Cc: Young, Michael <<u>youngm@adeq.state.ar.us</u>>
Subject: Anthony Forest Products Company Inspections (Union Co)

Please find attached the inspection reports submitted by Inspector Young. Thank you.

#### Kerri McCabe

Inspector Supervisor ADEQ – Water Division Field Services – Inspection Branch

Office – (501) 682-0642 Work Cell – (501) 352-5641 Fax – (501) 682-0880 5301 Northshore Drive North Little Rock, AR 72118-5317



From:	Amanda Gallagher
To:	Water-Inspection-Report
Cc:	Young, Michael; Evans, Randy
Subject:	Anthony-Urbana March 2017 ADEQ Inspection Response
Date:	Monday, April 03, 2017 3:31:35 PM
Attachments:	Anthony Urbana ADEQ Inspection March 2017 Response (2).pdf

To Whom It May Concern:

On behalf of Anthony Forest Products Company, LLC – Urbana Sawmill, please find attached the required response to ADEQ's Compliance Evaluation Inspection performed on February 06, 2017.

Amanda Gallagher, P.E. GBMc & Associates 219 Brown Lane Bryant, AR 72022 Phone: (501) 847-7077 April 03, 2017

Mr. Michael Young District 8 Field Inspector Water Division Arkansas Department of Environmental Quality 5301 Northshore Drive North Little Rock, AR 72118

 RE: Anthony Forest Products Company, LLC Compliance Inspection Response AFIN: 70-00473
 NPDES Permit No. AR0047384, Permit Tracking No. ARR000977, Permit Tracking No. ARG550398, and Permit Tracking No. ARG550540

Dear Mr. Young:

On February 06, 2017, ADEQ conducted a routine compliance evaluation inspection at Anthony Forest Products Company, LLC – Urbana Sawmill (Anthony – Urbana). A copy of this compliance inspection report and letter was received by Anthony-Urbana on March 06, 2017. The inspection report listed one finding associated with NPDES Permit No. AR0047384, seven findings associated with General Permit Tracking No. ARR000977, four findings associated with General Permit Tracking No. ARG550398, and no findings associated with General Permit Tracking No. ARG550540. The letter also requested that a written response to the findings including corrective actions be submitted by April 03, 2017. Anthony-Urbana's responses are as follows:

#### NPDES Permit No. AR0047384:

#### ADEQ Finding No. 1:

The flow device at Outfall 001 is not maintained to provide adequate volume of monitored discharges. Materials were observed in the weir box and roots growing up and through the V-notch weir.

#### Anthony-Urbana Response:

Vines, roots, and debris have been removed from the weir and weir box. Pictures showing the above described corrective actions can be found in Attachment 1.

#### General Permit Tracking No. ARR000977:

#### ADEQ Finding No. 1:

The facility has kiln ash pile with no control measures that is contributing to pollution of UT of Woodard Creek.

#### Anthony-Urbana Response:

Anthony-Urbana understands the need for appropriate control measures for the kiln ash pile in order to minimize exposure and manage storm water runoff in a manner that minimizes the discharge of potential pollutants off site.

The amount of kiln ash stored onsite varies throughout the year. Anthony-Urbana is constantly investigating new uses for the kiln ash in order to minimize the amount of kiln ash stored onsite.

Silt fence has been added to the downstream side of the kiln ash pile as a temporary control measure. Pictures showing the above described corrective action can be found in Attachment 2.

Anthony-Urbana is evaluating options for additional control measures and a long term storage solution in order to control runoff from the kiln ash pile. Options being considered include:

- Installation of a concrete or earthen berm with an outlet structure around the current biochar pile.
- Moving the storage location of the kiln ash pile away from a drainage path and install appropriate controls (berm with outlet). I.e. north end of the wet deck.

However, due to unknown future facility modifications, a final decision has not been feasible.

#### ADEQ Finding No. 2:

The facility has contributed kiln ash bottom deposits to UT of Woodard Creek through insufficient control measures

#### Anthony-Urbana Response:

See Anthony-Urbana Response to ADEQ Finding No. 1.

#### ADEQ Finding No. 3:

The facility is not making and effort to minimize exposure of the kiln ash pile, which is contributing to pollution of UT of Woodward Creek from Outfall 011.

#### Anthony-Urbana Response:

See Anthony-Urbana Response to ADEQ Finding No. 1.

## First ADEQ Finding No. 4:

Oil sheen was observed in the ditch draining to Outfall 003 from the kiln area. The facility needs to adequately use good housekeeping measures and maintain all equipment to prevent the discharge of pollutants in stormwater discharged to receiving waters.

#### Anthony-Urbana Response:

Equipment associated with the kilns were found to be a potential source for the oil sheen. Kiln equipment (motor, chain, lumber carts, etc) requires significant amount of lubrication due to repetitive use and the hot kiln environment. In future, employees will be trained to only use the amount of grease necessary on equipment associated with the kiln. Any spills will be immediately cleaned up and reported to the EHS manager.

The forklifts used to place lumber in the kiln were also found to be a potential source for the oil sheen. Forklifts are currently maintenanced once/month. However, they are still apt to have leaks due to heavy usage. Anthony-Urbana is in the process of replacing older forklifts, which are more apt to have more frequent leaks. In future, leaks from a fork lift will be immediately cleaned up and the forklift will be maintenanced in a timely manner in order to fix the leak.

Oil booms have been placed in the drainage ditch leading to Outfall 003, as can be seen in the picture found in Attachment 3. The kiln area and drainage ditch leading to Outfall 003 will be monitored weekly by the EHS manager to ensure good housekeeping practices are being maintained and the oil booms are properly maintained.

Please note that the exact location of the oil and grease noted on the ground that was noted in Photo No. 12 of the ADEQ inspection could not be determined. Attachment 3 contains pictures of the area taken during the quarterly inspection of the general area of the kilns.

## Second ADEQ Finding No. 4:

Erosion and sediment controls are not being utilized in the ditch that drains Outfall 008.

## Anthony-Urbana Response:

This ditch is normally vegetated. However, the ditch as clean out as part a major facility cleanup. Natural vegetation is currently being re-established. Rip-rap will be placed in areas where vegetation cannot be established. Pictures showing the above described corrective action can be found in Attachment 4.

During 2017, Anthony-Urbana also plans to re-route stormwater from the Outfall 008 drainage basin to the old wet deck pond associated with Outfall 009. The pond will allow any bark or other solids to settle out and not be discharge offsite.

#### ADEQ Finding No. 5:

The facility is not managing runoff at Outfall 011 in a manner to minimize the pollutants discharged to UT of Woodward Creek.

#### Anthony-Urbana Response:

See Anthony-Urbana Response to ADEQ Finding No. 1.

#### ADEQ Finding No. 6:

Sampling of Outfall 011 is not taking place and it has the greatest exposure to significant sources of pollution (kiln ash).

#### Anthony-Urbana Response:

The facility samples in accordance with the current ADEQ Notice of Coverage (NOC). The NOC states that Outfalls 003, 007, and 008 will be sampled while Outfalls 002, 004, 005, 006, and 009-012 are considered similar. The outfalls which are sampled and the ones that are considered similar was last "approved" by ADEQ. The SWPPP includes the required documentation on how the similar outfall determinations were made. Thus, Anthony Forest is meeting the requirements of Part 3.8 of the general permit and feels that this does not constitute a permit violation.

However pursuant to the ADEQ inspection, Anthony did review the similar outfall evaluation and determined that due to recent facility changes that Outfall 011 is no longer similar to Outfall 003 based on a consideration of industrial activity, significant materials and management practices, and activities within the area drained by the outfall. Outfall 011 will be sampled along with Outfalls 003, 007, and 008. Notification of this change has been made to ADEQ – Office of Water Quality Permits Section in order to update ADEQ records and the Notice of Coverage.

## General Permit Tracking No. ARG550398:

#### ADEQ Finding No. 1:

The influent tank had excessive solids.

#### Anthony-Urbana Response:

Per the operation and maintenance manual, the pretreatment chamber of the Norweco System is expected to have some floatable solids. The system was inspected/maintenanced on February 17<sup>th</sup> and March 20<sup>th</sup> and was determined to be in proper working order. The floatable solids and sludge levels in the system will be monitored in the future and pumped out when necessary.

#### ADEQ Finding No. 2:

The chlorine contact tube did not have any chlorine tablets.

#### Anthony-Urbana Response:

Chlorine tablets have been added to the system. This was verified during a site visit on March 15, 2017. A picture showing the above described actions can be found in Attachment 5.

#### ADEQ Finding No. 3:

The facility could not provide forms from the ADEQ website used to evaluate the system a minimum of four times per year.

#### Anthony-Urbana Response:

The ADEQ maintenance form will be utilized in the future. The system was last maintenanced on March 20, 2017. The completed ADEQ maintenance form can be found in Attachment 6.

#### ADEQ Finding No. 4:

Twenty-four hour reporting for violations of Monthly Average or a Daily Maximum discharge limitation for any of the pollutants listed in Part II are not being reported by the facility.

#### Anthony-Urbana Response:

Any future permit limit excursion will be reported within 24 hours of the known excursion in accordance with Part 6.4 of the general permit.

We appreciate ADEQ's concerns in this matter. We trust our responses satisfy the inspection findings. Please do not hesitate to me at (870) 962-3206 or Amanda Gallagher with GBMc at (501) 847-7077 should you have any questions or need additional information regarding this issue.

Respectfully submitted, Anthony Forest Products Company, LLC

Randy Evans EH&S Manager

Attachment

cc: Amanda Gallagher – GBM<sup>c</sup> & Associates

# Attachment 1 Outfall 001 Photo

Photograph of Outfall 001 weir.



# Attachment 2 Outfall 011 Photos



Photograph 1 of silt fence installed down gradient of the kiln ash pile.

Photograph 2 of silt fence installed down gradient of the kiln ash pile.



Photograph 3 of silt fence installed down gradient of the kiln ash pile.




Photograph 4 of silt fence installed down gradient of the kiln ash pile.



# Attachment 3 Outfall 003 Photos

Photograph showing oils booms that were placed in the drainage ditch leading to Outfall 003.



Photograph showing area in the vicinity of the kilns where excess grease has been observed.



## Attachment 4

## **Outfall 008 BMP Photos**

Photograph showing the upper part of the ditch leading to Outfall 008. Vegetation has been established in the lower part of the ditch and starting to grow in the upper portion.



# Attachment 5 ARG55 Photos

The following photograph shows chlorine tablets that were added to the ARG55 treatment system.



## Attachment 6

# ARG55 Maintenance Form for 1<sup>st</sup> Quarter 2017

Arkansas Department of Environmental Quality

5301 Northshore Drive, North Little Rock, AR 72118

## ARG550000 Individual Treatment System Evaluation

Permit Tra	king No.	398
Date of Ev;	aluation	1
Z	20	2017

#### Part 1 General Information

Permittee:	County: Phone Number:	
Canfred	Elms fro 370 962 325	-
Site Location (911 Address):	City State Zip	
1235 Unlan Rd	Unlean fil	

#### Part 2 Assessment

Items:		Description: In the space below, list any deficiency assessed and/or action(s) taken.
1 Electrical		
2 Pump(s)	13	
3 Discharge Route		
4 Chlorinator	Ø	
5 Contact Chamber	B	
6 Clean Outs	0	
7 Sludge Depth	ø	120° of Alundae
8 Other Components		

#### Part 3 Sludge Removal

1 Solids Removal Service	2 License Number	3 Date of Service
Part 4 Certification		
I certify that I have conducted all applicable assessn	nents listed above and have taken the appropriate	e action to maintain the proper
function of the above listed system in accordance wi		

Signature Date haugh ence -Phone Number Typed/Printed Name bicense Number (Min. Class II License) 9EZ 7e

ARG550000 Treatment System Evaluation Form - December 2010



May 16, 2017

Derek Ratchford, Area Manager Anthony Forest Products Company, LLC P.O. Box 724 Strong, AR 71765

#### RE: Anthony Forest Products - Response to Inspection (Union Co) AFIN: 70-00473 NPDES Permit No.: AR0047384 ARG550398 ARG550540 ARR000977

Dear Mr. Ratchford:

I have reviewed the response pertaining to my February 6, 2017 inspection of Anthony Forest Products, LLC – Urbana Mill. The information provided sufficiently addresses the violations referenced in my inspection report. At this time, the Department has no further comment concerning this particular inspection. Acceptance of this response by the Department does not preclude any future enforcement action deemed necessary at this site or any other site.

If we need further information concerning this matter, we will contact you. Thank you for your attention to this matter. Should you have any questions, feel free to contact me at (501) 837-2073 or you may e-mail me at <u>youngm@adeq.state.ar.us</u>.

Sincerely,

Mintel

Michael Young District 8 Field Inspector Office of Water Quality