

2650 Thousand Oaks Boulevard Suite 3200 Memphis, TN 38118 (901) 683-3900 FAX (901) 683-3990 www.ssr-inc.com

January 31, 2012

Arkansas Department of Environmental Quality Attn: Marilyn Stout Water Division Enforcement Branch 5301 Northshore Dr. North Little Rock, AR, 72118

Marilyn,

As you know, SSR is under contract to assist the City of Blytheville with attaining compliance under certain areas of their CAO (08-094). The City signed a professional services contract with SSR to conduct the collection system investigation for 10 areas of the collection system. The investigation included cleaning, televising and evaluating these 10 areas for sewer rehabilitation. The attached report summarizes these findings. If you have any questions about this report, please give me a call at (901) 683-3900.

Sincerely,

Daniel Bowling, El





PRESENTED TO: ADEQ

CITY OF BLYTHEVILLE

SANITARY SEWER COLLECTION SYSTEM REPORT



February 2012



CCTV and Smoke Test Results

This report describes observations and recommendations determined from televising multiple sewer collection system sites throughout the City of Blytheville. Sites were chosen using information from an inflow & infiltration study on Blytheville's sewer collection system which was completed in October of 2009. These sites were deemed critical to fixing the City's I&I problems. Exhibit #1 shows the sites that were televised.

Smoke test results are described below as well. Information detailed below pertains to smoke leaks along the main line. Many sewer service lines showed smoke leaks as well, but these lines do not contribute as much I&I as leaks along the main and therefore are not a priority over the main line repairs. Service lines missing caps should be recapped at the earliest convenience to decrease I&I from the service lines. Information related to each site is summarized below. The information provided below is just a summary of the problem areas found during the investigation. More detailed descriptions are provided in the report binders provided by Arkansas Cleaning and Televising. See *Appendix D* for sample pages from these binders.

Site Name: 705-1

- O See Exhibit #2 for the location and layout of the site.
- o Minor sags were recorded in lines at this site. A leaking service connection was observed in line WD4-WD5.
- o Determinations: One line at this site requires repair.

Site Name: 705-2

- See Exhibit #3 for the location and layout of the site.
- O This site was CCTV'ed after a rainfall event and infiltration in all lines was noted by the contractor. Bulges were noted in multiple sections of polypipe. Large sags were recorded in many lines at this site. Light circular and longitudinal cracks were observed in multiple concrete lines. Light roots were noted in some joints. Aluminum sleeves and stainless steel inserts for old point repairs were noted. Smoke tests showed potential infiltration areas around multiple sewer manholes and service connections.
- O Determinations: Infiltration areas should be sealed as soon as possible. Some lines at this site require repair. See attached tables for prioritization of lines requiring rehabilitation and associated estimated repair costs.

Site Name: 705-3

- O See Exhibit #4 for the location and layout of the site.
- o This site was CCTV'ed after a rainfall event and infiltration in all lines was noted by the contractor. Minor sags were recorded in most lines at this site. Larger sags were noted in line WD19-WD20. Light roots were observed in some joints. Aluminum



- sleeves and PVC lines for old point repairs were noted. Line WD23-WD24 contained a 2"-3" offset joint.
- Determinations: Infiltration areas should be sealed as soon as possible. Some lines at this site require repair. See attached tables for prioritization of lines requiring rehabilitation and associated estimated repair costs.

Site Name: 1767-1

- O See Exhibit #5 for the location and layout of the site.
- o Minor sags were recorded in many lines at this site. Light circular and longitudinal cracks were observed in multiple concrete lines. Light roots were noted in some joints. Stainless steel inserts for old point repairs were noted. Smoke tests showed potential infiltration areas around multiple sewer manholes and service connections.
- O Determinations: Infiltration areas should be sealed as soon as possible. Some lines at this site require repair. See attached tables for prioritization of lines requiring rehabilitation and associated estimated repair costs.

Site Name: 1767-2

- O See Exhibit #6 for the location and layout of the site.
- o Minor sags were recorded in most lines at this site. Light circular and longitudinal cracks were observed in multiple concrete lines. Light roots were noted in some joints on line WP79-WP80. Aluminum and PVC sections from old point repairs were noted. Smoke tests showed potential infiltration areas around multiple sewer manholes and service connections. Line WP80-WP81 contained a 2"-3" offset joint. Smoke tests showed potential infiltration areas around multiple sewer manholes and service connections.
- O Determinations: Infiltration areas should be sealed as soon as possible. Some lines at this site require repair. See attached tables for prioritization of lines requiring rehabilitation and associated estimated repair costs.

Site Name: Ruddle-1

- See Exhibit #7 for the location and layout of the site.
- Minor to severe sags were recorded in most lines at this site. Roots were observed in many lines. Circular cracks were noted in some lines. Line ND12-ND11 contained a 2"-3" offset joint. Smoke tests showed potential infiltration areas around multiple sewer manholes and service connections.
- O Determinations: Infiltration areas should be sealed as soon as possible. Most lines at this site require repair. See attached tables for prioritization of lines requiring rehabilitation and associated estimated repair costs.



Site Name: Walker Park-1

- O See Exhibit #8 for the location and layout of the site.
- O Minor sags were recorded in most lines at this site. Roots were observed in some lines. Circular & longitudinal cracks were noted in some lines. Some leaking joints were noted as well. Line NC75-NC74 has had a pipe bored through the top of it. Lines NC24-NC23 & NC25A-NC25contained offset joints. Smoke tests showed potential infiltration areas around multiple sewer manholes and service connections.
- O Determinations: Infiltration areas should be sealed as soon as possible. Some lines at this site require repair. See attached tables for prioritization of lines requiring rehabilitation and associated estimated repair costs.

Site Name: Walker Park-2

- O See Exhibit #9 for the location and layout of the site.
- Minor sags were recorded in most lines at this site. Roots were observed in some lines. Circular & longitudinal cracks were noted in some lines. Line NC81-NC81A contains a shattered pipe section. Line NC107-NC106 contained a 3" offset joint. Smoke tests showed potential infiltration areas around multiple sewer manholes and service connections.
- O Determinations: Infiltration areas should be sealed as soon as possible. Some lines at this site require repair. See attached tables for prioritization of lines requiring rehabilitation and associated estimated repair costs.

Site Name: Ward-1

- See Exhibit #10 for the location and layout of the site.
- o Minor sags were recorded in most lines at this site. Roots were observed in many lines, including heavy roots in line WF105-WS31 & WF118-WF116. Circular & longitudinal cracks were noted in some lines. Line 90W3-90W2 contains a shattered pipe section. Line WS29-WS28 contained a 3" offset joint. Smoke tests showed potential infiltration areas around multiple sewer manholes and service connections.
- O Determinations: Infiltration areas should be sealed as soon as possible. Many lines at this site require repair. See attached tables for prioritization of lines requiring rehabilitation and associated estimated repair costs.

Site Name: Ward-2

- O See Exhibit #11 for the location and layout of the site.
- Minor sags were recorded in most lines at this site. Roots were observed in some lines. Circular cracks were noted in some lines. Line 90W3-90W2 contains a shattered pipe section. Bottom of pipe is missing at a section of Line WF57-WF56. The pipe between WF68 & WF67 is missing.



O Determinations: Infiltration areas should be sealed as soon as possible. About half of the lines at this site require repair. See attached tables for prioritization of lines requiring rehabilitation and associated estimated repair costs.



APPENDIX A HIGH PRIORITY AREAS

Upst MH # to Dnst MH#	Line Length (ft)	PIPE TYPE	No. of Services	Line Conditions	Recommendations	Unit Cost*	Service Connect		Cost
705-1	Length (It)	TILL	Del Vices	COMMISSION					
WD5				FAIR/SMOKE					
WD4	346.1	LINER	2	LEAK	BURST/RELAY/CIPP	\$ 70.00	\$ 500.00	\$	25,227.00
						705	-1 Subtotal:	\$	25,227.00
705-2									
WD33				POOR/SMOKE		5			
WD32	121	CONC	1	LEAK	BURST/RELAY/CIPP	\$ 70.00	\$ 500.00	\$	8,970.00
WD34									
WD33	156.4	CONC	1	POOR	BURST/RELAY/CIPP	\$ 70.00	\$ 500.00	\$	11,448.00
WD35				·		•			
WD34	336.8	CONC	2	POOR	BURST/RELAY/CIPP	\$ 70.00	\$ 500.00	\$	24,576.00
WD40	_						÷		
WD2	232.7	LINER	0	POOR	BURST/RELAY/CIPP	\$ 70.00	\$ 500.00	\$	16,289.00
WD47				POOR/SMOKE					
WD46	234.1	CONC	1	LEAK	BURST/RELAY/CIPP	\$ 70.00	\$ 500.00	\$	16,887.00
WD53				POOR/SMOKE	•	•			
WD51	197.4	CONC	1	LEAK	BURST/RELAY/CIPP	\$ 70.00	\$ 500.00	\$	14,318.00
WD55				POOR/FULL OF	· .				
WD54	163	CONC	?	GROUT	RELAY	\$ 90.00	\$ 500.00	\$	14,670.00
	•.					705	-2 Subtotal:	\$	107,158.00
705-3						· .			
WD16				FAIR/SMOKE					
WD7	249.1	CONC	2	LEAK	BURST/RELAY/CIPP	\$ 70.00	\$ 500.00	.\$	18,437.00
WD21				POOR/SMOKE					
WD20	172.1	CONC	2	LEAK	BURST/RELAY/CIPP	\$ 70.00	\$ 500.00	\$	13,047.00
WD22				POOR/SMOKE			,		
WD21	216.1	CONC	2 ·	LEAK	BURST/RELAY/CIPP	\$ 70.00	\$ 500.00	-\$	16,127.00
			•	· · · · · · · · · · · · · · · · · · ·		705	5-3 Subtotal:	\$	47,611.00

TABLE 1 - HIGH PRIORITY REPAIRS

Upst MH # to Dnst MH#	Line Length (ft)	PIPE TYPE	No. of Services	Line Conditions	Recommendations	Uni	t Cost*		ervice nnect		Cost
1767-1		•					·				
WP18				POOR/SMOKE				٠, ,			
WP17	245.2	CONC	3	LEAK	BURST/RELAY/CIPP	\$	70.00	\$	500.00	\$	18,664.00
WP21				POOR/SMOKE							
WP20	75.2	CONC	1	LEAK	BURST/RELAY/CIPP	\$	70.00	\$	500.00	\$	5,764.00
WP27		•		POOR/SMOKE	· ·						:
WP24	206.1	CONC	3	LEAK	BURST/RELAY/CIPP	\$	70.00	\$	500.00	\$	15,927.00
WP29		1		POOR/SMOKE							
WP22	168.2	CONC	2	LEAK	BURST/RELAY/CIPP	\$	70.00	\$	500.00	\$	12,774.00
WP30					,				**		,
WP31	199.1	CONC	3	POOR	BURST/RELAY/CIPP	\$	70.00	\$	500.00	\$	15,437.00
WP35											
WP34	400	CONC	4	POOR	BURST/RELAY/CIPP	\$_	70.00	\$	500.00	\$	30,000.00
WP44											
WP42	363.9	CONC	3	POOR	BURST/RELAY/CIPP	\$	70.00	\$	500.00	\$	26,973.00
WP40				FAIR/SMOKE					•		
WP39	410.3	LINER	6	LEAK	BURST/RELAY/CIPP	\$	70.00	\$	500.00	\$	31,721.00
							1767	-1 Su	ıbtotal:	\$	72,410.00
1767-2		-			· · · · · · · · · · · · · · · · · · ·						
WP78				POOR/SMOKE	, .						
WP2	464	CONC	5	LEAK	BURST/RELAY/CIPP	\$	70.00	\$	500.00	\$	34,980.00
WP79										, .	
WP78	350.2	CONC	1	POOR	BURST/RELAY/CIPP	\$	70.00	\$	500.00	\$	25,014.00
WP80				POOR/SMOKE							
WP79	80	CONC	0	LEAK	BURST/RELAY/CIPP	\$	70.00	\$	500.00	\$	5,600.00
WP82				POOR/SMOKE							
WP81	391.6	CONC	2	LEAK	BURST/RELAY/CIPP	\$	70.00	\$	500.00	\$	28,412.00
							1767	-2 Su	ıbtotal:	\$	94,006.00
Ruddle-1	,					•					

TABLE 1 - HIGH PRIORITY REPAIRS

Upst MH # to Dnst MH#	Line Length (ft)	PIPE TYPE	No. of Services	Line Conditions	Recommendations	Uņi	t Cost*		ervice onnect		Cost
ND6	Length (1t)		551 (1555								
ND6A	17.2	CLAY	. ?	POOR	BURST/RELAY/CIPP	\$	70.00	\$	500.00	\$	1,204.00
ND7				POOR/SMOKE							
ND6	216.7	CLAY	1	LEAK	RELAY	\$	90.00	\$	500.00	\$	20,003.00
ND8				-						-	
ND7	282	CLAY	3	POOR	RELAY	\$	90.00	\$	500.00	\$	26,880.00
ND9		-									
ND8	290	CLAY.	• 2	POOR	BURST/RELAY/CIPP	\$	70.00	\$	500.00	\$	21,300.00
ND10								÷			
ND9	404	CLAY	4	POOR	BURST/RELAY/CIPP	\$	70.00	\$	500.00	\$	30,280.00
ND11						}					
ND10	160.6	CLAY	1	POOR	BURST/RELAY/CIPP	\$_	70.00	\$	500.00	\$	11,742.00
ND12											٠
ND11	205	CLAY	1	POOR	BURST/RELAY/CIPP	\$	70.00	\$	500.00	\$	14,850.00
ND15									•		
ND14	146.5	CLAY	4	POOR	BURST/RELAY/CIPP	.\$.	70.00	\$	500.00	\$	12,255.00
ND16				POOR/SMOKE							
ND15	182.3	CLAY	4	LEAK	BURST/RELAY/CIPP	\$	70.00	\$_	500.00	\$	14,761.00
ND17		-									
ND13	92.1	CLAY	1	POOR	BURST/RELAY/CIPP	\$	70.00	\$	500.00	\$	6,947.00
ND19			,	FAIR/SMOKE				١.		١.	
ND6A	140.9	PVC	0	LEAK	BURST/RELAY/CIPP	\$	70.00	\$	500.00	\$	9,863.00
ND21A	<u></u>		-								
ND21	174.5	CLAY	5	POOR	BURST/RELAY/CIPP	\$	70.00	\$	500.00	\$	14,715.00
ND21				·		١.				١.	
ND20	120.6	CLAY	3	POOR	BURST/RELAY/CIPP	\$	70.00	\$	500.00	\$	9,942.00
ND22	1			POOR/SMOKE							
ND21A	209.7	CLAY	2	LEAK	BURST/RELAY/CIPP	\$	70.00	\$	500.00	\$	15,679.00
ND23]			POOR/SMOKE						_	
ND22	233.8	CLAY	2	LEAK	BURST/RELAY/CIPP	\$	70.00	\$	500.00	\$	17,366.00
ND26										İ	

		DIDE			ORITI RELAIRS			Service		
Upst MH #	Line	PIPE	No. of	Line	Recommendations	Uni	t Cost*	Connect		Cost
to Dnst MH#	Length (ft)	TYPE	Services	Conditions		_				41,000,00
ND25	570	CLAY	4	POOR	BURST/RELAY/CIPP	\$	70.00	\$ 500.00	\$	41,900.00
ND27	<u>]</u> .			•						10.070.00
ND25	235.4	CLAY	5	POOR	BURST/RELAY/CIPP	\$_	70.00	\$ 500.00	\$	18,978.00

					· · · · · · · · · · · · · · · · · · ·		Ruddle-	1 Subtotal:	\$	288,665.00
Walker Park 1										
NC49A										
NC49	231.3	CLAY	4	POOR	BURST/RELAY/CIPP	\$	70.00	\$ 500.00	\$	18,191.00
NC49B										
NC8	246.4	CLAY	8	POOR	BURST/RELAY/CIPP	\$_	70.00	\$ 500.00	\$	21,248.00
NC49					e,					
NC49B	288.0	CLAY	9	POOR	BURST/RELAY/CIPP	\$	70.00	\$ 500.00	\$	24,660.00
NC50						1				
NC9	117.1	CLAY	2	POOR	BURST/RELAY/CIPP	\$	70.00	\$ 500.00	\$	9,197.00
NC51				•						
NC50	215.8	CLAY	4	POOR	BURST/RELAY/CIPP	\$	70.00	\$ 500.00	\$	17,106.00
NC53										
NC52	273.0	CLAY	1	POOR	BURST/RELAY/CIPP	\$	70.00	\$ 500.00	\$	19,610.00
NC54A										_
NC54	43.3	CLAY	1	POOR	BURST/RELAY/CIPP	\$	70.00	\$ 500.00	\$	3,531.00
NC54								:		
NC10A	98.6	CLAY	2	POOR	BURST/RELAY/CIPP	\$	70.00	\$ 500.00	\$	7,902.00
SERVICE CAP									Ì	
NC52	143.8	CONC	2	POOR	BURST/RELAY/CIPP	\$	70.00	\$ 500.00	\$	11,066.00
SERVICE CAP										
NC54A	47.2	CLAY	1	POOR	BURST/RELAY/CIPP	\$	70.00	\$ 500.00	\$	3,804.00
Locust & Lilly										• •
Popular & Lilly	229	CLAY	. 3	POOR	BURST/RELAY/CIPP	\$	70.00	\$ 500.00	\$	17,530.00
NC 20A									ŀ	
NC19	703	CONC	3	POOR	BURST/RELAY/CIPP	\$	70.00	\$ 500.00	\$	50,710.00
NC15A								1		

Upst MH # to Dnst MH#	Line Length (ft)	PIPE TYPE	No. of Services	Line Conditions	Recommendations	Unit Cost*	Service Connect		Cost
NC15	426.2	CLAY	9	POOR	BURST/RELAY/CIPP	\$ 70.00	\$ 500.00	\$	34,334.00
NC15									
NC16	23.7	CLAY	0	POOR	BURST/RELAY/CIPP	\$ 70.00	\$ 500.00	\$	1,659.00
NC24				POOR/SMOKE					
NC23	291	CLAY	. 2	LEAK	BURST/RELAY/CIPP	\$ 70.00	\$ 500.00	\$	21,370.00
NC25A									
NC25	344	CLAY	Ì1	POOR	BURST/RELAY/CIPP	\$ 70.00	\$ 500.00	\$	29,580.00
NC25									
NC24	193.9	CLAY	3	POOR	BURST/RELAY/CIPP	\$ 70.00	\$ 500.00	\$	15,073.00
						Walker Park	1 Subtotal:	\$	306,571.00
Walker Park 2							1		
1	·							_	
2	67.6	CLAY	1 .	POOR	RELAY	\$ 90.00	\$ 500.00	\$	6,584.00
NC66	ļ								- 0 - 4 00
NC65	80.6	CONC	2	POOR	BURST/RELAY	\$ 85.00	\$ 500.00	\$	7,851.00
NC86								١.	
NC85	349.5	CLAY	9	POOR	BURST/RELAY/CIPP	\$ 70.00	\$ 500.00	\$	28,965.00
NC87		l							22 700 00
NC86	397	CLAY	12	POOR	BURST/RELAY/CIPP	\$ 70.00	\$ 500.00	\$	33,790.00
NC89		- 						,	17.760.00
NC88	232.4	TRUSS	3	POOR	BURST/RELAY/CIPP	\$ 70.00	\$ 500.00	\$	17,768.00
NC93			<u>.</u>	2002		4 70.00	500.00	_	25 510 00
NC92	-343	CONC	3	POOR	BURST/RELAY/CIPP	\$ 70.00	\$ 500.00	\$	25,510.00
NC94	2001	aa		2002		, 7 0.00	# 500.00	_	21 507 00
NC93	300.1	CONC	1	POOR	BURST/RELAY/CIPP	\$ 70.00	\$ 500.00	\$	21,507.00
NC95	200.0	COME		DOOD		m 70.00	6 500.00	,	22 021 00
NC94	320.3	CONC	1	POOR	BURST/RELAY/CIPP	\$ 70.00	\$ 500.00	\$	22,921.00
NC99	240	COMO	_	DOOD	DIDOT/DELAZ/CIPP	e 70.00	¢ 500.00		10 200 00
NC98	240	CONC	5 .	POOR	BURST/RELAY/CIPP	\$ 70.00	\$ 500.00	\$	19,300.00
NC100	j	ŀ	١,			L	I	I	

TABLE 1 - HIGH PRIORITY REPAIRS

Upst MH # to Dnst MH#	Line Length (ft)	PIPE TYPE	No. of Services	Line Conditions	Recommendations	Uni	it Cost*		ervice onnect		Cost
NC99	217.1	CONC	5	POOR	BURST/RELAY/CIPP	\$	70.00	\$	500.00	\$	17,697.00
NC102											
NC101	263.2	CONC	6	POOR	BURST/RELAY/CIPP	\$	70.00	\$	500.00	\$	21,424.00
NC103				-							
NC92	361.9	CLAY	7	POOR	BURST/RELAY/CIPP	. \$	70.00	\$	500.00	\$	28,833.00
NC104				POOR/SMOKE							
NC103	563	CLAY	. 4	LEAK	BURST/RELAY/CIPP	\$	70.00	\$	500.00	\$	41,410.00
NC105				POOR/SMOKE							
NC104	246	CLAY	1	LEAK	BURST/RELAY/CIPP	\$	70.00	\$	500.00	\$	17,720.00
NC108											·
NC107	250	CLAY	3	POOR	RELAY	\$	90.00	\$	500.00	\$	24,000.00
NC109	:		•					ļ		ı	
NC108	242.7	CLAY	4	POOR	BURST/RELAY/CIPP	\$	70.00	\$	500.00	\$	18,989.00
NC110 ·											
NC109	160.7	CLAY	4	POOR	BURST/RELAY/CIPP	\$	70.00	\$	500.00	\$	13,249.00
NC111			. :								
NC110	264.9	CLAY	4	POOR	BURST/RELAY/CIPP	\$	70.00	\$	500.00	\$	20,543.00
NC72				•		-				٠.	·
NC71	257.4	CONC	4	POOR	BURST/RELAY/CIPP	\$	70.00	\$	500.00	\$	20,018.00
NC74							•				
NC73	335.5	CONC	2	POOR	BURST/RELAY/CIPP	\$	70.00	\$	500.00	\$	24,485.00
NC75											
NC74	245.9	CONC	2	POOR	BURST/RELAY/CIPP	\$	70.00	\$	500.00	\$	18,213.00
NC112				POOR/SMOKE							
NC109	86.1	CLAY	2	LEAK	BURST/RELAY/CIPP	\$	70.00	\$	500.00	\$	7,027.00
EOL											
NC24	148.3	CLAY	2	POOR	BURST/RELAY/CIPP	\$_	70.00	\$	500.00	\$	11,381.00
	· · · · · · · · · · · · · · · · · · ·				•	Wall	ker Park	2 Su	ıbtotal:	\$	469,185.00
Ward 1											
90W3											

TABLE 1 - HIGH PRIORITY REPAIRS

Upst MH #	Line	PIPE	No. of	Line	ORITI REPAIRS	TI C	Service	Cont
to Dnst MH#	Length (ft)	TYPE	Services	Conditions	Recommendations	Unit Cost*	Connect	Cost
90W2	323.7	CONC	2	POOR	BURST/RELAY/CIPP	\$ 70.00	\$ 500.00	\$ 23,659.00
LOCUST & LILY								
POPLAR & LILY	272.4	CLAY	4	POOR	BURST/RELAY/CIPP	\$ 70.00	\$ 500.00	\$ 21,068.00
MICHAELS JEWEL								
TEE IN LINE	183.9	CONC	6	POOR	BURST/RELAY/CIPP	\$ 70.00	\$ 500.00	\$ 15,873.00
WF105			•					,
WS31	225	CONC	5	POOR	BURST/RELAY/CIPP	\$ 70.00	\$ 500.00	\$ 18,250.00
WF108				,				
WF107	296.4	CONC	3	POOR	BURST/RELAY/CIPP	\$ 70.00	\$ 500.00	\$ 22,248.00
WF109								
WF108A	206.9	CONC	1	POOR	BURST/RELAY/CIPP	\$ 70.00	\$ 500.00	\$ 14,983.00
WF110								
WF109	340.7	CONC	3	POOR	BURST/RELAY/CIPP	\$ 70.00	\$ 500.00	\$ 25,349.00
WF111			,				-	
WF110	305.8	CONC	5	POOR	BURST/RELAY/CIPP	\$ 70.00	\$ 500.00	\$ 23,906.00
WF115					•			
WF114	507.2	CONC	12	POOR	BURST/RELAY/CIPP	\$ 70.00	\$ 500.00	\$ 41,504.00
WF116				•		•		•
WF107	347.6	CONC	3	POOR	BURST/RELAY/CIPP	\$ 70.00	\$ 500.00	\$ 25,832.00
WF118								
WF117	287.2	CONC	5	POOR	BURST/RELAY/CIPP	\$ 70.00	\$ 500.00	\$ 22,604.00
WF119								
WF118	359.8	CONC	8	POOR	BURST/RELAY/CIPP	\$ 70.00	\$ 500.00	\$ 29,186.00
WS1			•					
PS	51	CONC	0	POOR	BURST/RELAY/CIPP	\$ 70.00	\$ 500.00	\$ 3,570.00
WS30			٠.	*				
WS29	247.4	CONC	4	POOR	BURST/RELAY/CIPP	\$ 70.00	\$ 500.00	\$ 19,318.00
WS31								
WS29	62.4	CLAY	2	POOR	BURST/RELAY/CIPP	\$ 70.00	\$ 500.00	\$ 5,368.00
WS18				- · · · · · · · · · · · · · · · · · · ·				·
WS15	115	CLAY	2	FAIR	PC & INSTALL MH	\$ 2,000.00		\$ 2,000.00

Upst MH # to Dnst MH#	Line Length (ft)	PIPE TYPE	No. of Services	Line Conditions	Recommendations	Un	it Cost*		Service onnect	Cost
WS24	,									
WS23	175.2	CLAY	4	POOR	BURST/RELAY/CIPP	\$	70.00	\$	500.00	\$ 14,264.00
		٠.					Ward	1 S	ubtotal:	\$ 328,982.00
Ward 2										
WF57										
WF56	94.4	CONC	0	POOR	BURST/RELAY/CIPP	\$	70.00	\$	500.00	\$ 6,608.00
WF63										
WF62	138.5	CONC	1	POOR	BURST/RELAY/CIPP	\$	70.00	\$	500.00	\$ 10,195.00
WF68									• .	
WF67	252	PVC	?	PIPE MISSING	RELAY	\$	90.00	\$	500.00	\$ 22,680.00
WF72							,			•
WF71	447.4	CONC	17	POOR	BURST/RELAY/CIPP	\$	70.00	\$	500.00	\$ 39,818.00
WF71	·	·					-			
WF70	319.8	CONC	4	POOR .	BURST/RELAY/CIPP	\$	70.00	\$	500.00	\$ 24,386.00
	-						Ward	2 S	ubtotal:	\$ 103,687.00
					F	ligh]	Priority	Are	a Total:	\$ 1,843,502.00

^{*}Unit costs for BURST/RELAY/CIPP=\$70 per LF, RELAY/BURST=\$85 per LF, RELAY=\$90 per LF, REPAIR SERVICE or POINT REPAIR=\$1000 EA, SMH=\$2000 EA

APPENDIX B MEDIUM PRIORITY AREAS

Upst MH #	Line	Pipe	PIPE	No. of	Line	Recommendations	Unit Cost*	Service	Т	otal Cost
to Dnst MH#	Length	Size	TYPE	Services	Conditions	110001111101111101111		Connect		
705-2	······································		·	<u> </u>						
WD3			,			•				
WD2	238.4	8"	LINER	1	POOR	RELAY/BURST	\$ 85.00	\$ 500.00	\$	20,764.00
WD27										
WD2	184.9	10"	LINER	0	POOR	PT. REPAIR	\$ 1,000.00	\$ 500.00	\$	1,000.00
WD42						·				
WD41	252.2	8"	LINER	1	POOR	BURST/RELAY/CIPP	\$ 70.00	\$ 500.00	\$	18,154.00
		•	•				705	-2 Subtotal:	\$	39,918.00
705-3	* * *	· · · · · · · · · · · · · · · · · · ·								
WD20			,							
WD19	110.9	8"	CONC	0	POOR	BURST/RELAY/CIPP	\$ 70.00	\$ 500.00	\$	7,763.00
WD24								•		
WD23	40.7	8"	CONC	0 .	POOR	BURST/RELAY/CIPP	\$ 70.00	\$ 500.00	\$	2,849.00
	,									
							705	-3 Subtotal:	\$	10,612.00
1767-1						·	<u></u> .			
WP41										
WP40	379.6	8"	CONC	4	POOR	BURST/RELAY/CIPP	\$ 70.00	\$ 500.00	\$	28,572.00
WP48							·			
WP47	249	8"	CONC	1	POOR	BURST/RELAY/CIPP	\$ 70.00	\$ 500.00	\$	17,930.00
							:			
15.5	·						1767	-1 Subtotal:	\$	46,502.00
1767-2		· · · · ·	Г	T	· · · · · · · · · · · · · · · · · · ·			T		
WP81	•			1						0.500
WP80	384.8	8"	CONC	2	POOR	BURST/RELAY/CIPP	\$ 70.00	\$ 500.00	. \$	27,936.00
				•				• • • • • •		05.00 < 00
D., 441- 4					* .		1767	-2 Subtotal:	\$	27,936.00
Ruddle-1					T		T	1	-	
EOL	00.0					\TTP\(\) \ (\)			- -	2 000 00
ND10	82.8	6	CLAY	2	POOR	NEEDS M/H	\$ 2,000.00	J	\$	2,000.00

Upst MH # to Dnst MH#	Line Length	Pipe Size	PIPE TYPE	No. of Services	Line Conditions	Recommendations	Unit Cost*	Service Connect	'	Total Cost
EOL									.:	
ND22	83.1	6	CLAY	1 .	POOR	NEEDS M/H	\$ 2,000.00		\$	166,200.00
ND6A								-		
ND5	320.5	8	PVC	11	POOR	RELAY	\$ 90.00	\$ 500.00	\$	29,345.00
ND14								· ·		
ND13	293.7	6	CLAY	8	POOR	BURST/RELAY/CIPP	\$ 70.00	\$ 500.00	\$	24,559.00
ND20										
ND19	381	6	CLAY	. 8	POOR	BURST/RELAY/CIPP	\$ 70.00	\$ 500.00	\$	30,670.00
ND24					. 1					٠.
ND23	200.6	6	CLAY	3	POOR	BURST/RELAY/CIPP	\$ 70.00	\$ 500.00	\$	15,542.00
ND25			,							
ND21	315.3	. 6	CLAY	2	POOR	BURST/RELAY/CIPP	\$ 70.00	\$ 500.00	\$.	23,071.00
· .	÷.	·			· ·		Ruddle	-1 Subtotal:	\$	291,387.00
Walker Park	1									
NC27										
NC26	61.4	6"	CONC	?	POOR	BURST/RELAY/CIPP	\$ 70.00	\$ 500.00	\$	4,298.00
NC28	•					•				
NC20	154.7	6"	CONC	0	POOR	BURST/RELAY/CIPP	\$ 70.00	\$ 500.00	\$	10,829.00
NC52	•									
NC51	353.3	6"	CLAY	6	POOR	BURST/RELAY/CIPP	\$ 70.00	\$ 500.00	\$	27,731.00
NC16										
NC37	485.6	10"	CONC	2	POOR	BURST/RELAY/CIPP	\$ 70.00	\$ 500.00	\$	34,992.00
NC17		,								
NC16	27.9	10"	CONC	0	POOR	BURST/RELAY/CIPP	\$ 70.00	\$ 500.00	\$	1,953.00
NC18										
NC30	42.3	- 10"	CONC	0	POOR	BURST/RELAY/CIPP	\$ 70.00	\$ 500.00	\$	2,961.00
NC19										-
NC18	18.9	10"	CONC	0	POOR	BURST/RELAY/CIPP	\$ 70.00	\$ 500.00	\$	1,323.00
NC30										
NC17	234.2	10"	CONC	. 0	POOR	BURST/RELAY/CIPP	\$ 70.00	\$ 500.00	\$	16,394.00

Upst MH # to Dnst MH#	Line Length	Pipe Size	PIPE TYPE	No. of Services	Line Conditions	Recommendations	Unit Cost*	Service Connect	ר	Total Cost
to Dist Will#	Length	Size	IIIE	Ser vices	Conditions		Walker Park		\$	100,481.00
Walker Park	2					·				,
NC81A										
NC58	162	8"	CLAY	0	POOR	BURST/RELAY/CIPP	\$ 70.00	\$ 500.00	\$	11,340.00
NC81				,						
NC81A	318.9	8"	CLAY	. 2	POOR	BURST/RELAY/CIPP	\$ 70.00	\$ 500.00	\$	23,323.00
NC85] 		. *
NC84	152.7	8"	CLAY	4	POOR	BURST/RELAY/CIPP	\$ 70.00	\$ 500.00	\$	12,689.00
NC91				•						
NC91A	319.4	10"	CONC	2	POOR	BURST/RELAY/CIPP	\$ 70.00	\$ 500.00	\$	23,358.00
NC107										40.004.00
NC106	512.8	8"	CLAY	9	POOR	BURST/RELAY/CIPP	\$ 70.00	\$ 500.00	\$_	40,396.00
NC73										22 (56 00
NC68	316.8	8"	CONC	1	POOR	BURST/RELAY/CIPP	\$ 70.00	\$ 500.00	\$	22,676.00
NC88								. 500.00	_	02.467.00
NC59	328.1	8"	TRUSS	1	POOR	BURST/RELAY/CIPP	\$ 70.00	\$ 500.00	\$	23,467.00
NC57	40.4.1	10"	COM		noon		6 70.00	¢ 500.00	٠	20 297 00
NC56	434.1	12"	CONC	0	POOR	BURST/RELAY/CIPP	\$ 70.00	\$ 500.00	\$	30,387.00
				-		•	Walker Park	2 Subtotale	\$	187,636.00
Ward 1							Waikei I ai k	2 Subtotar.	Ф	107,030.00
WS20				 	1		1	T	T	
WS19	400.2	10"	CLAY	4	FAIR	PC & REPAIR SERVICE	\$ 1,000.00	\$ 500.00	\$	1,000.00
WF102	100.2		CLEATI		1744	TO & REFTING BERTICE	V 1,000.00	\$ 500.00	<u> </u>	1,000.00
WF101	506.9	6"	CONC	13	POOR	BURST/RELAY/CIPP	\$ 70.00	\$ 500.00	\$	41,983.00
WF106			1		1 0 0 1 1		7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7		Ť	
WF93	168.7	10''	CONC	1	FAIR	BURST/RELAY/CIPP	\$ 70.00	\$ 500.00	\$	12,309.00
WF107	<u> </u>		<u> </u>	-					Ė	· · · · · · · · · · · · · · · · · · ·
WF106	200.5	10"	CONC	3	POOR	BURST/RELAY/CIPP	\$ 70.00	\$ 500.00	\$	15,535.00
WF108A										
		1		1	•		1	'	• .	1

Upst MH # to Dnst MH#	Line Length	Pipe Size	PIPE TYPE	No. of Services	Line Conditions	Recommendations	Uni	it Cost*	Service Connect	7	Total Cost
WF108A	123.9	6"	CONC	3	POOR	BURST/RELAY/CIPP	\$	70.00	\$ 500.00	\$	10,173.00
WF114											
WF113	48	8"	CONC	0	POOR	BURST/RELAY/CIPP	\$	70.00	\$ 500.00	\$	3,360.00
WF117									• *		
WF116	299.9	8"	CONC	8	POOR	BURST/RELAY/CIPP	\$	70.00	\$ 500.00	\$	24,993.00
WS6							_				
WS5	364.1	8".	CLAY	6	POOR	BURST/RELAY/CIPP	\$	70.00	\$ 500.00	\$	28,487.00
WS29		4									22 250 00
WS28	305	6"	CONC	2	POOR	BURST/RELAY/CIPP	\$_	70.00	\$ 500.00	\$	22,350.00
WS21	202.0	0"	GT 4.77		2002			70.00	m 500.00		27 802 00
WS20	382.9	8"	CLAY	2	POOR	BURST/RELAY/CIPP	\$	70.00	\$ 500.00	\$	27,803.00
		• •						Ward	1 Subtotal:	\$	187,993.00
Ward 2						, a	•				
WF4A				· · · · · · · · · · · · · · · · · · ·							•
WF57	56	10"	CONC	0	POOR	BURST/RELAY/CIPP	\$_	70.00	\$ 500.00	\$	3,920.00
WF56	•										•
WF55	428.9	12"	CONC	1 .	POOR	BURST/RELAY/CIPP	\$	70.00	\$ 500.00	\$	30,523.00
WF60										1	*
WF59	307	8"	CONC	2	POOR	BURST/RELAY/CIPP	\$	70.00	\$ 500.00	\$	22,490.00
WF62											
WF61	313.8	8"	CONC	6	POOR	BURST/RELAY/CIPP	\$	70.00	\$ 500.00	\$	24,966.00
WF70				_		,					
WF59	311.6	8"	CONC	1 .	POOR	BURST/RELAY/CIPP	\$	70.00	\$ 500.00	\$	22,312.00
		·		• ,				Ward	2 Subtotal:	\$	104,211.00
						Med	dium	Priority	y Total Cost	: \$	996,676.00

^{*}Unit costs for BURST/RELAY/CIPP=\$70 per LF, RELAY/BURST=\$85 per LF, RELAY=\$90 per LF, REPAIR SERVICE or POINT REPAIR=\$1000 EA, SMH=\$2000 EA

APPENDIX C SMOKE TEST SUMMARY

*The table below summarizes specific smoke leak locations along sewer mains as documented by Arkansas Cleaning & Televising during tests. Sewer service line leaks are not included in the table.

	TABLE 3 - SMOKE TEST SUMMARY							
Site	Name	Smoke Leak Location						
705-1	WD5 to WD4	40' from WD5 over main						
705-2	WD46	All around SMH						
	WD53 to WD51	Storm Drain Connection						
,	WD33 to WD32	5' to 26' over main from WD33						
705-3	WD21 to WD20	Over main 2' from WD21						
•	WD22	Around SMH and sidewalk						
	WD20	Around SMH						
	WD16 to WD7	Storm Drain Connection						
1767-1	WP27 to WP24	Storm Drain Connection						
	WP29 to WP22	Storm Drain Connection						
	WP21 to WP20	Storm Drain Connection						
	WP18 to WP17	Storm Drain Connection						
	WP82 to WP81	70' from WP82 over main						
	WP82 to WP81	Crack in Street						
	WP80 to WP79	Storm Drain Connection						
	WP78 to WP2	Storm Drain Connection						
	WP40 to WP39	Inlet						
Walker Park 1	NC40 to NC3	26' from NC40 over main						
	NC24 to NC23	172' from NC24 over main						
	NC24 to NC23	213' from NC24 over main						
Walker Park 2	NC112 to NC109	Storm Drain Connection						
	NC105 to NC104	Sidewalk 3' from NC105						
	NC104 to NC103	Crack in Street						
Ruddle-1	ND23 to ND22	2' off main						
·	ND22 to ND21A	3' off main						
	ND19 to ND6A	Over main at 9' & 136' from ND19						
	ND16 to ND15	Over main at 245' from ND16						
	ND7 to ND6	Storm Drain Connection						

APPENDIX D

SAMPLE PAGES FROM ARKANSAS CLEANING & TELEVISING REPORT

Log No.	Disk No.	PIPE TYPE	Date	Upst MH # to Dnst MH#	Line Length	Pipe Size	No. of Services	Line Conditions	Recommendations
				WF1A		40"		D	D
31	4	Conc	4/26/2011	WF2A WF2A	298.2	10"	6	Poor	Burst/Relay/CIPP
32	4	Conc	`4/27/11	WF3A	274.3	10"	3	Poor	Burst/Relay/CIPP
				WF3A					
33	4	Conc	4/27/2011	WF4A	195.4	10"	1	Poor	Burst/Relay/CIPP
				WF4A		400			D
34	4	Conc	4/27/2011	WF57	56	10"	0	Poor	Burst/Relay/CIPP
35	4	Conc	4/28/2011	WF56 WF55	428.9	12"	1	Poor	Burst/Relay/CIPP
33	4	Conc	4/20/2011	WF57	420.5	12		1 001	Bulsertelayron
36&37	4	Conc	4/28/2011	WF56	94,4	12"	0	Poor	Burst/Relay/CIPP
00001		00.10	1120/2011	WF59					
38	4	Conc	4/28/2011	WF57	332.4	10"	0	Poor	Burst/Relay/CIPP
				WF60					
39	4	Conc	4/28/2011	WF59	307	8"	2	Poor	Burst/Relay/CIPP
				WF61					
40	4	Conc	4/21/2011	WF60	352.3	8"	10	Poor	Burst/Relay/CIPP
440.40		0	4/04/0044	WF62	242.0	8"	6	Door	Puret/Peley/CIPP
41842	4	Conc	4/21/2011	WF61 WF63	313.8	8	6	Poor	Burst/Relay/CIPP
43	4	Conc	4/21/2011	WF62	138.5	8"	1	Poor	Burst/Relay/CIPP
43	4	COILC	4/21/2011	WF64A	130.0	0		1 001	Duistriciayion
44	4	PVC	4/22/2011	WF57	188.8	8"	0	Fair	Periodic Cleaning
	<u> </u>	1.00	1/22/2011	WF64	100.0				
45	4	PVC	4/22/2011	WF64A	76.2	8"	0	Fair	Periodic Cleaning
				WF65					
46	4	PVC	4/22/2011	WF64	157.8	8"	0	Fair	Periodic Cleaning
				WF66					
47	4	PVC	4/22/2011	WF65	207.3	8"	0	Fair	Periodic Cleaning
40		DI /O	4/00/0044	WF67	150.4	0"		Foir	Dariadia Claanina
48	4	PVC	4/22/2011	WF66 WF68	150.1	8"	0	Fair	Periodic Cleaning
49&50	4	PVC	4/27/2011	WF67	5+	8"	?	Pipe Missing	Excavate
43000	4	1700	4/2//2011	WF70	3.	- 0		i ipo ivilasiliy	LAGGYGIG
51	4	Conc	4/21/2011	WF59	311.6	8"	1	Poor	Burst/Relay/CIPP
		33.13		WF72					
52	4	Conc	4/21/2011	WF71	447.4	8"	17	Poor	Burst/Relay/CIPP
				WF71					
53	4	Conc	4/21/2011	WF70	319.8	8"	4	Poor	Burst/Relay/CIPP
		-			-				

						501	-007-1010	
Projec	t#			Date	Operator			Direction
		YETHVILL	.E 4/	26/2011	TONY RUSHIN	IG		JPSTREAM
Tape	#	CD#	Location		Log#	Weather		
7		4	RAIL ROAD E	ASMENT	31	CLOUDY 8	& WARM	
Ups	strean	n MH	Downstream MH	Pipe Type	Pipe Size	Length	Depth	Flow Rate
	WF1/		WF2A	CONCRETE	10"	298.2	5'4"	1/4
More I	nfo:							
Foot	Cod	Fro						
age	е	m To	Description	Comn STAR				
0.0	MH		Manhole	AT MA WF2A	ANHOLE			
						11 145 17		
					e de la	Carlo.	100	110
					100			
							100	
52.7	SVR 3	2	Service Residential Protruding <1"	ai -				
	3		Protitioning 1		8		- Se	
							A Property of	
					1			
						· ·		24. 3
53.8	RTS		Roots in Joint - Lig	ght				
53.6	1		Roots					
					, ear	HERESTEEN .	175	
							40.4	
						- Salan		
84.6	SVR	12	Service Residentia	al	700			
						1100		
					1			
						6		
405						Also Also		
105. 4	SVR	2	Service Residentia	al PLUG	GED			
136. 9	SVR	2	Service Residentia	al PLUG	GED			
9				,				

Project #	Date	Operator	Direction
CITY OF BLYETHVILLE	4/26/2011	TONY RUSHING	UPSTREAM

Tape #	CD#	Location		Log #	Weather		
	4	RAIL ROAD E	ASMENT	31	CLOUDY	& WARM	
Upstrear	m MH	Downstream MH	Pipe Type	Pipe Size	Length	Depth	Flow Rate
WF1		WF2A	CONCRETE	10"	298.2	5'4"	1/4

More info:

Foot Fro


WF1A

age Code m To Description

Comments

169.5 SVR 2

Service Residential



175.6 SVR 3

Service Residential



229.0 SVR 2

Service Residential

PLUGGED

Project #	Date	Operator	Direction
CITY OF BLYETHVILLE	4/26/2011	TONY RUSHING	UPSTREAM

Tape #	CD#	Location	Log#	Weather
	4	RAIL ROAD EASMENT	31	CLOUDY & WARM

 Upstream MH
 Downstream MH
 Pipe Type
 Pipe Size
 Length
 Depth
 Flow Rate

 WF1A
 WF2A
 CONCRETE
 10"
 298.2
 5'4"
 1/4


More info:

Foot Fro age Code m To Description

Comments


256.1 SVR 3

Service Residential



257.9 SVR 3

Service Residential



298.2 MH

Manhole


ENDING AT MANHOLE WF1A

Project # CITY OF BLYETHVILLE		E 4/		Operator ALEX SCHINGLE			Direction DOWNSTREAM	
Tape #	CD#	Location RAIL ROAD E	EASMENT	Log #	Weather	& WARM		
Upstream	мн	Downstream MH	Pipe Type	Pipe Size	Length	Depth	Flow Rate	
WF2A		WF3A	CONCRETE	10"	274.3	5'4"	1/4	

More Info:

Foot age	Cod	Fro m	То	Description	Comments STARTING
0.0	МН			Manhole	AT MANHOLE WF2A
	SS1 SVR			Sag Starts - Minor Service Residential	PLUGGED

46.4 SVR 10 Service Residential



153. SVR 10 Service Residential



Project #	Date	Operator	Direction
CITY OF BLYETHVILLE	4/27/2011	ALEX SCHINGLE	DOWNSTREAM
	hada-gre-se-yaaya-e-eggin-e-has-se-de-green-a-se-de-green-		

 Tape #
 CD #
 Location
 Log #
 Weather

 4
 RAIL ROAD EASMENT
 32
 CLOUDY & WARM

 Upstream MH
 Downstream MH
 Pipe Type
 Pipe Size
 Length
 Depth
 Flow Rate

 WF2A
 WF3A
 CONCRETE
 10"
 274.3
 5'4"
 1/4

More info:

Foot Fro

age Code m To Description

Comments

FEELINGS, 1

249.1 SVR 9

Service Residential

274.3 MH

Manhole

ENDING AT MANHOLE WF3A



SEWER REHAB - PIPE CLEANING - CCTV

6625 BRODIE LANE LITTLE ROCK, AR. 72204

SMOKE TESTING LOG

	Log #: 3		Location: 72	
Manhole#	Length	Leak Y/N	Description/Comments	
NC4	373.6	N		
NC4	404.7	Υ		
NC4	420	Υ	PIC. 3	
NC41	449.1	N		
NC3	320.9	N		
NC3	437.2	Υ	PIC. 4, 5, 6	
NC38	453.5	N		
NC3	405	N		
NC25	344	N		
NC24	193.9	N		
NC24	148.3	N		
	3950.2			
	Manhole# NC4 NC4 NC4 NC41 NC3 NC3 NC3 NC3 NC38 NC38 NC3 NC25 NC24	Manhole# Length NC4 373.6 NC4 404.7 NC4 420 NC41 449.1 NC3 320.9 NC3 437.2 NC38 453.5 NC3 405 NC25 344 NC24 193.9	Manhole# Length Leak Y/N NC4 373.6 N NC4 404.7 Y NC4 420 Y NC41 449.1 N NC3 320.9 N NC3 437.2 Y NC38 453.5 N NC3 405 N NC25 344 N NC24 193.9 N NC24 148.3 N	Manhole# Length Leak Y/N Description/Comments NC4 373.6 N NC4 404.7 Y PIC. 1, 2 NC4 420 Y PIC. 3 NC41 449.1 N NC3 320.9 N NC3 437.2 Y PIC. 4, 5, 6 NC38 453.5 N NC3 405 N NC25 344 N NC24 193.9 N NC24 148.3 N

PICTURE #1










PICTURE #2














PICTURE #6


























From: (901) 683-3900 DANIEL BOWLING SSR ELLERS 2650 THOUSAND OAKS BLVD **SUITE 3200** MEMPHIS, TN 381182486


Origin ID: OLVA



SHIP TO-**BILL SENDER**

MARILYN STOUT ADEQ WATER DIV. ENFORCEMENT BRANCH **5301 NORTHSHORE DRIVE**

NORTH LITTLE ROCK, AR 721185317



Ship Date: 31JAN12 ActWgt 1.0 LB MAN CAD: 0922019/CAFE2510

Delivery Address Bar Code



Ref# Invoice # PO#

Dept#

5444

10612130

6100

WED - 01 FEB A4 PRIORITY OVERNIGHT

TRK# 0201

5172 8804 4789

X2 LITA

72118 AR-US **MEM**

