≎EPA

Form Approved OMB No. 2040-0003 Approval Expires 7-31-85

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY Washington, D.C. 20460

NPDES Compliance Inspection Report

				Section A: Natio	nal Da	ta Svst	em Codi	ng										
	Transaction Code		NPDES					/mo/da	v			Insr	ес. Ту	ne.	Inspec	tor	Fac	Туре
1	N 2 5 3 A R 0	0		5 0 11	12	0 /	1	1 1	Ī	4	17	18	\mathbf{v}	19	ı	20		
· L	IN 2 3 3 IN IN I	10	12 1 /		12 L Remark		, 10	-			1,	10		17	S			
I	A F I N 6	<u> 6</u>	- ₀ ₀	2 2 6			ĺ	I I	Ī	1	ĺ		1	Ī	I	I	1	
L					DI									1			<u> </u>	
	Inspection Work Days	rac	cility Evaluation F	_	BI ,	QA	Ī	 I I	 	 7.4	I	ıı 	Reserve	d	 	 		-
	67 69		70 N	71	N	72	N 73	Ш		74	75						80	
				Section 1	B: Faci	ility Da	ata											
Nar	me and Location of Facility Inspected	d (For in	ıdustrial users dis	scharging to POT	W, also	,	Entry Tir	ne /Da	te				Perm	it Effec	tive D	ate		
	lude POTW name and NPDES permit					-	1230 / 0	1-24	07				09-	01-03				
	ty of Fort Smith POTW Mas 09 North 9th	ssara I	<u>Plant</u>			-							_					
	rling, AR 72923						Exit Tim 1340 / (.07					it Expir 31-08	ation l	Date		
							134076	71-24	-07				00-	31-00				
	me(s) of On-Site Representative(s)/Ti				2001							Oth	er Faci	ity Data	ı			
Eac	die Pate / Fort Smith Utility D	epartn	nent / Truck #	313 / 4/9-783	5-2801	L						Co	ordina	es of C	verfl	ow:		
Nan	me, Address of Responsible Official/	Title/Pho	one and Fax Num	ber									19'30					
Ste	eve Parke / Utilities Director							Conta	cted			94	20'48'	W				
	00 Kelley Highway						Yes	N	No	X								
FOI	rt Smith, AR 72904						_		_									
Section C: Areas Evaluated During Inspection (S = Satisfactory, M = Marginal, U = Unsatisfactory, N = Not Evaluated)																		
N	Permit	N I	Flow Measureme	ent	N	Opera	ations &	Maint	enanc	e		U	CSO/S	sso				
N	Records/Reports	N	Self-Monitoring	Program	N	Slude			nocol		Ī	N	Pollut					
N.T		14	Sch-Montoring	, 8	11	Siuu	ge Handl	ing/Di	sposai			- '	I OHU	ion Pre	ventio	11		
N	Facility Site Review	N	Compliance Sch	_	N		ge Handl reatment		sposai		-	N	Multi		ventio	11		
N N	Facility Site Review Effluent/Receiving Waters	N		_		Pret			sposai		_			nedia	ventio	11		
	1	N N	Compliance Sch	_	N N	Pret Stori	reatment	t				N N	Multi	nedia	ventio			
In loc AI at Mi	1	Section of the Circle of the C	Compliance Sch Laboratory ion D: Summary d a sanitary seathley-Patterso ed by employe ty was unawa	of Findings/Conewer overflow on Electric was ees of AHTD or of the problem.	N N nments inspects s over on 01-	Storm (Attaction flowing 109-0° and City	reatment n Water ch addition in the 7 ng. AD 7. During y crews	onal sh 700 b DEQ w ng my woul	eets if lock vas no insp d res	of Sotification	South ed in on M	N N Zero rega r. Eo	Other o in Fard to	ort Sm the ovate (training on as	nith. Terflo	The m w by 515)	the arri adv	ved
In loc AH at Mr NH	response to a complaint, I percated adjacent to the entrance HTD. The overflow was first the site. He informed me that Ir. Pate to inform his Supervision.	Section of the North Nor	Compliance Sch Laboratory ion D: Summary d a sanitary seathley-Patterso ed by employe ty was unawa	of Findings/Conewer overflow on Electric was ees of AHTD or of the problem.	N N N nments inspects s over on 01- em an	Pret Stori (Attac ction flowir -09-0 ad City ncider	reatment in Water ch addition in the 7 ing. AD 7. During y crews int to be	ponal sh 700 b DEQ w ng my woul repor	eets if lock vas no insp d res	of Softification of Softier of So	Southed in Medical Control of the Co	N N Zero rega r. Eo	Other o in Fard to	ort Sm the ovate (transon as	nith. Terflo	The m w by 515)	the arri adv	ved
In loo AI at Mr NI	response to a complaint, I percated adjacent to the entrance HTD. The overflow was first the site. He informed me that Ir. Pate to inform his Supervise PDES Permit.	Section of the North Nor	Compliance Sch Laboratory ion D: Summary d a sanitary seathley-Patterso ed by employe ty was unawa	of Findings/Comewer overflow on Electric was ees of AHTD or eof the problement the need for Agency/Office.	N N N nments inspects s over on 01- em an	Pret Stori (Attac ction flowir -09-0 ad City ncider	reatment in Water ch addition in the 7 ing. AD 7. During y crews int to be	ponal sh 700 b DEQ w ng my woul repor	eets if lock vas no insp d res	of Softification of Softier of So	Southed in Medical Control of the Co	N N Zero rega r. Eo	Multin Other o in F and to Idie P e as so condit	ort Sm the ovate (transon as	nith. Terflo	The m w by 515)	the arri adv	ved



February 16, 2007

Mr. Steve Parke, Utilities Director City of Fort Smith 3900 Kelley Highway Fort Smith, AR 72904

Re: AFIN: No. 66-00226 NPDES Permit No. AR0021750

Dear Mr. Parke:

On January 24, 2007, I performed a sanitary sewer overflow inspection of the collection system in the 7700 block of South Zero in Fort Smith in response to a complaint. This inspection was performed in accordance with the provisions of the federal Clean Water Act, the Arkansas Water and Air Pollution Control Act and the regulations promulgated thereunder. This inspection revealed the following violation:

I arrived at the site at 1230, the manhole adjacent to the Keathley Patterson Electric entrance was overflowing. A substantial amount of untreated sewage and other material was flowing from the top. It appeared that the overflow had been occurring for an extended period of time, due to the heavy amounts of sewage that was pooling below the area. It also appeared that runoff from the overflow was entering the tributary to Massard Creek. During my inspection, City utility crews arrived at the site to address the problem. I advised them to notify the proper authorities with the City in regard to the overflow and the requirement to report the incident to the NPDES Enforcement Section of our Department per conditions of the City's permit.

This violation requires your immediate attention. Please submit a written response to this finding to the NPDES Enforcement Section of this Department. Your response should contain documentation describing the course of action taken to correct this item and the City's plan to prevent this occurrence in the future. The corrective action should be completed as soon as possible and the written response is due by **March 5, 2007**.

If you have any questions, please feel free to contact me at 479-452-4822 ext. 11.

Sincerely,

Jeff Tyler District Field Inspector

Water Division

cc: NPDES Enforcement Branch

Arkansas Department of Environmental Quality (ADEQ) Official Photograph Sheet

Location:	770	00 Bloc	k of Sout	h Zero in Fort Smith	rapii bii			
Photographe	er:	Jeff Ty	ler		Witness:	N/A		
Photo #	1	Of	4		Date:	01-24-07	Time:	1330
Description:		Manho	le overflo	owing adjacent to the entr	ance to Kea	thley Pattersor	Electric.	1
Photographe	er:	Jeff Ty	ler		Witness:	N/A		
Photo #	2	Of	4		Date:	01-24-07	Time:	1330
Description:		Untrea to Kear	ted sewaş	ge and other material flow erson Electric.	ing from to	p of manhole l	ocated besi	de the entrance

Arkansas Department of Environmental Quality (ADEQ) Official Photograph Sheet

			Official Photog	grapii Sii	leet		
770	00 blo	ck of Sout	h Zero in Fort Smith				
er:	Jeff T	yler		Witness:	N/A		
3	Of	4		Date:	01-24-07	Time:	1335
	Heav	y amounts	of untreated sewage poo	ling below th	ne overflowing	g manhole.	•
er:	Jeff T	yler		Witness:	N/A		
e r: 4	Jeff T			Witness: Date:	N/A 01-24-07	Time:	1335
4	Of Low	4 area below	the overflowing manhol utary to Massard Creek.	Date:	01-24-07		
	r:	r: Jeff T	r: Jeff Tyler 3 Of 4	3 Of 4	r: Jeff Tyler Witness: 3 Of 4 Date:	r: Jeff Tyler Witness: N/A 3 Of 4 Date: 01-24-07	r: Jeff Tyler Witness: N/A