		_							
	ADEQ		WATER	DIVISION I	NSP	ECT	101	I REP	ORT
	ADEU	AFIN: 18-00110			PERM	11T #: AF	₹002	21971	
=		CC	DUNTY: 18 Critte	nden	PDS #: 077286		6	N	MEDIA: WN
Α	RKANSAS	GF	PS LOCATION: L	AT: 35.190364 L	ONG:	-90.228	445	•	
De	partment of Environmental Quality		☐ Outfall /	☐ General Area	ı / 🛛 I	Entrance	e / 🔲	Sample	Point
	FACILITY INFORMAT	l	IN	SPECT	TION INI	FORI	MATION		
	ME: City of Marion WWTP		DATE(S):	3/18	/2014				
LO	CATION: West side of Hwy 118, S	out	h of the UP rail	ENTRY TIME:		:30			
road.				EXIT TIME:		:00			
CI	ΓΥ: Marion, AR			INSPECTION T				n Systen	n
	RESPONSIBLE OFFIC			INSPECTOR ID					
	INTACTED DURING INSPECTION:	: Ye	S	FACILITY TYPE					
	ME: Jim Shempert			PERMIT EFFEC					
	LE: Water Utilities Director			PERMIT EXPIR					
	MPANY: City of Marion			FACILITY EVAL					
	ILING P.O. Box 717			FAYETTEVILLE					
	DRESS:			FAYETTEVILLE SHALE VIOLATIONS: N					
	TY, STATE, ZIP: Marion, AR 72364	•		INSPECTION PARTICIPANTS					
	ONE & EXT: 870-739-5413			NAME/TITLE/PHONE/FAX/EMAIL/ETC.:					
	X: N/A			Jim Shempert /	Water	Utilities	s Dire	ector / 87	0-739-5413
	IAIL: N/A								
OT	HER: N/A								
	(S=S:	atisfad	AREA EVA		/Evaluated)			
S	PERMIT	**	FLOW MEASUR		**	STOR	MWA	TER	
**	RECORDS/REPORTS	**	LABORATORY		**	FACILI	TY S	ITE REV	EW
U	OPERATION & MAINTENANCE	**	EFFLUENT/REC	CEIVING WATER	**	* SELF-MONITORING PROGRAM			
**	SAMPLING	**	SLUDGE HAND	LING/DISPOSAL	**	** PRETREATMENT			
U	OTHER: SSO								
			SUMMARY C						
	is Sanitary Sewer Overflow (SSO)								
	pection. This SSO inspection rev	eale	ed excessive gre	ase and solids ir	າ the w	et well o	of the	Vintage	· Veranda
pu	mp station.								
			GENERAL (
	fer to the letter accompanying the	e Ma	arch 18, 2014 Co	mpliance Evalua	tion In	spectio	n for	addition	al
inf	information.								
	MilDs Greez								
	Medslo	fe	dy						
INS	SPECTOR'S SIGNATURE:	900	Michael Gr	eenway				DATE: 4	1/4/2014
		/	0111 -						
	/an	in R	William !					- ·	
SU	UPERVISOR'S SIGNATURE: Jason Bolenbaugh DATE: 4/14/2014								

Inspection Report: City of Marion WWTP, AFIN: 18-00110, Permit #: AR0021971
Water Division Photographic Evidence Sheet Location: City of Marion WWTP, Vintage Veranda Pump Station Photographer: Michael Greenway Date: 3/18/2014 Time: 13:54 Witness: None Photo #: View of excessive grease and solids in the wet well of the Vintage Veranda pump Description: 3/18/2014 / 13:54:26

Marion Water Department

MAYOR FRANK A FOGLEMAN

WATER UTILITIES MANAGER
JIM SHEMPERT

31 MILITARY ROAD P.O. BOX 814 MARION, ARKANSAS 72364 PHONE: 870-739-3073 FAX: 870-739-5415 WATER & SEWER COMMITTEE

JIM SPENCE, CHAIRMAN

KELLY O'NEAL
CLIFF WOOD

APRIL 23, 2014

Water Division Inspection Branch Arkansas Department of Environmental Quality 5301 Northshore Drive North Little Rock, AR 72118-5317

RE: WRITTEN RESPONSE TO SUMMARY OF FINDINGS

AFIN: 18-00110 Permit No: AR0021971, AR0021971C and ARR000189

- 1. Totalizing Meter was not in service at the time of inspection due to lighting damage in February. Van Brocklin and Associates had the meter making repairs. It is now in service. (Copy of invoice attached)
- 2. Influent sampling to calculate CBOD5 and TSS annually was a total oversight on my part as the operator. It is now scheduled with my contract lab to be performed annually. (Copy of report attached)
- 3. Excessive vegetation on lagoon levees will be addressed as weather permits.
- **4.** Staff gauge has been installed. (Photo attached)
- **5**. Sample time recording and the individual making the analysis will be reported on the DO sample. (Sample report sheet attached)
- **6.** Flow design was exceeded due to the auxiliary pumping. We anticipate compliance of Daily Flow with the implementation of our new permit allowing us to pump our effluent to the Mississippi River, giving us more control of our flow.
- **7**. We have removed the excessive grease and solids from the wet well at Vintage Veranda pump station. (Photo attached)

Inspection Report: City of Marion WWTP, AFIN: 18-00110, Permit #: AR0021971

L	ADEQ		WATER	DIVISIONI	NSF	ECT	ION REI	PORT:
	コレレ	AF	IN: 18-00110		PERN	/IT #: AI	R0021971	
		CC	DUNTY: 18 Critte	nden	PDS	#: 07728	37	MEDIA: WN
Α	RKANSAS	GF	S LOCATION: L	AT: 35.190364 L	ONG:	-90.228	445	
	epartment of Environmental Quality	<u> </u>	☐ Outfall /	General Area		Entrance	e / 🔲 Sample	Point
學學	, FACILITY INFORMAT	IOI		in the second	SPEC	TIONIN	FORMATION	literation of the
	AME: City of Marion WWTP			DATE(S):		/2014		·
LC	DCATION: West side of Hwy 118, S	out	h of the UP rail	ENTRY TIME:	10):30		
	ad.			EXIT TIME:		3:00		
	TY: Marion, AR			INSPECTION T				on
	RESPONSIBLE OFFIC			INSPECTOR ID				
	ONTACTED DURING INSPECTION	: Ye	s	FACILITY TYPE	: 1 - M	unicipa		
	AME: Jim Shempert			PERMIT EFFECTIVE DATE: 12/1/2013				
	TLE: Water Utilities Director			PERMIT EXPIRATION DATE: 6/30/2017				
	OMPANY: City of Marion			FACILITY EVALUATION RATING: 1 - Unsatisfactory				
	AILING P.O. Box 717			FAYETTEVILLE SHALE RELATED: N				
	DDRESS:		· - ···	FAYETTEVILLE SHALE VIOLATIONS: N				
	TY, STATE, ZIP: Marion, AR 72364	}		i in			The state of the s	
	ONE & EXT: 870-739-5413			NAME/TITLE/PH				
	X: N/A			Jim Shempert /	Water	Utilities	Director / 8	70-739-5413.
	//AIL: N/A							
	THER: N/A							
West of the state		atisfac	AREA EVA	LUATIONS Isfactory, N=Not Applicable	/Evaluated			
S	PERMIT	U	FLOW MEASUR	REMENT	**	STORI	MWATER	
U	RECORDS/REPORTS	S	LABORATORY		U	FACILI	TY SITE REV	/IEW
U	OPERATION & MAINTENANCE	M	EFFLUENT/REC	CEIVING WATER	U	SELF-I	MONITORING	G PROGRAM
U	SAMPLING	**	SLUDGE HAND	LING/DISPOSAL	**	PRETF	REATMENT	
**	OTHER:							
遊詢		A SECTION	SUMMARY	F FINDINGS		VACO IN		斯莱斯科特科 斯亚

This routine compliance inspection revealed the following violations:

- 1. The totalizing meter for flow measurements was not maintained (Photo 1). Instantaneous flow measurements were taken daily at the crest of the weir. This violates Part I, Section A, and Part III, Section B, Item 1A of the Permit.
- 2. The facility did not perform influent sampling and calculate the CBOD5 and TSS removal rate annually. This violates Part II, Item 2 of the Permit.
- 3. There was excessive vegetation on the north and east levees of the lagoon (Photos 2-3). This violates Part III, Section B, Item 1A of the Permit.
- 4.Head was measured improperly at the crest of the weir for instantaneous flow measurements (Photo 4). This violates Part III, Section C, Item 2 of the Permit. A staff gauge should be installed at least 3 times the expected head upstream of the weir for accurate flow measurement.
- 5. The time and individual performing sampling/analysis was not recorded for DO monitoring. This violates Part III, Section C, Item 8 of the Permit.
- 6. At the time of inspection, flow was measured and calculated to be greater than 2.39 MGD. This exceeds the 1.6 MGD design flow of the facility. It appears the facility may experience significant infiltration and inflow problems. Auxiliary pumps were installed and running to establish/maintain adequate freeboard in the lagoons (Photo 5).
- 7. The Sanitary Sewer Overflow (SSO) inspection revealed excessive grease and solids in the wet well of the Vintage Veranda pump station. This violates Part III, Section B, Item 1A of the Permit.



April 15, 2014

Jim Shempert, Water Utilities Director City of Marion WWTP P.O. Box 717 Marion, AR 72364

RE:

Compliance Inspection, Marion Wastewater Treatment Plant

AFIN: 18-00110

Permit No.: AR0021971, AR0021971C and ARR000189

Dear Mr. Shempert:

On March 18, 2014, I performed a routine compliance inspection of the above referenced facility. Throughout the course of the inspection, I conducted a compliance evaluation inspection (CEI), a sanitary sewer overflow (SSO) inspection, a stormwater no exposure verification, and a reconnaissance inspection of the proposed modifications to the WWTP. This inspection was conducted in accordance with the provisions of the Federal Clean Water Act, the Arkansas Water and Air Pollution Control Act, and the regulations promulgated thereunder. A copy of the inspection reports are enclosed for your records.

Please refer to the "Summary of Findings" section of the attached inspection report and provide a written response for each violation that was noted. This response should be mailed to the attention of the Water Division Inspection Branch at the address at the bottom of this letter or emailed to Water-Inspection-Report@adeq.state.ar.us. This response should contain documentation describing the course of action taken to correct each item noted. This corrective action should be completed as soon as possible, and the written response with all necessary documentation (i.e. photos) is due by April 29, 2014.

If I can be of any assistance, please contact me at greenway@adeq.state.ar.us or 870-935-7221.

Sincerely,

Michael Greenway

District 3 Field Inspector

Water Division

Inspection Report: City of Marion WWTP, AFIN: 18-00110, Permit #: AR0021971

	ADEQ	*		DIVISION	NSP	ECT	ION REI	PORT	
	コレレ	AF	IN: 18-00110		PERM	/IT #: A	R0021971	3.	
=		CC	OUNTY: 18 Critte	nden	PDS:	#: 07728	37	MEDIA: WN	
Α	RKANSAS	GF	S LOCATION: L	AT: 35.190364 L	ONG:	-90.228	445		
	partment of Environmental Quality		Outfall /	General Area					
	FACILITY INFORMAT	IOV		**	SPEC	TIONIN	FORMATION	How the second	
	AME: City of Marion WWTP			DATE(S):		/2014			
	OCATION: West side of Hwy 118, S	out	h of the UP rail	ENTRY TIME:	10	:30			
	ad.			EXIT TIME:		:00			
	TY: Marion, AR			INSPECTION T	YPE: C	omplia	nce Evaluati	on	
	RESPONSIBLE OFFIC			INSPECTOR ID:					
	INTACTED DURING INSPECTION	: Ye	S	FACILITY TYPE					
	ME: Jim Shempert			PERMIT EFFECTIVE DATE: 12/1/2013					
	TLE: Water Utilities Director			PERMIT EXPIRATION DATE: 6/30/2017					
	OMPANY: City of Marion			FACILITY EVALUATION RATING: 1 - Unsatisfactory					
	AILING P.O. Box 717			FAYETTEVILLE SHALE RELATED: N					
	DDRESS:			FAYETTEVILLE SHALE VIOLATIONS: N					
	TY, STATE, ZIP: Marion, AR 72364			i 'a in	VA CHARACTER AND THE	and the property of the state o	e in the time the autention of the military and the contract of the second of the seco	S. Grand	
	IONE & EXT: 870-739-5413			NAME/TITLE/PH					
	X: N/A			Jim Shempert /	Water	Utilitie	s Director / 8	70-739-5413.	
	MAIL: N/A								
01	THER: N/A								
	S=S	atisfac	AREA EVA	LEUATIONS :: Isfactory, N=Not Applicable	/Evaluated				
S	PERMIT		FLOW MEASUR		**	STOR	MWATER		
J	RECORDS/REPORTS	S	LABORATORY		U	FACIL	ITY SITE RE	VIEW	
υ	OPERATION & MAINTENANCE	M	EFFLUENT/REG	CEIVING WATER	U	SELF-	MONITORIN	G PROGRAM	
J	SAMPLING	**	SLUDGE HAND	LING/DISPOSAL	**	PRET	REATMENT		
**	OTHER:								
		27.	SUMMARY	F FINDINGS	34.00000	Milder Ma	34名西纳化造作公	到的复数 经存储	

This routine compliance inspection revealed the following violations:

- 1. The totalizing meter for flow measurements was not maintained (Photo 1). Instantaneous flow measurements were taken daily at the crest of the weir. This violates Part I, Section A, and Part III, Section B, Item 1A of the Permit.
- 2. The facility did not perform influent sampling and calculate the CBOD5 and TSS removal rate annually. This violates Part II. Item 2 of the Permit.
- 3. There was excessive vegetation on the north and east levees of the lagoon (Photos 2-3). This violates Part III, Section B, Item 1A of the Permit.
- 4.Head was measured improperly at the crest of the weir for instantaneous flow measurements (Photo 4). This violates Part III, Section C, Item 2 of the Permit. A staff gauge should be installed at least 3 times the expected head upstream of the weir for accurate flow measurement.
- 5. The time and individual performing sampling/analysis was not recorded for DO monitoring. This violates Part III, Section C, Item 8 of the Permit.
- 6. At the time of inspection, flow was measured and calculated to be greater than 2.39 MGD. This exceeds the 1.6 MGD design flow of the facility. It appears the facility may experience significant infiltration and inflow problems. Auxiliary pumps were installed and running to establish/maintain adequate freeboard in the lagoons (Photo 5).
- 7. The Sanitary Sewer Overflow (SSO) inspection revealed excessive grease and solids in the wet well of the Vintage Veranda pump station. This violates Part III, Section B, Item 1A of the Permit.

Van Brocklin & Associates, Inc.

INVOICE 19124

P.O. Box 17422 Memphis, Tennessee 38187 Phone: (901)795-6611 Fax: (901)363-1955

invoice Date	VENTONICALIE	O TO THE WAY	
Sansaga attivoice Date Sky Date	roureraer no.	euroruei ino.	
4/4/2014	Verhal	14-100 D	


SOLD TO:

City of Marion P.O. Box 814 Marion, AR 72364 SHIPPED TO:

Delivered by RLS

Attn: Jim Shempert

RLS Orid Shpid			escription	Toyota Truck	UnitiPrice	nphis
1 1	Replac	sement Chart Record				CHICA TO THE PARTY OF THE PARTY
		Sement Chart Necold	er for QCS	3-300IA Flowmeter	2,250.00	2,250.00
		APPROV	MENT T # ED BY PROVED			
					Subtotal	\$2,250.00
				Arkansas Sales Tax County Tax City Tax Shipping Charges	6.500% 1.750% 2.000%	146.25 39.38 45.00 18.45





Environmental Testing & Consulting, Inc.

2790 Whitten Road

Memphis, Tennessee 38133 (901) 213-2400 Fax (901) 213-2440


CHAIN OF CUSTODY

COC Number / Kit ID 0000036749



Company Name					Customer	Numbe	r	Telephone	е	RUSH	ICE
City of Marion Water Department				02608				(870) 739-5413			
Site Name			Project Co	omm	ent					FID No	ımber
Project			Project N	umbe	er	PO Nun	nber				
Project Manager / Contact Mr. Jim Shempert E-mail											
Sample ID	Container Type	1	ted Date / Time	# Cont	Preser	vative	Grab / Comp	Matrix	А	nalyses	
Annual Influent Grab	Plastic - Quart	4/23	14 9:30	Am	NC	NE	G	Aqueous	BOD	, CBOD, T	rss
Annual Effluent Grab		4/23	14 9:20		NO	NE	G	Aqueous	BOD	, CBOD, T	'SS

Sampled By	Method of Shipment	Blank / Cooler	Remarks
9).P-		Temperature	
Relinquished By (sign)	Date / Time	Received By (sign)	Date / Time
Treat Presty	4/23/14 1230	W. Tres	4/23/14 1230
Relinquished By (sign)	Date / Time	Received By (sign)	Date / Time
Relinquished By (sign)	Date / Time	Received by Lab (sign	Date / Time






City Of Marion D.O. & Flow Monthly Report

D.O.	TEMP	SAMPLED BY	SAMPLE TIME	ANALYSES TIME	FLOW
1					
2					
3					
4					
5					
6					
7					
8					
9					
10					
11					
12					
13					
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					
24					
25					
26					
27					
28					
29					
30					
31					



31 MILITARY RD. MARION, AR. 72364



WATER DIVISION INSPECTION BRANCH ADEQ 5301 NORTH SHORE DRIVE NORTH LITTUE ROCK, AR. 72118-5317



May 8, 2014

Jim Shempert, Water Utilities Director City of Marion WWTP P.O. Box 717 Marion, AR 72364

RE: Compliance Inspection, Marion Wastewater Treatment Plant

AFIN: 18-00110 Permit No.: AR0021971, AR0021971C and ARR000189

Dear Mr. Shempert:

I have reviewed the response pertaining to my March 18, 2014 inspection of the above referenced facility. The information provided sufficiently addresses the violations referenced in my inspection reports. At this time the Department has no further comment concerning this particular inspection. Acceptance of this response by the Department does not preclude any future enforcement action deemed necessary at this site or any other site.

If we need further information concerning this matter, we will contact you. Thank you for your attention to this matter. Should you have any questions, feel free to contact me at 870-935-7221 ext. 15, or greenway@adeq.state.ar.us.

Sincerely,

Michael B. Greenway District 3 Field Inspector

Water Division