Inspection Report: Pine Bluff Wastewater Utility, AFIN: 35-00149, Permit #: AR0033316


	<b>VDEO</b>	WATER DIVISION INSPECTION REPORT									
AULU		AFIN: <b>35-00149</b> PERMIT #: <b>AR003331</b>			316		DATE: <b>6/18/2014</b>				
ARKANSAS			COUNTY: <b>35 Jefferson</b> PI			#: <b>078566</b>	MEDIA: WN				
Dep	partment of Environmental Quality	S LAT: <b>34.26602</b>	.266026 LONG: -92.018023 LOCATION: General Area								
	FACILITY INFORMAT		INSPECTION INFORMATION								
Pine Bluff Wastewater Utility LOCATION:				1 - Municipal INSPECTOR ID#: 26075 S - State							
1520 South Ohio Street			FACILITY EVALUATION RATING: INSPECTION TYPE:  1 - Unsatisfactory Reconnaissance								
-	ne Bluff, Arkansas			RY TIME:	EXIT TIME: 11:30	PERMIT EFFECTIVE DATE:					
	RESPONSIBLE OFFIC	-	0,10,2014		11.00	7/31/2009 PERMIT EXPIRATION DATE:					
	n Johnson / Managor					8/1/2014					
Ken Johnson / Manager				FAYETTEVILLE SHALE RELATED: N							
Pine Bluff Wastewater Utility			FAYETTEVILLE SHALE VIOLATIONS: N								
MAILING ADDRESS: 1520 South Ohio Street			INSPECTION PARTICIPANTS								
CITY, STATE, ZIP:			NAME/TITLE/PHONE/FAX/EMAIL/ETC.:								
Pine Bluff, AR -716016055				Amber Zajac, Graphic Flexible Packaging Vincent Miles, Pine Bluff Wastewater Utility							
-	0-535- 6303 /			,			,				
EMAII	±										
CC	NTACTED DURING INSPECTION:	: No									
AREA EVALUATIONS  (S=Satisfactory, M=Marginal, U=Unsatisfactory, N=Not Applicable/Evaluated)											
N	PERMIT	N	FLOW MEASUR		N	STORMW	ATER				
Z	RECORDS/REPORTS	N	LABORATORY		N		SITE REVIEW				
N	OPERATION & MAINTENANCE	N		CEIVING WATER	N		NITORING PROGRAM				
N	SAMPLING	N	SLUDGE HAND	LING/DISPOSAL	N	PRETREA	TMENT				
M	OTHER: SSO		SUMMARY C	E EINDINGS							
Vic	plations to be noted on follow-up	rend			on Ju	ne 20 2014					
	name no se se notea en renen ap	. 0 0	on the sampling		011 04	20, 20					
				COMMENTS							
	econnaissance inspection was co		-	_	_		•				
recent break in a Pine Bluff Wastewater sewer main released a reported 6,000 gallons of raw sewage onto the											
ground and into an area drainage slough. At the time of the inspection, the sewer main had been repaired.											
However, no effort has been made to clean up the drainage slough containing the majority of wastewater lost.											
IN:	SPECTOR'S SIGNATURE:	40	5. Houdeesc	Steven L. Henderson			DATE: <b>6/26/2014</b>				
	SPECTOR'S SIGNATURE:										
	العال	זעו	~ ME CALL	۲			DATE 0/6=100.00				
	PERVISOR'S SIGNATURE		Kerri McCahe			DATE: 6/27/2014					

Water Division Photographic Evidence Sheet												
Location: Pine Bluff Wastewater Utility												
Photograph	er:	Steven L. Henderson		Date:	6/18/2014	Time:	09:58					
Witness: Amber Zajac, Graphic Flexible; Vincent Miles, PBWW Photo #: 1												
Description: Area where cower main brokes draining left to right												



Photographer:Steven L. HendersonDate:6/18/2014Time:09:57Witness:Amber Zajac, Graphic Flexible; Vincent Miles, PBWWPhoto #:2Description:Evidence of sewage release.







Photographer:Steven L. HendersonDate:6/18/2014Time:10:03Witness:Amber Zajac, Graphic Flexible; Vincent Miles, PBWWPhoto #:4

