

 A R K A N S A S Department of Environmental Quality		WATER DIVISION INSPECTION REPORT							
		AFIN: 18-00110		PERMIT #: AR0021971		DATE: 9/24/2014			
		COUNTY: 18 Crittenden			PDS #: 080303		MEDIA: WN		
		GPS LAT: 35.190364 LONG: -90.228445 LOCATION: Entrance							
FACILITY INFORMATION				INSPECTION INFORMATION					
NAME: City of Marion WWTP LOCATION: West side of Hwy 118, South of the UP Rail Road. CITY: Marion, AR				FACILITY TYPE: 1 - Municipal		INSPECTOR ID#: 86009 S - State			
				FACILITY EVALUATION RATING: ***		INSPECTION TYPE: Reconnaissance			
				DATE(S): 9/24/2014		ENTRY TIME: 12:15		EXIT TIME: 12:50	
								PERMIT EFFECTIVE DATE: 12/1/2013 PERMIT EXPIRATION DATE: 6/30/2017	
RESPONSIBLE OFFICIAL				FAYETTEVILLE SHALE RELATED: N					
NAME / TITLE: Jim Shempert / Water Utilities Director COMPANY: City of Marion MAILING ADDRESS: P.O. Box 717 CITY, STATE, ZIP: Marion AR 72364 PHONE & EXT. / FAX: 870-739-5413 / EMAIL: N/A				FAYETTEVILLE SHALE VIOLATIONS: N					
CONTACTED DURING INSPECTION: No				INSPECTION PARTICIPANTS					
				NAME/TITLE/PHONE/FAX/EMAIL/ETC.: Brent Walker / ADEQ Inspector / 870-935-7221					
AREA EVALUATIONS									
(S=Satisfactory, M=Marginal, U=Unsatisfactory, N=Not Applicable/Evaluated)									
S	PERMIT	**	FLOW MEASUREMENT	**	STORMWATER				
**	RECORDS/REPORTS	**	LABORATORY	M	FACILITY SITE REVIEW				
M	OPERATION & MAINTENANCE	M	EFFLUENT/RECEIVING WATER	**	SELF-MONITORING PROGRAM				
**	SAMPLING	**	SLUDGE HANDLING/DISPOSAL	**	PRETREATMENT				
**	OTHER:								
SUMMARY OF FINDINGS									
This reconnaissance inspection was performed as a follow-up to the March 18, 2014 compliance evaluation inspection (CEI). It appeared that the violations noted in the previous inspection were corrected and the facility has maintained compliance in those areas. However, it appeared that the sludge depth was close to the surface of the water in the primary lagoon (photos 1-4), and the facility has continued to report multiple effluent violations since the March 18, 2014 CEI. The facility has proposed changes to the treatment system and discharge location to correct effluent violations, which will be discussed again during the next CEI.									
GENERAL COMMENTS									
No letter will be sent with this inspection. Permit #AR0021971C expired on September 1, 2014. However, there were no construction activities or changes to the treatment system noted during this inspection.									
INSPECTOR'S SIGNATURE:  Michael Greenway				DATE: 10/13/2014					
SUPERVISOR'S SIGNATURE:  Jason Bolenbaugh				DATE: 10/14/2014					

Water Division Photographic Evidence Sheet

Location:	City of Marion WWTP		
Photographer:	Michael Greenway	Date:	9/24/2014
Time:	12:45		
Witness:	Brent Walker	Photo #:	1
Description:	View influent pipes and aerators in the primary lagoon. Note the accumulation of sludge.		



Photographer:	Michael Greenway	Date:	9/24/2014
Time:	12:23		
Witness:	Brent Walker	Photo #:	2
Description:	View of the NW corner of the primary lagoon. Note the sludge accumulation in bottom left.		



Water Division Photographic Evidence Sheet

Location:	City of Marion WWTP		
Photographer:	Michael Greenway	Date:	9/24/2014
Witness:	Brent Walker	Time:	12:19
		Photo #:	3
Description:	View along the north levee of the primary lagoon. Note the depth of water and visible sludge in the lagoon near the levee.		



Photographer:	Michael Greenway	Date:	9/24/2014
Witness:	Brent Walker	Time:	12:19
		Photo #:	4
Description:	Closer view of sludge accumulation along the north levee of the primary lagoon.		



Water Division Photographic Evidence Sheet			
Location:	City of Marion WWTP		
Photographer:	Michael Greenway	Date:	9/24/2014
Time:	12:33	Witness:	Brent Walker
Photo #:	5	Description:	View of effluent and the outfall weir.



Photographer:	Michael Greenway	Date:	9/24/2014
Time:	12:34	Witness:	Brent Walker
Photo #:	6	Description:	View of flow measurement equipment.

