



ARKANSAS
Department of Environmental Quality

WATER DIVISION INSPECTION REPORT

AFIN: 52-00073	PERMIT #: AR0022365	DATE: 4/25/2017
COUNTY: 52 Ouachita	PDS #: 097257	MEDIA: WN
GPS LAT: 33.563066 LONG: -92.816983 LOCATION: General Area		

FACILITY INFORMATION

NAME:
Camden WWTP

LOCATION:
101 Ouachita Road 197

CITY:
Camden, AR

RESPONSIBLE OFFICIAL

NAME / TITLE:
David Richardson / Manager

COMPANY:
Camden Water Utilities

MAILING ADDRESS:
P.O. Box J

CITY, STATE, ZIP:
Camden AR 71711

PHONE & EXT. / FAX:
870-836-4329 /

EMAIL:
davidrcamdenh2o@cablelynx.com

CONTACTED DURING INSPECTION: **Yes**

INSPECTION INFORMATION

FACILITY TYPE: 1 - Municipal	INSPECTOR ID#: 47009 S - State
FACILITY EVALUATION RATING: 5 - Satisfactory	INSPECTION TYPE: Reconnaissance
DATE(S): 4/25/2017	ENTRY TIME: 09:32
EXIT TIME: 10:45	PERMIT EFFECTIVE DATE: 7/24/2014
	PERMIT EXPIRATION DATE: 1/31/2018

FAYETTEVILLE SHALE RELATED: **N**

FAYETTEVILLE SHALE VIOLATIONS: **N**

INSPECTION PARTICIPANTS

NAME/TITLE/PHONE/FAX/EMAIL/ETC.:
Jessica Temple, ADEQ Permit Engineer
Keith Ballard/Plant Superintendent/keithballard101@yahoo.com

AREA EVALUATIONS

(S=Satisfactory, M=Marginal, U=Unsatisfactory, N=Not Applicable/Evaluated)

S	PERMIT	N	FLOW MEASUREMENT	**	STORMWATER
N	RECORDS/REPORTS	N	LABORATORY	N	FACILITY SITE REVIEW
S	OPERATION & MAINTENANCE	N	EFFLUENT/RECEIVING WATER	N	SELF-MONITORING PROGRAM
N	SAMPLING	**	SLUDGE HANDLING/DISPOSAL	**	PRETREATMENT
**	OTHER:				

SUMMARY OF FINDINGS

No violations were noted at the time of the inspection.

GENERAL COMMENTS

I attended a site visit with Jessica Temple, Permit Engineer. Plant Superintendent Keith Ballard and Camden Water Utilities Manager David Richardson attended. Jessica observed and discussed the treatment system as well as discussed the permit renewal process.

The treatment system consists of bar screens, grit separator, activated sludge, secondary clarifier, chlorine disinfection, and dechlorination. Mr. Ballard stated that a new auger had recently been installed at the grit separator (Photo 1). The aeration basin was observed (Photo 2) and was in good operating condition. Both clarifiers (Photos 3-4) were functional. A small leak was noted on the sludge thickener in an inspection performed on May 25, 2016 by ADEQ District 8 Inspector Michael Young. This patched leak (Photo 5) was observed and appeared to be adequate.

INSPECTOR'S SIGNATURE: Tobin Fulmer	DATE: 5/18/2017
---	------------------------

SUPERVISOR'S SIGNATURE: Kerri McCabe	DATE: 5/24/2017
--	------------------------

Water Division Photographic Evidence Sheet

Location:	Camden WWTP				
Photographer:	Tobin Fulmer	Date:	4/25/2017	Time:	9:54
Witness:	Keith Ballard, Jessica Temple			Photo #:	1
Description:	Grit separator with recently installed auger.				



Photographer:	Tobin Fulmer	Date:	4/25/2017	Time:	9:59
Witness:	Keith Ballard, Jessica Temple			Photo #:	2
Description:	Aeriation basin				



Water Division Photographic Evidence Sheet

Location:	Camden WWTP				
Photographer:	Tobin Fulmer	Date:	4/25/2017	Time:	10:03
Witness:	Keith Ballard, Jessica Temple			Photo #:	3
Description:	East clarifier				



Photographer:	Tobin Fulmer	Date:	4/25/2017	Time:	10:06
Witness:	Keith Ballard, Jessica Temple			Photo #:	4
Description:	West clarifier				



Water Division Photographic Evidence Sheet

Location:	Camden WWTP				
Photographer:	Tobin Fulmer	Date:	4/25/2017	Time:	10:06
Witness:	Keith Ballard, Jessica Temple			Photo #:	5
Description:	Patched leak on the sludge thickener.				



Photographer:	Tobin Fulmer	Date:	4/25/2017	Time:	10:10
Witness:	Keith Ballard, Jessica Temple			Photo #:	6
Description:	Effluent				



Figure 1. General area of Camden WWTP (Google Earth, imagery date: November 19, 2015).

