

OFFICE OF WATER QUALITY INSPECTION REPORT

AFIN: 17-00062	PERMIT #: AR0021482	DATE: 8/14/2019
COUNTY: 17 Crawford	PDS #: 109240	MEDIA: WN
GPS LAT: 35.430056 LONG: -94.951260 LOCATION: Entrance		

FACILITY INFORMATION	INSPECTION INFORMATION
NAME: River City Coatings, Inc. LOCATION: 306 Sycamore St. CITY: Van Buren	FACILITY TYPE: 2 - Industrial INSPECTOR ID#: 71330 S - State FACILITY EVALUATION RATING: 3 - Satisfactory INSPECTION TYPE: Industrial User DATE(S): 8/14/2019 ENTRY TIME: 12:00 EXIT TIME: 12:30 PERMIT EFFECTIVE DATE: 1/1/2015 PERMIT EXPIRATION DATE: 12/31/2019
RESPONSIBLE OFFICIAL NAME: / TITLE Steve Dufresne / COMPANY: Van Buren Municipal Utilities MAILING ADDRESS: PO Drawer 1269 CITY, STATE, ZIP: Van Buren AR 72959 PHONE & EXT: / FAX: 479-474-5067 / EMAIL: steve@vbmua.arcoxml.com CONTACTED DURING INSPECTION: No	FAYETTEVILLE SHALE RELATED: N FAYETTEVILLE SHALE VIOLATIONS: N INSPECTION PARTICIPANTS NAME/TITLE/PHONE/FAX/EMAIL/ETC.: James Dunn/City of Van Buren Chief Plant Operator/479.474.5067/james@vbmua.arcoxml.com Kim Redo/City of Van Buren Environmental Coordinator/479.474.0941/kim@vbmua.arcoxml.com Tony Jester/Plant Manager/479-471-7675/tony@rivercitycoatings.com

AREA EVALUATIONS <small>(S=Satisfactory, M=Marginal, U=Unsatisfactory, N=Not Applicable/Evaluated)</small>					
**	PERMIT	**	FLOW MEASUREMENT	U	STORMWATER
**	RECORDS/REPORTS	**	LABORATORY	**	FACILITY SITE REVIEW
**	OPERATION & MAINTENANCE	**	EFFLUENT/RECEIVING WATER	**	SELF-MONITORING PROGRAM
**	SAMPLING	**	SLUDGE HANDLING/DISPOSAL	S	PRETREATMENT
**	OTHER:				



SUMMARY OF FINDINGS

No violations of the pretreatment permit were noted during inspection.

GENERAL COMMENTS

I conducted this inspection on August 14, 2019 with the above-referenced inspection participants. Inspection included pretreatment facility assessment and questionnaire.

The pretreatment components and processing line were clean, operational, and well-maintained. Staff interviewed was familiar with both the pretreatment system and the permit and permit requirements through the city. A small quantity of hazardous waste is stored onsite, but it is labeled and stored properly. Spill kits were staged in obvious locations. Oil from equipment was observed leaking into a stormwater drainage feature during inspection. Prior to inspection completion, the Plant Manager had staff responded with absorbent and informed that the equipment would be serviced and the absorbent would be swept up and disposed of properly. Oil was not observed in a nearby stormwater drainage ditch.

INSPECTOR'S SIGNATURE:  Dannielle Gray	DATE: 8/23/2019
SUPERVISOR'S SIGNATURE:  Kerri McCabe	DATE: 9/5/2019

POTW Pretreatment Program

Industrial Site Visit

Name of Industry: River City Coatings, Inc.

Industry Contacts: Tony Jester, Plant Manager, 479-471-7675

Type of Industry: Metal finishing

Date of Visit: August 14, 2019

- | | | | | | | |
|---|------------|-----|------------|----|----------|----|
| 1. Significant industrial user? | <u> X </u> | Yes | <u> </u> | No | <u> </u> | NA |
| 2. Pretreatment equipment or procedures? | <u> X </u> | Yes | <u> </u> | No | <u> </u> | NA |
| 3. Pretreatment equipment maintained and operational? | <u> X </u> | Yes | <u> </u> | No | <u> </u> | NA |
| 4. Hazardous waste generated or stored? | <u> X </u> | Yes | <u> </u> | No | <u> </u> | NA |
| 5. Proper solid waste disposal? | <u> X </u> | Yes | <u> </u> | No | <u> </u> | NA |
| 6. Solvent management/TTO control? | <u> X </u> | Yes | <u> </u> | No | <u> </u> | NA |
| 7. Suitable sampling location? | <u> X </u> | Yes | <u> </u> | No | <u> </u> | NA |
| 8. Appropriate self-monitoring procedures/equipment? | <u> X </u> | Yes | <u> </u> | No | <u> </u> | NA |
| 9. Adequate spill prevention? | <u> </u> | Yes | <u> X </u> | No | <u> </u> | NA |
| 10. Industry familiar with limits and requirements? | <u> X </u> | Yes | <u> </u> | No | <u> </u> | NA |

Additional Comments: See "General Comments" above.

Visit Conducted By: Dannielle Gray

Date of Report: August 23, 2019

Office of Water Quality Photographic Evidence Sheet

Location:	River City Coatings, Inc.		
Photographer:	Dannielle Gray	Date:	8/14/2019
Witness:	None	Time:	1204
		Photo #:	1
Description:	5-stage wash tank system.		



Photographer:	Dannielle Gray	Date:	8/14/2019
Witness:	None	Time:	1207
		Photo #:	2
Description:	Sampling location.		



Office of Water Quality Photographic Evidence Sheet

Location:	River City Coatings, Inc.		
Photographer:	Dannielle Gray	Date:	8/14/2019
Witness:	None	Time:	1205
		Photo #:	3
Description:	Oil leaking into stormwater drainage observed near sampling location.		



Photographer:	Dannielle Gray	Date:	8/14/2019
Witness:	None	Time:	1213
		Photo #:	4
Description:	Absorbent placed over oil leak prior to inspection completion.		



Figure 1. Google Earth image dated May 31, 2019 showing facility overview and sampling location.

