

ENVIRONMENTAL

## OFFICE OF WATER QUALITY INSPECTION REPORT

AFIN: 26-00145 | PERMIT #: AR0033880 | DATE: 4/27/2023

COUNTY: **26 Garland** PDS #: **125868** MEDIA: **WN** 

I	GPS LAT: <b>34.450316</b> LONG: <b>-93.019033</b> LOCATION: <b>General Area</b>				
FACILITY INFORMATION	ON	INSPECTION INFORMATION			MATION
Davidson & Southwest Collection System		FACILITY TYPE:  1 - Municipal	INSPECTOR ID#: 34689 S - \$		
320 Davidson Drive		1 - Unsatisfacto	ry		Collection System
Hot Springs, AR 71901			RY TIME: EXIT : 14:		PERMIT EFFECTIVE DATE:
RESPONSIBLE OFFICIAL					9/1/2018 PERMIT EXPIRATION DATE:
Mr. Monty Ledbetter / Utilities Director					8/31/2023
COMPANY:		FAYETTEVILLE SHALE RELATED: <b>N</b>			
City of Hot Springs Davidson WWTP		FAYETTEVILLE SHALE VIOLATIONS: N			
320 Davidson Drive		INSPECTION PARTICIPANTS			
CITY, STATE, ZIP:  Hot Springs AR 71901  PHONE & EXT: / FAX:		Danny Burton/ C		Manag	er
501-262-1125 / 501-262-0339					
mledbetter@cityhs.net					
hmauldin@cityhs.net					
dburon@cityhs.net					
CONTACTED DURING INSPECTION: N	No				
/C=Cabi	AREA EVA sfactory, M=Marginal, U=Unsati	LUATIONS	Evaluated)		

#### **N** PERMIT **STORMWATER** FLOW MEASUREMENT N RECORDS/REPORTS Ν **FACILITY SITE REVIEW LABORATORY** Ν **EFFLUENT/RECEIVING WATER SELF-MONITORING PROGRAM N** OPERATION & MAINTENANCE N Ν N SAMPLING SLUDGE HANDLING/DISPOSAL PRETREATMENT M OTHER: Lift Stations

#### SUMMARY OF FINDINGS

 At the time of inspection, the 70W #9 lift station had a pump out, the Gulpha lift station had a pump motor out for repair, and grease was observed in the wet wells at 70W #9, Moore Road, and Winkler lift stations. These issues require maintenance and are violations of Part III.B.1.A of the permit. In addition, there was an on-going SSO at two manholes adjacent to the Gulpha lift station. The city had reported these SSO.

#### **GENERAL COMMENTS**

#### Introduction

I inspected five lift stations on April 27, 2023 as part of a CEI conducted at the Davidson WWTP. Mr. Danny Burton, Collections Manager, represented the city during the lift station inspections. The City of Hot Springs operates a collection system with 84 lift stations and over 3,000 grinder pumps, with wastewater received for the Davidson and the Southwest WWTPs.

#### **Lift Station Inspections**

I inspected each lift station, assessing station security, pump operability, presence of recent high levels or grease inside the wet wells, and recent or on-going SSO. Mr. Burton escorted me to each lift station. He demonstrated pump and alarm system operability at each station. Mr. Burton also opened each wet well hatch for inspection. See "Summary of Findings" for issues noted during the inspection.

INSPECTOR'S SIGNATURE:

Travis Harmon

DATE: 5/5/2023

SUPERVISOR'S SIGNATURE:

Kerri McCabe

DATE: 5/12/2023

COLLECTION SYSTEM INSPECTION AND OVERALL RAT	ING	⊠S □M □U □NA □NE
PROVIDE A BRIEF DESCRIPTION OF THE COLLECTION S <b>Domestic, Commercial, &amp; Industrial. Clay/PVC and force</b>		
POPULATION SERVED/NUMBER OF RESIDENTIAL AND (	COMMERCIAL CONNECTIONS	S: <b>23,000</b>
FEET OF SEWER SYSTEM: 2.2 million feet		
AGE OF SYSTEM: > 50 years		
DOES THE SYSTEM EXPERIENCE PROBLEMS DURING DESCRIPTION (EXPLAIN): <b>1&amp;1</b>	-	ØY □N □NA □NE
IS THERE A SYSTEM IN PLACE FOR REPORTING SSOS Online reporting via ADEQ website	ГО ADEQ (DESCRIBE):	☑Y □N □NA □NE
ARE ALL SSOs REPORTED REGARDLESS OF SIZE:		☑Y □N □NA □NE
HAVE SSOs REACHED "WATERS OF THE STATE" (LIST DEACH): Numerous; 147 reported total SSO from March 1,		⊠Y □N □NA □NE
PUMP STATIONS		☑S □M □U □NA □NE
NUMBER OF PUMP STATIONS IN SYSTEM: 84	NUMBER WITH BACKUP PO	WER: Some onsite
HOW OFTEN ARE PUMP STATIONS INSPECTED/MONITO	RED: Weekly	
ARE MAINTENANCE RECORDS AND/OR OPERATOR LOC	SS KEPT: <u>Yes</u>	
ADEQUATE INVENTORY OF SPARE PARTS: Yes		
TYPE OF REMOTE ELECTRONIC MONITORING USED (I.E	. SCADA OR AUTO DIALERS	):_SCADA
BRIEF SUMMARY OF EMERGENCY PROCEDURES: Repo	ort, pump truck, lime &/or dis	<u>infect</u>
NUMBER OF PUMP STATIONS VISITED DURING INSPEC	TION (SEE ATTACHED CHEC	KLISTS FOR EACH): <u>5</u>
SATELLITE SYSTEMS		□S □M □U ☑NA □NE
DOES THE COLLECTION SYSTEM RECEIVE FLOW FROM	SATELLITE SYSTEMS: None	<u>e</u>
TYPE(S) OF WASTE WATER RECEIVED:_	L □COMMERCIAL □INDUST	RIAL OTHER:
BRIEFLY DESCRIBE THE SATELLITE SYSTEM:		
ANY KNOWN PROBLEMS WITH SATELLITE SYSTEM:		
NAME, ADDRESS AND PHONE NUMBER OF PERSON RE	SPONSIBLE FOR SATELLITE	SYSTEM:

PUMP STATION VISIT (COMPLETE A SEPARATE CHECKLIST FOR EACH PUMP STATION VISITED)					
GENERAL INFORMATION AND OVERALL EVALUATION		Øs c	JM □U	□NA	
NAME AND/OR LOCATION OF PUMP STATION: <u>Bubba Brews</u>					
TYPE(S) OF WASTE WATER RECEIVED: MRESIDENTIAL	. ☑COMMERCIAL ☐INDUSTRIA	AL OTHER:	·		
NUMBER OF PUMPS:_2	NUMBER OPERATIONAL: 2				
NUMBER AND SIZE OF PUMPS APPEARS ADEQUATE:		⊠s □m □	U □NA	□NE	
EVIDENCE OF RECENT OVERFLOWS OR HIGH LEVELS:			N □NA	□NE	
GENERAL OPERATION AND MAINTENANCE		Øs c	⊐M □U	□NA	
CLEAN AND WELL MAINTAINED WITH MINIMAL STORAG EQUIPMENT:		⊠s □m □	U □NA	□NE	
GATES/DOORS/HATCHES/LIDS/ETC. LOCKED TO PREVENT UNAUTHORIZED ACCESS AND/OR TAMPERING:		⊠s □M □	U □NA	□NE	
WET WELLS, SUMPS AND PITS ADEQUATELY COVERED, GRATED OR OTHERWISE PROTECTED:		⊠s □M □	U □NA	□NE	
ELECTRICAL CONTROLS COVERS CONDUIT AND EQUIF INSTALLED AND MAINTAINED:		⊠s □m □	U □NA	□NE	
GUARDS AND SHIELDS IN PLACE AROUND MOVING EQI DRIVESHAFTS, ETC.):	UIPMENT (BELTS, PULLEYS,	□ѕ□м□	U ØNA	□NE	
ADEQUATE VENTILATION TO PREVENT EXCESSIVE COL GASES AND FUMES:	NDENSATION AND/OR	□ѕ□м□	U ØNA	□NE	
ADEQUATE LIGHTING FOR ROUTINE INSPECTION/MAIN	TENANCE:		U ØNA	□NE	
SEALS, VALVES AND PACKING ADEQUATELY MAINTAIN	ED TO PREVENT LEAKS:		U □NA	ØNE	
MINIMAL ACCUMULATION OF GREASE AND SOLIDS IN V	VET WELLS:	⊠S □M □	U □NA	□NE	
		T			
BACKUP POWER AND ALARMS		Øs c	□M □U	□NA	
PROVISIONS FOR GENERATOR AND/OR EMERGENCY T	RANSFER PUMP:	⊠S □M □	U □NA	□NE	
AUDIBLE/VISUAL ALARM WITH EMERGENCY CONTACT	INFORMATION POSTED:	⊠S □M □	U □NA	□NE	
SCADA SYSTEM (LIST PARAMETERS MONITORED):			N ⊠NA	□NE	


PUMP STATION VISIT (COMPLETE A SEPARATE CHE	CKLIST FOR EACH PUMP S	STATION VISITE	<b>D)</b>
GENERAL INFORMATION AND OVERALL EVALUATION			JU □NA
NAME AND/OR LOCATION OF PUMP STATION: 70W #9			
TYPE(S) OF WASTE WATER RECEIVED: ZRESIDENTIAL	☑COMMERCIAL □INDUSTRIA	AL OTHER:	
NUMBER OF PUMPS: 2	NUMBER OPERATIONAL: 1		
NUMBER AND SIZE OF PUMPS APPEARS ADEQUATE:		⊠S □M □U □N	NA □NE
EVIDENCE OF RECENT OVERFLOWS OR HIGH LEVELS:			NA □NE
GENERAL OPERATION AND MAINTENANCE		ØS □M □	JU UNA
CLEAN AND WELL MAINTAINED WITH MINIMAL STORAG EQUIPMENT:		ØS OM OU ON	NA □NE
GATES/DOORS/HATCHES/LIDS/ETC. LOCKED TO PREVENT UNAUTHORIZED ACCESS AND/OR TAMPERING:		ØS □M □U □I	NA □NE
WET WELLS, SUMPS AND PITS ADEQUATELY COVERED PROTECTED:	⊠S □M □U □I	NA □NE	
ELECTRICAL CONTROLS COVERS CONDUIT AND EQUIPMENT PROPERLY INSTALLED AND MAINTAINED:		⊠S □M □U □I	NA □NE
GUARDS AND SHIELDS IN PLACE AROUND MOVING EQUENCIES HAFTS, ETC.):	JIPMENT (BELTS, PULLEYS,		NA □NE
ADEQUATE VENTILATION TO PREVENT EXCESSIVE CONGASES AND FUMES:	NDENSATION AND/OR		NA □NE
ADEQUATE LIGHTING FOR ROUTINE INSPECTION/MAIN	TENANCE:		NA □NE
SEALS, VALVES AND PACKING ADEQUATELY MAINTAIN	ED TO PREVENT LEAKS:		NA ØNE
MINIMAL ACCUMULATION OF GREASE AND SOLIDS IN V	VET WELLS: <u>Grease</u>		NA □NE
BACKUP POWER AND ALARMS		Øs □m □	IU □NA
PROVISIONS FOR GENERATOR AND/OR EMERGENCY T	DANISEED DI IMD:		
AUDIBLE/VISUAL ALARM WITH EMERGENCY CONTACT I	NFORMATION POSTED:	⊠S □M □U □I	
SCADA SYSTEM (LIST PARAMETERS MONITORED):			NA □NE

PUMP STATION VISIT (COMPLETE A SEPARATE CHECKLIST FOR EACH PUMP STATION VISITED)			
GENERAL INFORMATION AND OVERALL EVALUATION		ØS □M □U □NA	
NAME AND/OR LOCATION OF PUMP STATION:  Moore Road lift station			
TYPE(S) OF WASTE WATER RECEIVED: MRESIDENTIAL	☑COMMERCIAL ☐INDUSTRIA	AL OTHER:	
NUMBER OF PUMPS: 2	NUMBER OPERATIONAL: 2		
NUMBER AND SIZE OF PUMPS APPEARS ADEQUATE:		☑S □M □U □NA □NE	
EVIDENCE OF RECENT OVERFLOWS OR HIGH LEVELS:		□Y ☑N □NA □NE	
GENERAL OPERATION AND MAINTENANCE		⊠S □M □U □NA	
CLEAN AND WELL MAINTAINED WITH MINIMAL STORAG EQUIPMENT:		⊠S □M □U □NA □NE	
GATES/DOORS/HATCHES/LIDS/ETC. LOCKED TO PREVE ACCESS AND/OR TAMPERING:	ENT UNAUTHORIZED	☑S □M □U □NA □NE	
WET WELLS, SUMPS AND PITS ADEQUATELY COVERED PROTECTED:	), GRATED OR OTHERWISE	ØS □M □U □NA □NE	
ELECTRICAL CONTROLS COVERS CONDUIT AND EQUIF INSTALLED AND MAINTAINED:	PMENT PROPERLY	⊠S □M □U □NA □NE	
GUARDS AND SHIELDS IN PLACE AROUND MOVING EQUIDRIVESHAFTS, ETC.):	JIPMENT (BELTS, PULLEYS,	□S □M □U ☑NA □NE	
ADEQUATE VENTILATION TO PREVENT EXCESSIVE COL GASES AND FUMES:	NDENSATION AND/OR	□S □M □U ☑NA □NE	
ADEQUATE LIGHTING FOR ROUTINE INSPECTION/MAIN	TENANCE:	□S □M □U ☑NA □NE	
SEALS, VALVES AND PACKING ADEQUATELY MAINTAIN	ED TO PREVENT LEAKS:	□S □M □U □NA ☑NE	
MINIMAL ACCUMULATION OF GREASE AND SOLIDS IN V	VET WELLS: <u>Grease</u>	□S □M □U □NA □NE	
BACKUP POWER AND ALARMS		⊠S □M □U □NA	
PROVISIONS FOR GENERATOR AND/OR EMERGENCY T	RANSFER PUMP:	☑S □M □U □NA □NE	
AUDIBLE/VISUAL ALARM WITH EMERGENCY CONTACT	INFORMATION POSTED:	☑S □M □U □NA □NE	
SCADA SYSTEM (LIST PARAMETERS MONITORED):		□Y □N ☑NA □NE	

PUMP STATION VISIT (COMPLETE A SEPARATE CHECKLIST FOR EACH PUMP STATION VISITED)					
GENERAL INFORMATION AND OVERALL EVALUATION		□S ☑M □U □NA			
NAME AND/OR LOCATION OF PUMP STATION:  Winkler					
TYPE(S) OF WASTE WATER RECEIVED: <b>Z</b> RESIDENTIAL	☑COMMERCIAL ☑INDUSTRIA	AL OTHER:			
NUMBER OF PUMPS: 2	NUMBER OPERATIONAL: 2				
NUMBER AND SIZE OF PUMPS APPEARS ADEQUATE:		☑S □M □U □NA □NE			
EVIDENCE OF RECENT OVERFLOWS OR HIGH LEVELS:		□Y ØN □NA □NE			
GENERAL OPERATION AND MAINTENANCE		□S ☑M □U □NA			
CLEAN AND WELL MAINTAINED WITH MINIMAL STORAG EQUIPMENT:		⊠S □M □U □NA □NE			
GATES/DOORS/HATCHES/LIDS/ETC. LOCKED TO PREVE ACCESS AND/OR TAMPERING:		⊠S □M □U □NA □NE			
WET WELLS, SUMPS AND PITS ADEQUATELY COVERED PROTECTED:		⊠S □M □U □NA □NE			
ELECTRICAL CONTROLS COVERS CONDUIT AND EQUIP INSTALLED AND MAINTAINED:		⊠S □M □U □NA □NE			
GUARDS AND SHIELDS IN PLACE AROUND MOVING EQUENCESHAFTS, ETC.):	JIPMENT (BELTS, PULLEYS,	□S □M □U ☑NA □NE			
ADEQUATE VENTILATION TO PREVENT EXCESSIVE CONGASES AND FUMES:	NDENSATION AND/OR	□S □M □U ☑NA □NE			
ADEQUATE LIGHTING FOR ROUTINE INSPECTION/MAIN	TENANCE:	□S □M □U ☑NA □NE			
SEALS, VALVES AND PACKING ADEQUATELY MAINTAIN	ED TO PREVENT LEAKS:	□S □M □U □NA ☑NE			
MINIMAL ACCUMULATION OF GREASE AND SOLIDS IN V	VET WELLS: <u>Grease</u>	□S ☑M □U □NA □NE			
BACKUP POWER AND ALARMS		ØS □M □U □NA			
PROVISIONS FOR GENERATOR AND/OR EMERGENCY T	RANSFER PUMP:	☑S □M □U □NA □NE			
AUDIBLE/VISUAL ALARM WITH EMERGENCY CONTACT I	NFORMATION POSTED:	ØS □M □U □NA □NE			
SCADA SYSTEM (LIST PARAMETERS MONITORED):		⊠Y □N □NA □NE			

PUMP STATION VISIT (COMPLETE A SEPARATE CHI	ECKLIST FOR EACH PUMP S	STATION VISITED)
GENERAL INFORMATION AND OVERALL EVALUATION		□S ØM □U □NA
NAME AND/OR LOCATION OF PUMP STATION: <u>Gulpha</u>		
TYPE(S) OF WASTE WATER RECEIVED: ☑RESIDENTIAL	. ☑COMMERCIAL ☑INDUSTRIA	AL OTHER:
NUMBER OF PUMPS: 3	NUMBER OPERATIONAL: 2- r	notor pending repair
NUMBER AND SIZE OF PUMPS APPEARS ADEQUATE:	,	⊠S □M □U □NA □NE
EVIDENCE OF RECENT OVERFLOWS OR HIGH LEVELS: manholes immediately north of lift station; can only oper repaired force main (pressure would blow force main).		⊠Y □N □NA □NE
GENERAL OPERATION AND MAINTENANCE		ØS □M □U □NA
CLEAN AND WELL MAINTAINED WITH MINIMAL STORAGEQUIPMENT:	E OF UNRELATED	☑S ☐M ☐U ☐NA ☐NE
GATES/DOORS/HATCHES/LIDS/ETC. LOCKED TO PREVE ACCESS AND/OR TAMPERING:		⊠S □M □U □NA □NE
WET WELLS, SUMPS AND PITS ADEQUATELY COVERED PROTECTED:	), GRATED OR OTHERWISE	☑S □M □U □NA □NE
ELECTRICAL CONTROLS COVERS CONDUIT AND EQUIF INSTALLED AND MAINTAINED:	-	⊠S □M □U □NA □NE
GUARDS AND SHIELDS IN PLACE AROUND MOVING EQUINORING EQ	•	⊠S □M □U □NA □NE
ADEQUATE VENTILATION TO PREVENT EXCESSIVE COLGASES AND FUMES:	NDENSATION AND/OR	☑S □M □U □NA □NE
ADEQUATE LIGHTING FOR ROUTINE INSPECTION/MAIN	TENANCE:	☑S □M □U □NA □NE
SEALS, VALVES AND PACKING ADEQUATELY MAINTAIN	ED TO PREVENT LEAKS:	☑S □M □U □NA □NE
MINIMAL ACCUMULATION OF GREASE AND SOLIDS IN V	VET WELLS:	ØS □M □U □NA □NE
BACKUP POWER AND ALARMS		⊠S □M □U □NA
PROVISIONS FOR GENERATOR AND/OR EMERGENCY T	RANSFER PUMP:	ØS □M □U □NA □NE
AUDIBLE/VISUAL ALARM WITH EMERGENCY CONTACT	INFORMATION POSTED:	ØS □M □U □NA □NE
SCADA SYSTEM (LIST PARAMETERS MONITORED):		☑Y □N □NA □NE





# Office of Water Quality Photographic Evidence Sheet Location: Davidson & Southwest Collection System Photographer: Travis Harmon Date: April 27, 2023 Time: 1300 Witness: None Photo #: 5 Description: Moore Road lift station



Photographer:Travis HarmonDate:April 27, 2023Time:1302Witness:NonePhoto #:6




Inspection Report: Davidson & Southwest Collection System, AFIN: 26-00145, Permit #: AR0033880

Office of Water Quality Photographic Evidence Sheet						
Location:	Location: Davidson & Southwest Collection System					
Photograp	Photographer: Travis Harmon Date: April 27, 2023 Time: 13				1310	
Witness:	None				Photo #:	7



Photographer: Travis Harmon	Date: April 27, 2023	Time:	1312
Witness: None		Photo #:	8





# Office of Water Quality Photographic Evidence Sheet Location: Davidson & Southwest Collection System Photographer: Travis Harmon Date: April 27, 2023 Time: 1337 Witness: None Photo #: 9

Description: Gulpha lift station

Photographer: Travis Harmon	Date: <b>April 27, 2023</b>	Time:	1344
Witness: None		Photo #:	10

Description: Three pumps; one with motor out for repair.



Office of Water Quality Photographic Evidence Sheet						
Location: Davidson & Southwest Collection System						
Photograp	oher:	Travis Harmon	Date:	April 27, 2023	Time:	1350
Witness:	None	•			Photo #	: 11
_	One of two manholes with active SSO adjacent/north of Gulpha lift station. Manhole					

Description: One of two mannoles with active 550 adjis submerged by sewer inside rock berm.




Photographer:	Travis Harmon	Date:	April 27, 2023	Time:	1352
Witness: None	1			Photo #	12

Description: Second manhole SSO near the manhole in Photo # 11.



Figure 1. Google Earth image of lift stations inspected for City of Hot Springs.



From: Travis Harmon (adpce.ad)

**Sent:** Wednesday, May 31, 2023 12:02 PM

To: Uniqika Marshall (adpce.ad)

Subject: FW: Response to April 15 Inspections: City of Hot Springs Utilities / AFIN: 26-

00145 | NPDES Permit No.: NPDES Permit No.: AR0033880 | NPDES Permit

No.: ARR000059

Attachments: DEQ Response\_4.15.23 Inspections\_Davidson.PS\_5.26.2023.pdf

Follow Up Flag: Follow up Flag Status: Flagged

Uniqika,

Could you attach the pdf response to PDS 125869 (ARR000059) and 125868 (AR0033880)?

Thanks, Travis

**From:** Howard Hoover [mailto:HHoover@cityhs.net]

**Sent:** Friday, May 26, 2023 8:26 AM

To: Uniqika Marshall (adpce.ad) < Uniqika.Marshall@adeq.state.ar.us>; Travis Harmon (adpce.ad)

<Travis.Harmon@adeq.state.ar.us>

Subject: Response to April 15 Inspections: City of Hot Springs Utilities / AFIN: 26-00145 | NPDES Permit

No.: NPDES Permit No.: AR0033880 | NPDES Permit No.: ARR000059

Attached: City of Hot Springs Utilities Response

Davidson Drive WWTP Inspection/Southwest WWTP Inspection/Pump

Station Inspections (April 15, 2023)

AFIN: 26-00145 | NPDES Permit No.: NPDES Permit No.: AR0033880 |

NPDES Permit No.: ARR000059



### CITY OF HOT SPRINGS

### **Utilities Department**

780 Adams Street

Hot Springs, Arkansas 71901

May 26, 2023

Mr. Travis Harmon, Inspector
Office of Water Quality
Arkansas Department of Energy and Environment
5301 Northshore Drive
North Little Rock, Arkansas 72118

VIA EMAIL

RE: Hot Springs – Davidson Drive Wastewater Treatment Plant Inspections/Pump Station Inspections AFIN: 26-00145 | NPDES Permit No.: AR0033880 | NPDES Permit No.: ARR000059

Dear Mr. Harmon,

On Thursday, April 15, 2023, a Compliance Evaluation Inspection was performed at the Davidson Wastewater Treatment Plant (NPDES Permit No: AR0033880). The inspection started at the Headworks and concluded at the final effluent. The entire treatment process was inspected and no violations were found at the Davidson or Southwest WWTPs.

It is noted that seeps in the primary clarifier wall should be sealed. We are scheduling that for summer months when flows into the plant are lower. It is noted that weir covers will soon be purchased for secondary clarifiers to prevent algae from growing in the troughs.

The violations reported within the past year are a result of high flows and a lab error with an outsource lab. These violations were reported, and was verified as such, in the inspection report.

The laboratory records request was sent in to Mr. Richard Healey- OWQ-Enforcement Branch Manager, for review. We are pleased that there were no violations at the Davidson Wastewater Treatment Plant.

Included in the inspection Summary of Findings for No-Exposure Exclusion was the following:

1. Facility must repair containment berm at sludge press loading to maintain conditions of No-Exposure Exclusion.

On Friday, May 19, 2023 work was performed to repair the berm to ensure sludge containment, as displayed in the following pictures.







The Summary of Findings for the Pump Station Inspections included the following:

1. At the time of inspection, the 70W #9 lift station has a pump out, the Gulpha lift station had a pump motor out for repair, and grease was observed in the wet wells at 70W#9, Moore Road and Winkler lift stations. These issues require maintenance and are violations of Part III.B.1.A of the permit.

The pump replacement for the 70W#9 lift station has been received and is being installed as of May 25, 2023. The Gulpha pump motor is being repaired for reinstallation. However, running the Gulpha station at full capacity will further degrade the forcemain, which will be replaced in the near future as part of the greater Gulpha Basin project. Maintenance for grease at pump stations in in progress. Further photographic verification will be provided upon completion.

Kindest Regards,

Monty Ledbetter Utilities Director

cc: Harold Mauldin, Wastewater Facilities Operations Manager; Gordon Yates, Davidson Drive WWTP Supervisor; Danny Burton, Lift Stations Manager



June 12, 2023

Monty Ledbetter, Utilities Director City of Hot Springs 320 Davidson Drive Hot Springs, AR 71901

Email: mledbetter@cityhs.net; hmauldin@cityhs.net; gyates@cityhs.net

RE: Hot Springs – Davison WWTP – Response to Inspection (Garland Co)

AFIN: 26-00145 NPDES Permit No.: AR0033880

ARR000059

Dear Mr. Ledbetter:

I have reviewed the response pertaining to my April 27, 2023 inspections of the City of Hot Springs POTW and Collection System and the Davidson WWTP IGP. The information provided sufficiently addresses the items referenced in my inspection reports. At this time, the Division has no further comment concerning these particular inspections. Acceptance of this response by the Division does not preclude any future enforcement action deemed necessary at this site or any other site.

If I require further information concerning this matter, I will contact you. Thank you for your attention to this matter. Should you have any questions, please contact me at (501) 837-2070 or you may email me at <a href="mailto:travis.harmon@adeq.state.ar.us">travis.harmon@adeq.state.ar.us</a>.

Sincerely,

Travis Harmon

Inspector, Office of Water Quality

5301 Northshore Drive, North Little Rock, AR, 72118

Travis Horman



July 3, 2023

Mr. Monty Ledbetter, Utilities Director City of Hot Springs 320 Davidson Drive Hot Springs, AR 71901

Email: mledbetter@cityhs.net hmsuldin@cityhs.net gyates@cityhs.net

**RE:** Hot Springs – Davidson WWTP – Response to Inspections (Garland Co)

AFIN: 26-00145 NPDES Permit No.: AR0033880/ ARR000059

Dear Mr. Ledbetter:

I have reviewed the response pertaining to my April 27, 2023 inspections of the City of Hot Springs - Davidson Wastewater Plant, Collection System, and IGP (No-Exposure Exclusion). The information provided sufficiently addresses the items referenced in my inspection reports. At this time, the Division has no further comment concerning these particular inspections. Acceptance of this response by the Division does not preclude any future enforcement action deemed necessary at this site or any other site.

If I require further information concerning this matter, I will contact you. Thank you for your attention to this matter. Should you have any questions, please contact me at (501) 837-2070 or you may email me at <a href="mailto:travis.harmon@adeq.state.ar.us">travis.harmon@adeq.state.ar.us</a>.

Sincerely,

Travis Harmon

Inspector, Office of Water Quality

5301 Northshore Drive, North Little Rock, AR, 72118