

Taylor, Bailey

From: Brandon Haynes <bhaynes58@yahoo.com>
Sent: Thursday, May 03, 2018 3:25 PM
To: Taylor, Bailey; 'Brandon Haynes'
Subject: Emailing: Osceola SSO 4-23-2018 001, Osceola SSO 4-23-2018 002
Attachments: Osceola SSO 4-23-2018 001.jpg; Osceola SSO 4-23-2018 002.jpg

Follow Up Flag: Follow up
Flag Status: Flagged

Bailey,

I attached copies of the SSO's that occurred on 4/23/18-4/24/18 that was faxed but not received. I will be doing the form online, from now on, if any other overflows occur. If there is anything else I need to do please let me know.

Thanks,
Brandon Haynes
Osceola W/WW Supt.

BYPASS/OVERFLOW NCR REPORT

Send Overflow Report to:

ADEQ
P O Box 8913
Little Rock, AR 72219
Phone: 1-501-682-0633
Fax: 1-501-682-0910

Facility Permit Number: AR0021580

Facility Name: CITY OF OSCEOLA

Date Overflow Began: 4/23/18 10 Am

Date Overflow Ended: 4/23/18 6 pm

Volume: (Type "unknown" if applicable, or give an estimate)

(1.) 2000 gallons

Environmental Damage: NONE

Correction Action Taken: (Short-term and long-term action, including clean-up and any plans to reinstate I&I.)

(1.) Mixed with drainages from rain
Flush with water

Description: (Give address, manhole number-if numbered. Include where the overflow went, yard, ditch, stream, storm sewer, building or other)

(1.) Phillips Pump Stations located on West Keiser Street

Cause of Overflow:

(1.) Dry Well at lift station flooded due to pump malfunction
Had to pump pit out.

Reported By: BL VP

(After the overflow/bypass is detected, this completed fax may be sent to ADEQ within 24 hours, as the initial report. The final report must have original signature by cognizant official and sent to ADEQ within 5 days of start of overflow.)

Date Reported: 4/24/18

BYPASS/OVERFLOW NCR REPORT

Send Overflow Report to:

**ADEQ
P O Box 8913
Little Rock, AR 72219
Phone: 1-501-682-0633
Fax: 1-501-682-0910**

Facility Permit Number: **AR0021580**

Facility Name: **CITY OF OSCEOLA**

Date Overflow Began: 4/23/18 2pm

Date Overflow Ended: 4/24/18 7am

Volume: (Type "unknown" if applicable, or give an estimate)

(1.) 8200 gals. est.

Environmental Damage: NONE

Correction Action Taken: (Short-term and long-term action, including clean-up and any plans to reinitiate I&I.)

(1.) flush with water, Hydrocleaned

Letting area dry up and going to clean area and put fresh dirt

Description: (Give address, manhole number-if numbered. Include where the overflow went, yard, ditch, stream, storm sewer, building or other)

(1.) CORNER of Airport Road + West Keiser

Cause of Overflow:

(1.) HEAVY Rainfall + Lift Station malfunction

Reported By: 

(After the overflow/bypass is detected, this completed fax may be sent to ADEQ within 24 hours, as the initial report. The final report must have original signature by cognizant official and sent to ADEQ within 5 days of start of overflow.)

Date Reported: 4/24/18