

Springdale Water Utilities

Springdale, Arkansas

System Overflow Report for April 2021

This report submitted to Arkansas Department of Environmental Quality in compliance with Permit Number AR00222063 AFIN: 72-00003

Date	Time	Duration	Address	Est. Vol.	Cause of overflow	Remedial Action	Environmental Impact	Discharge Location
04/28/2021	1:00 pm - 4:00 pm	3 hrs	Manhole #6152 between Pump Station Road and N Thompson Street	5,000 gal	High intensity rainfall event.	Debris was picked up and lime applied to residue.	None	Soaked into ground in overgrown area.
04/28/2021	1:00 pm - 4:00 pm	3 hrs	Manhole #7174 between Pump Station Road and N Thompson Street	5,000 gal	High intensity rainfall event.	Debris was picked up and lime applied to residue.	None	Soaked into ground in overgrown area.
04/28/2021	1:00 pm - 4:00 pm	3 hrs	Manhole #6386 between Pump Station Road and N Thompson Street	5,000 gal	High intensity rainfall event.	Debris was picked up and lime applied to residue.	None	Migrated approximately 10 L.F. into flooded tributary of Spring Creek, both of which were out of its banks.
04/30/2021	3:30 pm - 4:00 pm	30 mins	910 Mayes Ave Springdale, AR 72764	50 gal	Main line overflow/Grease	Jet/Vac. Spread Lime on affected area.	None	Soaked into ground.

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that all qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

Signature



Date: 05/13/2021