



**Exposed portion of ruptured pipe.**

**08/20/2015**



Flow pattern to the east,  
towards Lake Hamilton.

08/20/2015



Flow pattern to Lake  
Hamilton.

08/20/2015



**Location of waste  
topping seawall, entering  
Lake Hamilton.**

**08/20/2015**