

Sanitary Sewer Overflow (SSO) Monthly Report

Facility Name: Hot Springs Wastewater NPDES Permit No.: AR0033880 Monitoring Period (Month/Year) November / 2014

No Sanitary Sewer Overflows This Monitoring Period

Summary Report Code Descriptions

Cause(s) of SSO	SSO Impact	Action(s) Taken	Ultimate Discharge Location
CO -Construction	D -Debris	NEAH -No Evidence Adverse Health/Environmental Impact	CR -Creek/Stream/River (specify)
E -Equipment Failure	G -Grease	OEHC -Observed or Evidence of Human Contact	DI -Ditch
HC -Hydro Clean	LF -Line Failure	EFK -Evidence of Fish Kill	DR -Drop Inlet
R -Rainfall	RG -Roots/Grease		HR -Hand Rodded
RO -Roots	V -Vandalism		EN -Referred to Engineering
		PN -Public Notification	PA -Paved Area
			CB -Contained in Building

Location	Manhole #	Start Date of SSO	End Date of SSO	Estimated Volume (in gallons)	Cause of SSO	Environmental Impact	Action(s) Taken to Address SSO	Discharge Location
403 Farr Shores Dr.	Pump Station	11/07/2014	11/08/2014	2000	LF	NEAH	HC & EC	GR
1827 Carpenter Dam Rd.	Main Break	11/07/2014	11/08/2014	1500	LF	NEAH	HC & EC	GR


Signature of Cognizant or Ranking Official

12-10-2014

Date

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are

CONFIRMATION NUMBER

884278F6-3F33-4E54-A2C3-F4A236F5DB56

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 884278F6-3F33-4E54-A2C3-F4A236F5DB56

Date Sent: 11/10/2014

SSO Bypass Upset

Facility Permit Number:

AR00 23880

Facility name:

HWW

Date Overflow Began:

11/07/2014

Time:

11:30 am

Date Overflow Ended:

11/08/2014

Time:

11:00 pm

Location:

403 Farr Shores Drive at Farr Shores P.S.. On ground by station.

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume:

2,000 gallons

(Give an estimate in gallons)

Impact of SSO Event:

SSO Affected Private Property (ground)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

Raked and cleaned up.

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- OEEI - Observed or Evidence of Environmental Impact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- EFK - Evidence of Fish Kill

Reported By **Don Ashley**

Title **Utility Maintenance Controller**

Telephone Number **(501) 321-6200**

Additional Comments if Needed:

CONFIRMATION NUMBER

E50E8FF2-D839-4229-AE98-3588449B8E2B

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: E50E8FF2-D839-4229-AE98-3588449B8E2B

Date Sent: 11/10/2014

SSO Bypass Upset

Facility Permit Number: **AR0033880**
 Date Overflow Began: **11/07/2014**
 Date Overflow Ended: **11/08/2014**

Facility name:
 Time:
 Time:

HWW
2:00 pm
11:00 am

Location: **1827 Carpenter Dam Road on ground around valve.**

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume: 1,500 gallons

(Give an estimate in gallons)

Impact of SSO Event: SSO Affected Private Property (ground)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

Raked area and cleaned up.

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- OEEI - Observed or Evidence of Environmental Impact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- EFK - Evidence of Fish Kill

Reported By **Don Ashley**


Title **Utility Maintenance Controller**

Telephone Number **(501) 321-6200**


Additional Comments if Needed:

City of Hot Springs
Wastewater Treatment Plant
320 Davidson Drive
Hot Springs, AR 71901

CERTIFIED MAIL™



7011 2970 0004 3941 3616



U.S. POSTAGE
\$7.61
FCM LG ENV
71913
Date of sale
12/11/14
06 2S00
08259532

SSK

FOLD HERE

Ar Department of Environmental
Quality
5301 North Shore Drive
North Little Rock, AR ~~72118~~⁷²¹¹⁸-5317
72118

