


Ref: 40CFR433, Section 3(E)

B&M Painting Water Flow



B & M Painting submitted the above diagram with the Baseline Monitoring Report dated July 9, 2008.