

Appendix B

Sediment and Soil Photo Logs



0 – 0.5 ft CLAYEY SILT (ML), some clay, no plasticity, soft, dry, red, no odor



0.5 – 1.0 ft CLAYEY SILT (ML), some clay, no plasticity, soft, dry, red, no odor



1.0 – 1.5 ft CLAYEY SILT (ML), some clay, no plasticity, soft, dry, red, no odor



NOTE:

1. ft = feet

2. Location photo was collected after sampling was completed.

MAYFLOWER PIPELINE INCIDENT RESPONSE

EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT

SOIL SAMPLE FIELD PHOTOS: SO-DA-001





0 – 0.5 ft CLAY (CL), some silt, soft, medium plasticity, moist, trace organics, no odor



0.5 – 1.0 ft CLAY (CL), some silt, soft, medium plasticity, moist, trace organics, no odor



1.0 – 1.5 ft CLAY (CL), soft, medium plasticity, wet, brown, no odor



SOIL LOCATION PHOTO

NOTE: 1. ft = feet

2. Location photo was collected after sampling was completed.

MAYFLOWER PIPELINE INCIDENT RESPONSE

EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT

SOIL SAMPLE FIELD PHOTOS: SO-DA-002

FIGURE

B-2





0 – 0.5 ft CLAY (CL), trace silt, soft, trace gravel, medium to high plasticity, moist, trace organics, no odor, brown



0.5 – 1.0 ft CLAY (CL), trace silt, soft, trace gravel, medium to high plasticity, moist, trace organics, no odor, brown



1.0 – 1.5 ft CLAY (CL), stiff, low plasticity, dry–moist, no odor, red



NOTE:

1. ft = feet

2. Location photo was collected after sampling was completed.

MAYFLOWER PIPELINE INCIDENT RESPONSE

EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT

SOIL SAMPLE FIELD PHOTOS: SO-DA-003





0 – **0.5 ft** CLAY (CL), trace silt, trace gavel, soft, high plasticity, moist, reddish/brown, no odor, some organics



0.5 – 1.0 ft CLAY (CL), stiff, low plasticity, red, no odor



1.0 – 1.5 ft CLAY (CL), soft, high plasticity, no odor, brown

<image>

NOTE:

- 1. ft = feet
- 2. Location photo was collected after sampling was completed.

MAYFLOWER PIPELINE INCIDENT RESPONSE

EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT

SOIL SAMPLE FIELD PHOTOS: SO-DA-004

FIGURE

B-4





0 – 0.5 ft CLAY (CL), stiff, low to medium plasticity, moist, red, no odor



0.5 – 1.0 ft CLAY (CL), stiff, low to medium plasticity, moist, red, no odor



1.0 – 1.5 ft CLAY (CL), stiff, low to medium plasticity, moist, red, no odor



NOTE:

- 1. ft = feet
- 2. Location photo was collected after sampling was completed.

MAYFLOWER PIPELINE INCIDENT RESPONSE

EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT

SOIL SAMPLE FIELD PHOTOS: SO-DA-005

> FIGURE **B-5**





0 – 0.5 ft CLAY (CL), stiff, low plasticity, dry, red, no odor



0.5 – 1.0 ft CLAY (CL), stiff, low plasticity, dry, red, no odor



CLAY (CL), stiff, low plasticity, dry, red, no odor



1.0 – 1.5 ft

NOTE:

- 1. ft = feet
- 2. Location photo was collected after sampling was completed.

MAYFLOWER PIPELINE INCIDENT RESPONSE

EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT

SOIL SAMPLE FIELD PHOTOS: SO-DA-006





0 – 0.5 ft CLAY (CL), some silt, medium plasticity, dry, very soft, gray/light brown, no odor



0.5 – 1.0 ft CLAY (CL), some silt, medium plasticity, dry, very soft, gray/light brown, no odor



1.0 – 1.5 ft CLAY (CL), some silt, medium plasticity, dry, very soft, gray/light brown/reddish, no odor



MAYFLOWER PIPELINE INCIDENT RESPONSE

EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT

SOIL SAMPLE FIELD PHOTOS: SO-DA-007

FIGURE

B-7






0 – 0.5 ft SILT (ML), some clay, low plasticity when wet, dry, beige, no odor, trace organics



0.5 – 1.0 ft CLAY (CL), some silt, low to medium plasticity, dry, gray/brownish, no odor



1.0 – 1.5 ft CLAY (CL), some silt, low to medium plasticity, dry, gray/brownish, no odor



NOTE: 1. ft = feet

MAYFLOWER PIPELINE INCIDENT RESPONSE

EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT

SOIL SAMPLE FIELD PHOTOS: SO-DA-008







FIGURE



0 – **0.5** ft CLAY (CL), some silt, high plasticity, slightly damp, brown, no odor, some organics



0.5 – 1.0 ft CLAY (CL), some silt, medium plasticity, dry, brown/reddish, no odor, trace organics



1.0 – 1.5 ft CLAY (CL), some silt, medium plasticity, soft, gray/reddish brown, no odor



MAYFLOWER PIPELINE INCIDENT RESPONSE

EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT

SOIL SAMPLE FIELD PHOTOS: SO-DA-009

FIGURE





0 – 0.5 ft CLAYEY SILT (ML), no plasticity, dry, soft, light– red brown, no odor, some organics



0.5 – 1.0 ft SILT (ML), some clay, no plasticity, dry, light brown/beige, no odor, no organics



1.0 – 1.5 ft SILT (ML), little clay, no plasticity, dry, soft, beige, no odor, no organics



MAYFLOWER PIPELINE INCIDENT RESPONSE

EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT





0 – 0.5 ft SILTY CLAY (CL), 30–40% silt content, light brown, soft, low plasticity, dry, no odor, some organics



0.5 – 1.0 ft CLAYEY SILT (ML), no plasticity, dry, soft, brown/reddish brown, no odor, trace organics



1.0 – 1.5 ft SILTY CLAY/CLAYEY SILT (CL/ML), low plasticity, dry, soft, light brown, no odor, no organics

<image>


NOTE: 1. ft = feet

MAYFLOWER PIPELINE INCIDENT RESPONSE

EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT







0.5 – 1.0 ft SANDY CLAY (CL), reddish brown, no odor, trace SANDY CLAY (CL), reddish brown, low plasticity, no odor, trace organics



1.0 – 1.5 ft SANDY CLAY (CL), reddish brown, low plasticity, no odor. Bottom half: clay, gray, high plasticity, very soft, dry-slightly moist



NOTE: 1. ft = feet

MAYFLOWER PIPELINE INCIDENT RESPONSE

EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT


SOIL SAMPLE FIELD PHOTOS: SO-DA-012



organics



0 – 0.5 ft SILTY CLAY (CL), trace fine grain sand, reddish brown, gray, no plasticity, no odor, no sheen, trace organics



0.5 – 1.0 ft SILTY CLAY (CL), some sand, fine grain, reddish gray, low plasticity, soft, no sheen, no odor, organics



1.0 – 1.5 ft SILTY CLAY (CL), trace fine sands, reddish gray, low to medium plasticity, soft, no odor, no sheen, trace organics



MAYFLOWER PIPELINE INCIDENT RESPONSE

EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT





0 – 0.5 ft SILTY CLAY (CL), light brown, medium plasticity, very soft, no odor, organics



0.5 – 1.0 ft SILTY CLAY (CL), light brown, soft, medium to high plasticity, slightly moist, no odor



1.0 – 1.5 ft SILTY CLAY (CL), trace sand, light reddish brown, soft, medium to high plasticity, slightly moist, no odor



NOTE:

1. ft = feet

2. Location photo was collected after sampling was completed.

MAYFLOWER PIPELINE INCIDENT RESPONSE

EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT









0.5 – 1.0 ft SILTY CLAY (CL), reddish brown, soft, dry, no odor



1.0 – 1.5 ft SILTY CLAY/CLAYEY SILT (CL/ML), reddish brown, soft, slightly moist, no odor, low plasticity

0 – 0.5 ft SILTY CLAY/CLAYEY SILT (CL/ML), light brown, soft, low plasticity, no odor, organics

NOTE:

- 1. ft = feet
- 2. Location photo was collected after sampling was completed.

MAYFLOWER PIPELINE INCIDENT RESPONSE

EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT

SOIL SAMPLE FIELD PHOTOS: SO-DA-015



SOIL LOCATION PHOTO



0 – 0.5 ft SILTY CLAY (CL), moist, low plasticity, medium stiff, some organics, no odor, reddish brown



0.5 – 1.0 ft SILTY CLAY (CL), moist, low plasticity, medium stiff, some organics, no odor, reddish brown



 $$1.0-1.5\ ft$$ CLAY (CL), soft, medium plasticity, trace organics, no odor



MAYFLOWER PIPELINE INCIDENT RESPONSE

EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT





0 – 0.5 ft CLAY (CL), some silt, soft, no plasticity, some organics, dark brown, no odor, dry



0.5 – 1.0 ft CLAY (CL), some silt, soft, no plasticity, some organics, dark brown, no odor, dry



1.0 – 1.5 ft CLAY (CL), soft, medium plasticity, moist, light brown, no odor



MAYFLOWER PIPELINE INCIDENT RESPONSE


EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT







0 – 0.5 ft CLAY (CL), soft to medium stiff, medium to high plasticity, moist, red/brown, no odor



0.5 – 1.0 ft CLAY (CL), some silt, soft, dry, low plasticity, brown/gray, no odor



1.0 – 1.5 ft CLAY (CL), some silt, soft, dry, low plasticity, brown/gray, no odor




MAYFLOWER PIPELINE INCIDENT RESPONSE

EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT





0 – 0.5 ft CLAY (CL), trace silt, stiff, no plasticity, dry, some organics, no odor



0.5 – 1.0 ft CLAY (CL), trace silt, stiff, no plasticity, dry, some organics, no odor



1.0 – 1.5 ft CLAY (CL), trace silt, stiff, no plasticity, dry, some organics, no odor




NOTE: 1. ft = feet

MAYFLOWER PIPELINE INCIDENT RESPONSE

EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT

SOIL SAMPLE FIELD PHOTOS: SO-DA-019





1.5 – 2.0 ft CLAY (CL), trace silt, stiff, no plasticity, dry, some organics, no odor



2.0 – 3.0 ft CLAY (CL), trace silt, stiff, low plasticity, slightly moist, some organics, no odor



3.0 – 4.0 ft CLAY (CL), trace silt, stiff, low plasticity, slightly moist, some organics, no odor



SOIL LOCATION PHOTO

NOTE: 1. ft = feet

MAYFLOWER PIPELINE INCIDENT RESPONSE

EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT

SOIL SAMPLE FIELD PHOTOS: SO-DA-019 (Continued)

FIGURE

B-20





0 – **0.5 ft** CLAY (CL), trace silt, medium stiff, medium to high plasticity, slightly moist, organics, no odor, dark brown



0.5 – 1.0 ft CLAY (CL), trace silt, soft, low plasticity, light brown/gray, dry, some organics, no odor



1.0 – 1.5 ft CLAY (CL), trace silt, soft, low plasticity, light brown/gray, dry, some organics, no odor

<image>

NOTE: 1. ft = feet

MAYFLOWER PIPELINE INCIDENT RESPONSE

EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT






0 – **0.5** ft CLAY (CL), some silt, stiff, light brown, no plasticity, dry, organics, no odor



0.5 – 1.0 ft CLAY (CL), some silt, stiff, reddish brown, no plasticity, dry, organics, no odor



1.0 – 1.5 ft CLAY (CL), some silt, stiff, reddish brown, no plasticity, dry, organics, no odor

NOTE: 1. ft = feet

MAYFLOWER PIPELINE INCIDENT RESPONSE

EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT







1.5 – 2.0 ft CLAY (CL), some silt, stiff, reddish brown, no plasticity, dry, organics, no odor



2.0 – 3.0 ft CLAY (CL), some silt, stiff, reddish brown, no plasticity, moist, organics, no odor



3.0 – 4.0 ft CLAY (CL), soft, wet, high plasticity, light brown, no odor

NOTE: 1. ft = feet

MAYFLOWER PIPELINE INCIDENT RESPONSE

EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT

SOIL SAMPLE FIELD PHOTOS: SO-DA-021 (Continued)

FIGURE

B-23







0 – 0.5 ft CLAY (CL), soft, dry, no plasticity, reddish brown, no odor



0.5 – 1.0 ft CLAY (CL), soft, dry, no plasticity, reddish brown, no odor



1.0 – 1.5 ft CLAY (CL), soft, dry, no plasticity, light brown, no odor



MAYFLOWER PIPELINE INCIDENT RESPONSE

EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT

SOIL SAMPLE FIELD PHOTOS: SO-DA-022








0.5 – 1.0 ft CLAY (CL), soft–medium stiff, low plasticity, brown, moist, no odor



1.0 – 1.5 ft CLAY (CL), soft–medium stiff, low plasticity, brown, moist, no odor





MAYFLOWER PIPELINE INCIDENT RESPONSE

EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT

SOIL SAMPLE FIELD PHOTOS: SO-DA-023





1.5 – 2.0 ft CLAY (CL), soft, high plasticity, brown, moist-wet, no odor



2.0 – 3.0 ft CLAY (CL), stiff, dry, no plasticity, gravish brown, no odor



3.0 – 4.0 ft CLAY (CL), stiff, dry, no plasticity, grayish brown, no odor



NOTE: 1. ft = feet

MAYFLOWER PIPELINE INCIDENT RESPONSE

EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT

SOIL SAMPLE FIELD PHOTOS: SO-DA-023 (Continued)







0 – 0.5 ft CLAY (CL), medium stiff, no plasticity, dry, red/rusty, no odor



0.5 – 1.0 ft CLAY (CL), medium stiff, no plasticity, dry, red/rusty, no odor



1.0 – 1.5 ft CLAY (CL), medium stiff, no plasticity, dry, red/rusty, no odor




NOTE: 1. ft = feet

MAYFLOWER PIPELINE INCIDENT RESPONSE

EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT







0 – 0.5 ft SILTY CLAY (CL), soft, moist, medium plasticity, gray/brown, no odor



0.5 – 1.0 ft CLAY (CL), trace silt, dry, moist, medium plasticity, reddish brown, no odor



1.0 – 1.5 ft CLAY (CL), trace silt, dry, moist, medium plasticity, reddish brown, no odor



1. ft = feet2. The "5" in SO-DA-025 was accidentally omitted on whiteboard in photo.

NOTES:

MAYFLOWER PIPELINE INCIDENT RESPONSE

EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT





0 – 0.5 ft SILTY CLAY (CL), moist, soft, red, no odor, some organics



0.5 – 1.0 ft SILTY CLAY (CL), moist, soft, red, no odor, some organics



1.0 – 1.5 ft SILTY CLAY (CL), moist, soft, red, no odor, some organics



MAYFLOWER PIPELINE INCIDENT RESPONSE

EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT

SOIL SAMPLE FIELD PHOTOS: SO-DA-026






0 – 0.5 ft CLAY (CL), medium stiff, trace silt, no plasticity, organics, no odor



0.5 – 1.0 ft CLAY (CL), soft, medium plasticity, reddish brown, moist, no odor



1.0 – 1.5 ft



1.0 – 1.:

2. Location photo was collected after sampling was completed.

CLAY (CL), dry

NOTE: 1. ft = feet

MAYFLOWER PIPELINE INCIDENT RESPONSE

EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT

SOIL SAMPLE FIELD PHOTOS: SO-DA-027





0 – 0.5 ft CLAY (CL), soft, dry-moist, high plasticity, red,



0.5 – 1.0 ft CLAY (CL), soft, dry, high plasticity, red, no odor, organics



1.0 – 1.5 ft CLAY (CL), soft, dry, high plasticity, red, no odor, organics



NOTES:

- 1. ft = feet
 - 2. Whiteboard was mislabeled in photos for this location.

MAYFLOWER PIPELINE INCIDENT RESPONSE

EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT

SOIL SAMPLE FIELD PHOTOS: SO-DA-028



no odor, organics



0 – 0.5 ft CLAY (CL), some silt, soft, medium to high plasticity, brown/red, dry, no odor, organics



0.5 – 1.0 ft CLAY (CL), soft, high plasticity, moist, red, no odor



1.0 – 1.5 ft CLAY (CL), soft, high plasticity, moist, red, no odor



NOTE: 1. ft = feet

MAYFLOWER PIPELINE INCIDENT RESPONSE

EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT







0 – 0.5 ft CLAY (CL), some silt, soft to medium stiff, dry to moist, medium plasticity, brown, no odor



0.5 – 1.0 ft CLAY (CL), soft, wet, high plasticity, brown/reddish brown, no odor



1.0 – 1.5 ft CLAY (CL), soft, wet, high plasticity, brown/reddish brown, no odor



NOTE: 1. ft = feet

MAYFLOWER PIPELINE INCIDENT RESPONSE

EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT







0.0 – 0.5 ft SILTY CLAY (CL), soft to medium stiff, low plasticity, dry, red, no odor, trace organics



NOTES:

- 1. ft = feet
 - 2. Background samples only collected from surface interval (0.0 0.5 feet).
- 3. Location photo was collected after sampling was completed.

MAYFLOWER PIPELINE INCIDENT RESPONSE

EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT







0.0 – 0.5 ft GRAVELLY SAND (SP), some fine sand, fine to medium grained sand, coarse subangular gravel, brown, moist, no odor

SOIL LOCATION PHOTO



NOTES:

- 1. ft = feet
- 2. Background samples only collected from surface interval (0.0 0.5 feet).
- 3. Location photo was collected after sampling was completed.

MAYFLOWER PIPELINE INCIDENT RESPONSE

EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT

SOIL SAMPLE FIELD PHOTOS: SO-DA-BG-002

FIGURE





0.0 – 0.5 ft SILT (ML), some clay, soft, no plasticity, dry, reddish brown, no odor, organics



NOTES:


- 1. ft = feet
 - 2. Background samples only collected from surface interval (0.0 0.5 feet).
- 3. Location photo was collected after sampling was completed.

MAYFLOWER PIPELINE INCIDENT RESPONSE

EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT

SOIL SAMPLE FIELD PHOTOS: SO-DA-BG-003







0.0 – 0.5 ft SILTY CLAY (CL), some silt, soft, high plasticity, brown, organics, dry, no odor

SOIL LOCATION PHOTO



NOTES:

- 1. ft = feet
 - 2. Background samples only collected from surface interval (0.0 0.5 feet).
- 3. Location photo was collected after sampling was completed.

MAYFLOWER PIPELINE INCIDENT RESPONSE

EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT

SOIL SAMPLE FIELD PHOTOS: SO-DA-BG-004







0.0 – 0.5 ft SILTY CLAY (ML/CL), medium stiff, low plasticity, some organics, dry, dark brown, no odor

SOIL LOCATION PHOTO



NOTES:

- 1. ft = feet
- 2. Background samples only collected from surface interval (0.0 0.5 feet).
- 3. Location photo was collected after sampling was completed.

MAYFLOWER PIPELINE INCIDENT RESPONSE

EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT

SOIL SAMPLE FIELD PHOTOS: SO-DA-BG-005

FIGURE

B-38





0.0 – 0.5 ft SILT (ML), some organics, trace clay, some gravel, 1" subangular, loose/soft, dry, dark brown, no odor



NOTES:

- 1. ft = feet
 - 2. Background samples only collected from surface interval (0.0 0.5 feet).
- 3. Location photo was collected after sampling was completed.

MAYFLOWER PIPELINE INCIDENT RESPONSE

EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT

SOIL SAMPLE FIELD PHOTOS: SO-DA-BG-006







0.0 – 0.5 ft CLAY (CL), some silt, trace gravel, high plasticity, soft to medium stiff, red with some gray, moist, no odor



0.5 – 1.0 ft CLAY (CL), some silt, trace gravel, high plasticity, soft to medium stiff, red with some gray, moist, no odor

NOTES: 1. ft = feet 2. Sediment sample collected using hand auger.

MAYFLOWER PIPELINE INCIDENT RESPONSE

EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT





0.0 – 0.5 ft CLAY (CL), some gravel, high plasticity, moist to wet, red/brown, no odor



0.5 – 1.0 ft CLAY (CL), some gravel, high plasticity, moist to wet, red/brown, no odor

MAYFLOWER PIPELINE INCIDENT RESPONSE

EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT







0.0 – 0.5 ft CLAY (CL), stiff, low plasticity, dry to moist, red, no odor



0.5 – 1.0 ft CLAY (CL), stiff, low plasticity, dry to moist, red, no odor

MAYFLOWER PIPELINE INCIDENT RESPONSE

EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT





0.0 – 0.5 ft SILTY CLAY (CL/ML), soft, no plasticity, wet, strong odor, staining



0.5 – 1.0 ft CLAY (CL), stiff, dry, low plasticity, dark red, slight odor

MAYFLOWER PIPELINE INCIDENT RESPONSE

EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT






0 – 0.5 ft CLAY (CL), trace silt, medium plasticity, dry–moist, soft, no odor, light brown/gray



0.5 – 1.0 ft CLAY (CL), trace silt, medium plasticity, dry–moist, soft, no odor, light brown/gray





1.0 – 1.5 ft CLAY (CL), trace silt, medium plasticity, dry–moist, soft, no odor, light brown/gray

MAYFLOWER PIPELINE INCIDENT RESPONSE

EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT







0 – 0.5 ft CLAY (CL), some silt, no plasticity, dry, soft, gray/brown, no odor



0.5 – 1.0 ft CLAY (CL), trace silt, medium plasticity, dry, soft, no odor




1.0 – 1.5 ft CLAY (CL), trace silt, medium plasticity, dry, soft, no odor

MAYFLOWER PIPELINE INCIDENT RESPONSE

EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT





DEPTH INTERVAL (FT)	LITHOLOGY DESCRIPTION
0 – 0.5	CLAY (CL), trace silt, medium plasticity, medium stiff, moist, light gray, no odor
0.5 – 1.0	CLAY (CL), trace silt and coarse sand, medium plasticity, soft, moist, light
1.0 – 1.5	SILTY CLAY (ML/CL), wet from water above the boring, trace sand, soft, light, gray/brown, no odor

NOTES: 1. ft = feet 2. Sediment sample collected using Lexan core tube.


MAYFLOWER PIPELINE INCIDENT RESPONSE EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT







0 – **0.5 ft** CLAY (CL), trace silt, medium plasticity, dry, beige/light gray, no odor



0.5 – 1.0 ft CLAY (CL), trace silt, medium plasticity, dry, beige/light gray, no odor



1.0 – 1.5 ft CLAY (CL), trace silt, medium plasticity, dry, beige/light gray, no odor

MAYFLOWER PIPELINE INCIDENT RESPONSE

EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT



Mayflower, AR SED-DA-209 0-1.5' 8/2/2013 1415

LITHOLOGY DESCRIPTION

0 – 0.5	SILTY CLAY (CL), medium plasticity, soft, moist, no odor
0.5 – 1.0	SILTY CLAY (CL), medium plasticity, soft, moist, no odor
1.0 – 1.5	SILT (ML), some clay, low plasticity, stiff, dry, no odor

NOTES: 1. ft = feet 2. Sediment sample collected using Lexan core tube.

MAYFLOWER PIPELINE INCIDENT RESPONSE EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT

SEDIMENT SAMPLE FIELD PHOTOS: SED-DA-009


FIGURE

B-48





0 – 0.5 ft SANDY CLAY (CL), some sand, medium plasticity, soft, no odor brown, reddish brown, moist–wet



0.5 – 1.0 ft SANDY CLAY (CL), some sand, medium plasticity, soft, no odor brown, reddish brown, moist–wet



1.0 – 1.5 ft SANDY CLAY (CL), some sand, medium plasticity, soft, no odor brown, reddish brown, moist–wet

MAYFLOWER PIPELINE INCIDENT RESPONSE

EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT





0 – 0.5 ft CLAY (CL), some sand, soft, low plasticity, gray, moist, no odor



0.5 – 1.0 ft CLAYEY SAND (SC/CL), soft, fine grain sand, low plasticity, wet, no odor



1.0 – 1.5 ft CLAYEY SAND (SC/CL), soft, fine grain sand, low plasticity, wet, no odor

MAYFLOWER PIPELINE INCIDENT RESPONSE

EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT





0 – 0.5 ft SANDY CLAY (CL), fine sand, trace silt, soft, moist, low plasticity, ruddy brown, no odor



0.5 – 1.0 ft SANDY CLAY (CL), fine sand, trace silt, soft, moist, low plasticity, ruddy brown, no odor




1.0 – 1.5 ft SANDY CLAY (CL), fine sand, trace silt, soft, moist, low plasticity, ruddy brown, no odor

MAYFLOWER PIPELINE INCIDENT RESPONSE

EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT









0.5 – 1.0 ft CLAY (CL), some sand, fine grain sand, moist–wet, medium to high plasticity, red brown, no odor, trace organics



1.0 – 1.5 ft CLAY (CL), some sand, fine grain sand, moist–wet, medium to high plasticity, red brown, no odor, trace organics

MAYFLOWER PIPELINE INCIDENT RESPONSE

EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT





LITHOLOGY DESCRIPTION

0 – 0.5	CLAYEY SAND, brown, fine grained, no odor
0.5 – 1.0	SANDY CLAY (CL), reddish brown, medium plasticity, no odor

NOTES: 1. ft = feet 2. Sediment sample collected using Lexan core tube.

MAYFLOWER PIPELINE INCIDENT RESPONSE EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT

SEDIMENT SAMPLE FIELD PHOTOS: SED-DA-014



FIGURE



LITHOLOGY DESCRIPTION

0 – 0.5	SANDY CLAY (CL), soft, wet, no plasticity, HCO
0.5 – 1.0	SANDY CLAY (CL), soft, wet, low plasticity, reddish brown, slight HCO
1.0 – 1.5	SANDY CLAY (CL), soft, wet, low plasticity, reddish brown, slight HCO

NOTES:

1. ft = feet

- 2. Sediment sample collected using Lexan core tube.
- 3. HCO = hydrocarbon odor

MAYFLOWER PIPELINE INCIDENT RESPONSE EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT

SEDIMENT SAMPLE FIELD PHOTOS: SED-DA-015



FIGURE



LITHOLOGY DESCRIPTION

0 – 0.5	SANDY CLAY (CL), very soft, wet, low plasticity, brown, 50% organics
0.5 –1.0	SANDY CLAY (CL), very soft, wet, low plasticity, brown, 50% organics

NOTES: 1. ft = feet 2. Sediment sample collected using Lexan core tube.

MAYFLOWER PIPELINE INCIDENT RESPONSE EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT

SEDIMENT SAMPLE FIELD PHOTOS: SED-DA-016

FIGURE

B-55



Mayflower, AR SED-DA=017 (0-1.0) 8-5-13 1245 08.05.2013 14:58

LITHOLOGY DESCRIPTION

0 – 0.5	SILTY CLAY (CL), soft, wet, low plasticity, brown, no odor
0.5 –1.0	SILTY CLAY (CL), soft, wet, low plasticity, brown, strong HCO

NOTES:

1. ft = feet

- 2. Sediment sample collected using Lexan core tube.
- 3. HCO = hydrocarbon odor

MAYFLOWER PIPELINE INCIDENT RESPONSE EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT

SEDIMENT SAMPLE FIELD PHOTOS: SED-DA-017



FIGURE **B-56**



LITHOLOGY DESCRIPTION

2.0 -3.0	CLAY (CL), soft, medium to high plasticity, wet, reddish gray, no odor
3.0 – 3.2	CLAY (CL), soft, medium to high plasticity, wet, reddish gray, no odor, trace organics

NOTES: 1. ft = feet 2. Sediment sample collected using Lexan core tube.

MAYFLOWER PIPELINE INCIDENT RESPONSE EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT

SEDIMENT SAMPLE FIELD PHOTOS: SED-DA-018



FIGURE B-57



LITHOLOGY DESCRIPTION

2.0 – 3.0	CLAY (CL), soft, low plasticity, wet, gray to 2.5 feet, no odor
3.0 – 3.3	CLAY (CL), stiff, moist, high plasticity, reddish gray, no odor

NOTES: 1. ft = feet 2. Sediment sample collected using Lexan core tube.

MAYFLOWER PIPELINE INCIDENT RESPONSE EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT

SEDIMENT SAMPLE FIELD PHOTOS: SED-DA-019

FIGURE

B-58





LITHOLOGY DESCRIPTION

0 – 0.5	SILT (ML), brown, saturated, no odor
0.5 – 1.0	SILT (ML), brown, saturated, no odor
1.0 – 1.5	SILTY CLAY (CL), light brown, soft, wet, no odor

NOTES: 1. ft = feet 2. Sediment sample collected using Lexan core tube.

MAYFLOWER PIPELINE INCIDENT RESPONSE EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT

SEDIMENT SAMPLE FIELD PHOTOS: SED-DA-020



5

FIGURE

B-59



LITHOLOGY DESCRIPTION

0 – 0.5	MUD/SILT (ML), some clay, soft, some organics, moist-wet, brown/black, some odor
0.5 – 1.0	CLAY (CL), trace silt, soft, wet, low-medium plasticity, gray, no odor
1.0 – 1.5	CLAY (CL), trace silt, soft, wet, low-medium plasticity, gray, no odor
1.5 – 2.0	CLAY (CL), trace silt, soft, wet, low-medium plasticity, gray, no odor
2.0 - 3.0	CLAY (CL), medium stiff, high plasticity, moist, gray/red, no odor
3.0 – 3.3	CLAY (CL), stiff, low plasticity, moist-dry, brown/grayish red, no odor

NOTES: 1. ft = feet 2. Sediment sample collected using Lexan core tube.

MAYFLOWER PIPELINE INCIDENT RESPONSE EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT

SEDIMENT SAMPLE FIELD PHOTOS: SED-DA-021

FIGURE





LITHOLOGY DESCRIPTION

0.0 – 0.5	ORGANIC SILT (OL/PT), swamp soil, soft, organics, black, wet, organic odor
0.5 – 1.0	CLAY (CL), soft, low to medium plasticity, wet, gray, no odor
1.0 – 1.5	CLAY (CL), soft, low to medium plasticity, wet, gray, no odor
1.5 – 2.0	CLAY (CL), soft, low to medium plasticity, wet, gray, no odor
2.0 - 3.0	CLAY (CL), medium stiff, medium plasticity, moist to wet, gray with some red, no odor

NOTES: 1. ft = feet 2. Sediment sample collected using Lexan core tube.

MAYFLOWER PIPELINE INCIDENT RESPONSE EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT

SEDIMENT SAMPLE FIELD PHOTOS: SED-DA-022

FIGURE

B-61





DEPTH INTERVAL (FT)	LITHOLOGY DESCRIPTION
0.0 – 0.5	ORGANIC SILT (OL), organics, soft, wet, black, some odor
0.5 – 1.0	ORGANIC SILT (OL–CL), organics, soft, wet, black, some odor, transitions to clay at 11 inches
1.0 – 1.5	CLAY (CL), some silt, soft, wet, no plasticity, gray, no odor
1.5 – 2.0	CLAY (CL), some silt, soft, wet, no plasticity, gray, no odor
2.0 - 3.0	CLAY (CL), some silt, soft, wet, no plasticity, gray, no odor, at 2 feet 10 inches transition to stiff, dry to moist clay, gray with red, no odor
3.0 – 3.1	CLAY (CL), some silt, soft, wet, no plasticity, gray, no odor

NOTES: 1. ft = feet 2. Sediment sample collected using Lexan core tube.


MAYFLOWER PIPELINE INCIDENT RESPONSE EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT

SEDIMENT SAMPLE FIELD PHOTOS: SED-DA-023

FIGURE

B-62







LITHOLOGY DESCRIPTION

0 – 0.5	SILT (ML), brown, saturated, trace organics, slight odor (organic)
0.5 – 1.0	SILT (ML), brown, saturated, trace organics
1.0 – 1.5	SILT (ML), brown, saturated, trace organics
1.5 – 2.0	SILT (ML), brown, saturated, trace organics
2.0 - 3.0	SILT (ML), brown, saturated, trace organics

NOTES: 1. ft = feet 2. Sediment sample collected using Lexan core tube.

MAYFLOWER PIPELINE INCIDENT RESPONSE EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT

SEDIMENT SAMPLE FIELD PHOTOS: SED-DA-024

FIGURE

B-63





LITHOLOGY DESCRIPTION

0 – 0.5	SILT (ML), brown, saturated, root mass, no odor
0.5 – 1.0	SILT (ML), some clay, light brown, saturated, no odor
1.0 – 1.5	SILTY CLAY (CL), light brown, wet, no odor

NOTES: 1. ft = feet 2. Sediment sample collected using Lexan core tube.

MAYFLOWER PIPELINE INCIDENT RESPONSE EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT

SEDIMENT SAMPLE FIELD PHOTOS: SED-DA-025



FIGURE **B-64**



DEPTH INTERVAL (FT)	LITHOLOGY DESCRIPTION
0 – 0.5	SILT (ML), brown, no odor, root mass, saturated
0.5 –1.0	SILT (ML), brown, no odor, root mass, saturated
1.0 – 1.5	SILT (ML), light brown, saturated
1.5 – 2.0	SANDY CLAY (CL), light brown, wet, no odor, trace organics
2.0 - 3.0	SANDY CLAY (CL), light brown, wet, no odor, trace organics
3.0 - 3.4	SANDY CLAY (CL), light brown, wet, no odor, trace organics

NOTES: 1. ft = feet 2. Sediment sample collected using Lexan core tube.

MAYFLOWER PIPELINE INCIDENT RESPONSE EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT

SEDIMENT SAMPLE FIELD PHOTOS: SED-DA-026

FIGURE

B-65





DEPTH INTERVAL (FT)	LITHOLOGY DESCRIPTION
0 – 0.5	SILT (ML), brown, saturated, root mass
0.5 – 1.0	SILT (ML), brown, saturated, root mass
1.0 – 1.5	SILTY CLAY (CL), gray, trace organics
1.5 – 2.0	SILTY CLAY (CL), gray, saturated
2.0 - 3.0	CLAY (CL), gray, trace organics, no odor, saturated
3.0 - 3.6	CLAY (CL), gray, trace organics, no odor, saturated

NOTES:

1. ft = feet

- Sediment sample collected using Lexan core tube.
 Photo is from SED-DA-027 collected on 7/29/2013 at 1400 from 0 - 3.6 feet.

MAYFLOWER PIPELINE INCIDENT RESPONSE EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT

SEDIMENT SAMPLE FIELD PHOTOS: SED-DA-027

> FIGURE **B-66**





DEPTH INTERVAL (FT)	LITHOLOGY DESCRIPTION
0 – 0.5	SILT (ML), brown, no odor, root mass, saturated
0.5 – 1.0	SILT (ML), light brown, root mass, no odor, saturated
1.0 – 1.5	CLAY (CL), gray, trace organics, saturated

NOTES: 1. ft = feet 2. Sediment sample collected using Lexan core tube.

MAYFLOWER PIPELINE INCIDENT RESPONSE EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT







DEPTH INTERVAL (FT)	LITHOLOGY DESCRIPTION
0 – 0.5	SILT (ML), brown, no odor, saturated, trace organics, root mass
0.5 – 1.0	SILT (ML), brown, no odor, saturated, trace organics, root mass
1.0 – 1.5	SILT (ML), light brown, no odor, saturated, trace organics, and root mass
1.5 – 2.0	SILT (ML), light brown, no odor, saturated, trace organics, and root mass
2.0 – 3.0	SILT (ML), light brown, no odor, saturated, trace organics, and root mass

NOTES: 1. ft = feet 2. Sediment sample collected using Lexan core tube.

MAYFLOWER PIPELINE INCIDENT RESPONSE EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT

SEDIMENT SAMPLE FIELD PHOTOS: SED-DA-029

FIGURE

B-68



Mayflowers AR SED-DA-030 7/29/2013 1120 0-1.5

LITHOLOGY DESCRIPTION

0 – 0.5	SILT (ML), brown, no odor, saturated
0.5 – 1.0	CLAY (CL), gray, no odor, wet, low plasticity, soft
1.0 – 1.5	CLAY (CL), gray, no odor, wet, low plasticity, soft

NOTES: 1. ft = feet 2. Sediment sample collected using Lexan core tube.

MAYFLOWER PIPELINE INCIDENT RESPONSE EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT

SEDIMENT SAMPLE FIELD PHOTOS: SED-DA-030

FIGURE

B-69





LITHOLOGY DESCRIPTION

0 – 0.5	SILT (ML), brown, no odor, root mass
0.5 – 1.0	SILT (ML), brown, no odor, root mass
1.0 – 1.5	SILTY CLAY (CL), gray, root mass, no odor

NOTES: 1. ft = feet 2. Sediment sample collected using Lexan core tube.


MAYFLOWER PIPELINE INCIDENT RESPONSE EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT

SEDIMENT SAMPLE FIELD PHOTOS: SED-DA-031



5

FIGURE





LITHOLOGY DESCRIPTION

0 – 0.5	SILT (ML), brown, trace organics, mild odor, saturated
0.5 – 1.0	SILTY CLAY (CL), gray, no odor, saturated
1.0 – 1.5	CLAY (CL), gray, soft, no odor, saturated

NOTES: 1. ft = feet 2. Sediment sample collected using Lexan core tube.

MAYFLOWER PIPELINE INCIDENT RESPONSE EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT

SEDIMENT SAMPLE FIELD PHOTOS: SED-DA-032



FIGURE



DEPTH INTERVAL (FT)	LITHOLOGY DESCRIPTION
0 – 0.5	SILT (ML), brown, trace organics, saturated
0.5 – 1.0	SILTY CLAY (CL), gray, trace organics, saturated
1.0 – 1.5	CLAY (CL), gray, trace organics, wet

MAYFLOWER PIPELINE INCIDENT RESPONSE EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT

SEDIMENT SAMPLE FIELD PHOTOS: SED-DA-033





DEPTH INTERVAL (FT)	LITHOLOGY DESCRIPTION
0 – 0.5	CLAYEY SILT (ML), brown, trace organics, mild odor, saturated
0.5 – 1.0	SILTY CLAY (CL), gray, low plasticity, no odor
1.0 – 1.5	CLAY (CL), gray, low plasticity, no odor

MAYFLOWER PIPELINE INCIDENT RESPONSE EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT

SEDIMENT SAMPLE FIELD PHOTOS: SED-DA-034





LITHOLOGY DESCRIPTION

0 – 0.5	SILT (ML), brown, trace organics, mild odor, saturated
0.5 – 1.0	CLAYEY SILT (ML), brown to gray at 1 foot, saturated
1.0 – 1.5	SILTY CLAY (CL), gray, low plasticity, wet

NOTES: 1. ft = feet 2. Sediment sample collected using Lexan core tube.

MAYFLOWER PIPELINE INCIDENT RESPONSE EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT

SEDIMENT SAMPLE FIELD PHOTOS: SED-DA-035





LITHOLOGY DESCRIPTION

0 – 0.5	SILT (ML), brown saturated, trace organics, no odor
0.5 – 1.0	SILTY CLAY (CL), gray, trace organics, saturated, no odor
1.0 – 1.5	CLAY (CL), gray, trace organics, wet, no odor

NOTES: 1. ft = feet 2. Sediment sample collected using Lexan core tube.

MAYFLOWER PIPELINE INCIDENT RESPONSE EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT

SEDIMENT SAMPLE FIELD PHOTOS: SED-DA-036





LITHOLOGY DESCRIPTION

0 – 0.5	SILT (ML), brown, saturated, no odor
0.5 – 1.0	SILT (ML), dark gray, saturated, no odor
1.0 – 1.5	CLAY (CL), gray, soft, low plasticity, no odor

NOTES: 1. ft = feet 2. Sediment sample collected using Lexan core tube.

MAYFLOWER PIPELINE INCIDENT RESPONSE EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT

SEDIMENT SAMPLE FIELD PHOTOS: SED-DA-037





LITHOLOGY DESCRIPTION

0 – 0.5	SILT (ML), brown, saturated, no odor, trace organics
0.5 – 1.0	SILT (ML), brown, saturated, no odor, trace organics
1.0 – 1.5	CLAY (CL), gray, soft, no odor, trace organics

NOTES: 1. ft = feet 2. Sediment sample collected using Lexan core tube.

MAYFLOWER PIPELINE INCIDENT RESPONSE EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT

SEDIMENT SAMPLE FIELD PHOTOS: SED-DA-038





DEPTH INTERVAL (FT)	LITHOLOGY DESCRIPTION
0 – 0.5	SILTY CLAY (CL), soft, wet, some silt, medium plasticity, no odor, brown
0.5 – 1.0	SILTY CLAY (CL), soft, wet, some silt, medium plasticity, no odor, brown
1.0 – 1.5	SILTY CLAY (CL), soft, wet, some silt, medium plasticity, no odor, brown

DADAR_SedPhotolog_20131011.m

MAYFLOWER PIPELINE INCIDENT RESPONSE EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT

SEDIMENT SAMPLE FIELD PHOTOS: SED-DA-039

FIGURE

B-78





LITHOLOGY DESCRIPTION

0 – 0.5	CLAY (CL), trace silt, wet, medium-high plasticity, medium stiff
0.5 – 1.0	CLAY (CL), trace silt, wet, medium-high plasticity, medium stiff, light brown
1.0 – 1.5	CLAY (CL), trace silt, wet, medium-high plasticity, medium stiff, light brown

NOTES: 1. ft = feet 2. Sediment sample collected using Lexan core tube.

MAYFLOWER PIPELINE INCIDENT RESPONSE EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT

SEDIMENT SAMPLE FIELD PHOTOS: SED-DA-040

FIGURE





LITHOLOGY DESCRIPTION

0 – 0.5	SILT (ML/CL), soft, wet, black, very wet, slight odor, sheen
0.5 – 1.0	SILT (ML/CL), soft, wet, black, very wet
1.0 – 1.5	SILT (ML/CL), soft, wet, black, very wet

NOTES: 1. ft = feet 2. Sediment sample collected using Lexan core tube.

MAYFLOWER PIPELINE INCIDENT RESPONSE EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT

SEDIMENT SAMPLE FIELD PHOTOS: SED-DA-041

FIGURE

B-80





DEPTH INTERVAL (FT)	LITHOLOGY DESCRIPTION
0 – 0.5	MUD/SILT (ML), soft, trace clay, black, some organics, organic odor
0.5 – 1.0	SILTY CLAY (CL), soft, trace organics, low plasticity, organic odor, gray/black
1.0 – 1.5	CLAY (CL), soft-medium stiff, medium plasticity, gray, slight organic odor

MAYFLOWER PIPELINE INCIDENT RESPONSE EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT

SEDIMENT SAMPLE FIELD PHOTOS: SED-DA-042





LITHOLOGY DESCRIPTION

0 – 0.5	SILTY CLAY (ML/CL), soft, wet, no plasticity, trace organics, no odor, black
0.5 – 1.0	CLAY (CL), soft, medium plasticity, wet, no odor, gray/brown
1.0 – 1.5	CLAY (CL), soft, medium plasticity, wet, no odor, gray/brown

NOTES:

1. ft = feet

- Sediment sample collected using Lexan core tube.
 Sample was collected from SED-DA-043.

MAYFLOWER PIPELINE INCIDENT RESPONSE EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT

SEDIMENT SAMPLE FIELD PHOTOS: SED-DA-043



FIGURE **B-82**

Mayflower, AR SED-DA-044 8-12-13 1010 0-1.5' 08.12.2013 14:34

LITHOLOGY DESCRIPTION

0 – 0.5	ORGANIC SILT, PEAT (OL/PT), some clay, no plasticity, slight odor, black
0.5 – 1.0	CLAY (CL), soft, high plasticity, some organics, slight odor, gray
1.0 – 1.5	CLAY (CL), soft, high plasticity, some organics, slight odor, reddish brown

NOTES: 1. ft = feet 2. Sediment sample collected using Lexan core tube.

MAYFLOWER PIPELINE INCIDENT RESPONSE EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT

SEDIMENT SAMPLE FIELD PHOTOS: SED-DA-044

FIGURE **B-83**





1.0 – 1.5

CLAY (CL), trace coarse sand/gravel, soft, wet, light brown, no odor

NOTES: 1. ft = feet 2. Sediment sample collected using Lexan core tube.

MAYFLOWER PIPELINE INCIDENT RESPONSE EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT

SEDIMENT SAMPLE FIELD PHOTOS: SED-DA-045



FIGURE **B-84**



LITHOLOGY DESCRIPTION

0 – 0.5	SILTY CLAY (CL), soft, medium plasticity, wet, some organics, slight odor, black
0.5 – 1.0	CLAY (CL), soft, high plasticity, wet, some organics, slight odor, gray
1.0 – 1.5	CLAY (CL), soft, high plasticity, wet, some organics, slight odor, gray

NOTES: 1. ft = feet 2. Sediment sample collected using Lexan core tube.

MAYFLOWER PIPELINE INCIDENT RESPONSE EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT

SEDIMENT SAMPLE FIELD PHOTOS: SED-DA-046

FIGURE

B-85





LITHOLOGY DESCRIPTION

0 – 0.5	SILT (ML), some clay, some organics, soft, wet, no plasticity, HCO, black
0.5 – 1.0	CLAY (CL), trace silt, organics, soft, wet, low plasticity, gray, no odor
1.0 – 1.5	CLAY (CL), trace silt, organics, soft, wet, low plasticity, gray, no odor

NOTES:

1. ft = feet

- 2. Sediment sample collected using Lexan core tube.
- 3. HCO = hydrocarbon odor

MAYFLOWER PIPELINE INCIDENT RESPONSE EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT

SEDIMENT SAMPLE FIELD PHOTOS: SED-DA-047





LITHOLOGY DESCRIPTION

0 – 0.5	ORGANIC SILT, PEAT (OL/PT), trace clay, soft, wet, no plasticity, black, HCO
0.5 – 1.0	CLAY (CL), soft, wet, medium plasticity, gray, slight odor
1.0 – 1.5	CLAY (CL), soft, wet, medium plasticity, gray, slight odor

NOTES:

1. ft = feet

- 2. Sediment sample collected using Lexan core tube.
- 3. HCO = hydrocarbon odor

MAYFLOWER PIPELINE INCIDENT RESPONSE EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT

SEDIMENT SAMPLE FIELD PHOTOS: SED-DA-048





LITHOLOGY DESCRIPTION

0 – 0.5	ORGANIC SILT, PEAT (OL/PT), lots of organics, wet, slight odor, black
0.5 – 1.0	ORGANIC SILT, PEAT (OL/PT), lots of organics, wet, slight odor, black, clay in the last inch
1.0 – 1.5	CLAY (CL), soft, medium plasticity, moist-wet, no odor, brown/gray

NOTES: 1. ft = feet 2. Sediment sample collected using Lexan core tube.

MAYFLOWER PIPELINE INCIDENT RESPONSE EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT

SEDIMENT SAMPLE FIELD PHOTOS: SED-DA-049

FIGURE

B-88





LITHOLOGY DESCRIPTION

0 – 0.5	ORGANIC SILT, PEAT (OL/PT), organics, wet, swamp soils, some clay, soft, black, slight odor
0.5 – 1.0	CLAY (CL), some silt, wet, soft, low plasticity, light brown, no odor
1.0 – 1.5	CLAY (CL), some silt, wet, soft, low plasticity, light brown, no odor

NOTES: 1. ft = feet 2. Sediment sample collected using Lexan core tube.

MAYFLOWER PIPELINE INCIDENT RESPONSE EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT

SEDIMENT SAMPLE FIELD PHOTOS: SED-DA-050

FIGURE





LITHOLOGY DESCRIPTION

0 – 0.5	ORGANIC SILT, PEAT (OL/PT), organics, peat/swamp soils, wet, soft, black, organic odor
0.5 – 1.0	CLAY (CL), trace silt, low to medium plasticity, soft, wet, gray, slight odor
1.0 – 1.5	CLAY (CL), trace silt, low to medium plasticity, soft, wet, gray, slight odor

NOTES: 1. ft = feet 2. Sediment sample collected using Lexan core tube.

MAYFLOWER PIPELINE INCIDENT RESPONSE EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT

SEDIMENT SAMPLE FIELD PHOTOS: SED-DA-051

FIGURE





DEPTH INTERVAL (FT)	LITHOLOGY DESCRIPTION
1.5 – 2.0	CLAY/SILT (CL/ML), some organics, soft, wet, gray, no odor
2.0 – 2.6	CLAY/SILT (CL/ML), some organics, soft, wet, gray, no odor

MAYFLOWER PIPELINE INCIDENT RESPONSE EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT

SEDIMENT SAMPLE FIELD PHOTOS: SED-DA-052





DEPTH INTERVAL (FT)	LITHOLOGY DESCRIPTION
0 – 0.5	ORGANIC SILT, PEAT (OL/PT), swamp soil, organics, soft, wet, black, some odor
0.5 – 1.0	CLAY (CL), some silt, soft, wet to moist, low to medium plasticity, slight odor
1.0 – 1.5	CLAY (CL), some silt, soft, wet to moist, low to medium plasticity, slight odor

MAYFLOWER PIPELINE INCIDENT RESPONSE EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT

SEDIMENT SAMPLE FIELD PHOTOS: SED-DA-053





0.0 – 0.5 ft CLAY (CL), some silt, coarse gravel, soft, medium plasticity, moist, dark brown, no odor

MAYFLOWER PIPELINE INCIDENT RESPONSE

EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT

SEDIMENT SAMPLE FIELD PHOTOS: SED-DA-BG-001

FIGURE

B-93







0.0 – 0.5 ft CLAY (CL), soft to medium stiff, low plasticity, red, dry, no odor

MAYFLOWER PIPELINE INCIDENT RESPONSE

EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT

SEDIMENT SAMPLE FIELD PHOTOS: SED-DA-BG-002







0.0 – 0.5 ft SILTY CLAY (CL/ML), soft, low plasticity, wet, light brown, no odor, trace organics

MAYFLOWER PIPELINE INCIDENT RESPONSE

EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT

SEDIMENT SAMPLE FIELD PHOTOS: SED-DA-BG-003





0 – 0.5 ft CLAY (CL), some silt, soft, moist, medium to high plasticity, dark brown, no odor

> NOTES: 1. ft = feet 2. Sediment sample collected using hand auger.

> > MAYFLOWER PIPELINE INCIDENT RESPONSE

EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT

SEDIMENT SAMPLE FIELD PHOTOS: SED-DA-BG-004







0 – 0.5 ft CLAY (CL), some silt, soft, medium to high plasticity, dry to moist, no odor

MAYFLOWER PIPELINE INCIDENT RESPONSE

EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT

SEDIMENT SAMPLE FIELD PHOTOS: SED-DA-BG-005





0 – **0.5 ft** CLAY (CL), medium stiff, low plasticity, dry, no odor

MAYFLOWER PIPELINE INCIDENT RESPONSE

EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT

SEDIMENT SAMPLE FIELD PHOTOS: SED-DA-BG-006







LITHOLOGY DESCRIPTION

0 – 0.5

SILT (ML), brown, saturated, trace organics, no odor (0–0.25 foot) CLAY (CL), light brown, wet trace organics (0.25–0.5 foot)

NOTES: 1. ft = feet 2. Sediment sample collected using Lexan core tube.

MAYFLOWER PIPELINE INCIDENT RESPONSE EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT

SEDIMENT SAMPLE FIELD PHOTOS: SED-DA-BG-007





LITHOLOGY DESCRIPTION

0 – 0.5

SILTY CLAY (CL), light brown, trace organics, wet, slight organic odor

NOTES: 1. ft = feet 2. Sediment sample collected using Lexan core tube.

MAYFLOWER PIPELINE INCIDENT RESPONSE EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT

SEDIMENT SAMPLE FIELD PHOTOS: SED-DA-BG-008

FIGURE

B-100





LITHOLOGY DESCRIPTION

0 – 0.5

CLAY (CL), brown, trace organics, no odor, soft, wet

NOTES: 1. ft = feet 2. Sediment sample collected using Lexan core tube.

MAYFLOWER PIPELINE INCIDENT RESPONSE EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT

SEDIMENT SAMPLE FIELD PHOTOS: SED-DA-BG-009





LITHOLOGY DESCRIPTION

0 – 0.5

SILTY CLAY (CL), light brown, wet, trace organics, slight odor

NOTES: 1. ft = feet 2. Sediment sample collected using Lexan core tube.


MAYFLOWER PIPELINE INCIDENT RESPONSE EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT

SEDIMENT SAMPLE FIELD PHOTOS: SED-DA-BG-010

FIGURE

B-102






MAYFLOWER PIPELINE INCIDENT RESPONSE EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT

SEDIMENT SAMPLE FIELD PHOTOS: SED-DA-BG-011

FIGURE

B-103







LITHOLOGY DESCRIPTION

0.0 – 0.5

ORGANIC SILT, PEAT (OL/PT), some clay, soft, wet, no plasticity, black, organic odor, no sheen

NOTES: 1. ft = feet 2. Sediment sample collected using Lexan core tube.

MAYFLOWER PIPELINE INCIDENT RESPONSE EXXONMOBIL ENVIRONMENTAL SERVICES COMPANY DOWNSTREAM AREAS DATA ASSESSMENT REPORT

SEDIMENT SAMPLE FIELD PHOTOS: SED-DA-BG-012



