

## **Sheen Monitoring Report #12**

**Monitoring Period:** Daily\* from 01/06/2014 through 01/12/2014 \*Limited sheen monitoring due to icy (2-3 inches of snow/ice) and unsafe ground conditions.

<u>Mitigation:</u> Suspected petrogenic sheens were removed using absorbent materials.

### Observations in Drainage Ways:

- A-Main
  - One patch of metallic sheens; and one patch of metallic/rainbow sheens observed. Sheens broke apart when disturbed ("brittle")<sup>1</sup>.
- A365W
  - No sheens observed.
- A365E
  - No sheens observed.

### Observations in Dawson Cove Inlet Channel:

 One streamer and two patches/streamers of metallic/rainbow sheens, one streamer of metallic/rainbow/silver gray sheens, and one patch/streamer of metallic/silver gray sheens observed. Sheens did not break when disturbed ("non-brittle")<sup>2</sup>.

### Notes:

- 1. Brittle sheens are often of natural biogenic origin.
- 2. Non-brittle sheens are often related to anthropogenic sources, including petrogenic sources (e.g., petroleum hydrocarbons).
- 3. Laboratory testing is required to distinguish sheen sources (e.g., crude oil, roadway runoff, natural biologic activity).
- Sheen color (dark/metallic/rainbow/silver gray) and structure (patches/streamers/cover) terminology reference: NOAA 2007. NOAA Open Water Oil Identification Job Aid.

# Mayflower Pipeline Incident Response

## **Mayflower, Arkansas**

#### Legend:

Green Line – No Sheen
Aqua Circle – "Brittle" Sheen Location
Pink Circle – "Non-Brittle" Sheen Location



Drainage Ways (Summary of Observations from 01/06/2014 through 01/12/2014)



Metallic/Raintow/Silver Gray Sheen Streamer
Observation on 01/10/2014



Dawson Cove Inlet Channel (Summary of Observations from 01/06/2014 through 01/12/2014)



# Mayflower Pipeline Incident Response

## **Sheen Monitoring Report #12 (continued)**

## **Mayflower, Arkansas**

**Monitoring Period:** Daily\* from 01/06/2014 through 01/12/2014 \*Limited sheen monitoring due to icy (2-3 inches of snow/ice) and unsafe ground conditions.

### Observations in Dawson Cove:

· No sheens observed.



Icy Conditions at Dawson Cove on 01/07/2014

## Path Forward for 01/13/2014 to 01/19/2014:

• Continue sheen monitoring in all areas.

#### Legend:

Aqua Circle – "Brittle" Sheen Location
Pink Circle – "Non-Brittle" Sheen Location
OW-1 – Shoreline Observation Location



Dawson Cove (Summary of Observations from 01/06/2014 through 01/12/2014)

### Notes:

- 1. Brittle sheens are often of natural biogenic origin.
- 2. Non-brittle sheens are often related to anthropogenic sources, including petrogenic sources (e.g., petroleum hydrocarbons).
- 3. Laboratory testing is required to distinguish sheen sources (e.g., crude oil, roadway runoff, natural biologic activity).
- Sheen color (dark/metallic/rainbow/silver gray) and structure (patches/streamers/cover) terminology reference: NOAA 2007. NOAA Open Water Oil Identification Job Aid.