

# Mayflower Pipeline Incident Response

## Sheen Monitoring Report #20

Monitoring Period: Daily\* from 03/03/2014 through 03/09/2014 \*Limited sheen monitoring due to unsafe weather conditions.

### Mayflower, Arkansas

Legend: Green Line – No Sheen Aqua Circle – Brittle Sheen Location Pink Circle – Non-Brittle Sheen Location


<u>Mitigation:</u> Suspected petrogenic sheens were removed using absorbent materials.

### Observations in Drainage Ways:

- A-Main
  - Two covers (no particular structure) of silver gray sheens and one cover of metallic/silver gray sheens observed. Sheens broke apart when disturbed ("brittle")<sup>1</sup>.
- A-365W
  - Five covers (no particular structure) of brittle<sup>1</sup> silver gray sheens observed.
- A-365E
  - Two covers (no particular structure) of brittle<sup>1</sup> silver gray sheens observed.

### Observations in Dawson Cove Inlet Channel:


 Two covers (no particular structure) of brittle<sup>1</sup> metallic sheens and one cover of brittle<sup>1</sup> silver gray sheens observed.



Drainage Ways (Summary of Observations from 03/03/2014 through 03/09/2014)



Silver Gray Sheen Cover Observation on 03/08/2014



Dawson Cove Inlet Channel (Summary of Observations from 03/03/2014 through 03/09/2014)

#### Notes:

- 1. Brittle sheens are often of natural biogenic origin.
- 2. Non-brittle sheens are often related to anthropogenic sources, including petrogenic sources (e.g., petroleum hydrocarbons).
- 3. Laboratory testing is required to distinguish sheen sources (e.g., crude oil, roadway runoff, natural biologic activity).
- 4. Sheen color (dark/metallic/rainbow/silver gray) and structure (patches/streamers/cover) terminology reference: NOAA 2007. NOAA Open Water Oil Identification Job Aid.



# Mayflower Pipeline Incident Response

**Mayflower, Arkansas** 

### Sheen Monitoring Report #20 (continued)

# **Monitoring Period:** Daily\* from 03/03/2014 through 03/09/2014 \*Limited sheen monitoring due to unsafe weather conditions.

#### Observations in Dawson Cove:

 Six streamers (two with 0.25-inch wide oil spots) and one patch of non-brittle<sup>2</sup> silver gray sheens; and one patch of non-brittle<sup>2</sup> rainbow/silver gray sheens observed. Sheens did not break when disturbed ("non-brittle")<sup>2</sup>.

#### Legend:

Aqua Circle – Brittle Sheen Location Pink Circle – Non-Brittle Sheen Location Orange Circle – Non-Brittle Sheen with Oil Spot Location OW-1 – Shoreline Observation Location



Silver Gray Sheen Patch Observation on 03/09/2014

### Path Forward for 03/10/2014 to 03/16/2014:

· Continue sheen monitoring in all areas



03/03/2014 through 03/09/2014)



Silver Gray Sheen Streamer Observation on 03/08/2014

#### Notes:

- 1. Brittle sheens are often of natural biogenic origin.
- Non-brittle sheens are often related to anthropogenic sources, including petrogenic sources (e.g., petroleum hydrocarbons).
- 3. Laboratory testing is required to distinguish sheen sources (e.g., crude oil, roadway runoff, natural biologic activity).
- Sheen color (dark/metallic/rainbow/silver gray) and structure (patches/streamers/cover) terminology reference: NOAA 2007. NOAA Open Water Oil Identification Job Aid.