



A R K A N S A S
Department of Environmental Quality

WATER DIVISION COMPLAINT REPORT

AFIN: 41-00002 PERMIT #: AR0002968

COUNTY: 41 Little River PDS #: 019019

GPS LOCATION: LAT: 33.642416 LONG: -94.100819

Discharge Site / General Area / Entrance

COMPLAINANT NAME:

Leon Hood

MAILING ADDRESS:

CITY, STATE, ZIP:

Ashdown AR 71822

PHONE & EXT: / FAX:

870-898-3611 106 /

EMAIL:

RESPONSE REQUESTED BY COMPLAINANT:

No

HOW WAS COMPLAINT RECEIVED BY ADEQ: PHON

ADEQ = ADEQ Personnel | EML = E-Mail | FAX = Fax | LTR = Letter
PERS = Personal Contact | PHON = Telephone | WEB = ADEQ Website

PERSON RECEIVING REPORT:

M. McConnell

DATE:

7/21/2015

SUPERVISOR REFERRAL:

Kerri McCabe

DATE:

7/21/2015

MEDIA SUPERVISOR REFERRAL:

DATE:

RECEIVING INSPECTOR: (ID & Name)

26294 Red Smith

DATE:

7/21/2015

DETAILED DESCRIPTION OF COMPLAINT

From phone conversation:

"The complainant stated that he had received the information from a farmer in the area. The complainant was told that one of the watershed ditches that runs east between section 33 and 34 had a break in it due to the Red River flooding. He stated that he understood that Domtar was in the process of repairing the break, but wanted ADEQ to know so we could keep an eye on it because it was nasty stuff in the ditch."

DETAILED LOCATION

33.584520 -94.102655 Approximately 2.4 miles due south of Domtar's treatment plant.

PREVIOUS COMPLAINTS: Yes DATE(S): **6/19/2015**

FOLLOW-UP ON COMPLAINT

NUMBER OF SITE VISITS: 1 DATES: FIRST **7/21/2015** SECOND THIRD

PHOTOS TAKEN: Yes DISCHARGE TO WATER OF THE STATE: Yes SAMPLES COLLECTED: No

NAME OF WATERBODY: Unknown drainage area going into the Red River.


FAYETTEVILLE SHALE RELATED: No FAYETTEVILLE SHALE VIOLATIONS: No

INVESTIGATION & ACTION TAKEN

I met with Brandon Ayers, Senior Env. Engineer, Domtar A.W. Corporation at approximately 12:30 on 7/21/2015 and explained the complaint. He stated that he had reported the break to ADEQ on 6/19/2015 after the flood waters receded. I had evidence of that report as he copied me. I asked where Domtar was on the repair. He stated that the repair had started in the previous couple of days as it was too wet to get the heavy equipment to the site. We then went to the site and I noted that the break was approximately 40-50 wide. Mr. Ayers stated that the current from the flood flowed perpendicularly across the open canal and washed out the east levee. At that time, Domtar would have to build a crossing big enough for the heavy equipment to access the east-side. He felt that any effluent that flowed from out of the canal at that point would remain on Domtar property till it reached the Red River as Domtar owned the adjacent property.

For further info, see Reconnaissance Inspection dated 7/21/2015.

REFERRED: No	TO WHOM: N/A	DATE REFERRED:
--------------	--------------	----------------

RESPONSE TRACKING		
RESPONSE REQUESTED: No	RESPONSE PROVIDED: ***	RESPONSE PROVIDED DATE:
BY WHOM?(ID and Name):		ASSIGNED TO? (ID and Name):
RESPONSE COMMENT: Investigated; Domtar has reported the levee breach to the ADEQ. No further response.		
INSPECTOR: 	Red Smith	DATE: 7/28/2015
SUPERVISOR: 	Kerri McCabe	DATE: 7/31/2015

Revised: 5/13/2013

Water Division Photographic Evidence SheetLocation: **Domtar A.W. open canal flowing to Red River**Photographer: **Red Smith** Date: **7/21/2015** Time: **1304**Witness: **Brandon Ayers / Senior Env. Engineer, Domtar** Photo #: **1**Description: **Stabilizing a portion of the canal bank that was washed away due to the flood. This site was upstream approximately 300 feet from the levee breach.**Photographer: **Red Smith** Date: **7/21/2015** Time: **1308**Witness: **Brandon Ayers / Senior Env. Engineer, Domtar** Photo #: **2**Description: **The levee breach estimated to be 40 to 50 feet wide.**

Water Division Photographic Evidence Sheet

Location: **Domtar A.W. open canal flowing to Red River (33.584520 -94.102655)**

Photographer: **Red Smith** Date: **7/21/2015** Time: **1308**

Witness: **Brandon Ayers / Senior Env. Engineer, Domtar** Photo #: **3**

Description: **Another view of breach. Some effluent was flowing into the woods.**

