ADEO	WATER DIVISION COMPLAINT REPORT					
ADEU	AFIN: 20-00017		PERMIT #: AR0047503			
	COUNTY: 20) Dalla	ıs	PDS #: 024475		
ARKANSAS Department of Environmental Quality	GPS LOCAT		LAT: 33.076997 LON			
COMPLAINANT NAME:			scharge Site / 🔲 Ge	neral Area / 🗵 Entrance	<u>}</u>	
Anonymous MAILING ADDRESS:			Idaho Timber of Ca	rthage, LLC		
CITY, STATE, ZIP:			322 N Oak Street C	arthage, AR		
			P.O. Box 37			
PHONE & EXT: / FAX:			CITY, STATE, ZIP: Carthage AR 71725			
EMAIL:			PHONE & EXT: / FAX:	_		
RESPONSE REQUESTED BY COMPLAINANT:			870-254-2213 EMAIL:	/ 870-254-2212		
No			jpeaslee@idahotim	ber.com		
HOW WAS COMPLAINT RECEIVED B	Y ADEQ: PHO	N	ADEQ = ADEQ Personnel EML PERS = Personal Contact PHC	= E-Mail FAX = Fax LTR = Letter N = Telephone WEB = ADEQ Website		
PERSON RECEIVING REPORT: Jason Bolenbaugh	DATE: 9/12/20	018	SUPERVISOR REFERRAL: Kerri McCabe		DATE: 9/12/2018	
MEDIA SUPERVISOR REFERRAL:	DATE:	<u> </u>	RECEIVING INSPECTOR: (ID & Name)	ın a	DATE: 9/12/2018	
DI	TAILED DES	CRIP	101531 Michael Yo TION OF COMPLAIN		9/12/2016	
As recorded by J. Bolenbaugh, Brand		OITH	TIOTA OF COMIT EATIN			
	•					
"I spoke to a caller/complainant today						
and discharging to the ditch. He is co know about the layout and if I remem						
as a complaint."	ber correctly	you a	ile lallillal With this	acinity but he did want	iiis takeii	
	DETA	AILED	LOCATION			
See GPS coordinates above.						
PREVIOUS COMPLAINTS: Yes DATE	(S): 9/18/201 5	5				
	FOLLOW	-UP C	N COMPLAINT			
NUMBER OF SITE VISITS: 0 DATES:	FIRST 9/13/2 0)18 SE	COND THIRD			
PHOTOS TAKEN: Yes DISCHAR	RGE TO WAT	ER OF	THE STATE: No	SAMPLES COLLECT	ED: ***	
NAME OF WATERBODY:						
FAYETTEVILLE SHALE RELATED: No			FAYETTEVILLE SH	ALE VIOLATIONS: No		
INVESTIGATION & ACTION TAKEN						
On September 13, 2018 at 15:20, I cor						
Mr. Peaslee stated that there have be						
was unaware of any other compliance talking to other staff.	e issues. ne	State	that he would retur	n my phone call promp	ny arter	
taking to other stan.						
On September 13, 2018 at 15:35, Mr. I						
the wet-deck was valve operated and viewable from the outside of the facility; however, there is no water discharged offsite. I requested he supply a photo of the location and he provided it promptly. Along with the						
photo, the following information was						
drainage ditch that the flush pipe rele						
boundaries of our property and flows back to our retention pond." After viewing the discharge and talking with						
the facility, the complaint referred did	l not warrant	a Rec	onnaissance inspec	tion for unpermitted dis	charges.	
The last Compliance Evaluation Inspe	ection (CEI) o	ondu	cted at this facility w	as February 12, 2013 T	here was a	
reconnaissance inspection performe	d September	25, 20	15 as the result of a	complaint in which sto	rmwater	
compliance issues were documented	This facility	, will I	nave a complete CFI	performed in EV 2018-2	n19	

REFERRED: No

TO WHOM: N/A

DATE REFERRED:

Complaint Report: Idaho Timber of Carthage, LLC, AFIN: 20-00017, Permit #: AR0047503

RESPONSE TRACKING				
RESPONSE REQUESTED: No	RESPONSE PROVIDED: ***		RESPONSE PROVIDED DATE:	
BY WHOM?(ID and Name):		ASSIGN	NED TO? (ID and Name):	
RESPONSE COMMENT: Investigated; permitted activity not in violation of the NPDES permit. No further action required at this time.				
INSPECTOR: Mi	ichael Young		_	DATE: 9/26/2018
SUPERVISOR:	S Coly Kerri McCab	e		DATE: 10/2/2018

Povinced: E/12/2012

Water Division Photographic Evidence Sheet						
Location: Idaho Timber of Carthage, LLC						
Photographer: John Peaslee, General Manager	Date:	09/13/2018	Time:			
Witness:			Photo #:	1		

Description: Photo 1 supplied by John Peaslee.



Photographer: John Peasle	Date:	09/13/2018	Time:	
Witness:			Photo #:	2

Description: Photo 2 supplied by John Peaslee.

