≎EPA

Form Approved OMB No. 2040-0003 Approval Expires 7-31-85

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY									Approval Expires 7-31-85
NPDES Compliance Inspection Report									
Section A: National Data System Coding									
Transaction Code									Pec. Type Inspector Fac Type R
Name and Location of Facility Inspected (For industrial users discharging to POTW, also include POTW name and NPDES permit number) Northwest Arkansas Regional Airport (discharges to City of Bentonville POTW) One Airport Blvd., Suite 100 Bentonville, Arkansas 72712						Ť	Entry Time/Date 1425 / 08-27-10 Exit Time/Date 1445 / 08-27-10		Permit Effective Date March 1, 2009 Permit Expiration Date February 28, 2014
Name(s) of On-Site Representative(s)/Title(s)/Phone and Fax Number(s) No-one present Name, Address of Responsible Official/Title/Phone and Fax Number Steve Keith, Airport Facilities Manager Northwest Arkansas Regional Airport One Airport Blvd., Suite 100 Bentonville, Arkansas 72712							S		ner Facility Data O Location: 36.2966, -94.3032 Inhole before North Lift Station
479-205-1019, 479-790-9929 Section C: Areas Evaluated During Inspection									
(S = Satisfactory, M = Marginal, U = Unsatisfactory, N = Not Evaluated)									
N N	Permit Records/Reports	N N	Flow Measuremer Self-Monitoring P		N N	•	erations & Maintenance dge Handling/Disposal	N N	Sampling Pollution Prevention
N	Facility Site Review	N	Compliance Sched	Nogram Sia			etreatment	N	Multimedia
N	Effluent/Receiving Waters	N	Laboratory				rmwater	N	Other: SSO from satellite system
Section D: Summary of Findings/Comments (Attach additional sheets if necessar								v)	other. 550 irom satemite system
Northwest Arkansas Regional Airport has a waste collection system that currently discharges untreated sewage/waste to the City of Bentonville POTW and is responsible for the operation and maintenance of the collection system. On August 21, 2010, an SSO was discovered at a manhole south of the North Lift Station. The 08/24/10 inspection revealed that remediation of the SSO had not yet been completed. Following the initial inspection, the City of Bentonville assisted with the recovery and disposal of the remaining overfill waste. It was determined during this follow-up inspection that remediation of the impacted area was complete. The conditions observed during this inspection are discussed in the letter addressed to Mr. Keith attached to the 08/24/10 inspection report. Photographs taken during this inspection are included in the 08/24/10 inspection report.									
	ne(s) and Signature(s) of Inspector(s		Agency/Office/Telephone/Fax Arkansas Dept. of Environmental Quality Fayetteville Field Office 479-267-0811, ext. 16					Date 09/17/10	
Sign	nature of Reviewer		Agency/Office/Phone and Fax Numbers					Date	



NPDES Storm Water Construction Site Assessment