

ADEQ

ARKANSAS
Department of Environmental Quality

August 18, 2015

Monty Ledbetter, General Manager
Bryant Water Utilities
1019 S.W. 2nd Street
Bryant, AR 72022

RE: Bryant Water Utilities #10 Inspection
AFIN: 63-00065 Permit No.: AR0034002

Dear Mr. Ledbetter:




On August 6, 2015, I performed a Reconnaissance Inspection of the above referenced facility in accordance with the provisions of the Federal Clean Water Act, the Arkansas Water and Air Pollution Control Act, and the regulations promulgated thereunder. A copy of the inspection report is enclosed for your records.

If I can be of any assistance, please contact me at naus@adeq.state.ar.us or 501-682-0658.

Sincerely,



Chris Naus
District 9 Field Inspector
Water Division

 A R K A N S A S Department of Environmental Quality		WATER DIVISION INSPECTION REPORT				
		AFIN: 63-00065		PERMIT #: AR0034002		DATE: 8/6/2015
		COUNTY: 63 Saline		PDS #: 085913		MEDIA: WN
		GPS LAT: 34.626844 LONG: -92.459359 LOCATION: General Area				
FACILITY INFORMATION			INSPECTION INFORMATION			
NAME: Bryant Water Utilities #10 LOCATION: 2928 Raymar Lane CITY: Bryant, AR			FACILITY TYPE: 1 - Municipal INSPECTOR ID#: 107625 S - State FACILITY EVALUATION RATING: 1 - Unsatisfactory INSPECTION TYPE: Sanitary Sewer Overflow			
RESPONSIBLE OFFICIAL			DATE(S): 8/6/2015 ENTRY TIME: 14:10 EXIT TIME: 14:40 PERMIT EFFECTIVE DATE: 12/1/2014 PERMIT EXPIRATION DATE: 11/30/2019			
NAME / TITLE: Monty Ledbetter / General Manager COMPANY: Bryant Water Utilities MAILING ADDRESS: 1019 S.W. 2nd Street CITY, STATE, ZIP: Bryant AR 72022 PHONE & EXT. / FAX: 501-847-8083 / EMAIL: Imledbetter@sbcglobal.net			INSPECTION PARTICIPANTS			
CONTACTED DURING INSPECTION: No			NAME/TITLE/PHONE/FAX/EMAIL/ETC.: Chris Naus/ADEQ District 9 Water Inspector/ 501-682-0658/naus@adeq.state.ar.us Clark Baker/ADEQ District 9 Water Inspector/501-682-0657/BAKERCLARK@adeq.state.ar.us			
AREA EVALUATIONS						
(S=Satisfactory, M=Marginal, U=Unsatisfactory, N=Not Applicable/Evaluated)						
U	PERMIT	N	FLOW MEASUREMENT	U	STORMWATER	
N	RECORDS/REPORTS	N	LABORATORY	U	FACILITY SITE REVIEW	
U	OPERATION & MAINTENANCE	N	EFFLUENT/RECEIVING WATER	U	SELF-MONITORING PROGRAM	
N	SAMPLING	N	SLUDGE HANDLING/DISPOSAL	N	PRETREATMENT	
U	OTHER: Man Hole Monitoring					
SUMMARY OF FINDINGS						
GENERAL COMMENTS						
During the inspection it was observed that the SSO had not been properly remediated (Pictures 1-3) during the first visit by Bryant Utilities employees. To prevent potential pollution to "Waters of the State" and minimize potential risks to human health, SSO's should be properly contained, removed, and disinfected as soon as they are discovered. Failure to do so could result in violations of State and Federal regulations.						
INSPECTOR'S SIGNATURE: 				Chris Naus		
DATE: 8/13/2015						
SUPERVISOR'S SIGNATURE: 				Jason Bolenbaugh		
DATE: 8/17/2015						

Water Division Photographic Evidence Sheet

Location:	Bryant Water Utilities #10				
Photographer:	Chris Naus	Date:	8/6/2015	Time:	
Witness:				Photo #:	1
Description:					



Photographer:		Date:		Time:	
Witness:				Photo #:	2
Description:					



Water Division Photographic Evidence Sheet

Location:	Bryant Water Utilities #10		
Photographer:		Date:	Time:
Witness:		Photo #:	3
Description:			



Photographer:		Date:	Time:
Witness:		Photo #:	4
Description:			