



ARKANSAS
Department of Environmental Quality

CERTIFIED MAIL: 91 7199 9991 7035 3536 1416

December 8, 2015

James Olive, Owner
James Olive Salvage Yard
39143 Steel Bridge Rd.
Tyronza, AR 72386

RE: James Olive Salvage Yard Inspection
AFIN: 56-00000 Permit No.: ARR000000 - Unpermitted

Dear Mr. Olive:

On October 20, 2015, I performed a follow-up Industrial Stormwater Inspection of the above referenced facility in accordance with the provisions of the Federal Clean Water Act, the Arkansas Water and Air Pollution Control Act, and the regulations promulgated thereunder. A copy of the inspection report is enclosed for your records.


THIS CASE HAS BEEN REFERRED TO THE WATER DIVISION ENFORCEMENT BRANCH DUE TO THE SERIOUSNESS OF THE VIOLATIONS AND THE FAILURE TO RESPOND TO THE PREVIOUS INSPECTION.

Please refer to the "Summary of Findings" section of the attached inspection report and provide a written response for each violation that was noted. You should immediately initiate all actions necessary to resolve and correct the violations cited in the inspection report. Written notification of the corrective actions taken for the violations must be submitted within fifteen (15) calendar days from receipt of this letter to the attention of Richard Healey, Water Division Enforcement Branch Manager, at healeyr@adeq.state.ar.us or mailed to the address at the bottom of this letter. You may contact Richard Healey via telephone at 501-682-0649. This written notification should include, but not be limited to, photographs and copies of other necessary documentation.

If I can be of any assistance, please contact me at walker@adeq.state.ar.us or 870-935-7221 ext.-12.

Sincerely,

Brent L. Walker
District 3 Field Inspector
Water Division



	WATER DIVISION INSPECTION REPORT				
	AFIN: 56-00000	PERMIT #: ARR000000	DATE: 10/20/2015		
	COUNTY: 56 Poinsett	PDS #: 088062	MEDIA: WN		
	GPS LAT: 35.484233 LONG: -90.338308 LOCATION: Entrance				
FACILITY INFORMATION		INSPECTION INFORMATION			
NAME: James Olive Salvage Yard LOCATION: Steel Bridge Rd. CITY: Tyronza		FACILITY TYPE: 2 - Industrial INSPECTOR ID#: 52138 S - State FACILITY EVALUATION RATING: N INSPECTION TYPE: Industrial Stormwater DATE(S): 10/20/2015 ENTRY TIME: EXIT TIME: PERMIT EFFECTIVE DATE: PERMIT EXPIRATION DATE:			
RESPONSIBLE OFFICIAL		INSPECTION PARTICIPANTS			
NAME / TITLE: James Olive / Owner COMPANY: James Olive Salvage Yard MAILING ADDRESS: 39143 Steel Bridge Rd. CITY, STATE, ZIP: Tyronza AR 72386 PHONE & EXT. / FAX: 901-359-0995 / EMAIL:		NAME/TITLE/PHONE/FAX/EMAIL/ETC.: None			
CONTACTED DURING INSPECTION: No					
AREA EVALUATIONS (S=Satisfactory, M=Marginal, U=Unsatisfactory, N=Not Applicable/Evaluated)					
U	PERMIT	N	FLOW MEASUREMENT	U	STORMWATER
N	RECORDS/REPORTS	N	LABORATORY	N	FACILITY SITE REVIEW
N	OPERATION & MAINTENANCE	N	EFFLUENT/RECEIVING WATER	N	SELF-MONITORING PROGRAM
N	SAMPLING	N	SLUDGE HANDLING/DISPOSAL	N	PRETREATMENT
N	OTHER:				
SUMMARY OF FINDINGS					
<p>The following violations were noted:</p> <ol style="list-style-type: none"> The operation of a salvage yard without a permit for the discharge of stormwater associated with industrial activity as defined by 40 CFR 122.26(b)(14)(i-ix, xi). This is a violation of the Federal Clean Water Act and the Arkansas Water and Air Pollution Control Act - A.C.A. §8-4-217 (b)(1). ***This is a repeat violation originally cited during an inspection on May 28, 2015.*** Salvage vehicles were stored in the floodplain adjacent to a wetland area south of Steel Bridge Rd. This violates A.C.A. §8-4-217.(a)(2) Place or cause to be placed any sewage, industrial waste, or other wastes in a location where it is likely to cause pollution of any waters of this state. Failure to provide a written response to the May 28, 2015, inspection by August 19, 2015, as required by the inspection report. The May 28th inspection was discussed with Mr. Olive via telephone on or around August 13, 2015, following his receipt of the inspection report. He was reminded of the need for a written response at that time. <p>A permit application (Notice of Intent), a copy of the permit and other documents are available at: www.adeq.state.ar.us/water/branch_permits/general_permits/stormwater or by calling the Water Division General Permits Section at 501-682-0623.</p>					


GENERAL COMMENTS

Water Division Inspector Sarah Frasher also participated in this inspection.

Inspection was performed in response to additional complaints alleging salvage vehicles were being placed in a wetland area. At the time of the inspection, salvage vehicles were noted adjacent to a wetland area, in the apparent floodplain. Observations were made from Steel Bridge Rd. and adjacent residential properties.

Facility is 3+ acres in size and in excess of 100 vehicles. Additionally vehicles had been stored on the south side of Steel Bridge Rd. adjacent to a wetland area since the May 28, 2015 inspection.

INSPECTOR'S SIGNATURE:  Brent L. Walker	DATE: 12/7/2015
SUPERVISOR'S SIGNATURE:  Jason Bolenbaugh	DATE: 12/8/2015



Water Division Photographic Evidence Sheet

Location:	James Olive Salvage Yard, Steel Bridge Rd., Tyronza, AR				
Photographer:	Brent Walker	Date:	10/20/2015	Time:	1130
Witness:	Sarah Frasher	Photo #:	1		
Description:	Salvage vehicles stored adjacent to wetland area on south side of Steel Bridge Rd.				



Photographer:	Brent Walker	Date:	10/20/2015	Time:	1131
Witness:	Sarah Frasher	Photo #:	2		
Description:	Salvage vehicles stored adjacent to wetland area on south side of Steel Bridge Rd.				



Water Division Photographic Evidence Sheet

Location:	James Olive Salvage Yard, Steel Bridge Rd., Tyronza, AR				
Photographer:	Brent Walker	Date:	10/20/2015	Time:	1131
Witness:	Sarah Frasher	Photo #:	3		
Description:	Salvage vehicles stored adjacent to wetland area on south side of Steel Bridge Rd.				



Photographer:	Brent Walker	Date:	10/20/2015	Time:	1140
Witness:	Sarah Frasher	Photo #:	4		
Description:	Salvage vehicles on north side of Steel Bridge Rd.				



Water Division Photographic Evidence Sheet

Location: James Olive Salvage Yard, Steel Bridge Rd., Tyronza, AR			
Photographer:	Brent Walker	Date:	10/20/2015
Witness:	Sarah Frasher	Time:	1140
		Photo #:	5
Description: Salvage vehicles on north side of Steel Bridge Rd.			



Photographer: Brent Walker			
		Date:	10/20/2015
Witness:	Sarah Frasher	Time:	1141
		Photo #:	6
Description: Salvage vehicles on north side of Steel Bridge Rd.			



Water Division Photographic Evidence Sheet

Location:	James Olive Salvage Yard, Steel Bridge Rd., Tyronza, AR				
Photographer:	Brent Walker	Date:	10/20/2015	Time:	1146
Witness:	Sarah Frasher			Photo #:	7
Description:	Engine in back of salvage pickup truck.				



Photographer:	Brent Walker	Date:	10/20/2015	Time:	1154
Witness:	Sarah Frasher			Photo #:	8
Description:	Salvage vehicles on north side of Steel Bridge Rd.				



Water Division Photographic Evidence Sheet

Location:	James Olive Salvage Yard, Steel Bridge Rd., Tyronza, AR				
Photographer:	Brent Walker	Date:	10/20/2015	Time:	1157
Witness:	Sarah Frasher	Photo #:	9		
Description:	Vehicles and miscellaneous solid wastes near facility entrance.				



Photographer:	Brent Walker	Date:	10/20/2015	Time:	1157
Witness:	Sarah Frasher	Photo #:	10		
Description:	Salvage vehicle on north side of Steel Bridge Rd.				

