	-1	,		,	, -				
	ADEO	WATER	DIVISION INSPECTION REPORT						
AULU			AFIN: 67-00023 PERMIT #: AR002173		733		DATE: 1/4/2017		
Α	RKANSAS	CC	DUNTY: 67 Sevie	r	PDS #	#: 094792	MEDIA: WN		
	partment of Environmental Quality	GF	PS LAT: 34.02608	1 LONG: -94.3473	354 L	OCATION:	ntrance		
FACILITY INFORMATION			INS	SPEC1	TION INFOR	MATION			
City of DeQueen WWTP				FACILITY TYPE: INSPECTOR ID#: 26294 S - State					
LOCATION: 670 South 9 th Street				FACILITY EVALUATION RATING: INSPECTION TYPE: 2 - Marginal SSO/Collection System					
De	Queen			DATE(S): ENT	RY TIME:	EXIT TIME:	PERMIT EFFECTIVE DATE:		
	RESPONSIBLE OFFIC	CIAI			:00	16:00	11/1/2013		
	ET TITLE Chael Sims / WW Superintendent			1/5/2017 13:00 16:30 PERMIT EXPIRATION DATE: 10/31/2018					
COMI	PANY:	-		FAYETTEVILLE SHALE RELATED: N					
	y of DeQueen ng address:			FAYETTEVILLE S	SHALI	E VIOLATIO	NS: N		
_	Box 730					ION PARTI	CIPANTS		
	STATE, ZIP: Queen AR 71832			Mike Sims, WW		intendent			
PHON	NE & EXT: / FAX:			,	•				
870 EMAI	0-642-5231 /								
msims@cityofdequeen.com									
CC	INTACTED DURING INSPECTION:	Ye	s						
	(6.0	-4!-6		LUATIONS	(اد مدمد داد د				
S	PERMIT	N	FLOW MEASUR	isfactory, N=Not Applicable/E REMENT	N	STORMW	ATER		
S	RECORDS/REPORTS	N	LABORATORY		N		LITY SITE REVIEW		
M	OPERATION & MAINTENANCE	N	N EFFLUENT/RECEIVING WATER N SELF-				NITORING PROGRAM		
N	SAMPLING	N	SLUDGE HAND	LING/DISPOSAL	N	PRETREA	TMENT		
N	OTHER:		CUMMADY	AT TIMBINGS					
Th	e Hwy 70 West Lift Station has an	oily		F FINDINGS	SIIITA	for the stat	ion (Refer to nictures		
	3, 4, & 5). This leak is exposed to								
	· · · · · · · · · · · · · · · · · · ·				-		-		
from the inspection conducted on October 16, 2014. Refer to the Permit, Part III, Section B, 1 for a further explanation.									
GENERAL COMMENTS									
<u>A</u> r	A new lift station was installed and put into operation approximately two (2) months prior to this inspection. It								
is	is located approximately 900 feet east (34.045838 -94.315557) of the Hwy 71 East Station (34.046245								
-94.318358). This station is at the entrance to the John Deere Equipment Dealership. This station was added to									
handle the addition of a new business just east of the John Deere Dealership. Since the last inspection, the									
<u>W\</u>	WWTP had posted very good emergency contact information at the lift stations (See picture 1).								
	D. 12 H								
INS	SPECTOR'S SIGNATURE:				DATE: 1/13/2017				
1140	S. ESTORE SIGNATURE.	_	Red Smith				DATE: ITIOIZUIT		
	/an	n R	Heliford						
SU	PERVISOR'S SIGNATURE:		Jas	on Bolenbaugh			DATE: 1/17/2017		



February 13, 2017

Mr. Michael Sims, WW Superintendent City of DeQueen P.O. Box 730 DeQueen, AR 71832

RE: City of DeQueen SSO Inspection

AFIN: 67-00023 Permit No.: AR0021733

Dear Mr. Sims:

I have reviewed the response pertaining to my January 4 and 5, 2017 inspection of the City of DeQueen WWTP. The information provided sufficiently addresses the violations referenced in my inspection report. At this time the Department has no further comment concerning this particular inspection. Acceptance of this response by the Department does not preclude any future enforcement action deemed necessary at this site or any other site.

If we need further information concerning this matter, we will contact you. Thank you for your attention to this matter. Should you have any questions, feel free to contact me at 870-777-7585 or you may e-mail me at smithron@adeq.state.ar.us.

Sincerely,
Poly South

Red Smith


District 7 Field Inspector

Water Division

	,							
COLLECTION SYSTEM INSPECTION AND OVERALL RAT	⊠S □M □U □NA □NE							
PROVIDE A BRIEF DESCRIPTION OF THE COLLECTION SYSTEM: Main > Lift Stations > WWTP								
POPULATION SERVED/NUMBER OF RESIDENTIAL AND COMMERCIAL CONNECTIONS: 6500 residential, 150 commercial, and 1 industrial (Pilgrims Pride Poultry Processing Plant)								
FEET OF SEWER SYSTEM: 190,000 linear feet	· · · · · · · · · · · · · · · · · ·							
AGE OF SYSTEM: 40-50 years								
DOES THE SYSTEM EXPERIENCE PROBLEMS DURING DRY OR WET WEATHER (EXPLAIN): Some I & I during wet weather. Also issues with cooking grease being dumped down household drains. The City has an on-going educational program in place to address this.								
IS THERE A SYSTEM IN PLACE FOR REPORTING SSOS 24 hr. report and in monthly DMR's.	ØY □N □NA □NE							
ARE ALL SSOs REPORTED REGARDLESS OF SIZE:	☑Y □N □NA □NE							
HAVE SSOs REACHED "WATERS OF THE STATE" (LIST [EACH):	□Y ØN □NA □NE							
	· · · · · · · · · · · · · · · · · · ·							
PUMP STATIONS		□S □M □U □NA □NE						
NUMBER OF PUMP STATIONS IN SYSTEM: 5	WER: 5							
HOW OFTEN ARE PUMP STATIONS INSPECTED/MONITORED: daily M-F								
ARE MAINTENANCE RECORDS AND/OR OPERATOR LOGS KEPT: yes, pump run hrs.								
ADEQUATE INVENTORY OF SPARE PARTS: yes								
TYPE OF REMOTE ELECTRONIC MONITORING USED (I.E. SCADA OR AUTO DIALERS): none								
BRIEF SUMMARY OF EMERGENCY PROCEDURES: On SWEPCO's contact list during power outages.								
NUMBER OF PUMP STATIONS VISITED DURING INSPECTION (SEE ATTACHED CHECKLISTS FOR EACH): Two								
SATELLITE SYSTEMS		□S □M □U ØNA □NE						
DOES THE COLLECTION SYSTEM RECEIVE FLOW FROM	M SATELLITE SYSTEMS:							
TYPE(S) OF WASTE WATER RECEIVED: □RESIDENTIAL □COMMERCIAL □INDUSTRIAL □OTHER:								
BRIEFLY DESCRIBE THE SATELLITE SYSTEM:								
ANY KNOWN PROBLEMS WITH SATELLITE SYSTEM:								
NAME, ADDRESS AND PHONE NUMBER OF PERSON RESPONSIBLE FOR SATELLITE SYSTEM:								

PUMP STATION VISIT (COMPLETE A SEPARATE CHECKLIST FOR EACH PUMP STATION VISITED)					
GENERAL INFORMATION AND OVERALL EVALUATION	⊠S □M □U □NA				
NAME AND/OR LOCATION OF PUMP STATION: Hwy 71 East Lift Station (34.046245, -94.318358). Located be the AutoZone Car Parts store.					
TYPE(S) OF WASTE WATER RECEIVED: ☑RESIDENTIAL	☑COMMERCIAL □INDUSTRIA	AL DOTHER:			
NUMBER OF PUMPS: 2 (Submerged)	NUMBER OPERATIONAL: 2				
NUMBER AND SIZE OF PUMPS APPEARS ADEQUATE:		☑S □M □U □NA □NE			
EVIDENCE OF RECENT OVERFLOWS OR HIGH LEVELS:		□Y ØN □NA □NE			
GENERAL OPERATION AND MAINTENANCE		⊠S □M □U □NA			
CLEAN AND WELL MAINTAINED WITH MINIMAL STORAG EQUIPMENT:		⊠S □M □U □NA □NE			
GATES/DOORS/HATCHES/LIDS/ETC. LOCKED TO PREVE ACCESS AND/OR TAMPERING:		⊠S □M □U □NA □NE			
WET WELLS, SUMPS AND PITS ADEQUATELY COVERED PROTECTED:		⊠S □M □U □NA □NE			
ELECTRICAL CONTROLS COVERS CONDUIT AND EQUIP INSTALLED AND MAINTAINED:		⊠S □M □U □NA □NE			
GUARDS AND SHIELDS IN PLACE AROUND MOVING EQUENCES HAFTS, ETC.):	,	⊠S □M □U □NA □NE			
ADEQUATE VENTILATION TO PREVENT EXCESSIVE COL GASES AND FUMES:	NDENSATION AND/OR	⊠S □M □U □NA □NE			
ADEQUATE LIGHTING FOR ROUTINE INSPECTION/MAIN	TENANCE:	☑S □M □U □NA □NE			
SEALS, VALVES AND PACKING ADEQUATELY MAINTAIN	ED TO PREVENT LEAKS:	☑S □M □U □NA □NE			
MINIMAL ACCUMULATION OF GREASE AND SOLIDS IN V	VET WELLS:	⊠S □M □U □NA □NE			
BACKUP POWER AND ALARMS		⊠S □M □U □NA			
PROVISIONS FOR GENERATOR AND/OR EMERGENCY T	RANSFER PUMP:	☑S □M □U □NA □NE			
AUDIBLE/VISUAL ALARM WITH EMERGENCY CONTACT	NFORMATION POSTED:	☑S □M □U □NA □NE			
SCADA SYSTEM (LIST PARAMETERS MONITORED):		□Y □N ☑NA □NE			

PUMP STATION VISIT (COMPLETE A SEPARATE CHECKLIST FOR EACH PUMP STATION VISITED)						
GENERAL INFORMATION AND OVERALL EVALUATION	⊠5	S DM DU DNA				
NAME AND/OR LOCATION OF PUMP STATION: Hwy 71 West Lift Station (34.045250 , -94.366392). Located at the intersection of N Treating Plant Road and Hwy 71 West. Also the entrance to UACCC.						
TYPE(S) OF WASTE WATER RECEIVED: ☑RESIDENTIAL	☑COMMERCIAL □INDUSTRIA	AL DOTHE	ER:			
NUMBER OF PUMPS: 2 (Above ground)	NUMBER OPERATIONAL: 2					
NUMBER AND SIZE OF PUMPS APPEARS ADEQUATE:		⊠S □M	□U □NA □NE			
EVIDENCE OF RECENT OVERFLOWS OR HIGH LEVELS:		□Y	☑N □NA □NE			
GENERAL OPERATION AND MAINTENANCE		S ☑M □U □NA				
CLEAN AND WELL MAINTAINED WITH MINIMAL STORAG EQUIPMENT:		⊠s □m	□U □NA □NE			
GATES/DOORS/HATCHES/LIDS/ETC. LOCKED TO PREVE ACCESS AND/OR TAMPERING:		⊠S □M	□U □NA □NE			
WET WELLS, SUMPS AND PITS ADEQUATELY COVERED PROTECTED:), GRATED OR OTHERWISE	⊠S □M	□U □NA □NE			
ELECTRICAL CONTROLS COVERS CONDUIT AND EQUIF INSTALLED AND MAINTAINED:	PMENT PROPERLY	⊠S □M	□U □NA □NE			
GUARDS AND SHIELDS IN PLACE AROUND MOVING EQUIDRIVESHAFTS, ETC.):	•	⊠s □m	□U □NA □NE			
ADEQUATE VENTILATION TO PREVENT EXCESSIVE COL GASES AND FUMES:	NDENSATION AND/OR	ØS □M	□U □NA □NE			
ADEQUATE LIGHTING FOR ROUTINE INSPECTION/MAIN	TENANCE:	⊠S □M	□U □NA □NE			
SEALS, VALVES AND PACKING ADEQUATELY MAINTAIN	ED TO PREVENT LEAKS:	□S ØM	□U □NA □NE			
MINIMAL ACCUMULATION OF GREASE AND SOLIDS IN V	VET WELLS:	⊠S □M	□U □NA □NE			
BACKUP POWER AND ALARMS		Ø S	S DM DU DNA			
PROVISIONS FOR GENERATOR AND/OR EMERGENCY T	RANSFER PUMP:	□S □M	□U □NA □NE			
AUDIBLE/VISUAL ALARM WITH EMERGENCY CONTACT	INFORMATION POSTED:	⊠S □M	□U □NA □NE			
SCADA SYSTEM (LIST PARAMETERS MONITORED):		□Y	⊠N □NA □NE			





Photographer:Red SmithDate:1/4/2017Time:1514Witness:Mike Sims / WW SuperintendentPhoto #:2

Description: Oil Leak on north side of box at Hwy 71 West Station.




Water Division Photographic Evidence Sheet							
Location:	City	of DeQueen WWTP					
Photographer: Red Smith Date: 1/4/2017 Time: 1514							
Witness: Mike Sims / WW Superintendent					Photo #:	3	
Descriptio	_n . L	Looking at the inside of north side of Hwy 71 West Station. Appears that seals are					
Describing	· · · L	leaking or fluid reservoirs are being overfilled					



Photographer	r: Red Smith	Date:	1/4/2017	Time:	1516
Witness: Mil	ke Sims / WW Superintendent			Photo #:	4

Description:





Cc: Smith, Ronald

Subject: De Queen WWTP inspection response AR0021733, ARR00C398

Date: Friday, January 27, 2017 2:06:45 PM

Attachments: 01010022.JPG

01010025.JPG

Water Division Inspection Branch,

On January 4 & 5 2017 a compliance evaluation inspection was performed at the City of De Queen Wastewater Plant. In the summary of findings Collection System, it was reported that the Hwy 70 West Lift Station had an oily leak and needed to be cleaned and repaired. In the attach pictures you will see that the inside and outside has been cleaned, also in watching the pumps operate no leaking was seen, in talking to the maintenance staff it was found out that when the oil has been changed some will leak out into floor and not cleaned up properly. In the future all excess oil will be captured for disposal and I will keep a better watch on the situation.

If you have any questions please contact me at (870) 642-5231

Michael Sims City of De Queen Arkansas Wastewater Manager



