

February 3, 2017

Greg Holman, Reg. Agents BOTO- AR Properties, LLC 17901 Chenal Parkway Little Rock , AR 72223

RE: Emerald Mountain Inspection AFIN: 63-00820 Permit No.: ARR151435

Dear Mr. Holman:

On January 23, 2017, I performed a Construction Stormwater Inspection of the above referenced facility in accordance with the provisions of the Federal Clean Water Act, the Arkansas Water and Air Pollution Control Act, and the regulations promulgated thereunder. A copy of the inspection report is enclosed for your records.

Please refer to the "Summary of Findings" section of the attached inspection report and provide a written response for each violation that was noted. This case has been referred directly to the Water Division Enforcement Branch for further review. BOTO-AR Properties, LLC should immediately initiate all actions necessary to resolve and correct the alleged violations cited in the inspection report. Written notification of the corrective actions taken for the alleged violations must be submitted immediately upon receipt of this letter to the attention of Richard Healey, Water Division Enforcement Branch Manager, at (501) 682-0649 or healeyr@adeq.state.ar.us. This written notification.

Sincerely,

Keith Waters District 9 Field Inspector Office of Water Quality

CC: Richard Healey, ADEQ Water Enforcement Coordinator, <u>healeyr@adeq.state.ar.us</u> Jackie Trotta, ADEQ Water Enforcement Analyst, <u>trotta@adeq.state.ar.us</u> Inspection Report: Emerald Mountain, AFIN: 63-00820, Permit #: ARR151435

	1 1									
	WATER DIVISION INSPECTION REPORT							PORT		
ADLU		AFIN: 63-00820 PERMIT #: ARR151		14	1435			DATE: 1/23/2017		
ARKANSAS		COUNTY: 63 Saline		Ρ	DS #:	09511	4		MEDIA: WN	
Department of Environmental Quality			GPS LAT: 34.611232 LONG: -92.43		3733 LOCATION: General Area					
	FACILITY INFORMAT	ION		IN			ION IN	FORM	IATIO	N
Emerald Mountain				FACILITY TYPE: 1 - Municipal		INSPECTOR ID#: 97072 S - State				
LOCATION:				FACILITY EVALUATION RATING: INSPECTION TYPE:						
Valley Ridge Drive			1 - Unsatisfactory Construction Stormwater DATE(S): ENTRY TIME: EXIT TIME:							
Alexander, AR				3:0		13:40		PERMIT EI	FFECTIVE DATE:	
	RESPONSIBLE OFFIC	CIAL	-							XPIRATION DATE:
	eg Holman / Reg. Agents								10/31	/2021
COM	PANY:			FAYETTEVILLE SHALE RELATED: N						
	DTO- AR Properties, LLC			FAYETTEVILLE SHALE VIOLATIONS: N						
	901 Chenal Parkway			INSPECTION PARTICIPANTS						
	state, zip: tle Rock AR 72223			NAME/TITLE/PHONE/FAX/EMAIL/ETC.: Keith Waters/ ADEQ Water Inspector/ 501-683-6629						
	TIE ROCK AR / 2223 NE & EXT: / FAX:							Speed		1 000 0025
	1-339-0600 /									
EMAI ah										
gholman@bankozarks.com CONTACTED DURING INSPECTION: No										
			AREA EVA	LUATIONS						
			tory, M=Marginal, U=Unsati	sfactory, N=Not Applicable	e/Eva					
U	PERMIT	N	FLOW MEASUR	REMENT			STOR			
U	RECORDS/REPORTS	N								
U N	OPERATION & MAINTENANCE SAMPLING	N N		RECEIVING WATER			SELF-I			
N	OTHER:	IN	SLUDGE HAND	LING/DISPOSAL		Ν	FREIF			
14	Officia.		SUMMARY C	F FINDINGS						
	 The SWPPP was not in SWPPP box on site in violation of Part II, Section A.3 of the permit. The site map has not been updated to show the current locations of stormwater controls in violation of Part II. Section A 4 5 of your permit. 									
	Part II, Section A.4.F of your permit.									
	3. Inspection reports show signs of BMPs in need of maintenance with a time line to be corrected in 3 business days, but they are still in need of maintenance. This is in violation of Part II, A.4.M of your						acted in 3			
	business udys, but they die	อนแ	III IIEEU UI IIIdilli	CHANCE. 1115 15		violat		ιαιι	u, A.4.	

4. Silt fences, Check dams, and velocity dissipation devices are not properly installed or maintained as required by Part I, Section B.12.A and Part II, Section B.17.A of your permit (see photos 1-5 and 9-12).

permit (see photos 13 and 14).

5. Sedimentation basins are not properly maintained as required by Part II Section A.4.G.1.e and Part II Section B.17.A of your permit (see photos 6-8).

GENERAL COMMENTS

Keith Uster						
INSPECTOR'S SIGNATURE:	Keith Waters	DATE: 1/25/2017				
Clark Ba	Cr_					
SUPERVISOR'S SIGNATURE:	Clark Baker	DATE: 2/2/2017				


Inspection Report: Emerald Mountain, AFIN: 63-00820, Permit #: ARR151435

SECTION I: SITE POSTING AND SITE INFORMATION					
SITE NAME: Emerald Mountain TOTAL ACREAGE: 668 acres ACREAGE DISTURBED: 668acres	<u>6</u>				
LATITUDE:34.611232 LONGITUDE: -92.436733 STARTING DATE: 12/14/2005					
1. Is site posted with Notice of Coverage (NOC)? (Part II, A.2.D)	Ÿ ØN [™] NA [™] NE				
2. Is posting at construction entrance and visible to the public? (Part II, A.2.D)					
3. If project is linear, is posting at area actively under construction? (Part I, B.8.C)	"Y "N "NA "NE				
4. If project is part of larger common plan of development, what is development name and permit numb Development Name: Development Permit No:	er?				
SECTION II: STORMWATER POLLUTION PREVENTION PLAN EVALUATION AND IMPLE	MENTATION				
A. Is the SWPPP being maintained onsite from 08:00 am to 5:00 pm? (Part II, A.2.A)	Ÿ ØN [™] NA [™] NE				
B. Is the SWPPP properly signed as required by Part II, A.2.A of the permit?	Ÿ ØN [™] NA [™] NE				
C. Is the SWPPP being updated as required by Part II, A.3 of the permit?	Ÿ ⊠N [™] NA [™] NE				
D. Site Map in SWPPP (Part II, A.4.F)	Ÿ ⊠n [°] na [°] ne				
1) Pre-construction topographic view (Part II, A.4.F.1);					
2) Direction of stormwater flow (i.e., use arrows to show which direction stormwater will flow) and approximate slopes anticipated after major grading activities (<i>Part II, A.4.F.2</i>);	Y N NA ⊠NE				
3) Delineate on the site map areas of soil disturbance and areas that will not be disturbed under the coverage of this permit (<i>Part II, A.4.F.3</i>)	[™] Y [™] N [™] NA ⊠NE				
4) Location of major structural and nonstructural controls identified in the plan (Part II, A.4.F.4)	Y N NA ⊠NE				
5) Location of main construction entrance and exit (Part II, A.4.F.5)					
6) Location where stabilization practices are expected to occur (Part II, A.4.F.6)					
7) Locations of off-site materials, waste, borrow area, or equipment storage area (Part II, A.4.F.7)					
8) Location of areas used for concrete washout (Part II, A.4.F.8)					
9) Location of all surface waterbodies (including wetlands) (Part II, A.4.F.9)					
10) Locations where stormwater is discharged to a surface water and/or municipal separate storm sewer system if applicable (<i>Part II, A.4.F.10</i>)	¨Υ¨Ν¨ΝΑ ØΝΕ				
11) Locations where stormwater is discharged offsite (should be continuously updated) (Part II, A.4.F.11)	[™] Y [™] N [™] NA ⊠NE				
12) Areas where final stabilization has been accomplished and no further construction phase permit requirements apply (<i>Part II, A.4.F.12</i>)	y na ⊠ne				
E. Stormwater Controls					
1) Are all controls installed as described in the SWPPP? (Part II, A.4.G)	[™] Y ⊠n [™] na [™] ne				
2) Silt fences properly installed and maintained? (Part II, B.17.A)	Ÿ ØN [™] NA [™] NE				
3) Check dams and velocity dissipation devices properly installed and maintained? (Part II, B.17.A)	Ÿ ⊠N [™] NA [™] NE				
4) Sedimentation basins and sediment traps properly installed and maintained (sediment removed when 50% capacity)? (Part II, B.17.A) and (Part II, A.4.G.1.e)	[™] Y ⊠n [™] na [™] ne				
5) Has sediment that has gotten offsite been removed? (Part II, A.4.G.1.d)	Ÿ ØN [™] NA [™] NE				
6) Is construction site entrance sufficiently stabilized to prevent offsite tracking? (Part II, A.4.H.2)	ØY ″N ″NA ″NE				
7) Are stabilization methods described in SWPPP being implemented in a timely manner? (<i>Part II, A.4.G.2</i>)	Y N NA ⊠NE				

Inspection Report: Emerald Mountain, AFIN: 63-00820, Permit #: ARR151435

F. Inspections	
1) Inspection Frequency in SWPPP – " Once every 7 days 214 days and after 1/2 inch rain	n event
1a) If inspection frequency is every 14 days, do they have a rain gauge onsite? (<i>Part II, A.4.L.1.b</i>)	
1b) Is rain gauge properly installed? (nothing obstructing rain gauge) (Part II, B.17.A)	⊠Y ″N ″NA ″NE
2) Are inspection records being maintained onsite? (Part II, A.4.L.3)	
3) Are ADEQ inspection forms being used or do the forms contain the elements required by the permit? (<i>Part II, A.4.L.2</i>)	ØY ″N ″NA ″NE
3a) Inspector Name and Title (Part II, A.4.L.2.a)	⊠y ″n ″na ″ne
3b) Date of Inspection (Part II, A.4.L.2.b)	⊠y ″n ″na ″ne
3c) Amount of Rainfall and Days Since Last Rain Event (only if inspection frequency is 14 days) (<i>Part II, A.4.L.2.c</i>)	ØY ″N ″NA ″NE
3d) Approximate beginning and duration of the storm event (Part II, A.4.L.2.d)	ØY ″N ″NA ″NE
3e) Description of any discharges during inspection (Part II, A.4.L.2.e)	⊠Y ″N ″NA ″NE
3f) Locations of discharges of sediment/other pollutants (Part II, A.4.L.2.f)	⊠y ″n ″na ″ne
3g) Locations of BMPs in need of maintenance or where maintenance was performed (<i>Part II, A.4.L.2.g</i>)	⊠y [°] n [°] na [°] ne
3h) If the BMPs are in working order and if maintenance is required (when scheduled and completed) (<i>Part II, A.4.L.2.h</i>)	ØY ″N ″NA ″NE
3i) Locations that are in need of additional controls (Part II, A.4.L.2.i)	ØY ″N ″NA ″NE
3j) Location and Dates When Major Construction Activities Begin, Occur, or Cease (<i>Part II, A.4.L.2.j</i>)	ØY ″N ″NA ″NE
3k) Report Signature of Inspector (Part II, A.4.L.2.k)	ØY ″N ″NA ″NE
4) Are inspections conducted in accordance with the requirements of the SWPPP? (Part II, A.4.L)	⊠y ″n ″na ″ne
5) Are corrective actions being implemented within 3 business days? (Part II, A.4.M)	Ÿ ØN [™] NA [™] NE
G. Stormwater management	
1) Is solid waste being controlled as described in SWPPP? (Part II, A.4.H.1)	
2) Are stabilized buffer zones being maintained? (25 feet from stream, 50 feet if 303 d, TMDL, ERW, ESW, or NSW) (Part II, A.4.G.2.b)	
3) Have velocity dissipation devices been installed at discharge points, within concentrated flow areas serving two or more acres, and along drainage courses where required to prevent erosive flows? <i>(Part II, A.4.G.3.b)</i>	ØY ″N ″NA ″NE
4) Has silt or sediment gotten off the construction site? A.C.A.§ 8-4-217(a)(2)	⊠y ″n ″na ″ne
5) Has silt and sediment been discharged to the waters of the State? A.C.A.§ 8-4-217(a)(2)	ØY ″N ″NA ″NE
If yes, give the name of the stream or waterbody: Unnamed tributary to Otter Creek	
6) Is the washout of concrete being done at the designated location? (Part II, A.4.F.8)	
7) Does the liquid waste from concrete washout reach the waters of the State? (Part II, A.4.H.5)	ŸN ØNA NE
8) Are fuel storage areas protected as described by SWPPP? (Part II, A.4.H.6)	
9) Have temporary erosion controls been removed from areas finally stabilized? (Part II, A.4.G)	
10) Are there any allowable non-stormwater discharges that have not been addressed in the SWPPP? (<i>Part II, A.4.I</i>)	Ÿ ⊠n [°] na [°] ne
11) Are there any process waters or non-stormwater discharges that are not allowed under the permit being discharged? A.C.A.§ 8-4-217(b)(1)(E)	
12) Does the SWPPP include the required information about employee training (dates of training, records of training, etc.)? (<i>Part II, A.4.N</i>)	





Water Division Photographic Evidence Sheet								
	nerald Mountain							
Photographer		Date: 1/23/2017	Time: N/A					
Witness: N/A	A Erosion gullies behind lots 52 and 5	52 have not had any corrective as	Photo #: 5					
Description:	previous inspections.	55 have not had any corrective ac	situations since my					
Photographer	: Keith Waters	Date: 1/23/2017	Time: N/A					
Witness: N/A Description:	A The sediment basin between lots 33	and 80 is still in need of mainter	Photo #: 6					
	The sediment pash between lots 3	S and 63 is sim in need of manie						





