

CERTIFIED MAIL: 9489 0090 0027 6022 2427 07

October 25, 2017

Pat Sanders, Property Owner Route 1 Box 238 Western Grove, AR 72685

RE: Reconnaissance Inspection (Newton County) AFIN: 51-00000 NPDES Permit No.:

Dear Mr. Sanders:

On August 17 and October 4, 2017, I performed a Reconnaissance Inspection at your farm in accordance with the provisions of the Federal Clean Water Act, the Arkansas Water and Air Pollution Control Act, and the regulations promulgated thereunder. A copy of the inspection report is enclosed for your records.

Please refer to the "Summary of Findings" section of this report and provide a written response for each violation noted. This case has been referred directly to the Enforcement Branch of the Office of Water Quality for further review. Please immediately initiate all actions necessary to resolve and correct the violations cited.

If you have any questions please contact Richard Healey, Enforcement Branch Manager, at 501-682-0649 or <u>healeyr@adeg.state.ar.us</u>.

Sincerely,

5 Quinas

Garrett Grimes District 1 Field Inspector Office of Water Quality

CC: Stacie Wassell, Attorney, ADEQ Legal Division Richard Healey, Enforcement Branch Manager, Office of Water Quality

ADEO			OFFICE OF WATER QUALITY INSPECTION REPORT						
ADEQ		AFIN: 51-00000 PERMIT #:			[DATE: 8/17/2017			
A R K A N S A S		COUNTY: 51 Newto		on	PDS #: 099746			MEDIA: W	
Department of Environmental Quality			GPS LAT: 36.10192 LONG: -93.01016 LOCATION: General Area						
	FACILITY INFORMAT	INSPECTION INFORMATION							
NAME: Pat Sanders LOCATION:				FACILITY TYPE:	104111 5 - State				
Pat Sanders Farm, Newton County Rd 50				FACILITY EVALUATION RATING: INSPECTION TYPE: *** Reconnaissance					
CITY:									
Western Grove, AR					11:14	12:30	PERMIT EF	FECTIVE DATE:	
RESPONSIBLE OFFICIAL				10/04/2017 1	6:40	16:50	PERMIT EX	PIRATION DATE:	
NAME: / TITLE Ret Sandara / Branarty Owner									
Pat Sanders / Property Owner COMPANY:				FAYETTEVILLE SHALE RELATED: N					
				FAYETTEVILLE SHALE VIOLATIONS: N					
Mailing address: Route 1 Box 238				INSPECTION PARTICIPANTS					
CITY, STATE, ZIP:				NAME/TITLE/PHONE/FAX/EMAIL/ETC.:					
Western Grove AR 72685				Pat Sanders/ Property Owner/ 870.577.0478					
PHONE & EXT: / FAX: 870.577.0478 /				Garrett Grimes/ District 1 Inspector/ ADEQ					
EMAI									
CONTACTED DURING INSPECTION: Yes									
AREA EVALUATIONS (S=Satisfactory, M=Marginal, U=Unsatisfactory, N=Not Applicable/Evaluated)									
**	PERMIT	**	FLOW MEASUR			STORMWATER			
**	RECORDS/REPORTS	**	LABORATORY ** FACILITY			SITE REVIEW			
**	OPERATION & MAINTENANCE	**	EFFLUENT/RECEIVING WATER ** SELF-MO			SELF-MON	NITORING PROGRAM		
**	SAMPLING	**	SLUDGE HANDLING/DISPOSAL ** PRETREATMENT						
**	** OTHER:								
SUMMARY OF FINDINGS									
ADEQ arrived on-site on August 17, 2017. Upon arrival swine were observed on the County Road 50 and									

throughout the property (Photos #1 - #3). Water was observed flowing across the property, onto County Road 50, and south towards Cedar Creek (Photos #4 - #9, Figure 1). Water accumulated on the property was observed running off through an area where swine as well as piles of animal waste were located (Photos #2 #10 & #11).

I met with Mr. Pat Sanders, Property Owner, during the inspection. According to Mr. Sanders the property was previously used for approximately 11 years for raising turkeys, but switched to raising swine in August, 2015. Mr. Sanders stated he was having difficulty selling the swine on the farm due to disease and slow growth. Mr. Sanders explained that he had approximately 440 sows, 700 - 800 piglets, 1000 market sized swine, and 1000 feeder sized swine; and, that he did not have enough room in the barns to house all the swine so he allowed them to roam the property and surrounding area.


Mr. Sanders stated that he had a Nutrient Management Plan (NMP) through the Arkansas Natural Resource Commission (ANRC). However, ANRC confirmed the NMP was for the previous turkey operation. According to Mr. Sanders, he had been pushing waste out of the barns onto the surrounding ground because there was not enough room in the barns and verified that the previous observations were of animal waste. Mr. Sanders also stated that there was approximately three feet of manure piled in one of the barns (Photo #12).


I returned to the property on October 4, 2017. Swine were still observed throughout the property and animal waste was still present, but no water was observed running off the property at the time of the inspection (Photos #13 - #15).


Due to the runoff and inability to manage waste generated from your operation, you may be in violation of Arkansas Water and Air Pollution Control Act § 8-4-217(a)(2) which states, "It shall be unlawful for any person to place or cause to be placed any sewage, industrial waste, or other wastes in a location where it is likely to cause pollution of any waters of this state."


You are in violation of Arkansas Water and Air Pollution Control Act § 8-4-217(b)(1)(c) which states, "It shall be unlawful for any person to construct, install, or operate any building, plant, works, establishment, or facility, or any extension or modification thereof, or addition thereto, the operation of which would result in discharge of any wastes into the waters of this state or would otherwise alter the physical, chemical, or biological properties of any waters of this state in any manner not already lawfully authorized." Furthermore, it has been determined that your operation is within the Buffalo National River Watershed. Per Arkansas Pollution Control and Ecology Commission Regulation 5 (Section 5.901) and Regulation 6 (Section 6.602), the Director shall not issue a permit pursuant to either regulation for a Confined Animal Feeding Operation in the Buffalo National River Watershed with: (1) 750 or more swine weighing 55 pounds or more; or, (2) 3,000 or more swine weighing less than 55 pounds.

GENERAL COMMENTS									
1 1									
Ban- Hain									
INSPECTOR'S SIGNATURE: James Seines	Garrett Grimes	DATE: 10/24/2017							
ann Relationag									
SUPERVISOR'S SIGNATURE: Jason Bolent	DATE: 10/24/2017								



















Figure 1: Aerial view of the farm. The black line shown intersects the farm and is the dividing line for the Buffalo National River Watershed (USGS HUC 11010005) and Bull Shoals Lake Watershed (USGS HUC 11010003). The area to the south of the dividing line is the Buffalo National River Watershed and the area to the north of the dividing line is the Bull Shoals Lake Watershed.




Figure 2: Close-up aerial view of the farm and the watersheds.




Figure 3: Aerial view of the farm. The red line is the watersheds dividing line and the area highlighted in yellow is the Buffalo National River Watershed.




Figure 4: Topographic map showing the location of the farm (black dot and coordinates), elevations, watersheds dividing line, and the Buffalo National River Watershed and Bull Shoals Lake Watershed.




Figure 5: Map showing approximate runoff locations (red dots 1-3) from Photos #4 - #9 onto County Road 50. Area inside of the yellow box outlines pig and animal waste locations in Photos #2 & #10. All runoff observed was flowing towards Cedar Creek (blue line) in the Buffalo National River Watershed.

