

March 12, 2018

The Honorable Terry Ott Marion County Judge Ozark Mountain Regional Solid Waste Management District P.O. Box 545 Yellville, AR 72687

RE: Quarterly Inspection conducted on February 27, 2018 AFIN 03-00051 Permit Number 0249-S1-R2

Dear Judge Ott:

The Arkansas Department of Environmental Quality Office of Land Resources (ADEQ) conducted a routine inspection of your facility pursuant to the Arkansas Solid Waste Management Act (Arkansas Code, Annotated, § 8-6-201 <u>et seq</u>.), of 1971, as amended, the Arkansas Pollution Control & Ecology Commission Regulation 22 (Solid Waste Management), and the above-referenced permit. At the time of the inspection, no allegations of noncompliance were noted at your facility. A copy of the inspection report is attached.

If I can be of any further assistance, please do not hesitate to contact me at 501-837-6909 or norton@adeq.state.ar.us.

Sincerely, Dance Monton

Darrell Norton Solid Waste Inspector Office of Land Resources

Attachment

cc: Charles M. Johnson, Senior Manager, Regulated Waste Operations, Office of Land Resources



Arkansas Department of Environmental Quality Office of Land Resources-Solid Waste Management Class 1 Landfill Inspection



Site Name		County	Baxter	AFIN	03-00051
Facility Address	Mountain Home, Hwy 5N to CR16 to site entrance	Phone Number	870-425-3213 870-656-9463	Permit Number	0249-S1-R2
Permittee Address	P.O. Box 1715, Mountain Home, AR, 72602	E-Mail Address			PDS # 101816
Date	2/27/2018	Entry Time	1110	Exit Time	1240
	Regulation 22	– Operationa	l Standards		-
	Ca	tegory 1			
Regulation	Item Description			Comments	
411(l)	Adequate employee facilities	Facility is close	d and not accepting wa	aste. Site currently under close	ure project 9301601R
421(a)(b)	Record keeping meets requirements specified by regulations				
417	Access requirements				
411(j)	Adequate provisions for backup equipment				
421(d)	Waste receipt records, ticket system maintained				
411(k)	Telephone system & written emergency response plan on site				
423(b)	Annual compliance inspection by registered professional enginee	r AEIR has not be	een submitted since 20	13. Site currently under closur	re project 930160R
422	Facility implements operating plan and narrative				
421(f)	Leachate disposal/recirculation records				
421(g),701	Special waste disposal and procedures records				
	Cate	egory 2			
Regulation	Item Description			Comments	
411(a)	Operations in accordance with permit documents				
417(c)	Adequate all weather operational roads				
411(c)	Smallest practical area, unloading supervised, single working fac	xe 🛛			
411(e)	Salvage operations meet approved conditions				
411(f)(1)	Scavenging of waste prohibited				
411(p)	Proper wet weather repairs				
411(b)	Operations by licensed on-site personnel at all times				
411(d)	Waste spread and compacted as unloaded				
411(g)	Litter control provisions maintained				
414(a)	Disease vectors controlled				

					Cate	gory 2	continu	ed)		
	Regulation		Item D	escription						Comments
	427	Surface Wat	er Controls							
	411(h)(1)	Contouring	prevents surface wa	ater flowing into or thro	ough waste					
	418(a)(b)	Run-on/off c	ontrol system prese	ent and adequate						
	411(h)(2)	Surface wate	er control prevents	off-site sediment accum	ulation					
	411(i);427(f)	Adequate ma	aintenance of interr	nediate/final cover vege	etation					
	415	Gas monitor	ing program							
	411(o)	Leachate lea	ks or evidence of le	achate seepage						
	426	Survey contr	cols							
	429	Leachate col	lection system							
	420	Liquid Restr	rictions							
		-			Categ	ory 3				
	Regulation							Comments		
	412	Implementat	tion of hazardous/u	usion plan	sion plan					
	413(a)(b)	Satisfactory	daily/alternative co	ver						
	413(c)	Satisfactory	intermediate cover							
	416(b),411(f)(4)	Open burnir	ng prohibited							
	419	Cause discharge/leachate discharge leaving landfill								
	411(f)(3),419(a)(4)	Depositing w	vaste in standing wa	ter prohibited						
	411(o)	Erosion or o	ther cover defects r	esulting in exposed refu	ise					
	309(c)	Overfill/Off	lined area							
]	Regulati	ion 22	- Reco	ords		
421	l(a)(8), 1203(k)	Date of last g	roundwater monito	ring report	9/27/2017		Site Con	ditions		Damp
	423(b)	Date of last e	ngineering report		9/16/2013		Weather	Condition	s	Sunny
	428		iction in progress	Yes/No No	Notice of li	iner cons		Yes/No	No	Third party CQA on-site during construction Yes/No NA
	412(a)			or unauthorized waste	NA	7		or month	0	C 415(a) Explosive gas records current? Yes/No ves
	415, 421(e)),412(a)(2),701		uarterly methane n pecial waste receive		12/27/2017 10/26/2012		Detection		0 PO	C 415(a) Explosive gas records current? Yes/No yes
421(g)	421(d)		rter waste received	u	10/26/2012 Disposal location None since 12/2012 Tons		location			
	427(c)		r DMR records cur	rent?	Yes/No	12,2012	10115			
Faye	tteville Shale Rela	ted	Yes/No No	Out of Compliance v	with Fayette	eville Sh	ale ^Y	Ves/No No		
_	Dperator Name & Number NA						Signatu	re of Insp		Dance Monton
Exit 1	Interview Conduc	ted with	None]	Method	n/a			Date	n/a Time n/a

Location	NA	BORS	Class 1		Permit	0249-S1-R2	AFIN	03-00051	
Photograp	her	Darrel Waste	ll Norton, ADEQ Solid Inspector	ΣN	Witness	N/A			
Photo #	1	Of	8		Date	2/27/2018	Time	1117	
Description	n	A view	w of the signage and entra	nce to th	e Nabors L	andfill.	-		
						2018.02.27 11:	17		
Location	NA	ABORS	Class 1		Permit	0249-S1-R2	AFIN	03-00051	
Photograp	her		ll Norton, ADEQ Solid Inspector	ΣN	Witness	N/A		1	
Photo #	2		8		Date	2/27/2018	Time	1118	
Description	n	A view	w of the final cover install	ation oc	curring on t	he north slope of A	rea 1-2.		

Inspector Signature: Dance North

Location	NA	BC	ORS C	Class 1			Permit	0249-S1-R2	AFIN	03-00051
Photographer		L V)arrell Vaste	Norton Inspect	, ADEQ Solid or	۵N	Witness	N/A		
Photo #	3		Of	8		-	Date	2/27/2018	Time	1122
Description	l	A	view	⁷ of the r	new leachate tank	farm.				
								2018.02.27 11.2		
Location	NA	ABO	ORS (Class 1		Line Str	Permit	0249-S1-R2	AFIN	03-00051
Photograph	her	L V)arrell Vaste	Norton Inspecto	, ADEQ Solid or	λN	Witness	N/A		
Photo #	4		Of	8			Date	2/27/2018	Time	1125
Description	l	A	view	of the e	east side of Area 1	I-2, rece	eiving final	cover.		
							l.			

Inspector Signature: Dance North

Location	N	AB	ORS C	Class 1			Permit	0249-S1-R2	AFIN	03-00051
PhotographerDarrell Norton, ADEQ Solid Waste InspectorM						Witness	N/A			
Photo #	4	5	Of	8			Date	2/27/2018	Time	1126
Description	1		A view	of the	sedimentation por	nd south	neast of Are	ea 1-2.		
Location Photograph			Darrell	Class 1 Nortor Inspect	h, ADEQ Solid	20	Permit Witness	0249-S1-R2 N/A	AFIN	03-00051
Photo #	(5	Of	8			Date	2/27/2018	Time	1132
Description					east slope of Area	a 1-3 bei		d under the closure		
						14				



NABORS Class 1 0249-S1-R2 Location Permit AFIN 03-00051 Darrell Norton, ADEQ Solid 3N N/A Photographer Witness Waste Inspector Photo # 7 Of 8 Date 2/27/2018 Time 1137 Description A view of the north slope of Area 1-3. 03-00051 Location NABORS Class 1 Permit 0249-S1-R2 AFIN Darrell Norton, ADEQ Solid Photographer ΔN Witness N/A Waste Inspector 8 2/27/2018 1139 Photo # 8 Date Time Of Description An overview of the old borrow site, with the office visible in the background.

Revised 3/1/2017

Inspector Signature: Dance North



Regulated Waste Operations Compliance Branch OFFICE OF LAND RESOURCES ROUTING SLIP

Date: 3/8/2018

Subj: Nabors Landfill – 0249-S1-R2 Q1 2018 – Inspections Report

From: Darrell Norton, ADEQ Solid Waste Inspector

<u>Route in turn to:</u>	Action Needed	Date Received	<u>Date Reviewed</u>	<u>Initials</u>
Ryan Hayden	■Concurrence ■Review	3/8/18	3/8/18	RH
Chris Krou	■Concurrence ■Review			ZH

*Note: Marking the Concurrence box indicates the individual agrees with the applicable text as it relates to their individual discipline and Work Section (e.g., Engineer; Risk Assessor; Geology; Compliance; Policy/Management), as applicable. Marking the Review box indicates the individual has read the document.

COMMENTS: