



September 24, 2018

The Honorable Terry Ott
Marion County Judge
Ozark Mountain Regional Solid Waste Management District
P.O. Box 545
Yellville, AR 72687

RE: Quarterly Inspection conducted on September 14, 2018
AFIN 03-00051
Permit Number 0249-S1-R2

Dear Judge Ott:

The Arkansas Department of Environmental Quality Office of Land Resources (ADEQ) conducted a routine inspection of your facility pursuant to the Arkansas Solid Waste Management Act (Arkansas Code, Annotated, § 8-6-201 *et seq.*), of 1971, as amended, the Arkansas Pollution Control & Ecology Commission Regulation 22 (Solid Waste Management), and the above-referenced permit. At the time of the inspection, no allegations of noncompliance were noted at your facility. A copy of the inspection report is attached.

If I can be of any further assistance, please do not hesitate to contact me at 501-837-6909 or norton@adeq.state.ar.us.

Sincerely,

A handwritten signature in cursive script that reads "Darrell Norton".

Darrell Norton
Solid Waste Inspector
Office of Land Resources

Attachment

cc: Charles M. Johnson, Senior Manager, Regulated Waste Operations, Office of Land Resources



Arkansas Department of Environmental Quality
Office of Land Resources-Solid Waste Management
Class 1 Landfill Inspection



Site Name	NABORS Class 1 Landfill (Closed)	County	Baxter	AFIN	03-00051
Facility Address	Mountain Home, Hwy 5N to CR16 to site entrance	Phone Number	870-425-3213 870-656-9463	Permit Number	0249-S1-R2
Permittee Address	P.O. Box 1715, Mountain Home, AR, 72602	E-Mail Address		PDS #	104585
Date	9/14/2018	Entry Time	1000	Exit Time	1115

Regulation 22 – Operational Standards

Category 1

Regulation	Item Description	Comments
411(l)	Adequate employee facilities	Facility is closed and not accepting waste. Site currently under closure project 9301601R.
421(a)(b)	Record keeping meets requirements specified by regulations	
417	Access requirements	
411(j)	Adequate provisions for backup equipment	
421(d)	Waste receipt records, ticket system maintained	
411(k)	Telephone system & written emergency response plan on site	
423(b)	Annual compliance inspection by registered professional engineer	AEIR has not been submitted since 2013. Site currently under closure project 930160R.
422	Facility implements operating plan and narrative	
421(f)	Leachate disposal/recirculation records	636,000 gallons of leachate hauled 1 st half of 2018. Document #73895 addresses current leachate contract held by Harbor Environmental. Leachate sampling conducted April 18, 2018.
421(g),701	Special waste disposal and procedures records	

Category 2

Regulation	Item Description	Comments
411(a)	Operations in accordance with permit documents	
417(c)	Adequate all weather operational roads	
411(c)	Smallest practical area, unloading supervised, single working face	
411(e)	Salvage operations meet approved conditions	
411(f)(1)	Scavenging of waste prohibited	
411(p)	Proper wet weather repairs	
411(b)	Operations by licensed on-site personnel at all times	
411(d)	Waste spread and compacted as unloaded	
411(g)	Litter control provisions maintained	
414(a)	Disease vectors controlled	

Category 2 (continued)

Regulation	Item Description	Comments
427	Surface Water Controls	
411(h)(1)	Contouring prevents surface water flowing into or through waste	
418(a)(b)	Run-on/off control system present and adequate	
411(h)(2)	Surface water control prevents off-site sediment accumulation	
411(i);427(f)	Adequate maintenance of intermediate/final cover vegetation	
415	Gas monitoring program	
411(o)	Leachate leaks or evidence of leachate seepage	
426	Survey controls	
429	Leachate collection system	
420	Liquid Restrictions	

Category 3

Regulation	Item Description	Comments
412	Implementation of hazardous/unauthorized waste exclusion plan	
413(a)(b)	Satisfactory daily/alternative cover	
413(c)	Satisfactory intermediate cover	
416(b),411(f)(4)	Open burning prohibited	
419	Cause discharge/leachate discharge leaving landfill	
411(f)(3),419(a)(4)	Depositing waste in standing water prohibited	
411(o)	Erosion or other cover defects resulting in exposed refuse	
309(c)	Overflow/Off lined area	

Regulation 22 - Records

421(a)(8), 1203(k)	Date of last groundwater monitoring report	9/27/2017	Site Conditions	Dry			
423(b)	Date of last engineering report	9/16/2013	Weather Conditions	Sunny			
428	Liner construction in progress	Yes/No No	Notice of liner construction	Yes/No No	Third party CQA on-site during construction	Yes/No NA	
412(a)	Date of last random inspection for unauthorized waste	NA	Total # for month	0			
415, 421(e)	Date of last quarterly methane monitoring	12/27/2017	Detection level	0 POC	415(a)	Explosive gas records current?	Yes/No yes
421(g),412(a)(2),701	Date of last special waste received	10/26/2012	Disposal location				
421(d)	Previous quarter waste received	None since 12/2012	Tons				
427(c)	Surface water DMR records current?	Yes/No					

Fayetteville Shale Related	Yes/No No	Out of Compliance with Fayetteville Shale	Yes/No No
Operator Name & Number	N/A		Signature of Inspector <i>Darrell Norton</i>
Exit Interview Conducted with	None	Method	N/A
Date	N/A	Time	N/A

**Arkansas Department of Environmental Quality (ADEQ)
Official Photograph Sheet**

Location	NABORS Class 1			Permit	0249-S1-R2	AFIN	03-00051
Photographer	Darrell Norton, ADEQ Solid Waste Inspector		<i>DN</i>	Witness	N/A		
Photo #	1	Of	6	Date	9/14/2018	Time	1025
Description	A view of the signage and entrance road to the Nabors Landfill.						



Location	NABORS Class 1			Permit	0249-S1-R2	AFIN	03-00051
Photographer	Darrell Norton, ADEQ Solid Waste Inspector		<i>DN</i>	Witness	N/A		
Photo #	2	Of	6	Date	9/14/2018	Time	1029
Description	A view of the leachate panel east of Area 1-2 with the southwest slope of Area 1-3 visible in the background.						



**Arkansas Department of Environmental Quality (ADEQ)
Official Photograph Sheet**

Location	NABORS Class 1			Permit	0249-S1-R2	AFIN	03-00051
Photographer	Darrell Norton, ADEQ Solid Waste Inspector		<i>DN</i>	Witness	N/A		
Photo #	3	Of	6	Date	9/14/2018	Time	1031
Description	A view of the leachate panel and risers on the south slope of Cell 2 in Area 1-3.						



Location	NABORS Class 1			Permit	0249-S1-R2	AFIN	03-00051
Photographer	Darrell Norton, ADEQ Solid Waste Inspector		<i>DN</i>	Witness	N/A		
Photo #	4	Of	6	Date	9/14/2018	Time	1034
Description	A view of the new fenced entrance to the Class 1 site from the Class 4 site. The east slope of Area 1-2 and the sedimentation pond southeast of Area 1-2 are visible.						



Arkansas Department of Environmental Quality (ADEQ) Official Photograph Sheet

Location	NABORS Class 1			Permit	0249-S1-R2	AFIN	03-00051
Photographer	Darrell Norton, ADEQ Solid Waste Inspector		<i>DN</i>	Witness	N/A		
Photo #	5	Of	6	Date	9/14/2018	Time	1039
Description	A view of the leachate tank farm and secondary containment unit.						



Location	NABORS Class 1			Permit	0249-S1-R2	AFIN	03-00051
Photographer	Darrell Norton, ADEQ Solid Waste Inspector		<i>DN</i>	Witness	N/A		
Photo #	6	Of	6	Date	9/14/2018	Time	1044
Description	A view of the leachate tank farm and north slope of Area 1-2.						

