ARKANSAS ENERGY & ENVIRONMENT

ENVIRONMENTAL QUALITY

September 5, 2019

Mr. Heath Lockley BFI Waste Systems of Arkansas, LLC. 18511 W. Sardis Road Bauxite, AR 72011

RE: Quarterly Inspection conducted on August 1, 2019 AFIN 63-00155 Permit Number 0261-S1-R3

Dear Mr. Lockley:

The Arkansas Division of Environmental Quality (DEQ) Office of Land Resources conducted a routine inspection of your facility pursuant to the Arkansas Solid Waste Management Act (Arkansas Code, Annotated, § 8-6-201 *et seq.*), of 1971, as amended, the Arkansas Pollution Control & Ecology Commission Regulation 22 (Solid Waste Management), and the above-referenced permit. The inspection identified conditions at your facility which the ADEQ alleges constitutes violations. A copy of the inspection report is attached.

You should immediately initiate actions to correct the alleged violations cited. A written response of the corrective actions taken, or to be taken, must be submitted within thirty (30) calendar days from the date on this letter to the attention of Kim Davenport. The response may include, but is not limited to, photographs, copies of disposal receipts, records, or analytical results, as applicable. If you have any questions regarding the alleged violations, please do not hesitate to contact me at (501) 682-0586 or <u>davenport@adeq.state.ar.us</u>.

Sincerely,

Kim Davenport Solid Waste Inspector Office of Land Resources

Enclosure

cc: David Witherow P.E., Senior Manager, Office of Land Resources



Arkansas Division of Environmental Quality Office of Land Resources – Solid Waste Management Class 1 Landfill Inspection



Site Name	BFI Waste Systems of Arkansas, LLC.	County	Saline	AFIN	63-00155	
Facility Address	18511 W. Sardis Road, Bauxite, AR 72011	Phone Number	870-946-5583 Heath 501-602-8440 Robert	Permit Number	0261-S1-R3	
Permittee Address	18511 W. Sardis Road, Bauxite, AR 72011	E-Mail Address	hlockley@republicservic		PDS # 109219	
Date	8/1/2019	Entry Time	1001	Exit Time	1143	
	Regulatio	on 22 – Operationa	al Standards			
		Category 1				
Regulation	Item Description			Comments		
411(l)	Adequate employee facilities					
421(a)(b)	Record keeping meets requirements specified by regulation	18				
417	Access requirements					
411(j)	Adequate provisions for backup equipment					
421(d)	Waste receipt records, ticket system maintained					
411(k)	Telephone system & written emergency response plan on si	ite				
423(b)	Annual compliance inspection by registered professional en	ngineer				
422	Facility implements operating plan and narrative					
421(f)	Leachate disposal/recirculation records					
421(g),701	Special waste disposal and procedures records					
		Category 2				
Regulation	Item Description			Comments		
411(a)	Operations in accordance with permit documents					
417(c)	Adequate all weather operational roads					
411(c)	Smallest practical area, unloading supervised, single worki	ng face				
411(e)	Salvage operations meet approved conditions					
411(f)(1)	Scavenging of waste prohibited					
411(p)	Proper wet weather repairs					
411(b)	Operations by licensed on-site personnel at all times					
411(d)	Waste spread and compacted as unloaded					
X 411(g)	Litter control provisions maintained	Litter observed of to Photos #1, #2		nd in the drainage ditch le	ading to the sedimentation pond. (Re-	
414(a)	Disease vectors controlled					

			Cat	tegory 2	2 (continued)						
	Regulation	Item Description					Con	nments			
	427	Surface Water Controls									
	411(h)(1)	Contouring prevents surface water flowing into or throu	igh waste	:							
X	418(a)(b)	Run-on/off control system present and adequate			n-off controls observed from running through					to prevent	t surface
	411(h)(2)	Surface water control prevents off-site sediment accumu	lation		6 6			X * * *			
	411(i);427(f)	Adequate maintenance of intermediate/final cover veget	ation								
	415	Gas monitoring program									
	411(0)	Leachate leaks or evidence of leachate seepage									
	426	Survey controls									
	429	Leachate collection system									
	420	Liquid Restrictions									
			Ca	tegory	3						
	Regulation	Item Description					Con	nments			
	412	Implementation of hazardous/unauthorized waste exclusion	sion plan								
	413(a)(b)	Satisfactory daily/alternative cover									
	413(c)	Satisfactory intermediate cover									
	416(b),411(f)(4)	Open burning prohibited									
	419	Cause discharge/leachate discharge leaving landfill									
	411(f)(3),419(a)(4)	Depositing waste in standing water prohibited									
Х	411(0)	Erosion or other cover defects resulting in exposed refus	e	Expos	Exposed waste observed in the interim cover of Cell 4. (Refer to Photo #4.)						
	309(c)	Overfill/Off lined area									
			Regula	ation 22	2 - Records						
42	21(a)(8), 1203(k)	Date of last groundwater monitoring report	6/18/201	9	Site Conditions		Dry				
	423(b)		3/28/2019		Weather Conditions Overcast						
	428			f liner const		No	Third party C	QA on-site during co	onstruction	/es/No	N/A
	412(a)	*	7/31/2019		Total # for month	5	A1 P(-)	F		Voc/Nc	V
	415, 421(e)		7/31/2019		Detection level		415(a)	Explosive gas recor	ras current?	Yes/No	Yes
421			8/1/2019		Disposal location	Cell 2	2, Zone 2				
	421(d)		49,910 Yes/No		Tons						
Far	427(c) yetteville Shale R	Surface water DMR records current? elated Yes/No Yes Out of Compliance with the second sec		tteville Sh	ale Yes/No No						
гау	Sucone Shale K	Cated Tes Out of Compliance w	in raye	itevine olla							
Ор	erator Name & N	Iumber Spencer Robbins-003765			Signature of Inspe	ector	Xa	p			
Exi	t Interview Cond	ucted with Robert Sanchez M	lethod	In-person		Date	8/1/2019		Time 1120		

Arkansas Division of Environmental Quality Official Photograph Sheet

Location	BF	ΊV	Vaste S	Systems	s of Arkansas, L	LC	Permit	0261-S1-R3	AFIN	63-00155
Photograph	er		Kim Davenport, ADEQ Solid Waste Inspector			Witness	Annette Cusher, ADEQ Engineer Supervisor			
Photo #	1						Date	8/1/2019	Time	1046
Description		1	Northe	ast view	v of litter on the	slope of C	Cell 5.			
Location Photograph]	Kim D	avenpo	of Arkansas, Ll rt, ADEQ 1spector		Permit Witness	0261-S1-R3 Annette Cusher, Supervisor	AFIN ADEQ Eng	63-00155 ineer
Photo #	2		Of	5	Ispector		Date	8/1/2019	Time	1118
Description					d in the drainage	e ditch lea		mentation pond.	Time	1110

Arkansas Division of Environmental Quality Official Photograph Sheet

Location	BFI	Waste	Systems	s of Arkansas, I	LLC	Permit	0261-S1-R3	AFIN	63-00155
Photograph	ner			rt, ADEQ nspector	KQ	Witness	Annette Cusher, Supervisor	ADEQ Eng	ineer
Photo #	3	Of	5		•	Date	8/1/2019	Time	1057
Description	l	Worki	ng face	on the slope of	Cell 2 with	n no run-of	f controls observed	1.	
		1 1 2	The states		The same monthly	a star in the star	and the second s		
		Kim D	avenpo	of Arkansas, L rt, ADEQ		Permit	0261-S1-R3 Annette Cusher,	AFIN ADEQ Eng	63-00155 ineer
Photograph	ner	Kim D Solid V	avenpo Vaste Ir			Witness	Annette Cusher, Supervisor	ADEQ Eng	ineer
Photograph Photo #	her 4	Kim D Solid V Of	avenpor Vaste Ir 5	rt, ADEQ nspector	XQ	Witness Date	Annette Cusher, Supervisor 8/1/2019		
Photograph	her 4	Kim D Solid V Of	avenpor Vaste Ir 5	rt, ADEQ	XQ	Witness Date	Annette Cusher, Supervisor 8/1/2019	ADEQ Eng	ineer

Arkansas Division of Environmental Quality Official Photograph Sheet

Location	BFI	Waste S	System	s of Arkansas,	LLC	Permit	0261-S1-R3	AFIN	63-00155
Photograp	her			rt, ADEQ 1spector	KQ	Witness	Annette Cusher, Supervisor	ADEQ Eng	ineer
Photo #	5	Of	5		•	Date		Time	
Description	n	Litter of	bserve	d on top of Ce	ells 2 & 3.				
						-	¥		
				A The second		Alt of			
			X	· · · · · · · ·	- automation	The second	2.1000	11	
		and the	- 2	A CONTRACTOR					
			and the second	States and the second	Ar.		and the	E E	
			-			And the state	14.6	1	
		C. T.					A AM	NEL.	
				- 7 S.	14. 14. 19. 19. 19. 19. 19. 19. 19. 19. 19. 19		distant and	the second	
		and and					A CARA	1.5	
					Co.				

Blue, Karen

To: Subject: Davenport, Kimberly RE: Reply for quarterly inspection performed 8/1/2019

From: Sanchez, Robert [mailto:RSanchez2@republicservices.com] Sent: Saturday, September 14, 2019 1:54 PM To: Davenport, Kimberly Subject: Reply for quarterly inspection performed 8/1/2019

Good afternoon Kim,

A horseshoe berm is now being used when fill is on slopes. Flagging has been and continue to be picked up at the top deck and more interim cover has been placed on area of cell 4. More cover is being added to all north slopes and storm water berms rebuild. Ditches are being weed and picked. Class 4 has been mowed.

Please let me know if you have any questions. Thank you.

Rober E. Sanchez Operations Supervisor

18511 W Sardis RD 72011 e rsanchez2@republicservices.com o 501-569-3790 c 501-602-8440 w RepublicServices.com

Rec'd Digitally	
AFIN: <u>63-00155</u>	
PMT#: 0261-S1-R3	
RECEIVED By Karen Blue at 7:50 am, Sep 16, 2019	S
DOC ID#: 77020	w M
TO:_RH>FILE <kmb< td=""><td>D</td></kmb<>	D



We'll handle it from here."