

ENVIRONMENTAL

OFFICE OF WATER QUALITY INSPECTION REPORT

AFIN: **67-00023** PERMIT #: **AR0021733** DATE: 5/20/2021

MEDIA: WN COUNTY: 67 Sevier PDS #: 117345

GPS LAT: 34.025964 LONG: -94.347339 LOCATION: Entrance

FACILITY INFORMATION				INSPECTION INFORMATION					
City of DeQueen WWTP			FACILITY TYPE: INSPECTOR ID#: 129177 S - State						
670 South 9 th Street						SSO/	NSPECTION TYPE: SSO/Collection System		
DeQueen			DATE(S): 5/20/2021	ENTRY T		12:		PERMIT EFFECTIVE DATE: 4/1/2020	
	RESPONSIBLE OFFIC	CIAL	_	00					PERMIT EXPIRATION DATE:
	ह / तात्राह ffrey A. Brown / Mayor								3/31/2025
COMPANY:			FAYETTEVILLE SHALE RELATED: N						
City of DeQueen			FAYETTEVILLE SHALE VIOLATIONS: N						
P.O. Box 730			INSPECTION PARTICIPANTS						
CITY, STATE, ZIP:			NAME/TITLE/PHONE/FAX/EMAIL/ETC.:						
DeQueen AR 71832			Wesley Cox / Wastewater Operator Kerri McCabe / DEQ Inspector Supervisor						
870-584-3445 /			Trey Butler / OWQ Inspector						
_	EMAIL:			licy Butien /	O I I Q	1113	pecto		
Ма	Mayor@cityofdequeen.com								
CC	NTACTED DURING INSPECTION	***							
	AREA EVALUATIONS (S=Satisfactory, M=Marginal, U=Unsatisfactory, N=Not Applicable/Evaluated)								
**	PERMIT	**	FLOW MEASUR			**		RMWA	TER
**	RECORDS/REPORTS	**	LABORATORY			**	FACI	LITY S	ITE REVIEW
**	OPERATION & MAINTENANCE	**	EFFLUENT/REG	CEIVING WATE	R	**	SELF	-MON	TORING PROGRAM
**	SAMPLING	**	SLUDGE HAND	LING/DISPOSA	۸L	**	PRE1	ΓREAT	MENT

SUMMARY OF FINDINGS

OTHER: Collection System

GENERAL COMMENTS

I inspected the collection system with the participants listed above on May 20, 2021. We visited three lift stations. The lift stations in the collection system (total of 5) do not have on-site generators, but four lift stations have quick connection hook-up for a portable generator if needed. Mr. Cox monitors the lift stations on a daily basis.

Lift stations inspected include the following:

<u>70 East A Lift Station</u> (located at coordinates 34.046225; -94.318358): This lift station is just behind an AutoZone Auto Parts store. The lift station had a sign with emergency contact information and the light was in working order at the time of inspection. The wet well did not show any signs of solids or grease accumulations.

<u>70 West Lift Station</u> (located at coordinates 34.045231; -94.366398): This lift station is located across the street of University of Arkansas – Cossatot Community College. The lift station had two aboveground pumps that push the wastewater into the force main. The light was in working order and the gate had a sign with emergency contact information in the case of an overflow. The wet well did not show any signs of solids or grease accumulations.

<u>Culter Lift Station</u> (located at coordinates 34.030790; -94.362776): This lift station is located west of DeQueen Middle School. The lift station had emergency contact information and a working emergency overflow light (in working order) in case of any overflows. The wet well had grease and solids built up within it, which Mr. Cox stated they regularly place degreaser within the wet well to break the buildup apart.

claica they regularly place degreeder within the work to break the bandap aparti					
Brittanie Dlayd					
INSPECTOR'S SIGNATURE: Brittanie Gloyd	DATE: 8/21/2021				
Kerri Mª Cale					
SUPERVISOR'S SIGNATURE:Kerri McCabe	DATE: 9/8/2021				

COLLECTION SYSTEM INSPECTION AND OVERALL RATING	□S □M □U □NA □NE					
PROVIDE A BRIEF DESCRIPTION OF THE COLLECTION SYSTEM: Lift stations pumped into the main, which is under force and gravity flow, thence to the WWTP.						
POPULATION SERVED/NUMBER OF RESIDENTIAL AND COMMERCIAL CONNECTIONS: ~6,000						
FEET OF SEWER SYSTEM: <u>Unknown</u>						
AGE OF SYSTEM: Built in the 1930's & 1980's (some has been replaced since).						
DOES THE SYSTEM EXPERIENCE PROBLEMS DURING DRY OR WET WEATHER (EXPLAIN): 1 & I during rain events.						
IS THERE A SYSTEM IN PLACE FOR REPORTING SSOS TO ADEQ (DESCRIBE): Report SSO either by phone, email, or online system						
ARE ALL SSOs REPORTED REGARDLESS OF SIZE:	☑Y □N □NA □NE					
HAVE SSOs REACHED "WATERS OF THE STATE" (LIST DATE AND LOCATION OF EACH):	□Y □N □NA □NE					
PUMP STATIONS	⊠S □M □U □NA □NE					
NUMBER OF PUMP STATIONS IN SYSTEM: 5 NUMBER WITH BACKUP POV connections for a mobile get						
HOW OFTEN ARE PUMP STATIONS INSPECTED/MONITORED: Daily						
ARE MAINTENANCE RECORDS AND/OR OPERATOR LOGS KEPT: Yes – Daily hour logs and monthly checks						
ADEQUATE INVENTORY OF SPARE PARTS: Yes						
TYPE OF REMOTE ELECTRONIC MONITORING USED (I.E. SCADA OR AUTO DIALERS): N/A						
BRIEF SUMMARY OF EMERGENCY PROCEDURES: Shut everything down, pump wastewater into the main system, resolve the issue, report to DEQ if needed, clean/sanitize the area.						
NUMBER OF PUMP STATIONS VISITED DURING INSPECTION (SEE ATTACHED CHECKLISTS FOR EACH): 3						
SATELLITE SYSTEMS	☑S □M □U □NA □NE					
DOES THE COLLECTION SYSTEM RECEIVE FLOW FROM SATELLITE SYSTEMS: Yes (~6 connections)						
TYPE(S) OF WASTE WATER RECEIVED:_ ☑RESIDENTIAL □COMMERCIAL □INDUSTRIAL □OTHER:						
BRIEFLY DESCRIBE THE SATELLITE SYSTEM: Sumps at homes with a grinder pump that pump waste into the main sewer line.						
ANY KNOWN PROBLEMS WITH SATELLITE SYSTEM: None						
NAME, ADDRESS AND PHONE NUMBER OF PERSON RESPONSIBLE FOR SATELLITE SYSTEM: Homeowner						

PUMP STATION VISIT (COMPLETE A SEPARATE CHECKLIST FOR EACH PUMP STATION VISITED)					
GENERAL INFORMATION AND OVERALL EVALUATION	⊠S □M □U □NA				
NAME AND/OR LOCATION OF PUMP STATION: 70 East A Lift Station (Coordinates: 34.046225, -94.318358)					
TYPE(S) OF WASTE WATER RECEIVED: MIRESIDENTIAL	☑COMMERCIAL ☐INDUSTRIA	AL DOTHER:			
NUMBER OF PUMPS:_2	NUMBER OPERATIONAL: 2				
NUMBER AND SIZE OF PUMPS APPEARS ADEQUATE: <u>5</u>	HP grinder pumps	☑S □M □U □NA □NE			
EVIDENCE OF RECENT OVERFLOWS OR HIGH LEVELS:		□Y ☑N □NA □NE			
GENERAL OPERATION AND MAINTENANCE	ØS □M □U □NA				
CLEAN AND WELL MAINTAINED WITH MINIMAL STORAG EQUIPMENT:		⊠S □M □U □NA □NE			
GATES/DOORS/HATCHES/LIDS/ETC. LOCKED TO PREVE ACCESS AND/OR TAMPERING:	⊠S □M □U □NA □NE				
WET WELLS, SUMPS AND PITS ADEQUATELY COVERED PROTECTED:	⊠S □M □U □NA □NE				
ELECTRICAL CONTROLS COVERS CONDUIT AND EQUIF INSTALLED AND MAINTAINED:	PMENT PROPERLY	⊠S □M □U □NA □NE			
GUARDS AND SHIELDS IN PLACE AROUND MOVING EQUIDRIVESHAFTS, ETC.):	UIPMENT (BELTS, PULLEYS,	□S □M □U ☑NA □NE			
ADEQUATE VENTILATION TO PREVENT EXCESSIVE COL GASES AND FUMES:	NDENSATION AND/OR	⊠S □M □U □NA □NE			
ADEQUATE LIGHTING FOR ROUTINE INSPECTION/MAIN	TENANCE:	☑S □M □U □NA □NE			
SEALS, VALVES AND PACKING ADEQUATELY MAINTAIN	ED TO PREVENT LEAKS:	□S □M □U ☑NA □NE			
MINIMAL ACCUMULATION OF GREASE AND SOLIDS IN V	VET WELLS:	☑S □M □U □NA □NE			
BACKUP POWER AND ALARMS		⊠S □M □U □NA			
PROVISIONS FOR GENERATOR AND/OR EMERGENCY T	RANSFER PUMP:	☑S □M □U □NA □NE			
AUDIBLE/VISUAL ALARM WITH EMERGENCY CONTACT	INFORMATION POSTED:	☑S □M □U □NA □NE			
SCADA SYSTEM (LIST PARAMETERS MONITORED):		□Y □N ☑NA □NE			


PUMP STATION VISIT (COMPLETE A SEPARATE CHI	ECKLIST FOR EACH PUMP S	STATION VISITED)
GENERAL INFORMATION AND OVERALL EVALUATION	⊠S □M □U □NA	
NAME AND/OR LOCATION OF PUMP STATION: 70 West Lift Station (Coordinates: 34.045231, -94.366398)		
TYPE(S) OF WASTE WATER RECEIVED: ZRESIDENTIAL	☑COMMERCIAL □INDUSTRIA	AL OTHER:
NUMBER OF PUMPS: 2	NUMBER OPERATIONAL: 2	
NUMBER AND SIZE OF PUMPS APPEARS ADEQUATE: 1	5 HP pumps	☑S □M □U □NA □NE
EVIDENCE OF RECENT OVERFLOWS OR HIGH LEVELS:	□Y ØN □NA □NE	
GENERAL OPERATION AND MAINTENANCE		⊠S □M □U □NA
	E OF LINDEL ATED	M2 LIM LO LINA
CLEAN AND WELL MAINTAINED WITH MINIMAL STORAG EQUIPMENT:	E OF UNRELATED	☑S □M □U □NA □NE
GATES/DOORS/HATCHES/LIDS/ETC. LOCKED TO PREVE ACCESS AND/OR TAMPERING:	NT UNAUTHORIZED	☑S □M □U □NA □NE
WET WELLS, SUMPS AND PITS ADEQUATELY COVERED PROTECTED:	⊠S □M □U □NA □NE	
ELECTRICAL CONTROLS COVERS CONDUIT AND EQUIP INSTALLED AND MAINTAINED:	MENT PROPERLY	☑S □M □U □NA □NE
GUARDS AND SHIELDS IN PLACE AROUND MOVING EQUENCY DRIVESHAFTS, ETC.):	JIPMENT (BELTS, PULLEYS,	☑S □M □U □NA □NE
ADEQUATE VENTILATION TO PREVENT EXCESSIVE COL GASES AND FUMES:	NDENSATION AND/OR	☑S □M □U □NA □NE
ADEQUATE LIGHTING FOR ROUTINE INSPECTION/MAIN	TENANCE:	☑S □M □U □NA □NE
SEALS, VALVES AND PACKING ADEQUATELY MAINTAIN	ED TO PREVENT LEAKS:	ØS □M □U □NA □NE
MINIMAL ACCUMULATION OF GREASE AND SOLIDS IN V	VET WELLS:	☑S □M □U □NA □NE
BACKUP POWER AND ALARMS		⊠S □M □U □NA
PROVISIONS FOR GENERATOR AND/OR EMERGENCY T	RANSFER PUMP:	☑S □M □U □NA □NE
AUDIBLE/VISUAL ALARM WITH EMERGENCY CONTACT	INFORMATION POSTED:	☑S □M □U □NA □NE
SCADA SYSTEM (LIST PARAMETERS MONITORED):		□Y □N ☑NA □NE

PUMP STATION VISIT (COMPLETE A SEPARATE CHECKLIST FOR EACH PUMP STATION VISITED)					
GENERAL INFORMATION AND OVERALL EVALUATION	⊠S □M □U □NA				
NAME AND/OR LOCATION OF PUMP STATION: Culter Lift Station (Coordinates: 34.030790, -94.362776)					
TYPE(S) OF WASTE WATER RECEIVED: MRESIDENTIAL	. COMMERCIAL INDUSTRIA	AL OTHER:			
NUMBER OF PUMPS: 2	NUMBER OPERATIONAL: 2				
NUMBER AND SIZE OF PUMPS APPEARS ADEQUATE: 5	HP pumps	☑S □M □U □NA □NE			
EVIDENCE OF RECENT OVERFLOWS OR HIGH LEVELS:	□Y ØN □NA □NE				
GENERAL OPERATION AND MAINTENANCE		□S ØM □U □NA			
	E OF LINIDEL ATED	LIS MINI LIU LINA			
CLEAN AND WELL MAINTAINED WITH MINIMAL STORAG EQUIPMENT:		☑S □M □U □NA □NE			
GATES/DOORS/HATCHES/LIDS/ETC. LOCKED TO PREVE ACCESS AND/OR TAMPERING:		☑S □M □U □NA □NE			
WET WELLS, SUMPS AND PITS ADEQUATELY COVERED PROTECTED:	☑S □M □U □NA □NE				
ELECTRICAL CONTROLS COVERS CONDUIT AND EQUIP INSTALLED AND MAINTAINED:	ØS □M □U □NA □NE				
GUARDS AND SHIELDS IN PLACE AROUND MOVING EQUIDRIVESHAFTS, ETC.):	□S □M □U ØNA □NE				
ADEQUATE VENTILATION TO PREVENT EXCESSIVE COL GASES AND FUMES:	NDENSATION AND/OR	☑S □M □U □NA □NE			
ADEQUATE LIGHTING FOR ROUTINE INSPECTION/MAIN	TENANCE:	ØS □M □U □NA □NE			
SEALS, VALVES AND PACKING ADEQUATELY MAINTAIN	ED TO PREVENT LEAKS:	□S □M □U ØNA □NE			
MINIMAL ACCUMULATION OF GREASE AND SOLIDS IN V	VET WELLS:	□S ☑M □U □NA □NE			
BACKUP POWER AND ALARMS		⊠S □M □U □NA			
PROVISIONS FOR GENERATOR AND/OR EMERGENCY T	RANSFER PUMP:	⊠S □M □U □NA □NE			
AUDIBLE/VISUAL ALARM WITH EMERGENCY CONTACT	INFORMATION POSTED:	☑S □M □U □NA □NE			
SCADA SYSTEM (LIST PARAMETERS MONITORED):		□Y ☑N □NA □NE			

Office of Water Quality Photographic Evidence Sheet Location: City of DeQueen WWTP Photographer: Brittanie Gloyd Date: 05/20/2021 Time: 11:07 Witness: Kerri McCabe; Trey Butler Photo #: 1 Description: View inside 70 East A Lift Station wet well.



Photographer: Brittanie Gloyd	Date:	05/20/2021	Time:	11:10
Witness: Kerri McCabe; Trey Butler			Photo #	: 2








City of DeQueen WWTP Photographer: Brittanie Gloyd Date: 05/20/2021 Time: 11:21 Witness: Kerri McCabe; Trey Butler Photo #: 5 Description: Overview of the 70 West Lift Station.



Photographer:Brittanie GloydDate:05/20/2021Time:11:29Witness:Kerri McCabe; Trey ButlerPhoto #:6





Inspection Report: City of DeQueen WWTP, AFIN: 67-00023, Permit #: AR0021733 Office of Water Quality Photographic Evidence Sheet Location: City of DeQueen WWTP Photographer: Brittanie Gloyd Date: 05/20/2021 11:31 Time: Witness: Kerri McCabe; Trey Butler Photo #: Description: Overview of the Culter Lift Station. 05/20/2021 11:31

Figure 1. Google Earth aerial imagery dated Jan 23, 2015 showing the location of lift stations inspected.

