



July 1, 2022

Joanna Oneal, Controller Drew Foam Companies Inc. 1093 Hwy 278 East Monticello, AR 71655 Via email to: joneal@drewfoam.com

RE: Drew Foam Companies Inc. Inspection (Drew Co) AFIN: 22-00057 NPDES Permit No.: ARR000817

Dear Ms. Oneal:

On April 21, 2022, I performed an Industrial Stormwater Inspection of the above referenced facility in accordance with the provisions of the Federal Clean Water Act, the Arkansas Water and Air Pollution Control Act, and the regulations promulgated thereunder. A copy of the inspection report is enclosed for your records.

Please refer to the "Summary of Findings" section of the inspection report and provide a written response for each item that was noted. This response should be mailed to the attention of the Office of Water Quality Compliance Branch at the address below my signature or emailed to <u>Water-Inspection-Report@adeq.state.ar.us</u>. This response should contain documentation describing the course of action taken to correct each item noted. The corrective action(s) should be completed as soon as possible and the written response with all necessary documentation (i.e., photos) is due by <u>July 21, 2022</u>.

If I can be of any assistance, please contact me at <u>Trey.Butler@adeq.state.ar.us</u> or (501) 231-0062.

Sincerely,

B

Trey Butler Inspector, Office of Water Quality 5301 Northshore Drive, North Little Rock, AR, 72118

A SHI DEAR YOUR	OFFICE OF WATER QUALITY INSPECTION REPORT				
	AFIN: 22-00057 PERMIT #: ARR000817		0817	DATE	4/21/2022
OL AND ENVIRON	COUNTY: 22 Drew		PDS #: 1208	837	MEDIA: WN
	GPS LAT: 33.62824	7 LONG: -91.769	367 LOCAT	ION: Genera	I Area
FACILITY INFORMAT	ION		SPECTION I	NFORMATIC	DN
Drew Foam Companies Inc.		FACILITY TYPE: 2 - Industrial	INSPECTOR ID#: 141737 S -		
1093 HWY 278 East		FACILITY EVALUATION RATIN	G:	INSPECTION TYPE:	Stormwater
Monticello			ITRY TIME: EXIT . 0:00	TIME: PERMIT	EFFECTIVE DATE:
RESPONSIBLE OFFIC				PERMIT	EXPIRATION DATE:
Joanna Oneal / Controller					/2024
		INSPECTION PARTICIPANTS			
Drew Foam Companies Inc.		Cody Ballinger/ Maintenance Manager/ 870-209-4988/			
1093 Hwy 278 East		cballinger@drewfoam.com			
city, state, zip: Monticello AR 71655		Ben White/Maintenance Supervisor/ 870-723-4235/ bwhite@drewfoam.com			
PHONE & EXT: / FAX:		Joanna Oneal/ Controller/ 870-853-6575/			
870-853-6575 / EMAIL:		joneal@drewfo	am.com		
joneal@drewfoam.com					
CONTACTED DURING INSPECTION	Yes				
SUMMARY OF FINDINGS					
The following violations were noted at the time of inspection:					
 Housekeeping practices not implemented on east-side of facility. This includes excess garbage and scattered foam produced in the facility. This is a violation of Part 3.1.2 of the general permit. Facility Site Map was not included with the SWPPP. This is a violation of Part 4.2.3 of the general permit. 					

3) Documentation of Routine and Comprehensive facility inspections were not maintained. This is a violation of Part 4.2.6.3 of the general permit.

GENERAL COMMENTS

On April 21, 2022, I performed an inspection of the above-mentioned facility's IGP. The facility is covered under Section Y2 of the general permit, which includes the manufacturing of miscellaneous plastic products. Specifically, this facility manufactures polystyrene foam products.

Site Assessment:

I arrived at the above-mentioned site at approximately 10:00 on April 21, 2022, and I was met by a Ms. Joanna Oneal. I was then introduced to a Mr. Cody Ballinger and Mr. Ben White, who escorted me to the office where the facility SWPPP and other documents were held. After a records review, Mr. White began the facility tour, where we began at the southeast portion of the building onsite. It was noticed at this point that there was excess garbage built up in the area, mostly in or around uncovered dumpsters. We then traveled towards the northeast portion of the property, where there was a large amount of foam scattered on the ground near a large waste container. Some of this foam, which was produced in the facility, had washed into a nearby drainage to Outfall 003. We then traveled around the north-side of the facility to Outfall 002. This outfall serves the northwest portion of the property and it had some litter present. Mr. White then showed to me Outfall 001, which serves the southwest portion of the property. The actual location of the outfall is at the southwest corner of the parking lot to the west of the facility. It was discussed that this would be corrected using an Outfall Modification form, which can be found in the link included below. Finally, we traveled to Outfall 004, which was once the drainage for a parking lot on the east-side of the property. This parking lot is no longer in use and it has plenty of natural vegetation present.

https://www.adeq.state.ar.us/water/permits/npdes/stormwater/pdfs/outfall_modification_form.pdf

Records Review:

The facility SWPPP and SWAR were available for review. However, the SWPPP did not include a site map or quarterly and comprehensive inspection records. There was only record of a visual inspection conducted in December 2021. Mr. White did inform me that he does regular inspections, but he has not kept an official record of them.

1-SB			
INSPECTOR'S SIGNATURE: Trey Butler	DATE: 5/25/2022		
Kerri M' Cale			
SUPERVISOR'S SIGNATURE:Kerri McCabe	DATE: 6/30/2022		

Inspection Report: Drew Foam Companies Inc., AFIN: 22-00057, Permit #: ARR000817

Inspection Form Legend: S-Satisfactory, M-Marginal, U-Unsatisfactory, Y-Yes, N-No, NI-Not Implemented, NA-Not A If Y and a NI are checked it means it is in the SWPPP but not implemented in the field which is a violation.					
SECTION A: SWPPP & SITE MAP REVIEW	"S	М	Ü	"NA	" NE
1. Is the SWPPP available for review by ADEQ (Part 4.4)?	ØΥ	N	NI	NA	" NE
A. If yes, when was the SWPPP last updated? August 2019					
 Does the SWPPP identify specific individuals or positions as members of the Pollution Prevention Team, and does it outline the responsibilities of each team member (Part 4.2.2)? 	ØY	N	" NI	" NA	" NE
A. If yes, are the team members and positions current?	Ø۲	N	" NI	NA	" NE
3. Is the facility Site Map available for review (Part 4.2.3)?		ØΝ	" NI	" NA	" NE
A. If yes, does the site map contain the following items, if applicable?	•				
i. The size of the property.	Y	N	NI	⊠NA	" NE
ii. The location and extent of significant structures and impervious surfaces.		Ν	" NI	⊠NA	" NE
iii. The direction of stormwater flow (ex. use of arrows, topographical maps).		N	NI	⊠NA	" NE
iv. The locations of all existing structural control measures.		N	NI	⊠NA	" NE
v. The locations of all receiving waters in the immediate vicinity of the facility.			NI	⊠NA	" NE
vi. The locations of all stormwater conveyances including ditches, pipes, and					
swales.	Ϋ́	Ν	NI	⊠NA	" NE
vii. The locations of potential pollutant sources.	Y	Ν	" NI	⊠NA	" NE
viii. Locations of all stormwater monitoring points.	Y	N	NI	⊠NA	" NE
ix. The locations of stormwater inlets and outfalls.		Ν		⊠NA	" NE
 Where the stormwater discharges to Municipal Separate Storm Sewer System (MS4). 		N	" NI	⊠NA	" NE
 The locations and descriptions of allowable non-stormwater discharges identified in the SWPPP. 	Y	" N	NI	⊠NA	" NE
xii. The locations of the following activities if they are exposed to precipitation.		N	NI	⊠NA	" NE
a. Fueling Stations		Ν	" NI	⊠NA	" NE
b. Vehicle and equipment maintenance and/or cleaning areas	Y	N	NI	⊠NA	" NE
c. Loading and unloading areas	Y	N	NI	⊠NA	" NE
d. Locations used for the treatment, storage, or disposal of waste		Ν	NI	⊠NA	" NE
e. Liquid storage tanks		N	NI	⊠NA	" NE
f. Processing and storage areas		N		⊠NA	NE
 g. Immediate access roads and rail lines used or traveled by carriers of raw materials, manufactured products, waste materials, or byproducts used or created by the facility. 	" Y	N		⊠NA	" NE
h. Transfer areas for substances in bulk		Ν	" NI	⊠NA	" NE
 Locations of storage piles containing salt used for deicing or other commercial or industrial purposes. 	" Y	N	NI	⊠NA	" NE
xiii. The locations and sources of run-on to the site from adjacent property that contains significant quantities of pollutants (Part 4.2.3.13)?	" Y	" N	" NI	⊠NA	" NE
4. Does the stormwater discharge from the facility enter a waterbody that is listed on the most recently approved 303(d) list or has an approved TMDL?	₫Y	" N	NI	NA	" NE
A. If yes, provide the name of the waterbody. Bayou Bartholomew					
5. Does the SWPPP address one or more of the measures listed in Part 4.2.7.1.1 – 4?	Ø۲	N	NI	NA	" NE
A. If yes, describe the measures identified in the SWPPP. Pollutant not present at faci	ity				
6. Does the stormwater from the facility directly discharge to an ERW, NSW, or ESW?	Ø۲	N	NI	NA	" NE
A. If yes, provide the name of the waterbody.					
B. Does the SWPPP document the name of the listed waterbody and the approximate distance between the outfall and the listed waterbody?		N	NI	⊠NA	" NE
i. If yes, provide the approximate distance between the waterbody and the outfa	ll(s) (Pa	rt 4.2	.7.2.1).	
C. Does the SWPPP incorporate additional BMPs needed to prevent to the maximum extent practicable exposure of pollutants to stormwater that could potentially impact water quality?		N	" NI	⊠NA	" NE
i. If yes, describe each BMP that is implemented.					

ECTION B: MONITORING, INSPECTIONS, and RECORD KEEPING	" S	М	ΨU	"NA	" NE
. Provide the Sector/Sub-Sector listed for the facility. <u>Y2</u>			•		
. How many permitted outfalls are identified in the SWPPP? 4					
. Are any outfalls considered similar?	٧	N	NI	NA	NE
. Are samples being collected from the location(s) specified in the permit?					
. Is the sample location(s) suitable for the collection of representative samples?					" NE
A. If no, describe why the sample location(s) is not suitable.		IN	111	INA	INL
 Please list the benchmark parameters that are required to be sampled for under the Sec. 	tor/Sub-S	octor	2 n H	тее	
. Are all benchmark parameters being sampled and analyzed at least annually (Part 3.4)?		"N		" NA	NE
. Was all collected benchmark parameter samples properly preserved and analyzed (Part 3.4)					
3.8.2.5)?	ØΥ	"N	" NI	" NA	" NE
Did sampling reveal any exceedances of benchmark parameters?		⊠N	" NI	NA	" NE
A. If yes, was a process to develop a Corrective Action Plan started within 30 days of					
the exceedance(s)(Part 3.11.1)?				⊠NA	" NE
B. If yes, was the exceedance attributed to a natural background pollutant level?		"N		⊠NA	Ü NE
i. If yes, has the Department been notified?	Y	N	NI	⊠NA	" NE
0. Are at least 4 visual site inspections conducted annually (Part 5.1.1)?		⊠N		" NA	" NE
B. If yes, do the inspections include the following:			" NI	⊠NA	" NE
i. Date of the inspection		N	NI	⊠NA	NI
ii. Personnel conducting the inspection		ΠN	" NI	⊠NA	" NI
iii. Major observations		"N	NI	⊠NA	" NE
iv. Summary of actions taken as a result of the inspection		ΠN	" NI	⊠NA	" N
C. Did at least one inspection occur during a period when stormwater was discharging (Part 5.1)?	Y	N	" NI	⊠NA	NI
i. If yes, provide the date when the inspection occurred.					
1. Was a Comprehensive Site Compliance Evaluation conducted each year (Part 5.1.2)?		⊠N	" NI	" NA	" NI
A. If yes, provide the date when the inspection occurred.					
2. Was a Storm Water Annual Report (SWAR) for the previous monitoring period(s)	МY	N	NI	 NA	NE
completed?					
A. If yes, is the information provided on the SWAR accurate?	ØΥ	<u> </u>		<u> </u>	" NE
B. If yes, is the SWAR signed by the Responsible Official or Cognizant Official?	ØY		<u> </u>	" NA	" NE
3. Is the permittee retaining all records according to Part 5.2 of the permit?	ØY	" N	NI	" NA	" NE
Comments: Only records of one visual site inspection performed in Dec. 2021 available at time of ECTION C: FACILITY TOUR	-		<u></u>		
. Are the number and location of all outfalls accurate as described in the permit, SWPPP,					
and site map?	Y	⊡N	NI	" NA	" NI
. Are there any allowable non-stormwater discharges that are not identified in the SWPPF	• ¨Y	⊠N	" NI	" NA	N
Are there any non-stormwater discharges occurring that are not allowed in the permit?		⊠N		NA	" NI
				⊠NA	
. Has notification been given to the EPA or DEQ of any new, different, or increased					INI
discharges?		ΪN	" NI	" NA	NI
discharges? Are all discharges from this facility permitted, both stormwater and non-stormwater?					NI
 discharges? Are all discharges from this facility permitted, both stormwater and non-stormwater? Is there evidence of spills or leaks that have not been properly remediated as required b the SWPPP? 	v	⊠N	" NI	NA	INI
 discharges? Are all discharges from this facility permitted, both stormwater and non-stormwater? Is there evidence of spills or leaks that have not been properly remediated as required b the SWPPP? Is there evidence of erosion occurring or are there areas where the ground is not stabilized? 	^у "ү			NA "NA	
 discharges? Are all discharges from this facility permitted, both stormwater and non-stormwater? Is there evidence of spills or leaks that have not been properly remediated as required b the SWPPP? Is there evidence of erosion occurring or are there areas where the ground is not 	у ү ү ү	ØΝ	" NI " NI		NI


Comments:


OUTFALL VISUAL INSPECTION REPORT				
IS THIS A PERMITTED OUTFALL? \boxtimes Y \Box N				
OUTFALL LOCATION: <u>33.629374°, -91.771335°</u>	PHOTO NUMBER: 8			
OUTFALL DESCRIPTION: Outfall 001				
1. Does the outfall match the location in the SWPPP and or Site Map? \Box Y \Box N				
2. Does the outfall discharge from one of the following?: \Box Pond \Box Sheet flow \Box Ditch \boxtimes Other (Explain): <u>Culvert</u>				
3. If discharging from a pond is there a control structure in place? $\Box Y \Box N \boxtimes NA$				
4. Is the outfall considered similar to another outfall? $\boxtimes Y \Box N$				
A. If yes, which outfall(s) is/are considered similar? Outfalls 002, 003, 004				
5. What are the potential pollution sources in the drainage area? Common litter				
6. Are the BMPs associated with the outfall appropriate? $\boxtimes Y \square N$				
7. Does run-on from adjacent properties drain to this outfall? $\Box Y \boxtimes N$				
8. Are any exceedances at this outfall attributed to natural background levels? \Box Y \boxtimes N				
VISUAL OBSERVATION				
1. Was a discharge occurring at the time of inspection? $\Box Y \boxtimes N \Box NA$				
2. Discharge water flow color: □Clear □Turbid □Oil Sheen □Soapy/Foamy □Other	(Explain)			
3. Are odors present at the outfall? \Box Y \boxtimes N				
4. Are allowable non-stormwater discharges occurring near the outfall? $\Box Y \boxtimes N$				
5. Is the outfall suitable for the collection of representative samples? $\Box Y \Box N \boxtimes NA$				
6. Is there evidence of pollution occurring at the outfall? $\Box Y \boxtimes N$				
7. Is there excessive erosion occurring at the outfall? $\Box Y \boxtimes N$				
Comments:				

OUTFALL VISUAL INSPECTION REPORT	
IS THIS OUTFALL PERMITTED? ⊠Y □N	
OUTFALL LOCATION: <u>33.631129°, -91.770146°</u>	PHOTO NUMBER: <u>7</u>
OUTFALL DESCRIPTION: Outfall 002	
9. Does the outfall match the location in the SWPPP and or Site Map? \Box Y \Box N	
10. Does the outfall discharge from one of the following?: \Box Pond \Box Sheet flow \Box Ditch	⊠ Other (Explain): <u>Culvert</u>
11. If discharging from a pond is there a control structure in place? \Box Y \Box N \boxtimes NA	
12. Is the outfall considered similar to another outfall? $\boxtimes Y \Box N$	
B. If yes, which outfall(s) is/are considered similar? Outfalls 001, 003, 004	
13. What are the potential pollution sources in the drainage area? Common litter	
14. Are the BMPs associated with the outfall appropriate? $\boxtimes Y \Box N$	
15.Does run-on from adjacent properties drain to this outfall? \Box Y \boxtimes N	
16. Are any exceedances at this outfall attributed to natural background levels? $\Box Y \boxtimes N$	
VISUAL OBSERVATION	
8. Was a discharge occurring at the time of inspection? $\Box Y \Box N \Box NA$	
9. Discharge water flow color: Clear Turbid Oil Sheen Soapy/Foamy Other	r (Explain):
10. Are odors present at the outfall? $\Box Y \boxtimes N$	
11. Are allowable non-stormwater discharges occurring near the outfall? $\Box Y \boxtimes N$	
12. Is the outfall suitable for the collection of representative samples? $\boxtimes Y \square N \square NA$	
13.1s there evidence of pollution occurring at the outfall? $\boxtimes Y \Box N$	
14. Is there excessive erosion occurring at the outfall? $\Box Y \boxtimes N$	
Comments:	
Some litter present.	

OUTFALL VISUAL INSPECTION REPORT	
IS THIS OUTFALL PERMITTED? XY IN	
OUTFALL LOCATION: <u>33.629435°, -91.766982°</u>	PHOTO NUMBER: <u>9</u>
OUTFALL DESCRIPTION: Outfall 004	
17.Does the outfall match the location in the SWPPP and or Site Map? \Box Y \Box N	
18.Does the outfall discharge from one of the following?: \Box Pond \Box Sheet flow \Box Ditch	□ Other (Explain):
19. If discharging from a pond is there a control structure in place? \Box Y \Box N \Box NA	
20.Is the outfall considered similar to another outfall? $\boxtimes Y \Box N$	
C. If yes, which outfall(s) is/are considered similar? Outfalls 001, 002, 003	
21. What are the potential pollution sources in the drainage area? Common litter	
22. Are the BMPs associated with the outfall appropriate? \Box Y \Box N	
23. Does run-on from adjacent properties drain to this outfall? \Box Y \boxtimes N	
24. Are any exceedances at this outfall attributed to natural background levels? $\Box Y \boxtimes N$	
VISUAL OBSERVATION	
15. Was a discharge occurring at the time of inspection? $\Box Y \boxtimes N \Box NA$	
16.Discharge water flow color: Clear Turbid Oil Sheen Soapy/Foamy Other	r (Explain):
17.Are odors present at the outfall? \Box Y \boxtimes N	
18. Are allowable non-stormwater discharges occurring near the outfall? $\Box Y \boxtimes N$	
19. Is the outfall suitable for the collection of representative samples? \Box Y \Box N \boxtimes NA	
20.1s there evidence of pollution occurring at the outfall? $\Box Y \boxtimes N$	
21.Is there excessive erosion occurring at the outfall? □Y ⊠N	
Comments:	







Inspection Report:	Drew Foam Companies Inc.	, AFIN: 22-00057, Permit #	: ARR000817

	of Water Quality Photographic Evidence She	
Location: Drew Foam Comp		
Photographer: Trey Butler	Date: 4/21/2022	Time: 11:12
Witness: Ben White	· · ·	Photo #: 7
Description: Outfall 002		
	104. ⁻ 21-20	22414-12
Photographer: Trey Butler	Date: 4/21/2022	Time: 11:15
Witness: Ben White Description: Outfall 001		Photo #: 8

	Office of Water Quality Ph	notographic Evidence Sheet	
Location:	Drew Foam Companies Inc.		
	oher: Trey Butler	Date: 4/21/2022	Time: 11:23
	Ben White		Photo #: 9
Descriptio	n: Southeast corner of unused parkin	g lot; showing drainage to Ou	tfall 004.
		Carl Rolling and the	A CONTRACTOR
	ALL		现在 医尿 异
		Constant and and and a second	
		No 1/2 - Alexand	and the second
			and a second second
	N SIN STATISTICS		
			No. of States
			Same Berl
			and the second second
		A	
	Contraction of the second second		
			T South the
		04 21 2022 1	T 28
		の学生などの問題のでの	NO AND

From:	Butler, Trey
То:	<u>Marshall, Uniqika</u>
Cc:	McCabe, Kerri
Subject:	FW: Drew Foam Monticello Storm Water Follow Up
Date:	Tuesday, September 6, 2022 12:59:37 PM
Attachments: Response to 4-21 Inspection.docx	
	Stormwater Inspection Form.docx
	image003.png
	image004.png
	image005.png
	image006.png
	image007.png

Uniqika,

Can you please add this response to PDS 120837 (ARR000817)?

Thank you,

Trey Butler | Inspector Division of Environmental Quality | Office of Water Quality Compliance Branch 2215 W Hillsboro Street | El Dorado, AR 71730 c: 501.231.0062 | e : Trey.Butler@adeq.state.ar.us



From: Cory Balthrop [mailto:cbalthrop@hunt-sol.com] Sent: Tuesday, September 6, 2022 10:50 AM To: Butler, Trey Subject: RE: Drew Foam Monticello Storm Water Follow Up

Mr. Butler,

Attached is a digital copy of our official response to your inspection findings. Please let me know if you require a physical copy sent by mail as well.

Reach out with any questions you may have.

Thanks,

Cory Balthrop MS CSP

Director – Environmental, Health & Safety Foam Holdings, Inc. Desk: 615-510-2060 ext.112 Cell: 563-949-9620 Email: <u>cbalthrop@hunt-sol.com</u>



The content of this email is confidential and intended for the recipient specified in message only. It is strictly forbidden to share any part of this message with any third party, without a written consent of the sender. If you received this message by mistake, please reply to this message and follow with its deletion, so that we can ensure such a mistake does not occur in the future.

From: Cory BalthropSent: Friday, August 26, 2022 2:22 PMTo: Trey.Butler@adeq.state.ar.usSubject: Drew Foam Monticello Storm Water Follow Up

Mr. Butler,

I'm writing you in reference to the attached inspection report and request for corrective action. I apologize for our late response as this was communicated to the incorrect individual so it did not reach me in a timely manner.

I am meeting with the onsite operations team on 8/30/22 to review and compile our updates to you. I target having a summarized report by the end of the week.

Again, I apologize for this delay and I assure you it was not intentional.

If you have any questions please let me know.

Thanks,

Cory Balthrop MS CSP Director – Environmental, Health & Safety Foam Holdings, Inc. Desk: 615-510-2060 ext.112 Cell: 563-949-9620 Email: <u>cbalthrop@hunt-sol.com</u>



The content of this email is confidential and intended for the recipient specified in message only. It is strictly forbidden to share any part of this message with any third party, without a written consent of the sender. If you received this message by mistake, please reply to this message and follow with its deletion, so that we can ensure such a mistake does not occur in the future.





Cory Balthrop Director, Environmental Health & Safety Foam Holdings Inc. 6 Cadillac Drive Brentwood, TN 37027 Office: 615-510-2060 ext. 112 Mobile: 563-949-9620 Email: <u>cbalthrop@hunt-sol.com</u>

September 6, 2022

Trey Butler Inspector Office of Water Quality 5301 Northshore Drive North Little Rock, AR 72118

Subject: Follow Up to Drew Foam Companies Inc. Inspection (Drew Co)

Dear Mr. Butler

This letter addresses observations you made during your stormwater inspection on April 21, 2022 at the Drew Foam location in Monticello AR. The onsite team has been working diligently to address each of your concerns and I have outlined the corrective measures taken so far, and what is currently being implemented.

Corrective Action #1

Housekeeping practices not implemented on east-side of facility. This includes excess garbage and scattered foam produced in the facility. This is a violation of Part 3.1.2 of the general permit

Improvement photos on next page:



Corrective Action #2

Violation #2: Facility Site Map was not included with the SWPPP. This is a violation of Part 4.2.3 of the general permit.

Corrective Action: Facility map has been added to site SWPPP. Annual review to occur to ensure compliance is maintained.

Corrective Action #3

Violation #3: Documentation of Routine and Comprehensive facility inspections were not maintained. This is a violation of Part 4.2.6.3 of the general permit.

Corrective Action: Quarterly inspection requirements have been communicated to onsite teams and will be properly documented moving forward.

Corrective Actions Summary:

As mentioned above, all requested corrective actions have been completed or are in the process of implementation. Additionally, the unit has addressed the suggestions for improvement as part of their overall response. I have also attached as an appendices their Weekly Stormwater Inspection form. This is used by the facility to ensure all the corrective actions taken are maintained and sustainable moving forward.

Please feel free to contact me with any questions or concerns you may have.

Thanks,

Cory Balthrop Director, Environmental Health & Safety

WEEKLY STORMWATER INSPECTION FORM

Inspector: _____

DATE: _____

Loading docks	Notes:
Perimeter	Notes:
Fence line	Notes:
Storm drains	Notes:
Waste bins	Notes:





September 19, 2022

Joanna ONeal, Controller Drew Foam Companies, Inc. 1093 Hwy 278 East Monticello, AR, 71655 Via email to: joneal@drewfoam.com

RE: Drew Foam Co - Response to Inspection (Drew Co) AFIN: 22-00057 NPDES Permit No.: ARR000817

Dear Ms. ONeal:

I have reviewed the response pertaining to my April 12, 2022 inspection of Drew Foam Companies, Inc. facility. The information provided sufficiently addresses the items referenced in my inspection report. At this time, the Division has no further comment concerning this particular inspection. Acceptance of this response by the Division does not preclude any future enforcement action deemed necessary at this site or any other site.

If I require further information concerning this matter, I will contact you. Thank you for your attention to this matter. Should you have any questions, please contact me at (501) 231-0062 or you may email me at <u>Trey.Butler@adeq.state.ar.us</u>.

Sincerely,

Trey Butler Inspector, Office of Water Quality 5301 Northshore Drive, North Little Rock, AR, 72118