



ARKANSAS ENERGY & ENVIRONMENT

08/15/2022

Mr. Robert Hendrix
Craighead SWDA
P.O. Box 16777
Jonesboro, AR 72403

RE: Inspection conducted on August 3, 2022
AFIN 16-00199
Permit Number 0254-S1-R4

Dear Mr. Hendrix,

The Arkansas Division of Environmental Quality Office of Land Resources (DEQ) conducted a routine inspection of your facility pursuant to the Arkansas Solid Waste Management Act (Arkansas Code, Annotated, § 8-6-201 *et seq.*), of 1971, as amended, the Arkansas Pollution Control & Ecology Commission Regulation 22 (Solid Waste Management), and the above-referenced permit. The inspection identified conditions at your facility which the DEQ alleges constitutes violations. A copy of the inspection report is attached.

You should immediately initiate actions to correct the alleged violations cited. A written response of the corrective actions taken, or to be taken, must be submitted within thirty (30) calendar days from the date on this letter to the attention of Tobin Baker. The response may include, but is not limited to, photographs, copies of disposal receipts, records, or analytical results, as applicable. If you have any questions regarding the alleged violations, please do not hesitate to contact me at (501) 837-2097 or bakert@adeq.state.ar.us.

Sincerely,

A handwritten signature in cursive script that reads 'Tobin Baker'.

Tobin Baker
Solid Waste Inspector
5301 Northshore Drive, North Little Rock, AR 72118-5317

Enclosure

cc: Scott McWilliams, Senior Compliance Manager, Regulated Waste Operations



ARKANSAS
ENERGY & ENVIRONMENT

**Office of Land Resources
Regulated Waste Operations
Class 1 Landfill Inspection Form**

Site Name	Craighead County SWDA Class 1	County	Craighead	AFIN	16-00199
Facility Address	238 CR 476 Jonesboro, AR 72404	Phone #	870-972-6353	Permit #	0254-S1-R4
Permittee Address	P.O. Box 16777, Jonesboro AR 72403	Email Address	rhendrix@ccswda.com	PDS #	121348
Date	8/3/2022	Entry Time	0930	Exit Time	1145

Operational Standards

Category 1

	Regulation	Item Description	Comments
	417	Access Requirements	
	411(j)	Adequate Provision for Backup Equipment	
	423(b)	Annual Compliance Inspection by Registered Engineer	

Category 2


	Regulation	Item Description	Comments
	411(a)	Operations in Accordance with Permit Documents	
	411(c)	Smallest Practical Area, Unloading Supervised, Single Working Face	
	411(b)	Operations by Licensed On-site Personnel at All Times	
	411(g)	Litter Control Provisions Maintained	
	427	Surface Water Controls	
	411(h)(1)	Contouring Prevents Surface Water Flowing Into or Through Waste	
	418(a)(b)	Run-on/off Control System Present and Adequate	
	411(h)(2)	Surface Water Control Prevents Off-site Sediment Accumulation	
	411(i)	Adequate Maintenance of Intermediate/Final Cover Vegetation	
	415	Gas Monitoring Program	
X	411(o)	Leachate Leaks or Evidence of Leachate Seepage	Leachate leaks observed on the west slope of Cell 2. (Refer to Photo #2.)
	429	Leachate Collection System	

Category 3

	Regulation	Item Description	Comments
X	413(a)(b)(c)	Satisfactory Daily/Alternate/Intermediate Cover	Exposed waste observed on the west slope of Cell 2. (Refer to Photo #3.)
	419(a)(5)	Cause Discharge/Leachate Leaving Landfill	
	411(f)(3)	Depositing Waste in Standing Water Prohibited	
X	411(o)	Erosion or Other Cover Defects Resulting in Exposed Refuse	Erosion with exposed waste observed on the west slope of Cell 2. (Refer to Photo #1.)
	309(c)	Overfill/Off Lined Area	

Records

Date of Last Annual Report	3/30/2022	Date of Last Quarterly Methane Monitoring	5/19/2022
Date of Last Groundwater Monitoring Report	7/15/2022	Previous Quarter Waste Received	Class 1- 28,715.56 Class 4-11,959.14

Operator Name & Number	Robert Hendrix 00336	Signature of Inspector					
Exit Interview Conducted with	Robert Hendrix/David Passmore	Method	On-site	Date	8/3/2022	Time	1140

Division of Environmental Quality Official Photograph Sheet

Location	Craighead County SWDA Class 1				Permit	0254-S1-R4		AFIN	16-00199		
Photographer	Tobin Baker, Inspector				<i>TB</i>	Witness	N/A				
Photo #	1	Of	3		Date	8/3/2022		Time	1035		
Description	Erosion with exposed waste observed on the west slope of Cell 2.										
											
Location	Craighead County SWDA Class 1				Permit	0254-S1-R4		AFIN	16-00199		
Photographer	Tobin Baker, Inspector				<i>TB</i>	Witness	N/A				
Photo #	2	Of	3		Date	8/3/2022		Time	1059		
Description	Leachate leaks observed on the west slope of Cell 2.										
											

Division of Environmental Quality Official Photograph Sheet

Location	Craighead County SWDA Class 1				Permit	0254-S1-R4	AFIN	16-00199
Photographer	Tobin Baker, Inspector		TB		Witness	N/A		
Photo #	3	Of	3		Date	8/3/2022	Time	1101
Description	Exposed waste observed on the west slope of Cell 2.							
								