



ARKANSAS

ENERGY & ENVIRONMENT

3/16/2023

Mr. Blake Small
Eco-Vista, LLC
2210 Waste Management Drive
Springdale, AR 72762

RE: Q1 Follow-up #5 conducted on March 13, 2023
AFIN 72-00144
Permit Number 0290-S1-R3

Dear Mr. Small,

The Arkansas Division of Environmental Quality Office of Land Resources (DEQ) conducted a routine inspection of your facility pursuant to the Arkansas Solid Waste Management Act (Arkansas Code, Annotated, § 8-6-201 *et seq.*), of 1971, as amended, the Arkansas Pollution Control & Ecology Commission Regulation 22 (Solid Waste Management), and the above-referenced permit. The inspection identified conditions at your facility which the DEQ alleges are violations. A copy of the inspection report is attached.

You should immediately initiate actions to correct the alleged violations cited. A written response of the corrective actions taken, or to be taken, must be submitted within thirty (30) calendar days from the date on this letter to the attention of Jason Gilkey. The response may include, but is not limited to, photographs, copies of disposal receipts, records, or analytical results, as applicable. If you have any questions regarding the alleged violations, please do not hesitate to contact me at (501) 993-7188 or jason.gilkey@adeq.state.ar.us.

Sincerely,

A handwritten signature in black ink that reads 'Jason C. Gilkey'.

Jason Gilkey
Solid Waste Inspector
5301 Northshore Drive, North Little Rock, AR 72118-5317

Enclosure

cc: Scott McWilliams, Senior Compliance Manager, Regulated Waste Operations



ARKANSAS
ENERGY & ENVIRONMENT

**Office of Land Resources
Regulated Waste Operations
Class 1 Landfill Inspection Form**

Site Name	Eco-Vista Class 1 Landfill	County	Washington	AFIN	72-00144
Facility Address	2210 Waste Management Drive, Springdale, AR 72762	Phone #	870-510-0174	Permit #	0290-S1-R3
Permittee Address	2210 Waste Management Drive, Springdale, AR 72762	Email Address	bsmall@wm.com	PDS #	125009
Date	03/13/2023	Entry Time	0437	Exit Time	0918

Operational Standards

Category 1

Regulation	Item Description	Comments
417	Access Requirements	
411(j)	Adequate Provision for Backup Equipment	
423(b)	Annual Compliance Inspection by Registered Engineer	

Category 2


Regulation	Item Description	Comments
411(a)	Operations in Accordance with Permit Documents	
411(c)	Smallest Practical Area, Unloading Supervised, Single Working Face	
411(b)	Operations by Licensed On-site Personnel at All Times	
411(g)	Litter Control Provisions Maintained	
427	Surface Water Controls	
411(h)(1)	Contouring Prevents Surface Water Flowing Into or Through Waste	
418(a)(b)	Run-on/off Control System Present and Adequate	
411(h)(2)	Surface Water Control Prevents Off-site Sediment Accumulation	
411(i)	Adequate Maintenance of Intermediate/Final Cover Vegetation	
415	Gas Monitoring Program	
411(o)	Leachate Leaks or Evidence of Leachate Seepage	
429	Leachate Collection System	

Category 3

Regulation	Item Description	Comments
413(a)	Satisfactory Daily Cover	
419(a)(5)	Cause Discharge/Leachate Leaving Landfill	
411(f)(3)	Depositing Waste in Standing Water Prohibited	
X 411(o)	Erosion or Other Cover Defects Resulting in Exposed Refuse	Depressions and exposed waste caused by a truck used for hauling cover material were observed in the daily cover across the tops of Cells 10 & 11. (Refer to Photos #1 & #2.)
309(c)	Overfill/Off Lined Area	

Records

Date of Last Annual Report	3/31/2022	Date of Last Quarterly Methane Monitoring	11/16/2022
Date of Last Groundwater Monitoring Report	02/23	Previous Quarter Waste Received	109,062.21

Operator Name & Number	Don Tennison 2769	Signature of Inspector				
Exit Interview Conducted with	Don Tennison	Method	On-site	Date	3/13/2023	Time 0910

Division of Environmental Quality Official Photograph Sheet

Location	Eco-Vista Class 1 Landfill				Permit	0290-S1-R3	AFIN	72-00144
Photographer	Jason Gilkey, Inspector			JEG	Witness	N/A		
Photo #	1	Of	2		Date	03/13/23	Time	0821
Description	Depressions and exposed waste caused by a truck used for hauling cover material were observed in the daily cover across the tops of Cells 10 & 11.							



Location	Eco-Vista Class 1 Landfill				Permit	0290-S1-R3	AFIN	72-00144
Photographer	Jason Gilkey, Inspector			JEG	Witness	N/A		
Photo #	2	Of	2		Date	03/13/23	Time	0821
Description	Depressions and exposed waste caused by a truck used for hauling cover material were observed in the daily cover across the tops of Cells 10 & 11.							

