



3/21/2023

Mr. Blake Small Eco-Vista, LLC 2210 Waste Management Drive Springdale, AR 72762

RE: Inspection Follow-up #6 conducted on March 14, 2023 AFIN 72-00144 Permit Number 0290-S1-R3

Dear Mr. Small,

The Arkansas Division of Environmental Quality Office of Land Resources (DEQ) conducted a routine inspection of your facility pursuant to the Arkansas Solid Waste Management Act (Arkansas Code, Annotated, § 8-6-201 <u>et seq.</u>), of 1971, as amended, the Arkansas Pollution Control & Ecology Commission Regulation 22 (Solid Waste Management), and the above-referenced permit. The inspection identified conditions at your facility which the DEQ alleges are violations. A copy of the inspection report is attached.

You should immediately initiate actions to correct the alleged violations cited. A written response of the corrective actions taken, or to be taken, must be submitted within thirty (30) calendar days from the date on this letter to the attention of Tobin Baker. The response may include, but is not limited to, photographs, copies of disposal receipts, records, or analytical results, as applicable. If you have any questions regarding the alleged violations, please do not hesitate to contact me at (501) 837-2097 or <u>bakert@adeq.state.ar.us</u>.

Sincerely,

Jobin Booker

Tobin Baker Solid Waste Inspector 5301 Northshore Drive, North Little Rock, AR 72118-5317

Enclosure

cc: Scott McWilliams, Senior Compliance Manager, Regulated Waste Operations

A CONTROL OF		CKANSAS GY & ENVIRONMENT OF Class 1 Landfil	aste	Operation					
C:+	e Name	Eco-Vista Class 1 Landfill			Washington	A FINI	72-00144		
	cility Address	2210 Waste Management Drive, Springdale, AR 72762	Phor	V	870-510-0174	AFIN Permit #	0290-S1-R3		
	mittee Address		-	il Address	bsmall@wm.com	Permit #	125041		
		2210 Waste Management Drive, Springdale, AR 72762 03/14/2023	v Time	0950	Exit Time	123041			
Dat	le		v	0930	Exit Time	1349			
		Operation							
	Demalation		egory	· 1	C				
	Regulation	Item Description			Comme	nts			
	417 411(j)	Access Requirements Adequate Provision for Backup Equipment							
	411(J) 423(b)	Adequate Provision for Backup Equipment Annual Compliance Inspection by Registered Engineer							
	423(0)	Annual Compliance Inspection by Registered Engineer							
		Cat	egory	2					
	Regulation	Item Description	~8°-J	Comments					
	411(a)	Operations in Accordance with Permit Documents							
	411(c)	Smallest Practical Area, Unloading Supervised, Single Working	Face						
	411(b)	Operations by Licensed On-site Personnel at All Times							
	411(g)	Litter Control Provisions Maintained							
	427	Surface Water Controls							
	411(h)(1)	Contouring Prevents Surface Water Flowing Into or Through W	aste						
	418(a)(b)	Run-on/off Control System Present and Adequate							
	411(h)(2)	Surface Water Control Prevents Off-site Sediment Accumulation	n						
	411(i)	Adequate Maintenance of Intermediate/Final Cover Vegetation							
	415	Gas Monitoring Program							
Х	411(0)	Leachate Leaks or Evidence of Leachate Seepage		Leachate leaks v and the west slop	vere observed on the west slope o be of Cell 12. (Refer to Photos #1,	f Cell 5, the north and , #2 & #5 - #7.)	east slopes of Cell 8,		
	429	Leachate Collection System							
		Cat	egory	3					
	Regulation	Item Description	Comments						
	413(a)	Satisfactory Daily Cover							
	419(a)(5)	Cause Discharge/Leachate Leaving Landfill							
	411(f)(3)	Depositing Waste in Standing Water Prohibited							
Χ	411(0)	Erosion or Other Cover Defects Resulting in Exposed Refuse			l exposed waste caused by a tru laily cover across the top of Cells				
	309(c)	Overfill/Off Lined Area							

Records										
Date of Last Annual Report	3/31/2022	Date of Last Quarterly Methane Mon	nitoring	11/16/2022						
Date of Last Groundwater Monitoring F	Report 02/23	Previous Quarter Waste Received	Previous Quarter Waste Received 109,062.21							
Operator Name & Number	Don Tennison 2769	Signature of Inspector	(Jobin Bookor	S E					
Exit Interview Conducted with	Don Tennison	Method On-site Da	ate 3/14/	/2023 Ti	me	1340				

Location Ec	co-Vi	ista C	lass 1 L	andfill		Permit	0290-S1-R3	AFIN	72-00144
Photographer	Т	obin I	3aker, I	nspector	TB	Witness	N/A		
Photo #	1	Of	7			Date	3/14/2023	Time	1034
Description	L	eacha	te leaks	were observed	on the we	st slope of (Cell 12.		
	the base of the second s								
	1		lass 1 L		Ch	Permit	0290-S1-R3	AFIN	72-00144
Photographer				nspector	TB	Witness	N/A	I	
Photo # 2 Description	2	Of	7	were observed	41	Date	3/14/2023	Time	1046
		ł	E					3	

Location	Eco	-Vista Cla	ass 1 La	andfill		Permit	0290-S1-R3	AFIN	72-00144
Photograph	ner	Tobin B	aker, In	spector	TB	Witness	N/A		
Photo #	3	Of	7			Date	3/14/2023	Time	1059
Description	1			exposed waste as the top of Ce			for hauling cover ma	aterial were	e observed in the
Location	Eco	-Vista Cla	ass 1 La	andfill		Permit	0290-S1-R3	AFIN	72-00144
Photograph	ner	Tobin B	aker, In	spector	TB	Witness	N/A		
Photo #	4	Of	7			Date	3/14/2023	Time	1059
Description	1			exposed waste ss the top of Ce			for hauling cover ma	aterial were	e observed in the

Location	Ecc	o-V	vista C	lass 1 I	Landfill		Permit	0290-S1-R3	AFIN	72-00144
Photograph	er	Т	obin l	bbin Baker, Inspector Witness N/A				·		
Photo # 5			Of	7			Date	3/14/2023	Time	1144
Description		L	leacha	ite leaks	s were observed	l on the we	est slope of	Cell 5.		
Location	Ecc	-V	vista C	lass 1 I	andfill		Permit	0290-S1-R3	AFIN	72-00144
Photograph	er	Т	obin l	Baker, I	Inspector	TB	Witness	N/A	•	
Photo #	6	1	Of	7			Date	3/14/2023	Time	1243
Description		A	A leach	nate lea	k was observed	on the eas	st slope of C	cell 8.		•

Location	Eco-	-Vista C	lass 1 I	andfill		Permit	0290-S1-R3	AFIN	72-00144
Photograph	ner	Tobin I	Baker, l	nspector	TB	Witness	N/A		
Photo #	7	Of	7			Date	3/14/2023	Time	1252
Description	l	A leach	nate lea	k was observed	on the nor	th slope of	Cell 8 of the landfill.		
		hal	mark						
		-		Carls & Aller	The fund	Tor a Pala	Salaster 2 -		
		- Charles						and the second s	
		E.		Stand Street	The Cast of		Service and	and the Second	
				The Art State	and the second	A series and	CONK DO		
								A STATE	
			A State			PHENON !!	Contraction of the second		
					1. 5		The Total	8.41.3	
						E 18	NAL PROV	15 SA	
		12 /2			1			100	
				And the second second	1 / Jer		Seat maker	Sec.	
					11- C				
			the h		14.20		Ser Line	Si.	
		25		and all		(CEPEN	CALL A		
		A.		A Electron	The second				
					St a		XIV		