



ARKANSAS ENERGY & ENVIRONMENT

3/23/2023

Mr. Blake Small
Eco-Vista, LLC
2210 Waste Management Drive
Springdale, AR 72762

RE: Q1 Follow-up #7 conducted on March 15, 2023
AFIN 72-00144
Permit Number 0290-S1-R3

Dear Mr. Small,

The Arkansas Division of Environmental Quality Office of Land Resources (DEQ) conducted a routine inspection of your facility pursuant to the Arkansas Solid Waste Management Act (Arkansas Code, Annotated, § 8-6-201 *et seq.*), of 1971, as amended, the Arkansas Pollution Control & Ecology Commission Regulation 22 (Solid Waste Management), and the above-referenced permit. The inspection identified conditions at your facility which the DEQ alleges are violations. A copy of the inspection report is attached.

You should immediately initiate actions to correct the alleged violations cited. A written response of the corrective actions taken, or to be taken, must be submitted within thirty (30) calendar days from the date on this letter to the attention of Gerry Eddy. The response may include, but is not limited to, photographs, copies of disposal receipts, records, or analytical results, as applicable. If you have any questions regarding the alleged violations, please do not hesitate to contact me at (501) 837-6916 or eddy@adeq.state.ar.us.

Sincerely,

A handwritten signature in black ink that reads 'Gerry Eddy'.

Gerry Eddy
Solid Waste Inspector
5301 Northshore Drive, North Little Rock, AR 72118-5317

Enclosure

cc: Scott McWilliams, Senior Compliance Manager, Regulated Waste Operations



ARKANSAS
ENERGY & ENVIRONMENT

**Office of Land Resources
Regulated Waste Operations
Class 1 Landfill Inspection Form**

Site Name	Eco-Vista Class 1 Landfill	County	Washington	AFIN	72-00144
Facility Address	2210 Waste Management Drive, Springdale, AR 72762	Phone #	870-510-0174	Permit #	0290-S1-R3
Permittee Address	2210 Waste Management Drive, Springdale, AR 72762	Email Address	bsmall@wm.com dtenniso@wm.com	PDS #	125070
Date	03/15/2023	Entry Time	1044	Exit Time	1405

Operational Standards

Category 1


	Regulation	Item Description	Comments
	417	Access Requirements	
	411(j)	Adequate Provision for Backup Equipment	
	423(b)	Annual Compliance Inspection by Registered Engineer	



Category 2



	Regulation	Item Description	Comments
	411(a)	Operations in Accordance with Permit Documents	
	411(c)	Smallest Practical Area, Unloading Supervised, Single Working Face	
	411(b)	Operations by Licensed On-site Personnel at All Times	
	411(g)	Litter Control Provisions Maintained	
	427	Surface Water Controls	
	411(h)(1)	Contouring Prevents Surface Water Flowing Into or Through Waste	
	418(a)(b)	Run-on/off Control System Present and Adequate	
	411(h)(2)	Surface Water Control Prevents Off-site Sediment Accumulation	
	411(i)	Adequate Maintenance of Intermediate/Final Cover Vegetation	
	415	Gas Monitoring Program	
X	411(o)	Leachate Leaks or Evidence of Leachate Seepage	Leachate leaks were observed on the east slope of Phase 2 Cell 5 and north slope of Phase 2 Cells 5, 8, 9, & 10. (Refer to Photos #1 - #4.)
	429	Leachate Collection System	


Category 3

	Regulation	Item Description	Comments
	413(a)	Satisfactory Daily Cover	
	419(a)(5)	Cause Discharge/Leachate Leaving Landfill	
	411(f)(3)	Depositing Waste in Standing Water Prohibited	
X	411(o)	Erosion or Other Cover Defects Resulting in Exposed Refuse	Exposed waste was observed on the daily cover across the top of Cells 10 & 11. (Refer to Photos #5 and #6.)

	309(c)	Overfill/Off Lined Area				
Records						
Date of Last Annual Report		3/31/2022		Date of Last Quarterly Methane Monitoring		11/16/2022
Date of Last Groundwater Monitoring Report		02/23		Previous Quarter Waste Received		109,062.21
Operator Name & Number		Don Tennison 2769		Signature of Inspector		
Exit Interview Conducted with		Don Tennison and Blake Small		Method	On-site	Date
						3/15/2023
						Time
						1405

Location	Eco-Vista Class 1 Landfill				Permit	0290-S1-R3	AFIN	72-00144
Photographer	Gerry Eddy, Inspector			AE	Witness	Don Tennison, Landfill Manager Ryan Hayden, Inspector Supervisor		
Photo #	1	Of	6		Date	03/15/2023	Time	1259
Description	Leachate observed on the west slope of Phase 2 Cell 5.							
								
Location	Eco-Vista Class 1 Landfill				Permit	0290-S1-R3	AFIN	72-00144
Photographer	Gerry Eddy, Inspector			AE	Witness	Don Tennison, Landfill Manager Ryan Hayden, Inspector Supervisor		
Photo #	2	Of	6		Date	03/15/2023	Time	1314
Description	Leachate observed on the north slope of Phase 2 Cell 8.							
								

Location	Eco-Vista Class 1 Landfill				Permit	0290-S1-R3	AFIN	72-00144	
Photographer	Gerry Eddy, Inspector		AE		Witness	Don Tennison, Landfill Manager Ryan Hayden, Inspector Supervisor			
Photo #	3	Of	6		Date	03/15/2023	Time	1316	
Description	Leachate observed on the west slope of Phase 2 Cell 9.								
									
Location	Eco-Vista Class 1 Landfill				Permit	0290-S1-R3	AFIN	72-00144	
Photographer	Gerry Eddy, Inspector		AE		Witness	Don Tennison, Landfill Manager Ryan Hayden, Inspector Supervisor			
Photo #	4	Of	6		Date	03/15/2023	Time	1326	
Description	Leachate observed on the west slope of Phase 2 Cell 10.								
									

Location	Eco-Vista Class 1 Landfill				Permit	0290-S1-R3	AFIN	72-00144
Photographer	Gerry Eddy, Inspector		AS		Witness	Don Tennison, Landfill Manager Ryan Hayden, Inspector Supervisor		
Photo #	5	Of	6		Date	03/15/2023	Time	1328
Description	Exposed waste observed in the daily cover on top of Phase 2 Cell 10.							
								
Location	Eco-Vista Class 1 Landfill				Permit	0290-S1-R3	AFIN	72-00144
Photographer	Gerry Eddy, Inspector		AS		Witness	Don Tennison, Landfill Manager Ryan Hayden, Inspector Supervisor		
Photo #	6	Of	6		Date	03/15/2023	Time	1331
Description	Exposed waste observed in the daily cover on top of Phase 2 Cell 11.							
								