



ARKANSAS ENERGY & ENVIRONMENT

3/27/2023

Mr. Blake Small
Eco-Vista, LLC
2210 Waste Management Drive
Springdale, AR 72762

RE: Q1 Follow-up #8 conducted on March 21, 2023
AFIN 72-00144
Permit Number 0290-S1-R3

Dear Mr. Small,

The Arkansas Division of Environmental Quality Office of Land Resources (DEQ) conducted a routine inspection of your facility pursuant to the Arkansas Solid Waste Management Act (Arkansas Code, Annotated, § 8-6-201 *et seq.*), of 1971, as amended, the Arkansas Pollution Control & Ecology Commission Regulation 22 (Solid Waste Management), and the above-referenced permit. The inspection identified conditions at your facility which the DEQ alleges are violations. A copy of the inspection report is attached.

You should immediately initiate actions to correct the alleged violations cited. A written response of the corrective actions taken, or to be taken, must be submitted within thirty (30) calendar days from the date on this letter to the attention of Jason Gilkey. The response may include, but is not limited to, photographs, copies of disposal receipts, records, or analytical results, as applicable. If you have any questions regarding the alleged violations, please do not hesitate to contact me at (501) 993-7188 or jason.gilkey@adeq.state.ar.us.

Sincerely,

A handwritten signature in black ink that reads 'Jason C. Gilkey'.

Jason Gilkey
Solid Waste Inspector
5301 Northshore Drive, North Little Rock, AR 72118-5317

Enclosure

cc: Scott McWilliams, Senior Compliance Manager, Regulated Waste Operations



ARKANSAS
ENERGY & ENVIRONMENT

**Office of Land Resources
Regulated Waste Operations
Class 1 Landfill Inspection Form**

Site Name	Eco-Vista Class 1 Landfill	County	Washington	AFIN	72-00144
Facility Address	2210 Waste Management Drive, Springdale, AR 72762	Phone #	870-510-0174	Permit #	0290-S1-R3
Permittee Address	2210 Waste Management Drive, Springdale, AR 72762	Email Address	bsmall@wm.com	PDS #	125090
Date	03/21/2023	Entry Time	0933	Exit Time	1320

Operational Standards

Category 1

	Regulation	Item Description	Comments
	417	Access Requirements	
	411(j)	Adequate Provision for Backup Equipment	
	423(b)	Annual Compliance Inspection by Registered Engineer	


Category 2

	Regulation	Item Description	Comments
	411(a)	Operations in Accordance with Permit Documents	
	411(c)	Smallest Practical Area, Unloading Supervised, Single Working Face	
	411(b)	Operations by Licensed On-site Personnel at All Times	
	411(g)	Litter Control Provisions Maintained	
	427	Surface Water Controls	
	411(h)(1)	Contouring Prevents Surface Water Flowing Into or Through Waste	
	418(a)(b)	Run-on/off Control System Present and Adequate	
	411(h)(2)	Surface Water Control Prevents Off-site Sediment Accumulation	
	411(i)	Adequate Maintenance of Intermediate/Final Cover Vegetation	
	415	Gas Monitoring Program	
X	411(o)	Leachate Leaks or Evidence of Leachate Seepage	Leachate leaks were observed on Cells 4, 9, 10, 11, and 12. (Refer to Photos #3 - #8.)
	429	Leachate Collection System	

Category 3

	Regulation	Item Description	Comments
	413(a)	Satisfactory Daily Cover	
	419(a)(5)	Cause Discharge/Leachate Leaving Landfill	
	411(f)(3)	Depositing Waste in Standing Water Prohibited	
X	411(o)	Erosion or Other Cover Defects Resulting in Exposed Refuse	Depressions and exposed waste caused by a truck used for hauling cover material were observed in the daily cover across the tops of Cells 9 & 12. (Refer to Photos #1 & #2.)
	309(c)	Overfill/Off Lined Area	

Records

Date of Last Annual Report	3/31/2022	Date of Last Quarterly Methane Monitoring	11/16/2022		
Date of Last Groundwater Monitoring Report	02/23	Previous Quarter Waste Received	109,062.21		
Operator Name & Number	Don Tennison 2769	Signature of Inspector			
Exit Interview Conducted with	Don Tennison	Method	On-site	Date	3/21/2022
				Time	1315

Division of Environmental Quality

Official Photograph Sheet

Location	Eco-Vista Class 1 Landfill				Permit	0290-S1-R3	AFIN	72-00144
Photographer	Jason Gilkey, Inspector			JLG	Witness	N/A		
Photo #	1	Of	8		Date	3/21/2023	Time	1133
Description	Depressions and exposed waste caused by truck used for hauling cover material observed at the southern area of Cell 9.							



Location	Eco-Vista Class 1 Landfill				Permit	0290-S1-R3	AFIN	72-00144
Photographer	Jason Gilkey, Inspector			JLG	Witness	N/A		
Photo #	2	Of	8		Date	3/21/2023	Time	1214
Description	Depressions and exposed waste caused by truck used for hauling cover material observed at the eastern area of Cell 12.							



Division of Environmental Quality

Official Photograph Sheet

Location	Eco-Vista Class 1 Landfill				Permit	0290-S1-R3	AFIN	72-00144
Photographer	Jason Gilkey, Inspector			JLG	Witness	N/A		
Photo #	3	Of	8		Date	3/21/2023	Time	1122
Description	Leachate seep observed on the western slope of Cell 4.							



Location	Eco-Vista Class 1 Landfill				Permit	0290-S1-R3	AFIN	72-00144
Photographer	Jason Gilkey, Inspector			JLG	Witness	N/A		
Photo #	4	Of	8		Date	3/21/2023	Time	1149
Description	Leachate leak observed on the northern slope of Cell 9.							



Division of Environmental Quality

Official Photograph Sheet

Location	Eco-Vista Class 1 Landfill				Permit	0290-S1-R3	AFIN	72-00144
Photographer	Jason Gilkey, Inspector			<i>JLG</i>	Witness	N/A		
Photo #	5	Of	8		Date	3/21/2023	Time	1150
Description	Leachate leak observed on the northern slope of Cell 10.							



Location	Eco-Vista Class 1 Landfill				Permit	0290-S1-R3	AFIN	72-00144
Photographer	Jason Gilkey, Inspector			<i>JLG</i>	Witness	N/A		
Photo #	6	Of	8		Date	3/21/2023	Time	1206
Description	Leachate leak observed on the northern slope of Cell 11.							



Division of Environmental Quality Official Photograph Sheet

Location	Eco-Vista Class 1 Landfill				Permit	0290-S1-R3	AFIN	72-00144
Photographer	Jason Gilkey, Inspector			JLG	Witness	N/A		
Photo #	7	Of	8		Date	3/21/2023	Time	1222
Description	Leachate leak observed on the western slope of Cell 12.							



Location	Eco-Vista Class 1 Landfill				Permit	0290-S1-R3	AFIN	72-00144
Photographer	Jason Gilkey, Inspector			JLG	Witness	N/A		
Photo #	8	Of	8		Date	3/21/2023	Time	1223
Description	Leachate leak observed on the western slope of Cell 12.							

