



**DIVISION OF
ENVIRONMENTAL QUALITY**

126764

Sarah Huckabee Sanders
GOVERNOR

Shane E. Khoury
SECRETARY

7/25/2023

Mr. Robert Hendrix
Craighead SWDA
P.O. Box 16777
Jonesboro, AR 72403

**RE: Inspection conducted on July 18, 2023
AFIN 16-00199
Permit Number 0254-S1-R4**

Dear Mr. Hendrix,

The Arkansas Division of Environmental Quality Office of Land Resources (DEQ) conducted a routine inspection of your facility pursuant to the Arkansas Solid Waste Management Act (Arkansas Code, Annotated, § 8-6-201 *et seq.*), of 1971, as amended, the Arkansas Pollution Control & Ecology Commission Regulation 22 (Solid Waste Management), and the above-referenced permit. The inspection identified conditions at your facility which the DEQ alleges are violations. A copy of the inspection report is attached.

You should immediately initiate actions to correct the alleged violations cited. A written response of the corrective actions taken, or to be taken, must be submitted within thirty (30) calendar days from the date on this letter to the attention of Tobin Baker. The response may include, but is not limited to, photographs, copies of disposal receipts, records, or analytical results, as applicable. If you have any questions regarding the alleged violations, please do not hesitate to contact me at (501) 837-2097 or Tobin.Baker@adeq.state.ar.us.

Sincerely,

A handwritten signature in dark ink that reads 'Tobin Baker'.

Tobin Baker
Solid Waste Inspector

cc: Nicholas Jones P.E., Senior Operations Manager, Office of Land Resources

**Division of Environmental Quality
Office of Land Resources
Class 1 Landfill Inspection Form**

Site Name	Craighead County SWDA Class 1	County	Craighead	AFIN	16-00199
Facility Address	238 CR 476 Jonesboro, AR 72404	Phone #	870-972-6353	Permit #	0254-S1-R4
Permittee Address	P.O. Box 16777, Jonesboro AR 72403	Email Address	rhendrix@ccswda.com	PDS #	126764
Date	7/18/2023	Entry Time	0830	Exit Time	1125

Operational Standards

Category 1

Regulation	Item Description	Comments
417	Access Requirements	
411(j)	Adequate Provision for Backup Equipment	
423(b)	Annual Compliance Inspection by Registered Engineer	

Category 2

Regulation	Item Description	Comments
411(a)	Operations in Accordance with Permit Documents	
411(c)	Smallest Practical Area, Unloading Supervised, Single Working Face	
411(b)	Operations by Licensed On-site Personnel at All Times	
411(g)	Litter Control Provisions Maintained	
427	Surface Water Controls	
411(h)(1)	Contouring Prevents Surface Water Flowing Into or Through Waste	
418(a)(b)	Run-on/off Control System Present and Adequate	
411(h)(2)	Surface Water Control Prevents Off-site Sediment Accumulation	
411(i)	Adequate Maintenance of Intermediate/Final Cover Vegetation	
415	Gas Monitoring Program	
X	411(o) Leachate Leaks or Evidence of Leachate Seepage	Leachate leaks observed on the west and north slopes of the landfill. (Refer to Photo #1 & #2.)
	429 Leachate Collection System	

Category 3

Regulation	Item Description	Comments
413(a)(b)(c)	Satisfactory Daily/Alternate/Intermediate Cover	
419(a)(5)	Cause Discharge/Leachate Leaving Landfill	
411(f)(3)	Depositing Waste in Standing Water Prohibited	
X	411(o) Erosion or Other Cover Defects Resulting in Exposed Refuse	Erosion with exposed waste observed on the east slope of the landfill. (Refer to Photo #3.)
	309(c) Overfill/Off Lined Area	

Records

Date of Last Annual Report	3/23/2023	Date of Last Quarterly Methane Monitoring	6/28/2023
Date of Last Groundwater Monitoring Report	2/8/2023	Previous Quarter Waste Received	Class 1- 25,898.62 Class 4-13,265.16

Operator Name & Number	Robert Hendrix 003336	Signature of Inspector	
Exit Interview Conducted with	Robert Hendrix	Method	On-site
		Date	7/18/2023
		Time	1120

Division of Environmental Quality Official Photograph Sheet

Location	Craighead County SWDA Class 1				Permit	0254-S1-R4		AFIN	16-00199		
Photographer	Tobin Baker, Inspector				<i>TB</i>	Witness	N/A				
Photo #	1	Of	3		Date	7/18/2023		Time	0919		
Description		Leachate leaks observed on the north slope of the landfill.									
											
Location	Craighead County SWDA Class 1				Permit	0254-S1-R4		AFIN	16-00199		
Photographer	Tobin Baker, Inspector				<i>TB</i>	Witness	N/A				
Photo #	2	Of	3		Date	7/18/2023		Time	1013		
Description		Leachate leaks observed on the west slope of the landfill.									
											

Location	Craighead County SWDA Class 1				Permit	0254-S1-R4	AFIN	16-00199		
Photographer	Tobin Baker, Inspector			TB	Witness	N/A				
Photo #	3	Of	3		Date	7/18/2023	Time	1026		
Description	Erosion with exposed waste observed on the east slope of the landfill.									