



DIVISION OF
ENVIRONMENTAL QUALITY

128753

Sarah Huckabee Sanders
GOVERNOR

Shane E. Khoury
SECRETARY

1/4/2024

Mr. Blake Small
Eco-Vista, LLC
2210 Waste Management Drive
Springdale, AR 72762

RE: Inspection conducted on December 19, 2023
AFIN 72-00144
Permit Number 0290-S1-R4

Dear Mr. Small,

The Arkansas Division of Environmental Quality Office of Land Resources (DEQ) conducted a routine inspection of your facility pursuant to the Arkansas Solid Waste Management Act (Arkansas Code, Annotated, § 8-6-201 *et seq.*), of 1971, as amended, the Arkansas Pollution Control & Ecology Commission Regulation 22 (Solid Waste Management), and the above-referenced permit. At the time of the inspection, no allegations of noncompliance were observed at your facility. A copy of the inspection report is attached.

If I can be of any further assistance, please do not hesitate to contact me at (501) 993-7188 or jason.gilkey@adeq.state.ar.us

Sincerely,

A handwritten signature in black ink, reading 'Jason C. Gilkey'.

Jason Gilkey
Solid Waste Inspector

cc: Nicholas Jones P.E., Senior Operations Manager, Office of Land Resources

**Division of Environmental Quality
Office of Land Resources
Class 1 Landfill Inspection Form**

Site Name	Eco-Vista Class 1 Landfill	County	Washington	AFIN	72-00144
Facility Address	2210 Waste Management Drive, Springdale, AR 72762	Phone #	870-510-0174	Permit #	0290-S1-R4
Permittee Address	2210 Waste Management Drive, Springdale, AR 72762	Email Address	bsmall@wm.com dtenniso@wm.com	PDS #	128753
Date	12/19/2023	Entry Time	1245	Exit Time	1450

Operational Standards

Category 1

Regulation	Item Description	Comments
417	Access Requirements	
411(j)	Adequate Provision for Backup Equipment	
423(b)	Annual Compliance Inspection by Registered Engineer	

Category 2


Regulation	Item Description	Comments
411(a)	Operations in Accordance with Permit Documents	
411(c)	Smallest Practical Area, Unloading Supervised, Single Working Face	
411(b)	Operations by Licensed On-site Personnel at All Times	
411(g)	Litter Control Provisions Maintained	
427	Surface Water Controls	
411(h)(1)	Contouring Prevents Surface Water Flowing Into or Through Waste	
418(a)(b)	Run-on/off Control System Present and Adequate	
411(h)(2)	Surface Water Control Prevents Off-site Sediment Accumulation	
411(i)	Adequate Maintenance of Intermediate/Final Cover Vegetation	
415	Gas Monitoring Program	
411(o)	Leachate Leaks or Evidence of Leachate Seepage	
429	Leachate Collection System	

Category 3

Regulation	Item Description	Comments
413(a)(b)(c)	Satisfactory Daily/Alternate/Intermediate Cover	
419(a)(5)	Cause Discharge/Leachate Leaving Landfill	
411(f)(3)	Depositing Waste in Standing Water Prohibited	
411(o)	Erosion or Other Cover Defects Resulting in Exposed Refuse	
309(c)	Overfill/Off Lined Area	

Records

Date of Last Annual Report	3/31/2023	Date of Last Quarterly Methane Monitoring	8/8/2023
Date of Last Groundwater Monitoring Report	9/29/2023	Previous Quarter Waste Received	31,972.38 Tons (October 2023)

Operator Name & Number	Don Tennison 002769	Signature of Inspector					
Exit Interview Conducted with	Don Tennison	Method	On-site	Date	12/19/2023	Time	1445

Division of Environmental Quality Official Photograph Sheet

Location	Eco-Vista Class 1 Landfill				Permit	0290-S1-R4	AFIN	72-00144
Photographer	Jason Gilkey - Inspector			JEG	Witness	NA		
Photo #	1	Of	8		Date	12/19/2023	Time	1431
Description	Overall view of the working face unloading lanes, looking to the east.							



Location	Eco-Vista Class 1 Landfill				Permit	0290-S1-R4	AFIN	72-00144
Photographer	Jason Gilkey - Inspector			JEG	Witness	NA		
Photo #	2	Of	8		Date	12/19/2023	Time	1429
Description	Overall view of the working face, looking to the east.							



Division of Environmental Quality **Official Photograph Sheet**

Location	Eco-Vista Class 1 Landfill	Permit	0290-S1-R4	AFIN	72-00144
Photographer	Jason Gilkey - Inspector	SEG	Witness	NA	
Photo #	3	Of	8	Date	12/19/2023
Description	Another view of the working face being spread, compacted, and covered with soil, looking to the east.				



Location	Eco-Vista Class 1 Landfill	Permit	0290-S1-R4	AFIN	72-00144
Photographer	Jason Gilkey - Inspector	SEG	Witness	NA	
Photo #	4	Of	8	Date	12/19/2023
Description	A view of the previous working face from earlier in the day, looking northwest.				



Division of Environmental Quality

Official Photograph Sheet

Location	Eco-Vista Class 1 Landfill				Permit	0290-S1-R4	AFIN	72-00144
Photographer	Jason Gilkey - Inspector		JEG		Witness	NA		
Photo #	5	Of	8		Date	12/19/2023	Time	1429
Description	A view of the litter control fence on the north edge of the working face, facing northwest.							



Location	Eco-Vista Class 1 Landfill				Permit	0290-S1-R4	AFIN	72-00144
Photographer	Jason Gilkey - Inspector		JEG		Witness	NA		
Photo #	6	Of	8		Date	12/19/2023	Time	1420
Description	A view of the access road up the landfill slope to the working face, and new liner materials stacked looking west.							



Division of Environmental Quality Official Photograph Sheet

Location	Eco-Vista Class 1 Landfill			Permit	0290-S1-R4	AFIN	72-00144
Photographer	Jason Gilkey - Inspector			<i>JEG</i>	Witness	NA	
Photo #	7	Of	8	Date	12/19/2023	Time	1419
Description	Another view of the access road leading to the working face, looking southeast.						



Location	Eco-Vista Class 1 Landfill			Permit	0290-S1-R4	AFIN	72-00144
Photographer	Jason Gilkey - Inspector			<i>JEG</i>	Witness	NA	
Photo #	8	Of	8	Date	12/19/2023	Time	1535
Description	An overview of the Landfill showing the location of the Class 1 working face (blue), the new liner construction (green) and the Class 4 working face (red), facing northeast.						

