



DIVISION OF
ENVIRONMENTAL QUALITY

133948

Sarah Huckabee Sanders
GOVERNOR

Shane E. Khoury
SECRETARY

8/14/2025

Mr. Blake Small
Eco-Vista, LLC
2210 Waste Management Drive
Springdale, AR 72762

RE: Inspection conducted on August 8, 2025
AFIN 72-00144
Permit Number 0290-S4-R2

Dear Mr. Small,

The Arkansas Division of Environmental Quality Office of Land Resources (DEQ) conducted a routine inspection of your facility pursuant to the Arkansas Solid Waste Management Act (Arkansas Code, Annotated, § 8-6-201 *et seq.*), of 1971, as amended, the Arkansas Pollution Control & Ecology Commission Rule, codified as 8 CAR § 60-101 (Solid Waste Management Rules), and the above-referenced permit. At the time of the inspection, no allegations of noncompliance were observed at your facility. A copy of the inspection report is attached.

If I can be of any further assistance, please do not hesitate to contact me at (501) 993-7188 or jason.gilkey@arkansas.gov.

Sincerely,

A handwritten signature in black ink, reading 'Jason C. Gilkey'.

Jason Gilkey
Solid Waste Inspector

cc: Ryan Hayden, Compliance Program Manager, Office of Land Resources

Division of Environmental Quality - Office of Land Resources
Class 4 Landfill Inspection Form

Site Name	Eco-Vista Class 4 Landfill	County	Washington	AFIN	72-00144
Facility Address	2210 Waste Management Drive, Springdale, AR 72762	Phone #	870-510-0174	Permit #	0290-S4-R2
Permittee Address	2210 Waste Management Drive, Springdale, AR 72762	Email Address	bsmall@wm.com dtenniso@wm.com	PDS #	133948
Date	8/8/2025	Entry Time	1115	Exit Time	1340

Operational Standards

Category 1

	Citation	Description	Comments
	8 CAR § 60-617	Record Keeping Requirements	
	8 CAR § 60-607(j)	Adequate Provisions for Backup Equipment	
	8 CAR § 60-619	Annual Engineering Inspection Report	

Category 2


	Citation	Description	Comments
	8 CAR § 60-607(a)	Operations in Accordance with Permit Documents	
	8 CAR § 60-613(c)	Access and Operational Roads	
	8 CAR § 60-607(c)	Working Face	
	8 CAR § 60-607(b)	Operations by Licensed On-site Operator at All Times	
	8 CAR § 60-607(g)	Litter Control	
	8 CAR § 60-622	Survey Controls	
	8 CAR § 60-623	Surface Water Controls	
	8 CAR § 60-607(h)(1)	Contouring Prevents Surface Water Flowing Into or Through Waste	
	8 CAR § 60-607(h)(2)(A)	Surface Water Control Prevents Off-site Sediment Accumulation	
	8 CAR § 60-607(i)	Final Cover Vegetation and Maintenance	
	8 CAR § 60-607(o)(2)	Leachate Leaks or Evidence of Leachate Seepage	

Category 3

	Citation	Description	Comments
	6088 CAR § 60-608	Implementation of Hazardous Waste Exclusion Plan	
	8 CAR § 60-609(a)	Satisfactory Weekly or More Frequent Cover	
	8 CAR § 60-609(b)	Satisfactory Intermediate Cover	
	8 CAR § 60-615(a)(5)	Allow Leachate Unpermitted by NPDES to Leave the Landfill	
	8 CAR § 60-607(o)(1)	Erosion or Other Cover Defects Resulting in Exposed Refuse	
	8 CAR § 60-309(c)	Overfill / Off Lined Area	

Records

Date of Last Annual Report	3/31/2025	Date of Last Quarterly Methane Monitoring	7/15/2025
Date of Last Groundwater Monitoring Report	5/22/2025	Previous Quarter Waste Received	40152.61 Tons

Operator Name & Number	Don Tennison – 002769 C (Expires 12/31/2026)	Signature of Inspector	
-----------------------------------	--	-------------------------------	---

Exit Interview Conducted with	Don Tennison- Facility Manager	Method	On-site	Date	8/8/2025	Time	1335
--------------------------------------	--------------------------------	---------------	---------	-------------	----------	-------------	------

Division of Environmental Quality Official Photograph Sheet

Location	Eco-Vista Class 4 Landfill				Permit	0290-S4-R2	AFIN	72-00144
Photographer	Jason Gilkey - Inspector			JLG	Witness	NA		
Photo #	1	of	2		Date	8/8/2025	Time	1233
Description	The Class 4 working face was observed in operation, facing north.							



Location	Eco-Vista Class 4 Landfill				Permit	0290-S4-R2	AFIN	72-00144
Photographer	Jason Gilkey - Inspector			JLG	Witness	NA		
Photo #	2	of	2		Date	8/8/2025	Time	1233
Description	The working face was observed in operation, facing west.							

