



DIVISION OF ENVIRONMENTAL QUALITY

Sarah Huckabee Sanders

GOVERNOR

Shane E. Khouri

SECRETARY

8/26/2025

Ms. Sarah M. Ross
Georgia Pacific Crossett LLC
P.O. Box 3333
Crossett, AR 71635-3333

RE: Inspection conducted on August 21, 2025
AFIN 02-00013
Permit Number 0292-S3N

Dear Ms. Ross,

The Arkansas Division of Environmental Quality Office of Land Resources (DEQ) conducted a routine inspection of your facility pursuant to the Arkansas Solid Waste Management Act (Arkansas Code, Annotated, § 8-6-201 *et seq.*), of 1971, as amended, the Arkansas Pollution Control & Ecology Rule, codified as 8 CAR § 60 (Solid Waste Management Rules), and the above-referenced permit. The inspection identified conditions at your facility which the DEQ alleges are violations. A copy of the inspection report is attached.

You should immediately initiate actions to correct the alleged violations cited. A written response of the corrective actions taken, or to be taken, must be submitted within thirty (30) calendar days from the date on this letter to the attention of Casey Jackson. The response may include, but is not limited to, photographs, copies of disposal receipts, records, or analytical results, as applicable. If you have any questions regarding the alleged violations, please do not hesitate to contact me at (501) 682-0832 or casey.jackson@arkansas.gov.

Sincerely,

A handwritten signature in black ink that appears to read "Casey J. Jackson".

Casey Jackson
Solid Waste Inspector

cc: Ryan Hayden, Compliance Program Manager, Office of Land Resources

ARKANSAS DEPARTMENT OF ENERGY AND ENVIRONMENT

ee.arkansas.gov | 5301 Northshore Drive, North Little Rock, AR 72118 |
501.682.0744

Division of Environmental Quality - Office of Land Resources

Class 3 Landfill Inspection Form

Site Name	Georgia Pacific Crossett LLC	County	Ashley	AFIN	02-00013
Facility Address	100 Mill Supply Road , Crossett, AR	Phone #	870-415-6363	Permit #	0292-S3N
Permittee Address	P.O. Box 3333 Crossett, AR 71635	Email Address	sarah.ross@gapac.com	PDS #	133989
Date	8/21/2025	Entry Time	1121	Exit Time	1325

Operational Standards

Category 1

	Citation	Description	Comments
	8 CAR § 60-522	Annual Engineering Inspection Report	

Category 2

	Citation	Description	Comments
	8 CAR § 60-510(a)	Operations in Accordance with Permit Documents	
	8 CAR § 60-516(c)	Access and Operational Roads	
	8 CAR § 60-510(c)	Working Face	
	8 CAR § 60-510(b)	Operations by Licensed On-site Operator at all Times	
	8 CAR § 60-510(d)	Waste Spread and Compacted as Unloaded	
	8 CAR § 60-518	Surface Water Control	
	8 CAR § 60-517	Run-On/Run-Off Control System Present and Adequate	
	8 CAR § 60-510(h)(2)(A)	Surface Water Control Prevents Off-site Sediment Accumulation	
	8 CAR § 60-510(i)(1)	Final Cover Vegetation and Maintenance	
	8 CAR § 60-510(n)(2)	Leachate Leaks or Evidence of Leachate Seepage	
	8 CAR § 60-526	Survey Controls	
	8 CAR § 60-529	Leachate Collection System	

Category 3

	Citation	Description	Comments
	8 CAR § 60-512	Satisfactory Daily/Intermediate/Alternative Cover	
	8 CAR § 60-518(a)(5)	Allow Leachate unpermitted by NPDES to Leave Landfill	
X	8 CAR § 60-510(n)(1)	Erosion Resulting in Exposure of the Infiltration Barrier of the Final Cover System	Erosion exposing the barrier was observed in final cover on the southwest and northwest corners of the landfill. (Refer to Photos #1 - #2.)
	8 CAR § 60-309(c)	Overfill / Off Lined Area	

Records

Date of Last Annual Report	6/30/2025	Date of Last Quarterly Methane Monitoring	N/A
Date of Last Groundwater Monitoring Report	8/8/2025	Previous Quarter Waste Received	0 Tons (Not Active)

Operator Name & Number	William B. Simpson. – 001300 Sarah M. Ross - 002989	Signature of Inspector	<i>Sarah J. Ross</i>
Exit Interview Conducted with	Sarah M. Ross	Method	On-Site

Division of Environmental Quality
Official Photograph Sheet

Location	Georgia Pacific Crossett LLC			Permit	0292-S3N	AFIN	02-00013
Photographer	Casey Jackson			<i>CJS</i>	Witness	N/A	
Photo #	1	of	2		Date	8/21/2025	Time 1233
Description	Erosion was observed on the southwest corner of the landfill. The view is northeast to southwest.						



Location	Georgia Pacific Crossett LLC			Permit	0292-S3N	AFIN	02-00013
Photographer	Casey Jackson			<i>CJS</i>	Witness	N/A	
Photo #	2	of	2		Date	8/21/2025	Time 1242
Description	Erosion with exposed barrier observed on the northwest corner of the landfill. The view is from west to east.						

