


Sanitary Sewer Overflow Monthly Report

Facility Name: Mountain View, City of Permit Number: AR0020117 Reporting Period (Month/Year): Feb 2013
 No Sanitary Sewer Overflows This Monitoring Period

Summary Report Code Descriptions			
Cause(s) of SSO	SSO Impact	Action(s) Taken	Ultimate Discharge Loc
CO-Construction	D-Debris	NEAH-No Evidence of Adverse Health or Environmental Impact	CR-Creek/Stream/River (please specify)
E-Equipment Failure	G-Grease	ORHC-Observed or Evidence of Human Contact	DI-Ditch
HC-Hydro Clean	LF-Line Failure/Break	EFK-Evidence of Fish Kill	DR-Drop Inlet
R-Rainfall	RG-Roots & Grease	HR-Hand Rodded	GR-Ground Surface
RO-Roots	V-Vandalism	EN-Referred to Engineering	PA-Paved Area
		PN-Public Notification	CB-Contained in Build

Location	Manhole #	Start Date of SSO	End Date of SSO	Estimated Volume (in gallons)	Cause of SSO	Environmental Impact	Action (s) Taken to Address SSO	Ultimate Discharge Location
#6 lift station Hwy 66		2-13-13	2-14-13	10 000	R	NEAH		CR
#6 lift station Hwy 66		2-22-13	2-23-13	10 000	R	NEAH		CR
#6 lift station Hwy 66		2-26-13	2-27-13	10 000	R	NEAH		CR


Date: 3-1-13

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

CONFIRMATION NUMBER

244FAD66-7E2E-4D02-93BE-4A40768F2010

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 244FAD66-7E2E-4D02-93BE-4A40768F2010

Date Sent: 3/1/2013

SSO Bypass Upset

Facility Permit Number: **AR0020117**

Facility name: **Mountain View Wastewater**

Date Overflow Began: **02/26/2013**

Time: **6:00 am**

Date Overflow Ended: **02/27/2013**

Time:

Location: **Lift Station #6 Hwy 66**

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume: **10,000**

(Give an estimate in gallons)

Impact of SSO Event: **SSO Reached Receiving Water (river, stream)**

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- OEEI - Observed or Evidence of Environmental Impact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- EPK - Evidence of Fish Kill

Reported By **Joe Thatcher**

Title **Plant Manager**

Telephone Number **(870) 269-8284**

Additional Comments if Needed:

Empty text box for additional comments.

CONFIRMATION NUMBER

8F6DDBFE-00DE-429B-AD73-CCFEE5D6621

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

Close this window Print this page

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 8F6DDBFE-00DE-429B-AD73-CCFEE5D6621

Date Sent: 2/25/2013

SSO Bypass Upset

Facility Permit Number: AR0020117

Facility name:

Mountain View Wastewater

Date Overflow Began: 02/22/2013

Time:

6:00 am

Date Overflow Ended: 02/23/2013

Time:

Location: Lift Station #6 Hwy 66

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume: 10,000

(Give an estimate in gallons)

Impact of SSO Event: SSO Reached Receiving Water (river, stream)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- OEEL - Observed or Evidence of Environmental Impact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- EFK - Evidence of Fish Kill

Reported By Joe Thatcher

Title Plant Manager

Telephone Number (870) 269-8284

Additional Comments if Needed:

CONFIRMATION NUMBER

E3827133-AD7A-4F4B-987C-D426E022ECE0

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

Close this window Print this page

24-Hour Sanitary Sewer Overflow Report

SSO ID#: E3827133-AD7A-4F4B-987C-D426E022ECE0

Date Sent: 2/14/2013

SSO Bypass Upset

Facility Permit Number: AR0020117
Date Overflow Began: 2-13-13
Date Overflow Ended: 2-14-13
Location: Lift station #6 Hwy 66

Facility name: Mountain View Wastewater
Time: 6:30 am

Lift station #6 Hwy 66

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume: 10,000

(Give an estimate in gallons)

Impact of SSO Event: SSO Reached Receiving Water (river, stream)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded Disinfected and Deodorized
- Jet-Vac Hydro Cleaned
- Hand rodded Spread Lime on Affected Area
- Used Generator To Power Pumps/Equipment Public Notification
- Other: Describe

Environmental Damage

- OEHC - Observed or Evidence of Human Contact NEAH - No Evidence of Adverse Health/Environmental Impact
- OEEI - Observed or Evidence of Environmental Impact EFK - Evidence of Fish Kill

Reported By Joe Thatcher Title Plant Manager Telephone Number (870) 269-8284

Additional Comments if Needed:

MOUNTAIN VIEW
WATER & SEWER DEPARTMENT
DRAWER 360
MOUNTAIN VIEW, AR 72560



ADEQ
NPDES Enforcement Section
5301 Northshore Drive
N. Little Rock, AR 72118-5317

721185317 0015

