

Stormwater Management Department

Date/Time of report: 11/25/2014 1400

Location of discharge (Closest intersection or address; GPS Coordinates): Supermercado Las Americas  
400 S. 8th St. Suite A

Report filled out by: Camille Montgomery

Reporting person's phone or address: 479-273-7378 ext 311

Other observers/participants/witnesses: Paul Burns

Observation (odor, suds, sheen, color, stains, floating items, evidence of previous discharges, clear vs. muddy, etc.):

The grease interceptor is overflowing and all of the sewage is flowing into the storm drain.

The whole area is wet with the sewage with trash everywhere.

You can see the layer of grease in the storm drain. Pictures are attached to the e-mail.

Outlet or construction activity nearby: Storm drain

Date/Time of follow-up inspection: 12/09/2014 1300

Actions taken: On 11/18, I requested the G.I. be pumped. Pumping was confirmed on 11/20. However, the GI was still overflowing and on 11/25 I requested that a plumber be called in order to determine the problem with the line directly after the GI. This has been requested for 2 weeks. A plumber was called today 12/9 while I was on site.

Analyses performed on collected samples:

Photo details (notes concerning attached photos): Photo 1-11 shows the flow of the water Beginning with the grease interceptor, moving to the side of the road, into the storm drain, And to the other side of the road in the storm drain.

Additional monitoring recommended: Follow up inspection on 12/11 to confirm plumbing issue is fixed.

Final review and status:









original  
PHILADELPHIA  
original  
KEEP REFRIGERATED  
PHILADELPHIA  
original  
KEEP REFRIGERATED  
PHILADELPHIA  
original  
KEEP REFRIGERATED



DELTA VALLEY ENERGY  
Task ID 2016  
... in renewable energy





USE  
FIRST



