



NOTE:  
 These flows are highly dependent on production volumes. If semiannual report to ADEQ calculations differ by more than 20%, this diagram must be updated with the new numbers and submitted to ADEQ.



PUMP DETAIL



**NOTES:**

1. PRETREATMENT BASIN IS SURROUNDED BY A 4 FT. TALL CHAIN LINK FENCE.
2. PRETREATMENT BASIN IS COVERED BY A CORRUGATED ROOF.



prepared by:  
 Poague & Associates, Inc.  
 2315 Parkway Lane  
 Van Buren, AR 72956  
 www.poague.com

**FIGURE 2**  
 PRETREATMENT PROCESS  
 MACLEAN-ESNA  
 POCAHONTAS, ARKANSAS

REV. 1 9/15/2011