

Kacy Murillo (adpce.ad)

Subject: RE: Nabors Bi-Weekly Site Visit

AFIN: 03-00051

PMT#: 0249-S1-R2

Received

By Kacy Murillo at 11:28 am, Jun 7, 2023

DOC ID#: 84185

TO: MM>FILE <KM

From: Caleb Gourley [<mailto:cgourley@harborenv.com>]

Sent: Tuesday, June 6, 2023 8:30 AM

To: Clay McDaniel (adpce.ad) <Clay.McDaniel@adeq.state.ar.us>

Cc: Tom Huetter <thuetter@harborenv.com>

Subject: Nabors Bi-Weekly Site Visit

Clay,


Please see the attached inspection memo from the site visit conducted at NABORS Landfill on June 2, 2023.

If you have any questions, please let us know.

Thank you,

Caleb Gourley, *Project Manager*

C 501.351.0884 · cgourley@harborenv.com



DATE: June 6, 2023

TO: Clay McDaniel, *Engineer, Division of Environmental Quality
Office of Land Resources, Assessment and Remediation, Technical Branch*

FROM: Caleb Gourley, *Harbor Project Manager*

RE: Bi-weekly Site Inspection
NABORS Landfill
Mountain Home, AR
Harbor Project No: ADEQ-22340

Harbor visited the NABORS landfill in Mountain Home, Arkansas on June 2, 2023, to conduct the bi-weekly landfill inspection. Findings and observations from the landfill inspection are summarized below:

- No stormwater was observed in the tank battery secondary containment. As such, no stormwater was released. The level of leachate in the tanks was measured at 33.1”.
- VLCS-1 was at capacity and overflowing (see photographs 1-2). A large area of wet soil caused by the overflow appears to be attracting deer as evidenced by an abundance of deer tracks.
- VLCS-2 appeared to be functioning correctly.
- LCS-1 displayed a message that read “Autotest in Progress.”
- LCS-3 is functioning in “hand” mode only.
- LCS-2, LCS-5, and LCS-6 are not operational.
- LCS-4, LCS-7, and LCS-8 had pump faults.
- LCS-9 display was working, but level was at 0.0” and not working in “hand” mode.
- Closure turf remains torn on Area 1-2 above LCS-4 (see photographs 3-4).

Photographs are included in Attachment A. A copy of the field notes and the leachate collection system status form are included in Attachment B.

Attachments:

Attachment A – Site Photographs

Attachment B – Leachate Collection System Status Form

Attachment A
Site Photographs



Photograph 1: View of stressed vegetation from VLCS-1 overflow. Abundant deer tracks visible in mud.



Photograph 2: View of overflow at VLCS-1.



Photograph 3: Closure turf tear around turbine vent on the south side of Area 1-2, near LCS-4.



Photograph 4: Closure turf tear around PRV on the south side of Area 1-2, near LCS-4.

Attachment B

**Field Notes and Leachate Collection System
Status Inspection Form**

Date	Notes	Date	Notes
6/2/23	<p>Nabors Landfill Bi-weekly Leachate Management weather: 80's, Sunny, light breeze</p> <p>1040: C.Gourly on-site 1043: Arrive at VLCS-2 1046: Arrive at VLCS-1 1051: Arrive at Leachate tank battery - tank level @ 331" - no stormwater in containment 1056: Arrive at LCS-1 - station reads "Autotest in progress" 1102: Arrive at LCS-2 - station not operational 1105: Arrive at LCS-3 1108: Arrive at LCS-4 1112: Arrive at LCS-5 - station off-line 1117: Arrive at LCS-9 1123: Arrive at LCS-8 1127: Arrive at LCS-7 1129: Arrive at LCS-6 1135: Station not operational 1135: C.Gourly off-site</p>	5/16/23	<p>Nabors Landfill Bi-weekly site visit weather: 70's, clear, light breeze</p> <p>1050: C.Gourly on-site 1053: Arrive at VLCS-2 1056: Arrive at VLCS-1 1100: Arrive at Leachate tank containment - minimal stormwater - none released - tank level @ 483" 1104: Arrive at LCS-1 1109: Arrive at LCS-2 - display is not functioning, but green strobe is activated 1112: Arrive at LCS-3 - not working in AUTO 1115: Arrive at LCS-4 1122: Arrive at LCS-5 - station not operational 1127: Arrive at LCS-9 - no power to UFD 1134: Arrive at LCS-8 1137: Arrive at LCS-7 1139: Arrive at LCS-6 1152: C.Gourly off-site</p>



Leachate Collection System Status

 Date: 6/2/23 Arrival Time: 1040 Location: NABORS Landfill Leachate Tank Battery Level (inches): 0.0

 Weather Conditions: 80's, sunny, light breeze

Panel Number	Display Functioning (Yes/No)	Leachate Level (inches)	Green Flashing? (Yes/No)	Amber Flashing? (Yes/No)	Red Flashing? (Yes/No)	Working in Hand? (Yes/No)	Working in Auto? (Yes/No)	VFD Status	Hours	Alarm	Comments	
											Sump status:	
VLCS-1	N/A	N/A	N/A	N/A	N	N	N	N/A	N/A	N/A	Sump status: at capacity	
VLCS-2	N/A	N/A	N/A	N/A	N	Y	Y	N/A	N/A	N/A	Sump status: 1/2 full	
LCS-1	Y	-	-	-	-	-	-	-	-	-	Autotest in progress	
LCS-2	N	-	-	-	-	-	-	RDY	-	-	station not operational	
LCS-3	Y	14.1	N	N	N	Y	N	-	60	N	station ok	
LCS-4	Y	0.0	N	N	N	N	N	INF	210	Y	Pump fault	
LCS-5	N	-	-	-	-	-	-	-	-	-	Not operational	
LCS-6	N	-	-	-	-	-	-	-	-	-	"	
LCS-7	Y	0.0	N	N	Y	N	N	-	29	Y	Pump fault	
LCS-8	Y	9.7	N	N	N	N	N	OCF	1376	Y	Pump fault	
LCS-9	Y	0.0	N	N	N	N	N	N	2191	N		
General Comments:												