

November 16, 2007

Dan Hesse 1516 Fox Trace Drive Cordova, TN 38016

RE: Storm Water Inspection

AFIN: None NPDES Permit No.: None

Dear Mr. Hesse:

On October 10, 2007, I performed a routine compliance inspection of the waste water treatment facility in accordance with the provisions of the Federal Clean Water Act, the Arkansas Water and Air Pollution Control Act, and the regulations promulgated thereunder. This inspection revealed the following violations:

Sediment from the site had washed into waters of the state from several areas. This is a violation of the Arkansas Water and Air Pollution Control Act (8-4-217) a, 2. The sediment had washed under silt fencing installed on the property. The silt fencing needs repairing.

The above items require your immediate attention. Please submit a written response to these findings to the Water Division Enforcement Section of this Department at the following address:

Water Division Enforcement Section Arkansas Department of Environmental Quality 5301 Northshore Drive North Little Rock, AR 72118-5317

This response should contain detailed documentation describing the course of action taken to correct the items noted. This corrective action should be completed as soon as possible, and the written response is due by December 10, 2007.

For additional information you may contact the enforcement section by telephone at 501-682-0639 or by fax at 501-682-0910.

I also noted that you have an area of bare ground with no vegetative cover that is approximately 1 acre in size. Vegetative cover needs to be established as soon as possible. A suggestion might be to put out mulch or hay to cover the ground before the fall and winter rains.

Dan Hesse Dan Hesse Site November 16, 2007 Page 2

If I can be of any assistance, please contact me at 870-793-5819.

Sincerely,
Mike Kennedy.

Mike Kennedy

District 11 Field Inspector

Water Division

cc: Water Division Enforcement Branch

Water Division Permits Branch

ADEQ Water NPDES Inspection	AFIN: None	Permit #: None

≎ EPA					Form Approved OMB No. 2040-0003						
UNITED STATES ENVIRONM		GENCY									
NPDES Compliance Inspection Report											
Section A: National Data System Coding											
Transaction Code NPDES 1 N 2 5 3 N o - P e r m	Insp 18	w Inspector Fac. Type 19 S 20 2									
		narks									
Inspection Work Days Facility Evaluation F	I	1	QA] 	Reserved						
67 69 70 N	71 N	N 72	N 73 74 75	<u> </u>	80						
	Section B: I	Facility	Data								
Name and Location of Facility Inspected (For industrial users distinctude POTW name and NPDES permit number) Dan Hesse Site	charging to POTW, a	ılso	Entry Time/Date 1200 / 10-10-07		Permit Effective Date N/A						
In Greers Ferry, Arkansas on Highway #16 (Cleburne County)			Exit Time/Date 1300 / 10-10-07		Permit Expiration Date N/A						
Name(s) of On-Site Representative(s)/Title(s)/Phone and Fax Number(s) None Other Facility Data N35°33′58.490″											
Name, Address of Responsible Official/Title/Phone and Fax Num Dan Hesse – Owner / 901-254-2234 Cell 901-489-0816 1516 Fox Trace Drive	ber		Contacted	2°10′49.917″							
Cordova, TN 38016			Yes No								
	ction C: Areas Evalu		uring Inspection sfactory, N = Not Evaluated)								
N Permit N Flow Measureme	<u> </u>		erations & Maintenance	N	Sampling						
N Records/Reports N Self-Monitoring	Program N	_ ^	dge Handling/Disposal	N	Pollution Prevention						
U Facility Site Review N Compliance Scho	edules	Pre	etreatment	N	Multimedia						
U Effluent/Receiving Waters N Laboratory	N	N Sto	rm Water	N	Other:						
Section D: Summary	of Findings/Comme	ents (Att	tach additional sheets if necessar	y)							
The Department determined that a permit is not required, at this time. Sediment was observed to have left property lines and flowed into waters of the state. This was observed in several areas on the property; mainly where sediment had flowed under silt fencing that was in need of repair. This is a violation of the Arkansas Water and Air Pollution Act (8-4-217) a, 2. Also observed was an area approximately 1 acre in size that was bare ground with no vegetative cover.											
Name(s) and Signature(s) of Inspector(s) **Tilke **Kusuedy** Mike Kennedy	Agency/Office/Tel AR Dept. of Envir 870-793-5819 / 870	ronmen	tal Quality-Batesville	Date October 17, 2007							
Signature of Reviewer	Agency/Office/Ph	one and	Fax Numbers	Date							

ADEQ Water NPDES Inspection	AFIN: None	Permit #: None	
			=
	T		

Water Division NPDES Photographic Evidence Sheet							
Location: On the south side of Greers Ferry, Arkansas on Highway #16 (Cleburne County)							
Photographer: Mike Kennedy Witness: None							

 Photo #
 1
 Of
 8
 Date:
 10-10-07
 Time:
 1220

Description: This view shows the property looking south from the north side of Highway #16.



 Photographer:
 Mike Kennedy
 Witness:
 None

 Photo #
 2
 Of
 8
 Date:
 10-10-07
 Time:
 1206

Description: This view is looking south from the north side of the property. A branch runs through almost the middle of the property. The water flows north to south toward the tree line.



Water Division NPDES Photographic Evidence Sheet									
Location:	Location: On the south side of Greers Ferry, Arkansas on Highway #16 (Cleburne County)								
Photographer:	apher: Mike Kennedy Witness: None								
Photo #	3	3	Of	8		Date:	10-10-07	Time:	1217
Description: Note the bare ground located on the East side of the branch with a wet weather stream running through the bar The bare area covers approx. more than 1 acre.									ugh the bare ground.




Photographer:		Mike Ke	nnedy		Witness:	None	None		
Photo #	4	Of	8		Date:	10-10-07	10-10-07 Time: 1215		
Description: This is another view of the bare area farther south					n the property.				



Water Division NPDES Photographic Evidence Sheet									
Location:	Location: On the south side of Greers Ferry, Arkansas on Highway #16 (Cleburne County)								
Photographer :	:	Mike Ke	nnedy	Witness: None					
Photo #	5	Of	Of 8 Date: 10-10-07 Time: 1216						
Description:	Description: This view shows where sediment had washed under the silt fencing into waters of the state								



Photographer:		Mike Ke	Mike Kennedy Witness: None						
Photo #	6	Of	8		Date:	10-10-07	10-10-07 Time: 1216		
Description:	Cription: This is another view where sediment had washed under the silt fencing in a different area on the property.							operty.	



	Water Division NPDES Photographic Evidence Sheet								
Location:	Location: On the south side of Greers Ferry, Arkansas on Highway #16 (Cleburne County)								
Photographer	: Mike Kennedy	Witness:	None						

 Photo #
 7
 Of
 8
 Date:
 10-10-07
 Time:
 1211

Description: This view shows a different area where sediment had washed under the silt fencing into the branch.



 Photographer:
 Mike Kennedy
 Witness:
 None

 Photo #
 8
 Of
 8
 Date:
 10-10-07
 Time:
 1208

Description: This view is a little farther up the fence, again showing where sediment had washed into the branch from the property.







Dan G. Hesse, CFP®, CLU, LUTCF Financial Consultant Regional Management Associate dan.hesse@thrivent.com CA Insurance ID No. 0F39467

#03(990)

1516 Fox Trace Dr. Cordova, TN 38016 Office: 901-751-2234 Toll-free: 877-751-2234

10/6/07

Mike Kennedy, Water Div.

Gresponse to your letter daled Nov 16, 2007 I have purchased a truck load of 3" to 4" washed white stone that will be placed along the needed areas of the selt fencing and in the areas "in The ditch" where the Hay Bales Continue to be washed away from large rains. Also, I have Durchased and rec 20 addetional Hay Bales to be squad and placed on the have area, as you indicated, We will plant seed before placing & dist. the Hay. The Botone has been delivered, and should be placed this next week, as it was too muddy tweet for placement. The Hay well be spread as soon as we finish the Rock work.

AFIN: None

Permit #: None


3 T	Water Division NPDES Photographic Evidence Sheet									
Ī	Location: On the south side of Greers Ferry, Arkansas on Highway #16 (Cleburne County)									
Ţ	Photographer: Mike Kennedy Witness: None									
	7	7 Of 8 Date: 10-10-07 Time:								

Of |

1211

ription:

This view shows a different area where sediment had washed under the silt fencing into the branch.



Rockalse
Where the
Hay Bales
Run accross
the Detch
to Slow down
the Water Flow

ographer	:	M	ike Ke	nnedy		Witness:	None			
o #	8	ì	Of	8		Date:	10-10-07	10-10-07 Time:		
ription:		Tl	nis viev	w is a litt	e farther up the fence, again show	ving where sed	iment had washed	into the branch	from the property.	

