



**Appendix B**

Photographic Record

**SITE NAME: MAYFLOWER PIPELINE INCIDENT RESPONSE**  
**SITE LOCATION: MAYFLOWER, ARKANSAS**



DATE: 8/22/2014

**DESCRIPTION:**  
Maintenance activities at the Interstate Drive staging area



DATE: 8/22/2014

**COMMENTS:**  
Clearing and grubbing activities at the north side of the Inlet Channel



**SITE NAME: MAYFLOWER PIPELINE INCIDENT RESPONSE**  
**SITE LOCATION: MAYFLOWER, ARKANSAS**



DATE: 8/23/2014

DESCRIPTION:  
Culvert outlet under I-40



DATE: 8/23/2014

COMMENTS:  
Cove outlet to Lake Conway



**SITE NAME: MAYFLOWER PIPELINE INCIDENT RESPONSE**  
**SITE LOCATION: MAYFLOWER, ARKANSAS**



DATE: 8/25/2014

DESCRIPTION:  
Cleared area on the north side of the Inlet Channel



DATE: 8/27/2014

COMMENTS:  
Installation of polyethylene mats for temporary access road at the Inlet Channel



**SITE NAME: MAYFLOWER PIPELINE INCIDENT RESPONSE**  
**SITE LOCATION: MAYFLOWER, ARKANSAS**



DATE: 8/27/2014

**DESCRIPTION:**  
Locking of polyethylene mats for installation of temporary access road



DATE: 8/28/2014

**COMMENTS:**  
Bypass pump station at the southwest side of the Inlet Channel



**SITE NAME: MAYFLOWER PIPELINE INCIDENT RESPONSE**  
**SITE LOCATION: MAYFLOWER, ARKANSAS**



DATE: 8/28/2014

**DESCRIPTION:**  
Installation of high-density polyethylene pipes for the bypass pumping system



DATE: 9/4/2014

**COMMENTS:**  
Construction of the discharge point for the bypass pumping system



**SITE NAME: MAYFLOWER PIPELINE INCIDENT RESPONSE**  
**SITE LOCATION: MAYFLOWER, ARKANSAS**



DATE: 9/5/2014

DESCRIPTION:  
Installation of temporary dam at the upstream end of the Inlet Channel



DATE: 9/5/2014

COMMENTS:  
Excavation activities at the Inlet Channel



**SITE NAME: MAYFLOWER PIPELINE INCIDENT RESPONSE**  
**SITE LOCATION: MAYFLOWER, ARKANSAS**



DATE: 9/5/2014

**DESCRIPTION:**  
Interstate Drive staging area prepared for sediment solidification activities



DATE: 9/5/2014

**COMMENTS:**  
Sediment solidification in the mixing unit




**SITE NAME: MAYFLOWER PIPELINE INCIDENT RESPONSE**  
**SITE LOCATION: MAYFLOWER, ARKANSAS**



DATE: 9/6/2014

DESCRIPTION:  
Loading of excavated sediment to dump truck



DATE: 9/8/2014

COMMENTS:  
Confirmation sample



**SITE NAME: MAYFLOWER PIPELINE INCIDENT RESPONSE**  
**SITE LOCATION: MAYFLOWER, ARKANSAS**



DATE: 9/9/2014

DESCRIPTION:  
Excavated area at the upstream end of the Inlet Channel



DATE: 9/9/2014

COMMENTS:  
Roll-off boxes containing excavated material retained at the Rock Yard staging area



**SITE NAME: MAYFLOWER PIPELINE INCIDENT RESPONSE**  
**SITE LOCATION: MAYFLOWER, ARKANSAS**



DATE: 9/10/2014

**DESCRIPTION:**  
Backfilling and grading activities at the Inlet Channel



DATE: 9/10/2014

**COMMENTS:**  
Backfilled area at the upstream end of the Inlet Channel



**SITE NAME: MAYFLOWER PIPELINE INCIDENT RESPONSE**  
**SITE LOCATION: MAYFLOWER, ARKANSAS**



DATE: 9/12/2014

**DESCRIPTION:**

Water flowing over the temporary dam at the upstream end of the Inlet Channel, following a heavy rain event



DATE: 9/15/2014

**COMMENTS:**

Repaired temporary dam at the upstream end of the Inlet Channel



**SITE NAME: MAYFLOWER PIPELINE INCIDENT RESPONSE**  
**SITE LOCATION: MAYFLOWER, ARKANSAS**



DATE: 9/18/2014

DESCRIPTION:  
Seen at the excavated surface of the Inlet Channel



DATE: 9/18/2014

COMMENTS:  
Tree stump removed from the Inlet Channel



**SITE NAME: MAYFLOWER PIPELINE INCIDENT RESPONSE**  
**SITE LOCATION: MAYFLOWER, ARKANSAS**



DATE: 9/19/2014

DESCRIPTION:  
Surveying activities at the Inlet Channel



DATE: 9/24/2015

COMMENTS:  
Sample for the Paint Filter Test



**SITE NAME: MAYFLOWER PIPELINE INCIDENT RESPONSE**  
**SITE LOCATION: MAYFLOWER, ARKANSAS**



DATE: 9/30/2014

**DESCRIPTION:**  
Removal of tree stumps from the Open Water Area



DATE: 10/2/2014

**COMMENTS:**  
Temporary crossing at the Inlet Channel for vehicle traffic



**SITE NAME: MAYFLOWER PIPELINE INCIDENT RESPONSE**  
**SITE LOCATION: MAYFLOWER, ARKANSAS**



DATE: 10/2/2014

DESCRIPTION:  
Inlet Channel following completion of excavation and backfilling activities



DATE: 10/8/2014

COMMENTS:  
Loading of PMFI® organoclay onto the deck buggy



**SITE NAME: MAYFLOWER PIPELINE INCIDENT RESPONSE**  
**SITE LOCATION: MAYFLOWER, ARKANSAS**



DATE: 10/8/2014

**DESCRIPTION:**  
Loading of PMFI® organoclay in the excavator bucket



DATE: 10/8/2014

**COMMENTS:**  
Amendment placement at the Heavily Vegetated Area



**SITE NAME: MAYFLOWER PIPELINE INCIDENT RESPONSE**  
**SITE LOCATION: MAYFLOWER, ARKANSAS**



DATE: 10/15/2014

**DESCRIPTION:**  
Interstate Drive staging area prepared for mixing organoclay and sand for the reactive cap placement



DATE: 10/15/2014

**COMMENTS:**  
Decontamination activities



**SITE NAME: MAYFLOWER PIPELINE INCIDENT RESPONSE**  
**SITE LOCATION: MAYFLOWER, ARKANSAS**



DATE: 10/16/2014

**DESCRIPTION:**  
Manual distribution of PMFI® organoclay in the Heavily Vegetated Area



DATE: 10/21/2014

**COMMENTS:**  
Reactive cap placement in the Open Water Area



**SITE NAME: MAYFLOWER PIPELINE INCIDENT RESPONSE**  
**SITE LOCATION: MAYFLOWER, ARKANSAS**



DATE: 10/27/2014

DESCRIPTION:  
Placement of test pan in the Open Water Area



DATE: 10/27/2014

COMMENTS:  
Test pan retrieved from the Open Water Area to verify reactive cap thickness



**SITE NAME: MAYFLOWER PIPELINE INCIDENT RESPONSE**  
**SITE LOCATION: MAYFLOWER, ARKANSAS**



DATE: 10/30/2014

**DESCRIPTION:**  
Temporary staging area for loading of reactive cap material onto the deck buggies



DATE: 10/31/2014

**COMMENTS:**  
Boat launch #1 following the reactive cap placement



**SITE NAME: MAYFLOWER PIPELINE INCIDENT RESPONSE**  
**SITE LOCATION: MAYFLOWER, ARKANSAS**



DATE: 11/6/2014

DESCRIPTION:  
Restored area on the west side of decontamination area



DATE: 11/6/2014

COMMENTS:  
Decontamination activities



**SITE NAME: MAYFLOWER PIPELINE INCIDENT RESPONSE**  
**SITE LOCATION: MAYFLOWER, ARKANSAS**



DATE: 11/6/2014

**DESCRIPTION:**  
Demobilization activities at the Interstate Drive staging area



DATE: 11/6/2014

**COMMENTS:**  
Inlet Channel following completion of construction activities



**SITE NAME: MAYFLOWER PIPELINE INCIDENT RESPONSE**  
**SITE LOCATION: MAYFLOWER, ARKANSAS**



DATE: 11/6/2014

**DESCRIPTION:**  
Open Water Area following completion of construction activities



DATE: 11/6/2014

**COMMENTS:**  
Heavily Vegetated Area following completion of construction activities



**SITE NAME: MAYFLOWER PIPELINE INCIDENT RESPONSE**  
**SITE LOCATION: MAYFLOWER, ARKANSAS**



DATE: 11/6/2014

**DESCRIPTION:**  
Cove downstream of the construction area following completion of construction activities



DATE: 11/19/2014

**COMMENTS:**  
Placement of temporary erosion controls in the Open Water Area