

CONFIRMATION NUMBER

F91D588B-64AD-4ECB-8061-3EE3C6BAC60E

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: F91D588B-64AD-4ECB-8061-3EE3C6BAC60E
Date Sent: 10/28/2015

SSO Bypass Upset Unpermitted Discharge

| | | | |
|-------------------------|---|----------------|-----------------|
| Facility Permit Number: | AR0021750 | Facility name: | Massard |
| Date Overflow Began: | 10/28/2015 | Time: | 11:00 am |
| Date Overflow Ended: | 10/28/2015 | Time: | 12:15 pm |
| Location: | 5704 Free Ferry Road, S003-0200 to 0100, ditch | | |

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm.)

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume: **75**

(Give an estimate in gallons)

Impact of SSO Event: **SSO Reached Receiving Water (river,stream)**

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- | | |
|--|--|
| <input type="checkbox"/> Machine rodded | <input checked="" type="checkbox"/> Disinfected and Deodorized |
| <input type="checkbox"/> Jet-Vac | <input type="checkbox"/> Hydro Cleaned |
| <input type="checkbox"/> Hand rodded | <input type="checkbox"/> Spread Lime on Affected Area |
| <input type="checkbox"/> Used Generator To Power Pumps/Equipment | <input type="checkbox"/> Public Notification |
| <input checked="" type="checkbox"/> Other: Describe | repaired service |

Environmental Damage

- | | |
|--|---|
| <input type="checkbox"/> OEHC - Observed or Evidence of Human Contact | <input checked="" type="checkbox"/> NEAH - No Evidence of Adverse Health/Environmental Impact |
| <input type="checkbox"/> OEEI - Observed or Evidence of Environmental Impact | <input type="checkbox"/> EFK - Evidence of Fish Kill |

Reported By **Jimmie B. Johnson** Title **Superintendent** Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:
jjohnson@fsark.com

CONFIRMATION NUMBER

2C238223-9644-4EDA-8DC7-FD288F1B6886

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 2C238223-9644-4EDA-8DC7-FD288F1B6886
 Date Sent: 10/27/2015

SSO Bypass Upset Unpermitted Discharge
 Facility Permit Number:
 Date Overflow Began:
 Date Overflow Ended:
 Location:

AR0033278
10/26/2015
10/26/2015
3529 South 34th Street, P009-2290, yard

Facility name:
 Time:
 Time:

P Street
10:25 am
10:25 am

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume:

1

(Give an estimate in gallons)

Impact of SSO Event:

SSO Affected Private Property (ground)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded Disinfected and Deodorized
- Jet-Vac Hydro Cleaned
- Hand rodded Spread Lime on Affected Area
- Used Generator To Power Pumps/Equipment Public Notification
- Other: Describe

Environmental Damage

- OEHC - Observed or Evidence of Human Contact NEAH - No Evidence of Adverse Health/Environmental Impact
- OEEI - Observed or Evidence of Environmental Impact EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Superintendent**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:
jjohnson@fsark.com

CONFIRMATION NUMBER

A50FE3F6-81E3-49A9-A963-1BF2A0C3A61C

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: A50FE3F6-81E3-49A9-A963-1BF2A0C3A61C

Date Sent: 10/20/2015

SSO Bypass Upset Unpermitted Discharge

Facility Permit Number:

AR0033278

Facility name:

P Street WWTP

Date Overflow Began:

10/19/2015

Time:

8:54 pm

Date Overflow Ended:

10/19/2015

Time:

11:45 pm

Location:

3005 Pendell Lane P009, 0250-0245

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

Manhole Overflow

Lift Station Overflow

Main Line Overflow

Service Line Overflow

Other Overflow Type: **building overflow**

(Enter overflow type if not listed)

Volume:

171

(Give an estimate in gallons)

Impact of SSO Event:

SSO Affected Private Property (ground)

Cause of Overflow

I & I - Rainfall

Roots

Grease

Debris

Equipment Failure

Construction

Vandalism

Power Failure

Line Failure/Break

Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

Machine rodded

Disinfected and Deodorized

Jet-Vac

Hydro Cleaned

Hand rodded

Spread Lime on Affected Area

Used Generator To Power Pumps/Equipment

Public Notification

Other: Describe

Environmental Damage

OEHC - Observed or Evidence of Human Contact

NEAH - No Evidence of Adverse Health/Environmental Impact

OEEI - Observed or Evidence of Environmental Impact

EFK - Evidence of Fish Kill

Reported By **Steve Floyd**

Title **Supt.**

Telephone Number **(479) 461-0914**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:

CONFIRMATION NUMBER

56652DF4-20FB-4E61-B90C-5548F2D6032F

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 56652DF4-20FB-4E61-B90C-5548F2D6032F

Date Sent: 10/14/2015

SSO Bypass Upset Unpermitted Discharge

Facility Permit Number:

Date Overflow Began:

Date Overflow Ended:

Location:

AR0021750

10/14/2015

10/14/2015

Facility name:

Time:

Time:

Massard WWTP

10:00 am

11:00 am

No. 9 Riverlyn Terrace Basin: RL01 Manhole: 0140

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

Manhole Overflow

Lift Station Overflow

Main Line Overflow

Service Line Overflow

Other Overflow Type: **Pump Station Failure**

(Enter overflow type if not listed)

Volume: 350

(Give an estimate in gallons)

Impact of SSO Event: SSO Reached Receiving Water (river,stream)

Cause of Overflow

I & I - Rainfall

Roots

Grease

Debris

Equipment Failure

Construction

Vandalism

Power Failure

Line Failure/Break

Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

Machine rodded

Disinfected and Deodorized

Jet-Vac

Hydro Cleaned

Hand rodded

Spread Lime on Affected Area

Used Generator To Power Pumps/Equipment

Public Notification

Other: Describe

Pumping Restored

Environmental Damage

OEHC - Observed or Evidence of Human Contact

NEAH - No Evidence of Adverse Health/Environmental Impact

OEEI - Observed or Evidence of Environmental Impact

EFK - Evidence of Fish Kill

Reported By **Steve Floyd**

Title **Supt.**

Telephone Number **(479) 461-0914**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:

sfloyd@fortsmithar.gov

CONFIRMATION NUMBER

081D7931-4259-468A-8EA8-68856EBB4147

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 081D7931-4259-468A-8EA8-68856EBB4147

Date Sent: 10/14/2015

SSO Bypass Upset Unpermitted Discharge

Facility Permit Number:

Date Overflow Began:

Date Overflow Ended:

Location:

AR0021750

10/14/2015

10/14/2015

Facility name:

Time:

Time:

Massard WWTP

10:00 am

11:00 am

No. 3 Riverlyn Terrace Basin: RL01 Manhole: 0110 Overflow at manhole 0110 caused by pump station #8 failure.

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

Manhole Overflow

Lift Station Overflow

Main Line Overflow

Service Line Overflow

Other Overflow Type: **Pump Station Failure**

(Enter overflow type if not listed)

Volume: 350

(Give an estimate in gallons)

Impact of SSO Event: SSO Reached Receiving Water (river,stream)

Cause of Overflow

I & I - Rainfall

Roots

Grease

Debris

Equipment Failure

Construction

Vandalism

Power Failure

Line Failure/Break

Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

Machine rodded

Disinfected and Deodorized

Jet-Vac

Hydro Cleaned

Hand rodded

Spread Lime on Affected Area

Used Generator To Power Pumps/Equipment

Public Notification

Other: Describe

Pumping Restored

Environmental Damage

OEHC - Observed or Evidence of Human Contact

NEAH - No Evidence of Adverse Health/Environmental Impact

OEEL - Observed or Evidence of Environmental Impact

EFK - Evidence of Fish Kill

Reported By **Steve Floyd**

Title **Supt.**

Telephone Number **(479) 461-0914**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:

sfloyd@fortsmithar.gov

24-Hour Sanitary Sewer Overflow Report

SSO ID#: ACD4FEB3-FA18-4564-8B89-FAD1C70E87D8

Date Sent: 10/17/2015

SSO Bypass Upset Unpermitted Discharge

| | | | |
|-------------------------|--|----------------|-----------------|
| Facility Permit Number: | AR0033278 | Facility name: | P Street |
| Date Overflow Began: | 10/17/2015 | Time: | 9:40 am |
| Date Overflow Ended: | 10/17/2015 | Time: | 11:40 am |
| Location: | 4515 Free Ferry Road, P007-2910 to 2900, yard | | |

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, b

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume: **550**

(Give an estimate in gallons)

Impact of SSO Event: **SSO Affected Private Property (ground)**

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Disinfected and Deodorized
- Jet-Vac
- Hydro Cleaned
- Hand rodded
- Spread Lime on Affected Area
- Used Generator To Power Pumps/Equipment
- Public Notification
- Other: Describe

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- OEEI - Observed or Evidence of Environmental Impact
- EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson** Title **Superintendent** Telephone Number (479) 784-2274

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:

jjohnson@fsark.com

CONFIRMATION NUMBER

DE7D6F51-60A0-4740-AC80-AEF3B4C91026

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: DE7D6F51-60A0-4740-AC80-AEF3B4C91026

Date Sent: 10/15/2015

SSO Bypass Upset Unpermitted Discharge

Facility Permit Number:

AR0021750

Facility name:

Massart

Date Overflow Began:

10/15/2015

Time:

8:30 am

Date Overflow Ended:

10/15/2015

Time:

9:15 am

Location:

3922 Mary Street, FL02-0720, yard

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm.)

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume:

450

(Give an estimate in gallons)

Impact of SSO Event:

SSO Affected Private Property (ground)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Disinfected and Deodorized
- Jet-Vac
- Hydro Cleaned
- Hand rodded
- Spread Lime on Affected Area
- Used Generator To Power Pumps/Equipment
- Public Notification
- Other: Describe

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- OEEI - Observed or Evidence of Environmental Impact
- EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Superintendent**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:
jjohnson@fsark.com

CONFIRMATION NUMBER

8450EB57-CF66-4B8B-8BDC-EE1032CEF293

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 8450EB57-CF66-4B8B-8BDC-EE1032CEF293
Date Sent: 11/2/2015

SSO Bypass Upset Unpermitted Discharge

| | | | |
|-------------------------|--|----------------|----------------|
| Facility Permit Number: | AR0021750 | Facility name: | Massart |
| Date Overflow Began: | 10/13/2015 | Time: | 1:55 pm |
| Date Overflow Ended: | 10/13/2015 | Time: | 2:10 pm |
| Location: | 1107 North 52 Street, S006-0490 to 0480, yard | | |

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume:

15

(Give an estimate in gallons)

Impact of SSO Event:

SSO Reached Receiving Water (river,stream)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded Disinfected and Deodorized
- Jet-Vac Hydro Cleaned
- Hand rodded Spread Lime on Affected Area
- Used Generator To Power Pumps/Equipment Public Notification
- Other: Describe

Environmental Damage

- OEHC - Observed or Evidence of Human Contact NEAH - No Evidence of Adverse Health/Environmental Impact
- OEEI - Observed or Evidence of Environmental Impact EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Superintendent**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Correction to Confirmation Number E07DEA34-1FE8-4367-A8B6-A9719EB0BCFB Manhole numbers were originally reported at S006-0275 to 0270

Email a Copy of This Report to the Email Address:
jjohnson@fsark.com

CONFIRMATION NUMBER

E07DEA34-1FE8-4367-A8B6-A9719EB0BCFB

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: E07DEA34-1FE8-4367-A8B6-A9719EB0BCFB

Date Sent: 10/13/2015

SSO Bypass Upset Unpermitted Discharge

Facility Permit Number:

AR0021750

Facility name:

Massart

Date Overflow Began:

10/13/2015

Time:

1:55 pm

Date Overflow Ended:

10/13/2015

Time:

2:15 pm

Location:

1107 North 52 Street, S006-0275 to 0270, yard

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm.)

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume:

15

(Give an estimate in gallons)

Impact of SSO Event:

SSO Reached Receiving Water (river,stream)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded Disinfected and Deodorized
- Jet-Vac Hydro Cleaned
- Hand rodded Spread Lime on Affected Area
- Used Generator To Power Pumps/Equipment Public Notification
- Other: Describe

Environmental Damage

- OEHC - Observed or Evidence of Human Contact NEAH - No Evidence of Adverse Health/Environmental Impact
- OEEL - Observed or Evidence of Environmental Impact EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Superintendent**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:
jjohnson@fsark.com

CONFIRMATION NUMBER

292D3756-58CD-466A-9363-7F5FE2F716A4

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 292D3756-58CD-466A-9363-7F5FE2F716A4

Date Sent: 10/9/2015

SSO Bypass Upset Unpermitted Discharge

Facility Permit Number:

AR0033278

Facility name:

P Street

Date Overflow Began:

10/9/2015

Time:

9:15 am

Date Overflow Ended:

10/9/2015

Time:

10:00 am

Location:

3830 Crystal Lane, FL02-0720, Ditch

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume:

450

(Give an estimate in gallons)

Impact of SSO Event:

SSO Reached Receiving Water (river,stream)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded Disinfected and Deodorized
- Jet-Vac Hydro Cleaned
- Hand rodded Spread Lime on Affected Area
- Used Generator To Power Pumps/Equipment Public Notification
- Other: Describe

Environmental Damage

- OEHC - Observed or Evidence of Human Contact NEAH - No Evidence of Adverse Health/Environmental Impact
- OEEI - Observed or Evidence of Environmental Impact EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Superintendent**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:
jjohnson@fsark.com

CONFIRMATION NUMBER

6347A795-D138-4354-9C16-D25B888B7BB4

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 6347A795-D138-4354-9C16-D25B888B7BB4

Date Sent: 10/7/2015

SSO Bypass Upset Unpermitted Discharge

Facility Permit Number:

AR0033278

Facility name:

P Street

Date Overflow Began:

10/6/2015

Time:

2:00 pm

Date Overflow Ended:

10/6/2015

Time:

3:15 pm

Location:

3604 North View Drive, FL01-1120 to 1110, paved area

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm.)

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume:

75

(Give an estimate in gallons)

Impact of SSO Event:

SSO Reached Receiving Water (river, stream)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Disinfected and Deodorized
- Jet-Vac
- Hydro Cleaned
- Hand rodded
- Spread Lime on Affected Area
- Used Generator To Power Pumps/Equipment
- Public Notification
- Other: Describe **repair**

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- OE EI - Observed or Evidence of Environmental Impact
- EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Superintendent**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:

jjohnson@fsark.com

24-Hour Sanitary Sewer Overflow Report

SSO ID#: CCCAB624-722E-4695-B457-09AF2D95F469

Date Sent: 10/3/2015

SSO Bypass Upset Unpermitted Discharge

Facility Permit Number:

AR0021750

Facility name:

Massard

Date Overflow Began:

10/2/2015

Time:

11:30 am

Date Overflow Ended:

10/2/2015

Time:

4:30 pm

Location:

3317 Royal Scotts Way, 2004-1170 to 1160, yard

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, b

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume:

600

(Give an estimate in gallons)

Impact of SSO Event:

SSO Reached Receiving Water (river,stream)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe repaired service
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- OEEL - Observed or Evidence of Environmental Impact
- EFK - Evidence of Fish Kill

Reported By Jimmie B. Johnson

Title Superintendent

Telephone Number (479) 784-2274

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:

jjohnson@fsark.com

Monthly SSO Report October 2015

| Permit Number | Manhole Number | Location | Receiving Water | Duration Min. | Cause | Volume (Gallons) | Component | Date Overflow Started | Date Overflow Stopped | Started | Stopped | Steps Taken |
|---------------|--|---|-----------------|---------------|---------------------|------------------|--------------|-----------------------|-----------------------|----------|----------|-------------------------------------|
| AR0021750 | Z004-1170 to 1160 | 3317 Royal Scotts Way | yard | 300 | Line Failure/Break | 600 | Service Line | 10/02/2015 | 10/02/15 | 11:30 AM | 4:30 PM | Repair |
| AR0021750 | S006-00490 to 0480 Originally miss reported as S006-0275 to 0270 | 1107 North 52 Street | yard | 15 | Roots | 15 | Service Line | 10/13/2015 | 10/13/15 | 1:55 PM | 2:10 PM | Machine Rodded |
| AR0021750 | RL01-0140 | No. 9 Riverlyn Terrace - Caused by pump station #8 failure. | Creek | 60 | Equipment Failure | 350 | Manhole | 10/14/2015 | 10/14/15 | 10:00 AM | 11:00 AM | Restored Pumping |
| AR0021750 | RL01-0110 | No. 3 Riverlyn Terrace - Caused by pump station #8 failure. | Creek | 60 | Equipment Failure | 350 | Manhole | 10/14/2015 | 10/14/15 | 10:00 AM | 11:00 AM | Restored Pumping |
| AR0021750 | FL02-0720 | 3922 Mary Street | yard | 45 | Grease | 450 | Manhole | 10/15/2015 | 10/15/15 | 8:30 AM | 9:15 AM | Jet-Vac, Dsinfected and Deodorized |
| AR0021750 | S003-0200 to 0100 | 5704 Free Ferry Road | ditch | 75 | Line Failure/Break | 75 | Service Line | 10/28/2015 | 10/28/15 | 11:00 AM | 12:15 PM | Rpaired, Disinfected and Deororized |
| AR0033278 | FL01-1120 to 1110 | 3604 North View Drive | paved area | 75 | Roots | 75 | Service Line | 10/06/2015 | 10/06/15 | 2:00 PM | 3:15 PM | Repair |
| AR0033278 | FL02-0720 | 3830 Crystal Lane | Ditch | 45 | Roots | 450 | Manhole | 10/09/2015 | 10/09/15 | 9:15 AM | 10:00 AM | Machine Rodded |
| AR0033278 | P007-2910 to 2900 | 4515 Free Ferry Road | yard | 110 | Grease | 550 | Service Line | 10/17/2015 | 10/17/15 | 9:40 AM | 11:30 AM | Jet-Vac, Dsinfected and Deodorized |
| AR0033278 | P009-0250 to 0245 | 3005 Pendell Lane | Building | 171 | Roots, Line Failure | 171 | Mainline | 10/19/2015 | 10/19/15 | 8:54 AM | 11:45 PM | Jet-Vac, Dsinfected and Deodorized |
| AR0033278 | P009-2290 | 3529 South 34th Street | yard | 1 | Roots | 1 | Manhole | 10/26/2015 | 10/26/15 | 10:25 AM | 10:25 AM | Machine Rodded, Jet Vac |

ORIGIN ID:FSMA (479) 784-2330
STEVE FLOYD
CITY OF FORT SMITH
3900 KELLEY HIGHWAY
FORT SMITH, AR 72904
UNITED STATES US

SHIP DATE: 20NOV15
ACTWGT: 0.50 LB
CAD: 1731127//NET3670


BILL SENDER

TO NPDES ENFORCEMENT SECTION, WATER
ADEQ
5301 NORTSHORE DRIVE

NORTH LITTLE ROCK AR 72118

(501) 682-0638 REF:
INV. PO: DEPT:

530123F5681D0




TUE - 24 NOV 4:30P

** 2DAY **

TRK# 7750 2519 9499
0201

SA LITA

72118
AR-US LIT



After printing this label:

1. Use the 'Print' button on this page to print your label to your laser or inkjet printer.
2. Fold the printed page along the horizontal line.
3. Place label in shipping pouch and affix it to your shipment so that the barcode portion of the label can be read and scanned.

Warning: Use only the printed original label for shipping. Using a photocopy of this label for shipping purposes is fraudulent and could result in additional billing charges, along with the cancellation of your FedEx account number. Use of this system constitutes your agreement to the service conditions in the current FedEx Service Guide, available on fedex.com. FedEx will not be responsible for any claim in excess of \$100 per package, whether the result of loss, damage, delay, non-delivery, misdelivery, or misinformation, unless you declare a higher value, pay an additional charge, document your actual loss and file a timely claim. Limitations found in the current FedEx Service Guide apply. Your right to recover from FedEx for any loss, including intrinsic value of the package, loss of sales, income interest, profit, attorney's fees, costs, and other forms of damage whether direct, incidental, consequential, or special is limited to the greater of \$100 or the authorized declared value. Recovery cannot exceed actual documented loss. Maximum for items of extraordinary value is \$1,000, e.g. jewelry, precious metals, negotiable instruments and other items listed in our ServiceGuide. Written claims must be filed within strict time limits, see current FedEx Service Guide.