

Monthly SSO Report June 2015

Permit Number	Manhole Number	Location	Receiving Water	Duration Min.	Cause	Volume (Gallons)	Component	Date Overflow Started	Date Overflow Stopped	Started	Stopped	Steps Taken
AR0021750	Z001-0540 to 0530	1806 South Zero Street	building	23	Roots, Debris	115	Main Line	06/01/2015	6/1/2015	9:57 AM	10:20 AM	Machine Rodded
AR0021750	S009-0240 to 0230	4712 Wirsing Avenue	yard	335	Line Failure/Break	335	Service	06/05/2015	6/5/2015	8:00 AM	12:15 PM	repaired line
AR0033278	P008-0330 to 0320	1012 North 34th Street	yard	30	Roots	30	Main Line	06/05/2015	6/5/2015	10:30am	2:30 PM	repaired line
AR0033278	Millcreek Pump Station Force Main	1001 Ballman Road	Storm Drain		Line Failure/Break		Force Main	06/11/2015		2:05 PM		
AR0033278	Millcreek Pump Station Force Main	1001 Ballman Road	Storm Drain	3415	Line Failure/Break	341500	Force Main	06/11/2015	6/13/2015	2:05 PM	11:00 PM	Follow up to SSO ID # OCE0D037-4317-41AA-8A16-113FB52F86F8
AR0033278	MC03-0160-0160	1901 Wheeler Avenue	creek		Line Failure/Break		Main Line	06/13/2015		10:21 AM		
AR0033278	MC03-0170 to 0160	1901 Wheeler Avenue	creek	789	Line Failure/Break	118350	Main Line	06/13/2015	6/13/2015	10:21 AM	11:30 PM	Follow up of SSO ID# 2519F8C9-FA6A-4900-8542-268FFCC7BB7C The overflow was caused by Mill Creek Pumps Station being offline while repairing Force Main.
AR0033278	Z007-0320 to 0300	9500 Belhaven View	yard	75	Roots	375	Main Line	06/20/2015	6/20/2015	1:15 PM	2:45 PM	Jet-Vac, Disinfected and Deodorized
AR0033278	MC05-2315 to 2310	2414 Independence Street	yard	35	Roots	350	Main Line	06/25/2015	6/25/2015	12:10 PM	12:50 PM	Jet-Vac, Disinfected and Deodorized

CONFIRMATION NUMBER

00BB8456-05AE-4EB4-B938-5CB31165CF09

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

Close this window Print this page

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 00BB8456-05AE-4EB4-B938-5CB31165CF09
Date Sent: 6/1/2015

SSO Bypass Upset

Facility Permit Number: **AR0021750**
Date Overflow Began: **6/1/2015**
Date Overflow Ended: **6/1/2015**
Location: **1806 South Zero Street, building**

Facility name: **Massard**
Time: **9:57 am**
Time: **10:20 am**

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume: **115**

(Give an estimate in gallons)

Impact of SSO Event: **SSO Reached Receiving Water (river,stream)**

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded Disinfected and Deodorized
- Jet-Vac Hydro Cleaned
- Hand rodded Spread Lime on Affected Area
- Used Generator To Power Pumps/Equipment Public Notification
- Other: Describe

Environmental Damage

- OEHC - Observed or Evidence of Human Contact NEAH - No Evidence of Adverse Health/Environmental Impact
- OEEI - Observed or Evidence of Environmental Impact EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Superintendent**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:
fjohnson@fsark.com

CONFIRMATION NUMBER

63A03FA9-0C56-4AFC-ADC4-D1F707CFA728

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 63A03FA9-0C56-4AFC-ADC4-D1F707CFA728

Date Sent: 6/8/2015

SSO Bypass Upset

Facility Permit Number: **AR0021750**

Facility name:

Massard

Date Overflow Began: **6/5/2015**

Time:

8:00 am

Date Overflow Ended: **6/5/2015**

Time:

12:15 pm

Location: **4712 Wirsing Avenue, S009-0240 to 0230, yard**

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume:

335

(Give an estimate in gallons)

Impact of SSO Event:

SSO Affected Private Property (ground)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Disinfected and Deodorized
- Jet-Vac
- Hydro Cleaned
- Hand rodded
- Spread Lime on Affected Area
- Used Generator To Power Pumps/Equipment
- Public Notification
- Other: Describe **repaired service**

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- OEEI - Observed or Evidence of Environmental Impact
- EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Superintendent**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:

jjohnson@fsark.com

CONFIRMATION NUMBER

8AF679B7-5455-4957-93F7-AB1AB808092B

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 8AF679B7-5455-4957-93F7-AB1AB808092B

Date Sent: 6/9/2015

SSO Bypass Upset

Facility Permit Number: **AR0033278**

Facility name:

P Street

Date Overflow Began: **6/5/2015**

Time:

10:30 am

Date Overflow Ended: **6/5/2015**

Time:

2:30 pm

Location:

1012 North 34th Street, Is P008-0330 to 0320, yard

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Volume:

30

(Give an estimate in gallons)

Impact of SSO Event:

SSO Affected Private Property (ground)

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe **repaired line**
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- OEEI - Observed or Evidence of Environmental Impact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Superintendent**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Employee delayed turning in paper work.

Email a Copy of This Report to the Email Address:

jjohnson@fsark.com

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 0CE0D037-4317-41AA-BA16-113FB52F86FB

Date Sent: 6/12/2015

SSO Bypass Upset

Facility Permit Number: AR0033278

Date Overflow Began: 6/11/2014

Date Overflow Ended:

Location:

Facility name:

Time:

Time:

P Street

2:05 pm

1001 Ballman Road, Millcreek Pump Station Force Main, Storm Drain

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type: **Force Main**

(Enter overflow type if not listed)

Volume:

(Give an estimate in gallons)

Impact of SSO Event: SSO Reached Receiving Water (river,stream)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe **repair**
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- OEI - Observed or Evidence of Environmental Impact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- EFK - Evidence of Fish Kill

Reported By Jimmie B. Johnson

Title Superintendent

Telephone Number (479) 784-2231

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:

jjohnson@fsark.com

CONFIRMATION NUMBER

1887A4B3-155D-4CF2-8495-ACF85B233019

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 1B87A4B3-155D-4CF2-8495-ACF85B233019

Date Sent: 6/19/2015

SSO Bypass Upset

Facility Permit Number: **AR0033278**

Facility name:

P Street

Date Overflow Began: **6/11/2015**

Time:

2:05 pm

Date Overflow Ended: **6/13/2015**

Time:

11:00 pm

Location: **1001 Ballman Road, Millcreek Pump Station Force Main, Storm Drain**

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow

Other Overflow Type: **Force Main**
(Enter overflow type if not listed)

Volume: **341500**

(Give an estimate in gallons)

Impact of SSO Event: **SSO Reached Receiving Water (river,stream)**

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

repaired line

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- OEEI - Observed or Evidence of Environmental Impact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Superintendent**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Follow up to SSO ID # 0CE0D037-4317-41AA-BA16-113FB52F86FB

Email a Copy of This Report to the Email Address:

jjohnson@fsark.com

CONFIRMATION NUMBER

2519F8C9-FA6A-4900-8542-268FFCC7BB7C

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 2519F8C9-FA6A-4900-8542-268FFCC7BB7C
Date Sent: 6/13/2015

SSO Bypass Upset

Facility Permit Number: AR0033278
Date Overflow Began: 6/13/2015

Facility name:
Time:
Time:

P Street
10:21 am

Location:

1901 Wheeler Avenue, MC03-0160-0160, creek

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume:

(Give an estimate in gallons)

Impact of SSO Event:

SSO Reached Receiving Water (river,stream)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- OEEL - Observed or Evidence of Environmental Impact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- EFK - Evidence of Fish Kill

Reported By Jimmie B. Johnson

Title Superintendent

Telephone Number (479) 784-2231

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:
jjohnson@fsark.com

CONFIRMATION NUMBER

9BC01157-68C3-4FA0-A7AA-1C3B484FAE23

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 9BC01157-68C3-4FA0-A7AA-1C3B484FAE23

Date Sent: 6/19/2015

SSO Bypass Upset

Facility Permit Number: **AR0033278**

Facility name:

P Street

Date Overflow Began: **6/13/2015**

Time:

10:21 am

Date Overflow Ended: **6/13/2015**

Time:

11:30 pm

Location:

1901 Wheeler Avenue, MC03-0170 to 0160, creek

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume: 118,350

(Give an estimate in gallons)

Impact of SSO Event: SSO Reached Receiving Water (river,stream)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe **repaired line**
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- OEEI - Observed or Evidence of Environmental Impact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Superintendent**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Follow up of SSO ID# 2519F8C9-FA6A-4900-8542-268FFCC7BB7C The overflow was caused by Mill Creek Pumps Station being offline will repairing Force Main.

Email a Copy of This Report to the Email Address:

jjohnson@fsark.com

CONFIRMATION NUMBER

AD046D04-F51D-4BE8-9185-4FB58B18D0FA

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

Close this window Print this page

24-Hour Sanitary Sewer Overflow Report

SSO ID#: AD046D04-F51D-4BE8-9185-4FB58B18D0FA
Date Sent: 6/22/2015

[x] SSO [] Bypass [] Upset

Facility Permit Number: AR003
Date Overflow Began: 6/20/2015
Date Overflow Ended: 6/20/2015
Location: 9500 Belhaven View, 2007-0320 to 0300, yard

Facility name:
Time:
Time:

P Street
1:15 pm
2:45 pm

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- [] Manhole Overflow
[] Lift Station Overflow
[x] Main Line Overflow
[] Service Line Overflow
[] Other Overflow Type:

(Enter overflow type if not listed)

Volume: 375

(Give an estimate in gallons)

Impact of SSO Event: SSO Affected Private Property (ground)

Cause of Overflow

- [] I & I - Rainfall
[x] Roots
[] Grease
[] Debris
[] Equipment Failure
[] Construction
[] Vandalism
[] Power Failure
[] Line Failure/Break
[] Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- [] Machine rodded [x] Disinfected and Deodorized
[x] Jet-Vac [] Hydro Cleaned
[] Hand rodded [x] Spread Lime on Affected Area
[] Used Generator To Power Pumps/Equipment [] Public Notification
[] Other: Describe

Environmental Damage

- [] OEHC - Observed or Evidence of Human Contact [x] NEAH - No Evidence of Adverse Health/Environmental Impact
[] OEEI - Observed or Evidence of Environmental Impact [] EFK - Evidence of Fish Kill

Reported By Jimmie B. Johnson

Title Superintendent

Telephone Number (479) 784-2231

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:
jjohnson@fsark.com

CONFIRMATION NUMBER

3DDC5E95-6273-4C4F-BB03-37DBD7C7A125

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 3DDC5E95-6273-4C4F-BB03-37DBD7C7A125
Date Sent: 6/26/2015

SSO Bypass Upset

Facility Permit Number: AR0033278
Date Overflow Began: 6/25/2015
Date Overflow Ended: 6/25/2015
Location:

Facility name:
Time:
Time:

P Street
12:10 pm
12:50 pm

2414 Independence Street, MC05-2315 to 2310, yard

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume: 350

(Give an estimate in gallons)

Impact of SSO Event: SSO Affected Private Property (ground).

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Disinfected and Deodorized
- Jet-Vac
- Hydro Cleaned
- Hand rodded
- Spread Lime on Affected Area
- Used Generator To Power Pumps/Equipment
- Public Notification
- Other: Describe

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- OEEI - Observed or Evidence of Environmental Impact
- EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Superintendent**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:
jjohnson@fsark.com