

BOND CONSULTING ENGINEERS EAST, INC.
3683 STATE HIGHWAY 77 NORTH
MARION, ARKANSAS 72364

PHONE: (870)739-2228

FAX: (870)739-8407

E-mail: bondengineering@hotmail.com

C.H. BOND, JR., P.E.
JEROME B. ALFORD, P.E.
JACK G. BOND, P.E.

October 19, 2015

ADEQ
5301 Northshore Drive
North Little Rock, AR 72118-5317

Attn: Alan Anderson
Water Division Enforcement Branch

RE: NPDES Permit No.AR0021971
Outfall #002


Dear Alan,

We previously reported that our discharge to the River (#002) is now in operation. Through the several weeks of the final construction we held the volume in the pond. Now that we are in operation we have been lowering the pond level in anticipation of winter rains. Because of this our discharge has been quite high. As you review our DMR you will see the concentration of BOD and TSS are well within our permit limits however we suffered overage in mass loading in each of these parameters.

We are now seeing our pond free board at a reasonable level therefore the discharge will drop off correcting the situation creating mass loading violations.

Sincerely,


Jerome Alford, P.E.



Mayor Frank Fogleman

Sanitary Sewer Overflow Monthly Report

Facility Name: Marion, City of Permit Number: AR0021971 Reporting Period (Month/Year): SEPTEMBER 2015
 No Sanitary Sewer Overflows This Monitoring Period

Cause(s) of SSO		Summary Report Code Descriptions		
		SSO Impact	Action(s) Taken	Ultimate Discharge Location
CO-Construction	D-Debris	NEAH-No Evidence of Adverse Health or Environmental Impact		CR-Creek/Stream/River. (please specify)
E-Equipment Failure	G-Grease	OEHC-Observed or Evidence of Human Contact	EC-Environmental Cleanup	DI-Ditch
HC-Hydro Clean	LF-Line Failure/Break	EFK-Evidence of Fish Kill	HC-Hydro Cleaned	DR-Drop Inlet
R-Rainfall	RG-Roots & Grease		HR-Hand Rodded	GR-Ground Surface
RO-Roots	V-Vandalism		EN-Referred to Engineering	PA-Paved Area
			PN-Public Notification	CB-Contained in Building


Location	Manhole #	Start Date of SSO	End Date of SSO	Estimated Volume (in gallons)	Cause of SSO	Environmental Impact	Action (s) Taken to Address SSO	Ultimate Discharge Location


 Signature of Cognizant or Ranking Official

Date 10/20/2015

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

31 MILITARY RD.
MARION AR
72364



ENFORCEMENT BRANCH
ADEQ
5301 NORTH SHORE DR.
NORTH LITTLE ROCK, AR
72118-5317