This a five day follow up to an overflow at liftstation #9. The overflow was caused by an equipment failure. The area affected by the overflow was disinfected and deodorized. Approximately 300 gallons was overflowed. The liftstation was repaired and returned to service.

The confirmation number is 2b45669e-07ef-420d-88cf-de400088781f

John M. Peppers John M. Peppers Treatment Superintendent El Dorado Water Utilitics 870-814-1764

